

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

08 OCT 2018

ESTIMATE

Estimate No. : b1 48690
Date Estimated : 08/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Yong Poh Choo Cindy
15 Kew Heights

Singapore 466013

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME3072S	WE60262	26/09/2018	520i	0

DESCRIPTION

To repair on front left door assembly including remove & installation all attachments.

Painting on front left door assembly

To check electrical wiring systems for proper function.

Sundries.

VALUE

880 1,700.00

796 885.00

150 177.00

? 40.00

Total Labour 1: 2,802.00

No. of Working Days Recommendation _____

Surveyor's E-mail _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Time _____

Surveyor's Signature _____

Surveyor's Tel _____

Authorised Date _____

Excess \$S _____

Date & Time _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 29/10/18 Excess \$S _____

Surveyor's Name Taylor Sign Taylor

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Taylor E. Iwanjaron

No. of Working Days Recommendation 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	2,802.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	196.14
Grand Total	:	2,998.14

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **