

ASS. REC. BY:

REF: CS3/CTI/8018358/Gcd3²

Special Instruction:

Surveyor:

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 10/10/18 @ 11:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCP 51H

Insured:

SGW 2607H

at Workshop m/s

Em solution

Tel:

6456 0226

of

160 Sin Ming Drive # 03-18

Policy No:

DMPCSN 3067 611804

Claim No:

3NM/8D04825C2

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11:35am @ 10/10/18

Person Contacted:

Josephine

Vehicle

IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SCP 51H - X
	SGW 2607H - X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2018		10 Oct 2018 11:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SEET TEE YONG, ID: S6930260B		
Main Claimant:	NGAI YI QIAN, ID: S8845938E		
Vehicle Reg. No.:	SCP51H	Date of Loss:	05/10/2018 20:00 - :59
Claim Type:	TP / SNM18D04825C2	Policy/Cover Note No.:	DMPCSN3067611804 (Comprehensive)
Vehicle Reg. No. (Insured):	SGW2607H	Policy No. (Claimant):	5098503751
		Excess:	S\$0.00
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/10/2018]		
Driver/Custodian (Insured):	SEET TEE YONG (49 / Male), NRIC: S6930260B		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Sally Chong <sallychong@visionlawllc.com>
Sent: Tuesday, 9 October, 2018 5:14 PM
To: Irene Tay; Lucas Lee
Cc: 'EM Solution Pte Ltd'; judysoh@visionlawllc.com
Subject: OUR REF.: E21-108302.18 // RE: CTP REF NO. SGN2607H VL REF NO. SCP51H - ACCIDENT INVOLVING SGN2607H AND SCP51H ON 06 OCTOBER 2018

VERY URGENT

Dear Irene,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: NGAI YI QIAN

ACCIDENT INVOLVING SCP 51H & SGW 2607H ON 5 OCT ALONG UPP SERANGOON ROAD AT ABOUT 20:50 HRS

We refer to the above matter and your list of surveyors.

TAKE NOTICE that we object to your surveyor stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

<u>Name of Surveyor</u>	<u>Company Name</u>
Dennis Yap	Pal's Appraiser Pte Ltd
Michael Yap	Mc-coy Appraiser Pte Ltd
Andy Yap	LCW Appraiser Pte Ltd
B J Loi	Par Automotive Consultancy
Sebastian Lim	Constant Appraiser Services
Lee Yew Hok	Constant Appraiser Services
Alan Cheong	CL Appraiser Pte Ltd

Please be informed that the said vehicle can be inspected at:-

Venue : **E M SOLUTION PTE LTD**
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong
(Secretary)

VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL: 6534-2811 (ext 115)
FAX : 6535-6802

From: Irene Tay [mailto:irene.tay@sg.cntaiping.com]
Sent: Tuesday, 9 October, 2018 4:25 PM
To: Sally Chong; Lucas Lee
Cc: EM Solution Pte Ltd; judysoh@visionlawllc.com
Subject: CTP REF NO. SGN2607H VL REF NO. SCP51H - ACCIDENT INVOLVING SGN2607H AND SCP51H ON 06 OCTOBER 2018

WITHOUT PREJUDICE

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

STA

LKK

LBS

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Tuesday, 9 October, 2018 11:54 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: EM Solution Pte Ltd <emautosolution@singnet.com.sg>; judysoh@visionlawllc.com

Subject: RE: OUR REF.: E21.MISC.18 (SCP 51H @ 06.10.2018) // CHINA TAIPING REF NO : SGN 2607H

Importance: High

URGENT REMINDER
VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: NGAI YI QIAN

ACCIDENT INVOLVING SCP 51H & SGW 2607H ON 5 OCT ALONG UPP SERANGOON ROAD AT ABOUT 20:50 HRS

We are instructed by **NGAI YI QIAN** to notify you of a road traffic accident **ON 5 OCT ALONG UPP SERANGOON ROAD AT ABOUT 20:50 HRS** involving our client's vehicle registration number **SCP 51H** and vehicle registration number **SGW 2607H** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Monday, 8 October, 2018 5:13 PM
To: 'claimsdept@sg.cntaiping.com'; 'Angie Foo'; 'Lucas Lee'; 'Irene Tay'
Cc: EM Solution Pte Ltd (emautosolution@singnet.com.sg); 'Judysoh@visionlawllc.com'
Subject: OUR REF.: E21.MISC.18 (SCP 51H @ 06.10.2018) // CHINA TAIPING REF NO : SGN 2607H
Importance: High

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: NGAI YI QIAN

ACCIDENT INVOLVING SCP 51H & SGW 2607H ON 6 OCT ALONG UPP SERANGOON ROAD AT ABOUT 20:50 HRS

We are instructed by **NGAI YI QIAN** to notify you of a road traffic accident **ON 6 OCT ALONG UPP SERANGOON ROAD AT ABOUT 20:50 HRS** involving our client's vehicle registration number **SCP 51H** and vehicle registration number **SGW 2607H** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL: 6534-2811 (ext 115)

FAX : 6535-6802

C.c.: VEHICLE OWNER OF SGW 2607H

SEET TEE YONG

207D, Compassvale Lane,

#03-60,

Singapore 547207

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2018 17:19
Date Of Accident	06/10/2018 20:50
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCP51H
Insured/Policyholder	
Name Of Registered Owner	NGAI YI QIAN
NRIC No	S8845938E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97562381
Alternative Phone No	OTHERS-97562381

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098503751
Cover Note Number	

Driver

Name of Driver	NGAI YI CONG
NRIC No	S9204885C
Date Of Birth	10/02/1992
Occupation	INDOOR
Date Of Driving Pass	06/08/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97562381
Fax Number	
Contact Number	OTHERS-97562381
Email Address	NOEMAIL

Address	8 WHAMPOA EAST #13-18
Postcode	338520
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DING XUAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	POTONG PASIR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 142 POTONG PASIR AVENUE 3 , POSTCODE: 350142 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2829999 - FAX NO: 62815964
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGW2607H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SEET TEE YONG
NRIC/Passport Number	S6930260B
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NHAI YI CONG

Approximate Age

Injuries Sustain

REFER POLICE REPORT

Injured person in which vehicle?

SCP51H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

DING XUAN

Approximate Age

Injuries Sustain

REFER POLICE REPORT

Injured person in which vehicle?

SCP51H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Please refer To Police Report ATTACHED

Police report ATTACHED T/20181006/2017

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5938E
Vehicle Details	
Vehicle No.:	SCP51H
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 (R18 BI)
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	27091030403267
Chassis No.:	WDD1173422N094870
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,415.00
Original Registration Date:	18 Jun 2014
First Registration Date:	18 Jun 2014
Transfer Count:	2
Actual ARF Paid:	\$20,381.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2024
PARF Rebate Amount:	\$14,266.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$65,501.00
COE Rebate Amount:	\$28,100.00
Total Rebate Amount:	\$42,366.00

The information contained herein is correct as at 11 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2018		10 Oct 2018 11:17 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SEET TEE YONG, ID: S6930260B		
Main Claimant:	NGAI YI QIAN, ID: S8845938E		
Vehicle Reg. No.:	SCP51H	Date of Loss:	05/10/2018 20:00 - :59 [51 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04825C2	Policy/Cover Note No.:	DMPCSN3067611804 (Comprehensive)
Vehicle Reg. No. (Insured):	SGW2607H	Policy No. (Claimant):	S098503751
		Excess:	S\$0.00
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/10/2018]		
Driver/Custodian (Insured):	SEET TEE YONG (49 / Male), NRIC: S6930260B		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCP51H (SNM18D04825C2)**
[SGW2607H]

TP

NGAI YI QIAN

Oct 5 2018 8:00PM

[SEET TEE YONG]

E M Solution Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	08/10/18 17:32	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	08/10/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 17:09	General View	Load PDF	
2	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
3	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
4	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
5	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
6	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
7	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
8	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
9	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
10	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
11	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
12	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
13	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
14	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
15	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
16	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
17	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
18	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
19	13/10/18 13:10	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
20	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	13/10/18 13:10	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/10/18 11:16	PRS	 Load PDF	
2	10/10/18 11:17	OI GIA	 Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	08/10/18 17:30	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	08/10/18 17:30	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	08/10/18 17:31	Common Statement [Linked Accident Report Documents]	 Load TIF	
4	08/10/18 17:31	Common Statement [Linked Accident Report Documents]	 Load TIF	
5	08/10/18 17:31	Common Statement [Linked Accident Report Documents]	 Load TIF	
6	08/10/18 17:31	Common Statement [Linked Accident Report Documents]	 Load TIF	
7	08/10/18 17:31	Common Statement [Linked Accident Report Documents]	 Load TIF	
8	08/10/18 17:31	Common Statement [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	08/10/18 17:32	Accident Statement	 Load HTM	
2	11/10/18 16:36	Addendum Sheet	 Load TIF	
3	11/10/18 16:41	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	08/10/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	08/10/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	08/10/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	08/10/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	✓
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
7	08/10/18 17:29	Accident Photo	 Load JPG	✓
8	08/10/18 17:29	Accident Photo	 Load JPG	✓
9	08/10/18 17:29	Accident Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	08/10/18 17:30	Sketch Plan	 Load TIF	
2	08/10/18 17:30	Sketch Plan #2	 Load TIF	
3	08/10/18 17:31	Common Statement	 Load TIF	
4	08/10/18 17:31	Common Statement	 Load TIF	
5	08/10/18 17:31	Common Statement	 Load TIF	
6	08/10/18 17:31	Common Statement	 Load TIF	
7	08/10/18 17:31	Common Statement	 Load TIF	
8	08/10/18 17:31	Common Statement	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18018358/GCD3S2

Date: 17/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3067611804
Claimant Vehicle No :	SCP51H	Insured Vehicle No :	SGW2607H
Date of Loss:	05/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04825C2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCP51H	Engine No:	27091030403267
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Chassis No:	WDD1173422N094870
Reg. Date:	18/06/2014 (Man. Year: 2014)	Odometer:	129919 km
Colour:	Silver		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	10/10/2018	
Date Inspected:	10/10/2018	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2018)

Parts: 143 MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCP51H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >