

22/03/2002

ASS. REC. BY:

REF:

CS3/FWD18018381/Ucd31

Special instruction:

Surveyor:

menmin

Marius

ASSIGNMENT (Office)

From (Person):

clara li

of

FWD

Date/Time:

10/10/18 @ 2.39pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 586G

Insured:

SKA 470R

at Workshop m/s

Z-One Automotive

Tel:

9755 2115

of

1 kaki Bkt Ave 6 # 01-87

Policy No:

PNPV 2018-00010248

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/10/2018

CA / REV / REP. / REV 24 HRS (up)

11/10/2018

H.O.D. Endorsement:

Date/Time:

2.49pm @ 10/10/18

Person Contacted:

Yvonne

Vehicle:

IN/OUT

Date/Time	Action/Instruction (x) Estimate
	SMC 586G - X
	SKA 470R - X
	After repair : 17/10/2018

REF: FWD

ASSIGNMENT

From: _____ Date: 11/10/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 586G

at Workshop m/s Z-One Automotive

of Ikaki Bkt Ave G # 01-87

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 3200

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

3/8/2013

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMC 586G Yr Regn: 1008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Toyota wsh C.C. 1794

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 18690 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2N6100410669

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215/45ZRH

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

no Lot 488 LTA 22488
 4-5h. Exhaust repair Trim board No 212.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee: 80

2)

Add Fee:

☐ : Site Insp (\$)

Transportation: 50

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format: PRE

Lump Sum / I.B.I: (\$)

130

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Wednesday, 10 October 2018 2:39 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Our client's vehicle no. SMC586G (Z-One); Your insured's vehicle no. SKA470R - PRI Our Ref: PNPV2018-00010248
Attachments: Z-One - Pre-Repair Notice (FWD)(SMC586G).pdf

Hi LKK team,

Please refer to the email below and liaise with TP repairer for survey arrangement.

Attached is the TP GIA report.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



From: Clara Li Zirong - SGUser
Sent: Wednesday, 10 October, 2018 2:38 PM
To: 'Hui Ting'
Cc: Motor Claims SG - SG Common; Corene

Subject: RE: Our client's vehicle no. SMC586G (Z-One); Your insured's vehicle no. SKA470R - PRI Our Ref: PNPV2018-00010248

WITHOUT PREJUDICE

Dear Huiting,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your client's vehicle, SMC586G. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Clara Li

Senior Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



From: Hui Ting [<mailto:huiting@crossbordersllc.com>]

Sent: Wednesday, 10 October, 2018 2:36 PM

To: Clara Li Zirong - SGUser

Cc: Motor Claims SG - SG Common; Corene

Subject: RE: Our client's vehicle no. SMC586G (Z-One); Your insured's vehicle no. SKA470R - PRI Our Ref: PNPV2018-00010248

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Clara

1. We refer to your email dated 10 October 2018.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-
 - a) Dennis Yap PAL'S Appraiser Pte Ltd
 - b) Yap Teck Lee LCW Appraiser Pte Ltd
 - c) Yap Teck Chye MC-Coy Appraiser Pte Ltd
 - d) Dixon Yeo Treasure Appraiser Pte Ltd
 - e) Marc Ananda United Appraisal and Management Pte Ltd
 - f) Andrew How Prominent Appraiser Services
 - g) Alan Cheong K.H. C L Appraiser Pte Ltd
 - h) T.T. Rajan ST Appraisal Services
 - i) Sebastian Lim Constanct Appraiser Services
 - j) Aeon Auto Consultants LLP
4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: clara.li@fwd.com <clara.li@fwd.com>

Sent: Wednesday, 10 October 2018 2:33 PM

To: Hui Ting <huiting@crossborderllc.com>

Cc: motorclaims.sg@fwd.com

Subject: RE: Our client's vehicle no. SMC586G (Z-One); Your insured's vehicle no. SKA470R - PRI Our Ref: PNPV2018-00010248

WITHOUT PREJUDICE

Dear Huiting,

We refer to your letter dated 10 October 2018 of the PRI Notice of your client's vehicle SMC586G.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg





From: Hui Ting [<mailto:huiting@crossbordersllc.com>]

Sent: Wednesday, 10 October, 2018 11:27 AM

To: Motor Claims SG - SG Common

Cc: Corene

Subject: Our client's vehicle no. SMC586G (Z-One); Your insured's vehicle no. SKA470R - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. Please find attached our PRI notice dated 10 October 2018 for your kind attention.
2. Please reply email to corene@crossbordersllc.com & huiting@crossbordersllc.com

Thank You.

Regards

Huiting

TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.Z (SMC586G)
Your Ref: SKA470R

10 October 2018

FWD SINGAPORE PTE. LTD.
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Attn: Motor Claims Department

BY FAX EMAIL ONLY
motorclaims.sg@fwd.com

URGENT

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY
CLAIMANT: WONG CHI MENG
TRAFFIC ACCIDENT ON 10 OCTOBER 2018 AT 07:33 HRS ALONG PIE TOWARDS
CHANGI BEFORE SIMEI EXIT INVOLVING VEHICLES NO. SMC586G & SKA470R

We are instructed by Wong Chi Meng to notify you of a road accident on 10 October 2018 at about 07:33 hrs along PIE towards Changi before Simei Exit involving our client's vehicle registration number SMC586G and vehicle registration number SKA470R driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Z-One Automotive Pte Ltd
Address: 1 Kaki Bukit Avenue 6
#01-87/85 Autobay @ Kaki Bukit
Singapore 417883
Contact: Yvonne @ 9755 2115 / 6250 2115

Please liaise with the above workshop directly.

Yours faithfully

Crossborders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2208C
Vehicle Details	
Vehicle No.:	SMC586G
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8XE A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1ZZ3107498
Chassis No.:	ZNE100410669
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,461.00
Original Registration Date:	17 Oct 2008
First Registration Date:	17 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$10,776.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2018
PARF Rebate Amount:	\$5,388.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$17,496.00
COE Rebate Amount:	\$17,100.00
Total Rebate Amount:	\$22,488.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Oct 2018

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory


Products

Insurance

Articles

Forum

Resources



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

1 Owner Oct 2015 Volvo S60 T5 Drive-E, Low Mileage.



Special Interest Rate Of 1.98%!
Best Price And Best Interest
Rate In Market!
Auto Zoom Enterprise StarAd

PRIME MOTOR & LEASING
JOHNSON YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

* Back (1 2 3 4) Next *

Sort by Date Posted

20 results/page

68 vehicles

Toyota wish

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota wish		Any	Any	2008	Any	Any	Any	Available



**Toyota Wish 1.8A Aero Tourer
(New 5-yr COE)**

\$33,800

\$6,760 /yr

16-Sep-2008

1,794 cc

MPV

Available

In House Loan Available, At Low Monthly Installment, Flexible Loan Available. 100% Accident Free. Trade In Are Welcome, View To Believe Before It's Gone. Please Call For Appointment!

Posted: 11-Oct-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A XE (COE till
08/2023)**

\$36,800

\$7,600 /yr

14-Aug-2008

1,794 cc

136,380 km

MPV

Available

Low Down Payment Of \$6k For Most Sought After MPV, Worn Out Parts Replaced With Comprehensive Warranty! Low Maintenance, Low Cost, Low Fuel Consumption, Highest Trade In Value Guaranteed For Your Car!...

Tay Motor & Credit Pte Ltd

Posted: 11-Oct-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A X (New 10-
yr COE)**

\$54,800

\$5,480 /yr

01-Dec-2008

1,794 cc

120,000 km

MPV

Available

100% Guaranteed No Repair Required, Buy Used Cars From AI Car - Hassle Free With One Stop Motor Workshop Service, 1 Yr Warranty Engine Gearbox With AI Motor Workshop For Renew COE, Accident Free, Opti...

Posted: 10-Oct-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till
07/2023)**

\$34,800

\$7,240 /yr

01-Aug-2008

1,794 cc

MPV

Available

Full Service Done, 3 Months Engine/Gearbox Warranty From Our In House Workshop, Excellent Condition, Accident Free, Bank Loan/In-House Loan Available, Trade In Welcome.

Posted: 10-Oct-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



**Toyota Wish 1.8A X (New 5-yr
COE)**

\$34,800

\$6,960 /yr

18-Nov-2008

1,794 cc

MPV

Available

Up To 95% Loan Package Available. High Approval Rate. Balloon Scheme To Lessen Your Monthly Installment Burden. All Vehicles Are Inspected By Our Professional Team For Highest Quality. Extended Warrant...

Avant Automobile Pte Ltd

Posted: 10-Oct-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (New 5-yr
COE)**

\$34,800

\$6,960 /yr

15-Oct-2008

1,794 cc

90,000 km

MPV

Available

The Most Reliable And Fuel Efficient MPV. Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper! Call Now!

Posted: 10-Oct-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (New 5-yr
COE)**

\$35,800

\$7,160 /yr

30-Oct-2008

1,794 cc

100,890 km

MPV

Available

Posted: 10-Oct-2018 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

Compare

MSME18131403 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 10/10/2018 11:32
SUBMITTED BY: Ghia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2018 11:32
Date Of Accident	10/10/2018 07:35
Exact Location Of Accident	ALONG PIE TWDS CHANGI BEFORE SIMEI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC586G
Insured/Policyholder	
Name Of Registered Owner	WONG CHI MENG
NRIC No	S0102208C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97485221
Alternative Phone No	OFFICE-97485221

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA376034
Cover Note Number	

Driver

Name of Driver	WONG YEE LING SARAH
NRIC No	S8200782B
Date Of Birth	19/01/1982
Occupation	INDOOR
Date Of Driving Pass	09/02/2004
Driving Experience	14 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87918155
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	203 TANAH MERAH KECHIL AVE
Postcode	465729
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 10/10/2018 AT 7.33AM, I WAS TRAVELLING ALONG PIE TOWARDS SIMEI EXIT. THERE IS A TRAFFIC JAM AT THE EXIT. SO, THE VEHICLE IN FRONT OF ME ALL SLOWED DOWN, I ALSO STOPPED. SUDDENLY, I FELT AN IMPACT FROM MY REAR. VEHICLE B (SKA470R) CANNOT STOP IN TIME AND HIT ON MY REAR PORTION. THERE IS NO INJURY IN THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA470R
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	VICTOR LOW SUE KHAI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Insurer's Signature
(if driver joined the police report)
Date & Time:

Reporting Centre Personnel's Signature
(Name):
NIP ID, Photo:

Sketch Plan #2 Pg. 1

SKETCH PLAN



Vehicle A: SMC586G

Vehicle B: SKA470R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/10/2018 7:33am, I was travelling along PIE toward Simeier Exit. There is a traffic jam at the exit. So the vehicle in front of me all slow down, I also stopped. Suddenly I feel an impact from my rear. The vehicle B SKA470R cannot stopped in time and hit on my rear portion. There is no injury in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Date & Time

[Signature]
 Date & Time

[Signature]
 Date & Time

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2018 Edit Reg		10 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Victor Low Sue Khai, ID: S74021851

Main Claimant:

-

Vehicle Reg. No.:

SMC586G

Date of Loss:

10/10/2018 00:00 - :59
[119 Months and 23 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 1201800013089

Policy/Cover Note No.:

PNPV2018-00010248 (Comprehensive)

Vehicle Reg. No. (Insured):

SKA470R

Policy No. (Claimant):

Excess:

Repairer:

Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:

Handling Insurer:

FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/10/2018]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS






































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















Claim Documents

***SMC586G (1201800013089)**
[SKA470R]
TP

-
Oct 10 2018 12:00AM
[Victor Low Sue Khai]
Z-one Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
65	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
66	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
67	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
68	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
69	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
70	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
71	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
72	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
73	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
74	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
75	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
76	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
77	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
78	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
79	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
80	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
81	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
82	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
83	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
84	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
85	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
86	12/10/18 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
87	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	19/10/18 10:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18018381/UCD3E2

Date: 19/10/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010248

Claimant Vehicle No: SMC586G Insured Vehicle No: SKA470R

Date of Loss: 10/10/2018 Nature of Claim: TP Claim No: 1201800013089

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC586G	Engine No:	1ZZ3107498
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100410669
Reg. Date:	17/10/2008 (Man. Year: 2008)	Odometer:	186810 km
Colour:	White		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	RADAR 6 mm	Rear Left Side:	RADAR 6 mm
Front Right Side:	RADAR 6 mm	Rear Right Side:	RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/10/2018

Date Inspected: 11/10/2018 Inspected At:

Z-one Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6,, Blk D #01-87,
Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 19 Oct 2018)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC586G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >