

22/03/2002

ASS. REC. BY:

REF: CS3/FWD18018417/Gcd3dz

Special Instruction:

Surveyor: Guo Qiang

ASSIGNMENT (Office)

From (Person): Joseph Loh

of PWD

Date/Time: 10/10/18 @ 4:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 7081 L

Insured: FF 2402H

at Workshop m/s MJE Motor

Tel: 6454 2203

of Blk 7 - Sin Ming Sec. C # 01-96

Policy No: PNMC 2018-00003141

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 9/10/2018

CA / REV / REP. / REV 24 HRS 1up

H.O.D. Endorsement:

Date/Time: 4:38pm @ 10/10/18

Person Contacted: Michael

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLC 7081 L - CS3 / ECD16018718 / Gh32
	FF2402H - X

DOA: 3/10/16

PRR
Surrey

REF: FWD

96400 /

ASSIGNMENT

From: _____ Date: 17-10-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 7081L

at Workshop m/s: MJE motor

of: Blk 7 Sim Ming Ind Est #01-96

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) after 11am

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$65K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC7081L Yr Regn: 24 May 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Nissan Sylphy c.c. 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 43508 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MNTD BAB 178 0026742

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60 R16 R: 11

B / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear
R/Bal. 6 mm		R/Bal. 6 mm
L/Bal. 6 mm		L/Bal. 6 mm

D.O.A. _____ D.O.I. 17-10-18

Survey held at: w/s 4pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$500 - \$1000

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format: PRR

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: Site Insp (\$ _____) Interview (\$ _____) Tech. Invs (\$ _____) Weekend (\$ _____)

Survey Fee: 80

Transportation: _____

S + RS, SI: _____

Photos: _____

Others: _____

TOTAL: 80

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Wednesday, 10 October 2018 4:15 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: PRS for SLC 7081 L involving FF 2402 H on 9 October 2018 along Ang Mo Kio Ave 5 Towards CTE (Our ref: LCH.lg/SJEM-80939.18) (Our Ref: PNMC2018-00003141)
Attachments: SKMBT_C364e18101015360.pdf

Hi LKK team,

Please refer to the attached and liaise with TP repairer for PRS.

Attached is the TP GIA report.

Please create the case in Merimen and indicate insured's policy no PNMC2018-00003141.

Thank you.


Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg

FWD
insurance



From: Motor Claims SG - SG Common
Sent: Wednesday, 10 October, 2018 4:12 PM
To: Cheonghoh Law
Cc: Motor Claims SG - SG Common
Subject: RE: PRS for SLC 7081 L involving FF 2402 H on 9 October 2018 along Ang Mo Kio Ave 5 Towards CTE (Our ref: LCH.lg/SJEM-80939.18) (Our Ref: PNMC2018-00003141)

WITHOUT PREJUDICE

Dear Catherine,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, SLC7081L. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]

Sent: Wednesday, 10 October, 2018 4:06 PM

To: Motor Claims SG - SG Common

Subject: Re: PRS for SLC 7081 L involving FF 2402 H on 9 October 2018 along Ang Mo Kio Ave 5 Towards CTE (Our ref: LCH.lg/SJEM-80939.18) (Our Ref: PNMC2018-00003141)

Dear Sirs,

We refer to the above matter and your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Lee Kok Weng
- (2) Patrick Ng Kong Beng

- (3) Ang Guea Kiang
- (4) How Andrew
- (5) Chang Fuh Keong
- (6) Philip Foo
- (7) Ong Ah Keng, Kent
- (8) Ong Poh Meng
- (9) Ng Soon Aik Francis
- (10) Ng Soon Chuan Louis

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre- repair survey of SLC 7081 L and contact our client's workshop, MJE Motor , Blk 7 Sin Ming Sector C #01-96 Singapore 575642 for the said survey.

Contact Person : Y Y / Jo
9225 1391 / 6454 2203

Please proceed to do the needful.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 10 Oct 2018, at 3:57 PM, motorclaims.sg@fwd.com wrote:

WITHOUT PREJUDICE

Dear Catherine,

We refer to your letter dated 10 October 2018 of the PRI Notice of your client's vehicle FF2402H.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards
Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg

<image001.png>

<image002.png>

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]
Sent: Wednesday, 10 October, 2018 3:46 PM
To: Motor Claims SG - SG Common
Subject: Re: PRS for SLC 7081 L involving FF 2402 H on 9 October 2018 along Ang Mo Kio Ave 5 Towards CTE (Our ref: LCH.lg/SJEM-80939.18)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: c364@cheonghoh.sg
Subject: Message from KMBT_C364e
Date: 10 October 2018 at 3:36:32 PM SGT
To: mail@cheonghoh.sg
Reply-To: c364@cheonghoh.sg

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of

the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9640D
Vehicle Details	
Vehicle No.:	SLC7081L
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	HR16983781B
Chassis No.:	MNTBBAB17Z0026742
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,283.00
Original Registration Date:	24 May 2016
First Registration Date:	24 May 2016
Transfer Count:	0
Actual ARF Paid:	\$16,283.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 May 2026
PARF Rebate Amount:	\$12,212.00
Intended COE Rebate Details	
COE Expiry Date:	23 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$36,380.00
Total Rebate Amount:	\$48,592.00

The information contained herein is correct as at 18 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2018 08:43
Date Of Accident	09/10/2018 13:15
Exact Location Of Accident	AMK AVE 5 TOWARD CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC7081L
Insured/Policyholder	
Name Of Registered Owner	CHYE WEN JIE
NRIC No	S9039640D
Email Address	CHYEWJ90@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91187341
Alternative Phone No	OFFICE-91187341

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00005388
Cover Note Number	

Driver

Name of Driver	CHYE WEN JIE
NRIC No	S9039640D
Date Of Birth	20/10/1990
Occupation	INDOOR
Date Of Driving Pass	19/03/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91187341
Fax Number	
Contact Number	OFFICE-91187341
EEmail Address	CHYEWJ90@GMAIL.COM

Address BLK 164 JALAN TECK WHYE #08-242
 Postcode 680164
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions AFTER RAIN
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : TOH
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name CHOA CHU KANG NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 116 TECK WHYE LANE , POSTCODE: 680116 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7629999 - FAX NO: 67636615
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SAME AS SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number FF2402H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9th October 2018 at about 1315hrs I was driving vehicle A along Ang Mo Kio Ave 5 towards CTE in lane 3. Approaching the above junction, the traffic light was red, I slow down & stopped before the stop line. As the traffic light turns green, I made my left turn into Nanyang Polytechnic. Suddenly vehicle B (motor cycle) came ^{in straight} from my rear left & collided into my vehicle. I stopped but I saw another vehicle wanting to turn in. Therefore I proceeded straight to find a place I can park my car. I came out but vehicle B has left the scene video footage is available.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Sketch Plan must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If Driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:





**SINGAPORE
POLICE FORCE**



T/20181009/2193

Police Station Of Origin:
Choa Chu Kang N P C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No. 1800-7659999

2 of 3

Report No T/20181009/2193

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLC7081L	FWD Singapore Pte Ltd	PNPV2018-00005388	24/05/2018	23/05/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHYE WEN JIE	ID No.	S9039640D
Related Vehicle	SLC7081L (Car)	Contact No	91187341
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/10/2018 at around 1310hr , I was traveling on my vehicle(SLC7081L) , along Ang Mo Kio Ave 5. I was making a turn into Ang Mo Kio Ave 9 (Nanyang Poly Entrance) , where I suddenly heard a loud bang. I assumed that I have hit on to the curb or may have collided on to the traffic light. I made a check and discovered that there was a motorcyclist(FF2402H) wobbling but did not fall. I was unable to confirm if I have collided on to him as he did no show any sign. However, he stopped at the junction but did not approach me. The motorcyclist subsequently rode off . I then proceeded in to the polytechnic , before stopping . as there was 2 lane and I will not be causing any traffic congestion.

I alighted and made a check and discovered a scratch mark near the rear left light area. Subsequently I proceeded back to my office and view my rear dash cam footage. I discovered that the motorcyclist actually collided onto my vehicle. I was only able to retrieve the motorbike plate number. FF2402H.

I have saved a copy of the footage.



SINGAPORE
POLICE FORCE



T/20181009/2193

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No. 1800-7659999

3 of 3

Report No T/20181009/2193

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report:  Sgt 2 HONG KEN NAM Signature	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/10/2018 20:34
Officer In Charge Of Case TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No. 65476368	Classification Of Case:

Authentication Stamp
NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2018 Edit Reg		10 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Aizat Bin Kamislan , ID: S9023664D								
Main Claimant:	-								
Vehicle Reg. No.:	SLC7081L	Date of Loss:	09/10/2018 00:00 - :59 [28 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800013073	Policy/Cover Note No.:	PNMC2018-00003141 (Third Party Only)						
Vehicle Reg. No. (Insured):	FF2402H	Policy No. (Claimant):							
		Excess:							
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLC7081L (1201800013073)**
[FF2402H]
TP
-
Oct 9 2018 12:00AM
[Aizat Bin Kamislan]
Mje Motor

Upload Documents | Upload Photos | Compose New Letter

View View In Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
6	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
7	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
8	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
9	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>
10	23/10/18 17:52	General View	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18018417/GCD3E2
Date: 08/11/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2018-00003141
Claimant Vehicle No : SLC7081L **Insured Vehicle No :** FF2402H
 Date of Loss: 09/10/2018 Nature of Claim: TP Claim No: 1201800013073

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC7081L**
 Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) Engine No: HR16983781B
 Reg. Date: 24/05/2016 (Man. Year: 2015) Chassis No: MNTBBAB17Z0026742
 Colour: Grey Odometer: 43508 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/10/2018
 Date Inspected: 17/10/2018 Inspected At: Mje Motor (HQ)
 BLK 7 SIN MING IND EST SEC C
 #01-96 SINGAPORE 575642
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500.00 -\$1,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2018)
Parts: 143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC7081L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >