

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2018 14:21
Date Of Accident	04/10/2018 17:25
Exact Location Of Accident	HOUGANG AVE 2 ENTRANCE TO FLORENCE REGENCY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW5055R
Insured/Policyholder	
Name Of Registered Owner	TAN SIANG ING
NRIC No	S7717469I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94509796
Alternative Phone No	OFFICE-94509796

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.6L 5AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1125051807
Cover Note Number	

Driver

Name of Driver	TAN SIANG ING (CHEN XIANYING)
NRIC No	S7717469I
Date Of Birth	19/06/1977
Occupation	INDOOR
Date Of Driving Pass	10/01/1995
Driving Experience	23 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94509796
Fax Number	
Contact Number	OFFICE-94509796
Email Address	NOEMAIL

Address	23A LIM AH PIN ROAD
Postcode	547843
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20181005/7003.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM5750Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name	TAN SIANG ING (CHEN XIANYING)
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SDW5055R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Accident Sketch Plan

SKETCH PLAN

Vehicle A: SDW5055R

Vehicle B: SJM 5750Z

[Entrance to
Florence Regency]




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true to every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Scanned by CamScanner

Police Report



**SINGAPORE
POLICE FORCE**



T/20181005/7003

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181005/7003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/10/2018 12:09		Vide Report No.: F/20181004/0127		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN SIANG ING			Address: 23A LIM AH PIN ROAD SINGAPORE 547843		
ID Type / ID No.: NRIC NO / S7717469I			Contact No.: Home/Office: Mobile: 94509796		
Nationality: SINGAPORE CITIZEN			Email: siangintan@gmail.com		
Sex: Female	Age: 41	Date of Birth: 19/06/1977	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TEAM HEAD			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/10/2018 17:25	Type of Location: T-Junction
Location: HOUGANG AVENUE 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDW5055R	Car	HONDA	CIVIC+1.6L+5AT	Silver	Seriously Damaged	1
SJM5750Z	Car				Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SDW5055R	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN1125051807	10/09/2018	09/09/2019

Police Report



**SINGAPORE
POLICE FORCE**



T/20181005/7003

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20181005/7003

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN SIANG ING	ID No.	S7717469I
Related Vehicle	SDW5055R (Car)	Contact No.	94509796
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

ON 04/10/2018, AT ABOUT 17:25HR, I WAS TRAVELLING STRAIGHT ALONG HOUGANG AVENUE 2 TOWARDS MY HOME AT LIM AH PIN ROAD. APPROACHING THE ENTRANCE TO FLORENCE REGENCY, SUDDENLY VEHICLE NUMBER - SJM5750Z, CUT INTO MY LANE, INTENDING TO TURN INTO FLORENCE REGENCY AND HIT ONTO MY VEHICLE'S FRONT RIGHT PORTION. THE GREAT IMPACT CAUSED MY VEHICLE TO SWERVE SLIGHT TO THE LEFT AND THE CAR IMMEDIATELY SHIFT AND PARK IN FRONT OF MINE.

I WAS THEN CONVEYED TO SENGKANG GENERAL HOSPITAL & GIVEN 2 DAYS MC.

Police Report



**SINGAPORE
POLICE FORCE**



T/20181005/7003

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20181005/7003

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SHAHRUL NIZAM BIN SAMARRI
Contact No.: 65476904

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
05/10/2018 12:09

Classification Of Case:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



A close-up photograph of a car's instrument cluster. The primary focus is a tachometer with a blue and silver face, featuring a needle pointing to approximately 1000 RPM. The scale is marked from 0 to 8, with the text "1000r/min" printed near the top. Below the tachometer, a digital display shows "138743" followed by "TRIP A" and "47.8". To the right, a portion of another gauge is visible, showing a red needle and some illegible text.