

ASS. REC. BY:

REF: cs/CTI18018449/Uqd3m2

Special Instruction:

Surveyor
Meimien

Marcus

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time: 10/10/18 @ 4:49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGR 3232A

Insured:

EY120X

at Workshop m/s

ZOOM Autowerks

Tel:

9450 7920

of

15 Kaki Blk Rd 4 #01-53

Policy No:

DMPCSN1662141802

Claim No:

8NM18D04839C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/10/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:23am @ 11/10/18

Person Contacted:

Elin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGR 3232A - NA / INC 18018305 / 24	DOA: 8/10/18
	EY 120X - NA / INC 18018305 / 24	DOA: 8/10/18

Enrique Norcus

REF:

CT1/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGR3232A
 at Workshop m/s: 700m

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 52

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

0965M

Date: _____ Person Contacted: 30/6/2016

Vehicle IN / OUT

Veh No: SGR3232A Yr Regn: 7/06

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA1

Make: MINI COOPERS cc: 1598

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: 178350 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMWRE32050T694268

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

215/452R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 8/10/18

D.O.I. 11/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LT 35847 1yrs. Insur.?

18/10/18 4/5 @ 5200 confirmed with E.I.N. (Red #8683.80, 63%)

RECEIVED 16 OCT 2018

Date/Time. File Pass to?

☐

: Preli. Report

16/10 1yrs. Insur.

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

1) Photos

2) Others

3) Total

TOTAL

Report Format:

MER-7P

Lump Sum / I.B.N. (\$

5200

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2018		10 Oct 2018 16:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	MDM CHONG KIAT CHING EUNICE MRS EUNICE YEO, ID: S1234835E		
Main Claimant:	SOH GUAN YUAN, ID: S8570965H		
Vehicle Reg. No.:	SGR3232A	Date of Loss:	08/10/2018 14:00 - :59
Claim Type:	TP / SNM18D04839C02	Policy/Cover Note No.:	DMPCSN1662141802 (Comprehensive)
Vehicle Reg. No. (Insured):	EY120X	Policy No. (Claimant):	5087572302-01
		Excess:	S\$0.00
Repairer:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53, 417808 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/10/2018]		
Driver/Custodian (Insured):	MDM CHONG KIAT CHING EUNICE MRS EUNICE YEO (61 / Female), NRIC: S1234835E		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Zoom Autowerks <zoomautowerks@gmail.com>
Sent: Tuesday, 9 October, 2018 6:51 PM
To: Claims Dept of CTI
Cc: Lucas Lee
Subject: Pre-Repair Inspection for SGR 3232 A // Accident on 08/10/2018 @ 13:30HR at along Hong Lim Market & Food Centre Carpark involving Vehicle Number SGR 3232 A & EY 120 X
Attachments: SGR3232A_08102018.PDF

Dear Sir/Madam,

We are instructed by Soh Guan Yuan to notify you of a road traffic accident on 08/10/2018 at about 14:30HR at along Hong Lim Market & Food Centre Carpark involving our client's vehicle registration number SGR 3232 A and vehicle registration number EY 120 X driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 417808.

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339 Singapore 470130
☎9450 7920
✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

**CONNECTING CAR BUYERS & SELLERS.**

We'll handle your loans, insurance & other paperwork for FREE.

Find o

Post an AdvertisementSell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

1 Owner, Aug 2016 Volkswagen Passat 2.0A TSI R-Line.

10% Driveaway Scheme
Available! 3 Years Warranty By
Volkswagen, Like New!
Auto Zoom Enterprise StarAd

- Free VICOI
- Free groom
- In-house w
- Member of
- 100% depo



Browse by Category ▼

Sort b

9 vehicles

MINI Cooper

Advant

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
------	-------	-------	--------------	----------	---------	------

Search Selection

MINI Cooper

Any

Any

> 10 year(s)
old

Any

**MINI Cooper S Cabriolet 1.6A
(COE till 05/2026)**

\$58,800

\$7,700 /yr

28-Jun-2006

1,598 cc

63

Genuine Low Mileage, Like New! Rare Fully Stock Mini Cooper S Cabriolet! Mint Interior! Trade In Welcome! Please Call C
Before Its Gone! You Cant Find Another Similar Unit ...

Posted: 06-Oct-2018 Tags: 2006 MINI Cooper, 2006 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used M

**MINI Cooper S Cabriolet 1.6A
(COE till 01/2027)**

\$72,800

\$8,760 /yr

22-Feb-2007

1,598 cc

Cabriolet JCW Edition! Come And Get It Today! Visit Us At Classic Credit P/L At AML Now! Only \$7380 Down Payment. U
Provide Lowest Interest Rate. Flexible Loan And High Trade...

Classic Credit Pte Ltd

Posted: 04-Oct-2018 Tags: 2007 MINI Cooper, 2007 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used M

**MINI Cooper Cabriolet 1.6A
(COE till 03/2028)**

\$75,888

\$8,050 /yr

17-Mar-2008

1,598 cc

New 10 Years COE. Perfect Condition, All Wear And Tear Parts Replaced With Original Parts. Engine And Undercarriage I
Quiet And Drives Like New. Mint Stylish Cool Convertible. ...

Posted: 01-Oct-2018 Tags: 2008 MINI Cooper, 2008 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used M

**MINI Cooper S 1.6M (COE till
11/2027)**

\$60,000

\$6,560 /yr

30-Apr-2008

1,598 cc

My Loss Will Be All Your Gain! Total \$100k Invested. Please Whatsapp Me And Make Your Sensible Offer Would Consider
Be Retained. \$60k Exclude Recaro Seats, AP BBK, Super ...

Posted: 17-Sep-2018 Tags: 2008 MINI Cooper, 2008 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used M

COE expiring? Let us help you renew it!

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0965H

Vehicle Details

Vehicle No.: SGR3232A

Vehicle to be Exported: No

Intended Deregistration Date: 12 Oct 2018

Vehicle Make: MINI

Vehicle Model: COOPER S

Primary Colour: Green

Manufacturing Year: 2006

Engine No.: D006O727

Chassis No.: WMWRE32050TG94268

Maximum Power Output: 120.0 kW (160 bhp)

Open Market Value: \$32,697.00

Original Registration Date: 24 Jul 2006

First Registration Date: 24 Jul 2006

Transfer Count: 2

Actual ARF Paid: \$35,967.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2026

COE Category: E - Open Category

COE Period(Years): 10

PQP Paid: \$46,454.00

COE Rebate Amount: \$35,847.00

Total Rebate Amount: \$35,847.00

The information contained herein is correct as at 12 Oct 2018

OK



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

11 October 2018

REG NO.: SGR 3232 A
MAKE/MODEL: MINI COOPER S

Not Authorised
Lahr
1/5 @ 5200/-
527.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front bonnet 1125	\$ 1125 1,150.00 ✓
2	Front bonnet hinges	\$ 11 296.00 X
1	Front bonnet lock 0/5	\$ 145.00 ✓
1	Front bonnet chrome moulding	\$ 11 155.00 X
1	Front bonnet logo	\$ 90.00 ✓
1	Front bonnet side arch garnish	\$ 256.00 ✓
1	Front headlamp -R/H	\$ 1,455.00 ✓
1	Front headlamp chrome rim	\$ 285.00 ✓
1	Front grille assy	\$ 11 425.00 X
1	Front bumper 715	\$ 715 755.00 ✓
1	Front bumper centre grille	\$ 11 145.00 X
1	Front bumper clip (1 set)	\$ 80.00 ✓
1	Front bumper lamp	\$ 295.00 ✓
1	Front bumper fog lamp	\$ 255.00 ✓
1	Front bumper lower garnish	\$ 11 260.00 X
1	Front bumper side arch garnish	\$ 185.00 ✓
2	Front bumper side retainers 55	\$ 116.00 100
1	Front support panel	\$ 535.00 ✓
1	Front fender inner shield	\$ 165.00 ✓
1	Front fender inner shield clip (1 set)	\$ 50.00 ✓
1	Front fender wheel arch garnish	\$ 220.00 X
1	Front wheel rim	\$ 11 850.00 X
1	Front shock absorber	\$ 11 485.00 X
1	Front lower arm	\$ 11 425.00 X
1	Front knuckle arm	\$ 11 550.00 X
1	Front wheel hub with bearing	\$ 11 455.00 X
		\$ 10,082.00
Less 10%		\$ 1,008.20
		\$ 9,073.80

P-5690
102
577

SPECIAL NETT ITEMS

1

Front tyre

\$	500.00	X
\$	500.00	

S/NLABOUR CHARGES

- 1 To check wiring and reset headlamps focusing.
- 2 To remove and refit front undercarriage.
- 3 To conduct wheel alignment.
- 4 To apply undercoating.
- 5 Panel beating.
- 6 To re-spray painting on the affected areas.

\$	80.00	20
\$	450.00	X
\$	180.00	60
\$	200.00	40
\$	1,800.00	600
\$	1,600.00	680
\$	4,310.00	

GRAND TOTAL :

\$	13,883.80
----	-----------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To fit any damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018449/UQD3N2

Date: 17/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1662141802
Claimant Vehicle No :	SGR3232A	Insured Vehicle No :	EY120X
Date of Loss:	08/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04839C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGR3232A	Engine No:	D0060727
Make & Model:	MINI COOPER S, 1.6 (A)	Chassis No:	WMWRE32050TG94268
Reg. Date:	24/07/2006 (Man. Year: 2006)	Odometer:	178350 km
Colour:	Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,573.80	5,121.00	4,452.80	46.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	1,400.00	2,910.00	67.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,883.80	6,521.00	7,362.80	53.03
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	13,883.80	5,200.00	8,683.80	62.55

INSPECTION

Date of Assignment:	10/10/2018	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Date Inspected:	11/10/2018		
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2018)
Parts: M1-COUPE	MINI COOPER S 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGR3232A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented/Buckled	1,150.00 FL	*1,125.00 FL
2	2		*FRONT BONNET HINGES	Not Necessary	296.00 FL	*- FL
3	1		*FRONT BONNET LOCK O/S	Twisted/Jammed	145.00 FL	*145.00 FL
4	1		*FRONT BONNET CHROME MOULDING	Not Necessary	155.00 FL	*- FL
5	1		*FRONT BONNET LOGO	Necessary	90.00 FL	*90.00 FL
6	1		*FRONT BONNET SIDE ARCH GARNISH	Deformed/Warped	255.00 FL	*255.00 FL
7	1		*FRONT HEADLAMP-R/H	Cracked	1,455.00 FL	*1,455.00 FL
8	1		*FRONT HEADLAMP CHROME RIM	Cracked	285.00 FL	*285.00 FL
9	1		*FRONT GRILLE ASSY	Not Necessary	425.00 FL	*- FL
10	1		*FRONT BUMPER	Distorted	755.00 FL	*715.00 FL
11	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	145.00 FL	*- FL
12	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
13	1		*FRONT BUMPER LAMP	Broken	295.00 FL	*295.00 FL
14	1		*FRONT BUMPER FOG LAMP	Cracked	255.00 FL	*255.00 FL
15	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	260.00 FL	*- FL
16	1		*FRONT BUMPER SIDE ARCH GARNISH	Distorted	185.00 FL	*185.00 FL
17	1		*FRONT BUMPER SIDE RETAINERS	O/s Bent	116.00 FL	*55.00 FL
18	1		*FRONT SUPPORT PANEL	Cracked	535.00 FL	*535.00 FL
19	1		*FRONT FENDER INNER SHIELD	Torn	165.00 FL	*165.00 FL
20	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FL	*50.00 FL
21	1		*FRONT FENDER WHEEL ARCH GARNISH	Repeated	220.00 FL	*- FL
22	1		*FRONT WHEEL RIM	Not Necessary	850.00 FL	*- FL
23	1		*FRONT SHOCK ABSORBER	Not Necessary	485.00 FL	*- FL
24	1		*FRONT LOWER ARM	Not Necessary	425.00 FL	*- FL
25	1		*FRONT KNUCKLE ARM	Not Necessary	550.00 FL	*- FL
26	1		*FRONT WHEEL HUB WITH BEARING	Not Necessary	455.00 FL	*- FL
27	1		*FRONT TYRE	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,582.00	5,690.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,008.20	569.00
Total Parts (S\$)	9,573.80	5,121.00

Report was unsubmitted during this print-out.