

ASS. REC. BY:

REF: CS3 / CTL17006565 / Gvb-1 Special Instruction: *single*

ASSIGNMENT (Office)

Surveyor:                       
From (Person): Irene Tay of CTL Date/Time: 11.10.2018

Estimated Cost:                      Bill to:                     

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GU 5738D Insured: GBA 6573U

at Workshop m/s N-51 Automotiv Tel: 68420051

of 2 Kaki Bukit Ave 3 # 01-17

Policy No: DMCVSN 3084761600 Claim No: SMM1700184302

Sum Insured:                      Excess:                     

Make of Veh:                      D.O.A. 270207  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement:                     

Date/Time: 04/11/2017 9:30am Person Contacted: Hui Xin Vehicle: IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	GU 5738D - CCH / III 17006565 / M1063 Den: 10/12/17
	GBA 6573U - CCB / IIG 19020051 / 11020 Den: 11/10/2018
	Dismantle Part : 17052017
	After repair : 19052017

12/10/18 Submit LS \$ 2100 (Red 16,500, 89%)  
7 days *[Signature]*  
11/10/2018

**URGENT**  
Submit by 12.10.2018

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s N-51  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: 6457380 Yr Regn: 2001, Apr 06  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: ISUZU NHR69E cc 3059  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 999999 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_  
 C/No: JAA NHR69EY 7100926  
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195 R 150  
 R: 165 R 130

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Fit

Front Rear Rear  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 15-05-170

Survey held at W/S N-51 Automotive 4pm  
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair range \$3,500 - \$4,500
	<i>[Signature]</i>
	27/10/2017
	RECEIVED 2 OCT 2017

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) 27.10.2017  
 Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_) ) S - RS, SI  
 : Interview (\$ \_\_\_\_\_) ) Photos  
 : Tech. Invs (\$ \_\_\_\_\_) ) Others  
 : Weekend (\$ \_\_\_\_\_) )

Report Format : PRS  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)

80
80
80
TOTAL
240

## Catherine Chong (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Thursday, 11 October, 2018 12:59 PM  
**To:** assignments@lkkauto.com; Admin A  
**Cc:** Alfred Toh  
**Subject:** CTP REF NO. SNM17D01843C02 LKK REF NO. TBA - ACCIDENT INVOLVING GU5738D AND GBA6573V ON 27 MARCH 2017  
**Attachments:** LETTER OF DEMAND FROM TCMG.pdf

Dear Janice/Catherine,

We refer to the above matter.

We require your speedy service to issue a re-inspection report based on third party survey report/photos.

Kindly forward to us latest by tomorrow as we have a upcoming hearing next week.

Thank you.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6192  
Fax (65) 62247478/62247175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*



中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Tel: 6389 6111 Fax: 6222 1033  
Website: www.sg.ontaping.com  
Co. Reg. No. 200206384E

OUR REF : SNM17D01843/0001045324

YOUR REF : LLH/ING/1044/0118/N51

DATE : 23 JANUARY 2018

BY FAX ( 65389850 )  
& POST

TOMMY CHOO, MARK GO LLC  
151 CHIN SWEE ROAD  
#14-15/16  
SINGAPORE 169876

-----  
(WHICHEVER APPLICABLE)

Dear Sir/Madam,

Re : GBA6573U & GU5738D ON 27.03.17

We acknowledge receipt of your letter/claim form dated 23 JANUARY 2018 with enclosure(s), which will be subjected to further verification by our office. Should we require additional information or other documents relating to the claim, we shall contact you again.

Please be assured that we are looking into your claim immediately and will revert to you shortly.

Kindly take note that this acknowledgement of the above-mentioned submitted to our office shall not be construed as an admission of liability.

Kindly contact our Claims Department @ 6389 6116 for further assistance.

Thank you.

Claims Department

# TOMMY CHOO, MARK GO LLC

Advocates & Solicitors    Commissioner For Oaths    Notary Public

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16  
MANHATTAN HOUSE  
SINGAPORE 169876  
TEL : (65) 6532 2455  
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref : LLH/ing/1044/0118/N51

Your Ref : GBA 6573 U

23 JAN 2018

## M/S LIBRA ENGINEERING PTE LTD

53 Loyang Drive  
Loyang Industrial Estate  
Singapore 508957

## M/S CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909

### Attn: Motor Claims Department

Dear Sirs,

### **ACCIDENT INVOLVING GU 5738 D AND GBA 6573 U ON 27 MARCH 2017 ALONG BUANGKOK DRIVE TOWARDS BUANGKOK GREEN**

We are instructed by **M/s JH Towing Service**, to claim damages against you or your insured, the driver of motor vehicle no. **GBA 6573 U**, in connection with a road traffic accident on 27 of March 2017, at about 17:05 hours along Buangkok Drive towards Buangkok Green, involving our client's motor vehicle no. **GU 5738 D** and motor vehicle no. **GBA 6573 U** driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

1 Costs of Repair	\$ 19,902.00
2 Loss of Use (\$250 x 12 days)	\$ 3,000.00
3 Loss of Use(Pre-repair)(\$250 x 2 days)	\$ 500.00
4 LTA Search Fee	\$ 5.35
5 Survey Fees	\$ 1,071.00
6 Disbursement (at this stage)	\$ 93.00
7 Legal Cost (at this stage)	\$ <u>1,000.00</u>
	\$ <u>25,571.35</u>

DIRECTOR : LING LEONG HUI

CONSULTANTS : TOMMY CHOO TUCK SOON  
POOTS LAURENCE JAMES

23 JAN 2018

17 | 1843 | 3  
By Certificate of Posting  
(For your attention:without enclosures)

BY PDX NO. 8178

PDX Intercompany Exchange Pte Ltd



010808222770

FROM TOMMY CHOO, MARK GO LLC  
PDX Rcv No R141

# **TOMMY CHOO, MARK GO LLC**

**Advocates & Solicitors    Commissioner For Oaths    Notary Public**

**UEN NO : 201523418E**

**(a law corporation with limited liability)**

151 CHIN SWEE ROAD #14-15/16  
MANHATTAN HOUSE  
SINGAPORE 169876  
TEL : (65) 6532 2455  
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)  
Email: lhling@tcmg.com.sg

A copy each of the following supporting documents is enclosed:

1. Copy of accident report and LTA search;
2. Certificate of Insurance & PARF/COE Particulars;
3. Copy of survey report and invoice and repair bill;
4. Colour photographs pertaining to our client's motor vehicle for your perusal.

Our client had on 28 March 2017 notified your insurer, M/s China Taping Insurance's Pte Ltd about the accident and the pre-repair inspection was conducted.

Please note that if you are insured and you wish to claim from your insurance policy, you should immediately pass this letter to your insurer.

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,



Encs.

cc. client

**Enquire Vehicle & Owner Information ( Vehicle No. GBA6573U As At 27 Mar 2017 / 17:05:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LLH.GU5738D.N51

**Current Owner Details**

Owner ID Type: Company

Owner ID: 200514501D

Owner Name: LIBRA ENGINEERING PTE LTD

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House  
No.: 53

Registered Street Name: LOYANG DRIVE

Registered Unit No.: -

Registered Building Name: LOYANG INDUSTRIAL ESTATE

Registered Postal Code: 508957

**Current Vehicle Details**

Vehicle No.: GBA6573U

Make Description/Model: FIAT / DOBLO 1.3MJTD

Insurance Company Name: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 6936D

### Vehicle Details

Vehicle No.: GU5738D  
Vehicle to be Exported: No  
Intended De-registration Date: 28 Mar 2017  
Vehicle Make: ISUZU  
Vehicle Model: NHR69E  
Primary Colour: White  
Manufacturing Year: 2000  
Engine No.: 4JG2726994  
Chassis No.: JAANHR69EY7100926  
Maximum Power Output: -  
Open Market Value: \$30,991.00  
Original Registration Date: 06 Apr 2001  
First Registration Date: 06 Apr 2001  
Transfer Count: 4  
Actual ARF Paid: \$1,550.00

### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Mar 2022  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 5  
PQP Paid: \$24,394.00  
COE Rebate Amount: \$0.00  
Total Rebate Amount: \$0.00

### Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.  
The information contained herein is correct as at 28 Mar 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).  
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution  
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

MSME17040925 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 28/03/2017 17:02

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/03/2017 17:02
Date Of Accident	27/03/2017 17:05
Exact Location Of Accident	BUANGKOK DRIVE TWDS BUANGKOK GREEN TRAFFIC LIGHT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GU5738D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JH TOWING SERVICE
Co Reg No	53246936D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-95883760
<b>Vehicle Particulars</b>	
Manufacturer	ISUZU
Model	NHR69E
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Commercial Vehicle
<b>Insurance Company</b>	
Name of Insurance Company	AXA Insurance Pte Ltd
Type Of Coverage	Third Party Fire and/or Theft
Fleet Policy	No
Policy Number	P12222152
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEOW KOK CHENG
NRIC No	S1721356C
Date Of Birth	28/05/1965
Occupation	Indoor
Date Of Driving Pass	27/01/1984
Driving Experience	33 Years And 2 Months
Gender	Male
Mobile Number	(Local) +65-93883760
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 476B UPPER SERANGOON VIEW #05-52B  
 Postcode 532476  
 Was driver an employee of the Insured's Company Yes  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident Collision- Head to Rear (TP Hit Insured)  
 Weather Conditions Clear  
 Road Surface Dry

**Other Information**

Was any foreign vehicle involved in this accident? No  
 Was any body injured in the Accident? No  
 Was any other material or property damaged? Yes  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? No  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? No  
 If Yes, against whom?

**Circumstances of Accident**

ON THE ABOVE DATE AND TIME, I WAS TRAVELLING ALONG BUANGKOK DRIVE TOWARDS BUANGKOK GREEN ON A SINGLE LANE ROAD. AS I WAS PROCEEDING TOWARDS BUANGKOK GREEN, I SLOWED DOWN AND CAME TO A STOP TO GIVE WAY TO ONCOMING TRAFFIC. OUT OF A SUDDEN, VEHICLE B FROM THE BACK CAME AND COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

**Attachment(s)**

Are accident photos available for attachment? Yes  
 Was there any video captured by Car Camera? No  
 Was there any audio recorded? No

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBA6573U  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Name of Driver TING FOO MING  
 NRIC/Passport Number  
 Contact Number 96167347  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number  
 Email Address



Sketch Plan #2 Pg.1

Describe Circumstances of the Accident

On the above date and time, I was travelling along  
 Ruangkok Drive towards Bangkok green on a single lane road.  
 As I was proceeding towards Bangkok green, I slowed down  
 and came to a stop to give way to on coming  
 traffic. Out of a sudden, vehicle (B) from the back  
 came and collided onto the rear portion of my vehicle.

A-GU5738D  
 B-GRB657SM

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**AXA INSURANCE SINGAPORE PTE LTD**

8 Shenton Way, #27-01  
 AXA Tower, Singapore 068811  
 Customer Service Centre #81-01  
 Tel:(65)63387288 Fax:(65)63382522  
 Website:www.axa.com.sg  
 GST Registration Number: M2-0009922-2  
 customer.care@axa.com.sg

**CERTIFICATE OF INSURANCE**

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VCC/P1222152 Account No. : 04041  
 Coverage : Third Party Fire & Theft Only  
 Sum Insured : Market Value At The Time Of Loss  
 Name of Policy Holder : JH TOWING SERVICE  
 Vehicle Registration No. : GU5738D  
 Period of Insurance : From 06/10/2016 To 05/10/2017 (Both Dates Inclusive)

**PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\***

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**LIMITATIONS AS TO USE\***

- (a) Use in connection with the Policyholder's business
- (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business
- (c) Use for social, domestic and pleasure purposes

This Policy does not cover

- (a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing
- (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

(05)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act. (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE SINGAPORE PTE LTD

  
 Authorized Signature

Issued by - SGOVGBP on 04/10/2016

**IMPORTANT :**

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189)).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

JH TOWING SERVICE  
BLK 648 HOUGANG AVE 8 #04-229  
SINGAPORE 530648

Contact : 93883760

## TAX INVOICE

Date : 08/01/2018  
Date in : 13/05/2017  
Vehicle Num. : GU5738D  
Make/Model : ISUZU NHR69E-2000  
Chassis/Eng# : JAANHR69EY7100926/4JG2726994  
Accident Date : 27/03/2017  
Claim No : CLM13973  
Reference : MAR-54/2017  
Policy No. : VCC/P1222152 (05/10/2017)

LUMPSUM REPAIR BILL  
AS PER SURVEYOR REPORT  
REF : CLM13973TP/N DATED 13/12/2017  
BY CARLINK CONSULTANCY

Amount S\$  
18,600.00

E. & O.E. Sub S\$ : 18,600.00  
Add GST ( 7 % ) S\$ : 1,302.00  
Total Amount S\$ : 19,902.00



for N-51 AUTOMOTIVE PTE LTD



*bizSAFE<sub>3</sub>*

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-170328-001473

Previous Receipt No. :

**S/N Item Description/  
 Business Transaction  
 Reference No.**

**Amount Before  
 GST (\$\$)**      **GST  
 Amount (\$\$)**      **Amount  
 After GST  
 (\$\$)**

Result of Insurance Enquiry - GBA6573U  
 As at 27 Mar 2017/17:05:00  
 Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

1	Insurance Enquiry - GBA6573U Enquiry Fee 20170328161042282571	5.00	0.35	5.35
	<b>Sub-Total</b>	5.00	0.35	5.35
	<b>Total Before Rounding</b>	5.00	0.35	5.35
	<b>Rounding Difference</b>			0.00
	<b>Total Amount Payable</b>			5.35
	<b>Paid By</b>			
	xxxxxxxxxxxxx2392		Credit Card: Visa/MasterCard	5.35
	<b>Total</b>			5.35
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			5.35
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

# CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009  
Fax: 62874788 Tel: 62856178

## INVOICE

M/S JH Towing Service  
C/o Kaki Bukit Autohub  
2 Kaki Bukit Avenue 2, #01-18  
Singapore 417921

Invoice No: CLM13973TP/N

Date: 13th December 2017

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	<u>Vehicle No: GU 5738 D</u> Charges for accident vehicle inspection and appraisal report, transportation, photographs & misc*** (photographs - 96 copies)			\$1,071.00
			<b>Total:</b>	<b>\$1,071.00</b>

We thank you for the opportunity to serve you and assure you of our best at all times



PATRICK NG  
Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, ENG, LAE, CGLI FTC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"


**CARLINK CONSULTANCY**60 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

**ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT**

Our Ref: CLM13973TP/N

<b>1 REFERENCE</b>			
Date of request	:	15th May 2017	
Requested by	:	M/S JH Towing Service C/o Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18 Singapore 417921	
Type of claim	:	Third party	
Workshop	:	M/S N-51 Automotive Pte Ltd Kaki Bukit Autohub, 2 Kaki Bukit Avenue 2, #01-18 Singapore 417921	
Date of survey	:	15th May 2017	
Accident date	:	27th March 2017	
<b>2 DETAILS OF VEHICLE</b>			
Registration No.	:	GU 5738 D	
Make & Model	:	Isuzu NHR69E	
Engine No.	:	4JG2728994	
Chassis No.	:	JAANHR69EY7100926	
Year of Registration	:	6th April 2001	
Speedometer reading	:	999999 Km	
Transmission	:	Manual	
Colour	:	Blue	
<b>3 STATIC CHECK</b>			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
<b>4 TYRE CONDITION</b>			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	6mm/Michelin	6mm/Michelin : 195 R15C
Rear tyre	:	6mm/Yokohama	6mm/Yokohama : 165 R13C
<b>5 POINT OF IMPACT</b>			
See Annex(es) and Motor Accident Reports			
<b>6 REMARK</b>			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

Report No. CLM13973TP/N

Vehicle No. GU5738D

**Parts and Labour Assessment**

**PARTS**

Description of part	Repairer's Qty	Qty	Condition	Repairer's estimate	Our adjustment
HYDRAULIC FLUID (1 DRUM)	1	1	NECESSARY	150.00	150.00-NECV
HYDRAULIC JACK HOSE	2	2	CUT/LEAKED	800.00	400.00-800.00-CUT✓
LIFT FORK "T" MEMBER	1	1	DISTORTED	3,000.00	3,000.00-RX
LIFT FORK "T" MEMBER HYDRAULIC CYLINDER JACK	1	1	DISTORTED/LEAKED	1,800.00	1,800.00-RX
LIFT FORK MAIN HYDRAULIC CYLINDER JACK	1	1	DISTORTED/LEAKED	1,800.00	1,800.00-RX
LIFT FORK OUTER MAIN MEMBER	1	1	DENTED/DISTORTED	4,500.00	4,500.00-RX
LIFT FORK OUTER MAIN MEMBER PIVOT PIN	1	1	NECESSARY	380.00	200.00-380.00-NECV
LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET	1	1	DISTORTED/RATTLE	1,900.00	1,900.00-NNX
LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET HYDRAULIC CYLINDER JACK	1	1	LEAKED	1,500.00	1,500.00-RX
MAIN TOWING LIFTING CRANE HYDRAULIC CYLINDER JACK	1	1	LEAKED	1,800.00	1,800.00-RX
REAR END HANG PANEL	2	0	REPAIR	1,400.00	0.00
REAR NUMBER PLATE	1	0	SERVICEABLE	35.00	0.00
TAILLAMP	2	2	SHIFTED/SLACK	460.00	460.00-RX
Subtotal before discount				SS 19,525.00	SS 18,090.00
<b>Sub-total</b>				<b>SS 19,525.00</b>	<b>SS 18,090.00</b>
<b>Parts-total</b>				<b>SS 19,525.00</b>	<b>SS 18,090.00</b>

**LABOUR**

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,800.00	1,250.00
To check wiring and light system	200.00	60.00
Labour to dismantle, replaced towing forks, jacks, pin etc and to check and align system for proper operation	3,000.00	1,800.00
To apply anti-rust chemical on repaired and replaced panel.	200.00	100.00
<b>Labour Total</b>	<b>SS 5,200.00</b>	<b>SS 3,810.00</b>
<b>Parts &amp; Labour Total</b>	<b>SS 24,725.00</b>	<b>SS 21,900.00</b>

Results of inspection of the accident vehicle are as shown above,  
 We have taken into consideration the age and condition of the vehicle in our recommendation.  
 Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 18,600.00  
 and the recommended number of working days for the repairs is within 12 day(s).

  
 PATRICK OWEYEYOR  
 Automotive Appraiser

Repair days 7

TGrim  
 Um  
 11/10/18



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI17006565/Gvbn2-1	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 12-10-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 6573U	Veh. Inspected	GU 5738D
Policy No.	DMCVSN3084761600	Coverage (\$)	0.00
Claim No.	SNM17D01843C02	Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	11/10/2018
2. Vehicle Particulars & Condition			
Make & Model	ISUZU NHR69E	c.c	3059
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	JAANHR69EY7100926	Colour	BLUE
Odometer	999999	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	6 mm
L/H Front Tyre	195 R15C	MICHELIN	6 mm
R/H Rear Tyre	165 R13C	YOKOHAMA	6 mm
L/H Rear Tyre	165 R13C	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/03/2017	Inspection Date	15/05/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 5738D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HYDRAULIC FLUID (1 DRUM)	NECESSARY	150.00	100.00
2	HYDRAULIC JACK HOSE	CUT	800.00	400.00
1	LIFT FORK "T" MEMBER	TO REPAIR SEE LABOUR	3,000.00	-
1	LIFT FORK "T" MEMBER HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,800.00	-
1	LIFT FORK MAIN HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,800.00	-
1	LIFT FORK OUTER MAIN MEMBER	TO REPAIR SEE LABOUR	4,500.00	-
1	LIFT FORK OUTER MAIN MEMBER PIVOT PIN	NECESSARY	380.00	200.00
1	LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET	NOT NECESSARY	1,900.00	-
1	LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,500.00	-
1	MAIN TOWING LIFTING CRANE HYDRAULIC CYLINDER JACK	TO REPAIR SEE LABOUR	1,800.00	-
2	REAR END HANG PANEL	TO REPAIR SEE LABOUR	1,400.00	-
1	REAR NUMBER PLATE	SERVICEABLE	35.00	-
2	TAILLAMP	TO REPAIR SEE LABOUR	460.00	-
			19,525.00	700.00
<b><u>LABOUR</u></b>				
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.			1,800.00	800.00
LABOUR TO DISMANTLE.REPLACED TOWING FORKS,JACKS,PIN ETC AND TO CHECK AND ALIGN SYSTEM FOR PROPER OPERATION.INCLUSIVE OF THE REPAIR OF LIFT FORK "T" MEMBER,LIFT FORK "T" MEMBER HYDRAULIC CYLINDER JACK,LIFT FORK MAIN HYDRAULIC CYLINDER JACK,LIFT FORK OUTER MAIN MEMBER,LIFT FORK OUTER MAIN MEMBER SLIDING BRACKET HYDRAULIC CYLINDER JACK,MAIN TOWING LIFTING CRANE HYDRAULIC CYLINDER JACK,REAR END HANG PANEL AND TAILLAMP.			3,000.00	1,000.00

Report Ref No. CS3/CT117006565/Gvbn2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		200.00	60.00
	TO CHECK WIRING AND LIGHT SYSTEM.		200.00	60.00
			5,200.00	1,920.00
<b>GRAND TOTAL</b>			<b>24,725.00</b>	<b>2,620.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,100.00</b>

Report Ref No. CS3/CTI17006565/Gvbn2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.