SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	11/10/2018 12:52
Date Of Accident	11/10/2018 10:40
Exact Location Of Accident	JUNC CLEMENTI RD & AYE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	XE1125G
Insured/Policyholder	
Name Of Registered Owner	MASINDO LOGISTIC PTE LTD
Co Reg No	200301939M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68427228
Vehicle Particulars	
Manufacturer	UD TRUCKS
Model	GKB5ELDHNT ESCOT V
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994545/100862844
Cover Note Number	
Driver	
Name of Driver	TEO WEI LOCK ANDY

Passport No/FIN G2015067Q
Date Of Birth 22/09/1994
Occupation OUTDOOR
Date Of Driving Pass 24/09/2016

Driving Experience 2 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98386981

Fax Number

Contact Number OFFICE-98386981

EMail Address NOEMAIL

3017 UBI ROAD 1 Address

#02-131 KAMPOG UBI INDUSTRIAL ESTATE

Postcode 408708

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - CHANGE/CROSS LANE Type Of Accident

Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO Number of vehicles involved in the accident 2 Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

YES Was any other material or property damaged? I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. 1

Details of Police Action

YES Was the accident reported to the police?

If Yes, Please state which Police Station

Number of Passengers (Including Driver)

Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

NO

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: Police Station Address

SINGAPORE

TEL NO: 65470000 - FAX NO: Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20181011/2054.

Attachment(s)

YES Are accident photos available for attachment? Was there any video captured by Car Camera? NO NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN798L

Vehicle Make/Model/Colour

Details Of Properties

COMMERCIAL VEHICLE Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Date & Time:

Driver's Signature


(If driver is not the policyholder) Date & Time:

Name

NRIC/FIN No.:

Reporting Centre Personnel's Signature

Accident Sketch Plan



Police Report





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 3 Report No. T/20181011/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/10/2018 12:14		Made:	Vide Report No.:	Station Diary No.	
Informa	nt's Partic	ulars	TAN PORT OF THE PERSON	C TO PART PART PART PART PART PART PART PART	
	ame of Informant: Address: EO WEI LOCK ANDY 3017 UBI ROAD 1 #02-131 KAMPONG UBI INDI ESTATE SINGAPORE 408708			KAMPONG UBI INDUSTRIAL	
ID Type / ID No.: NRIC NO / G2015067Q			Contact No.: Home/Office:	Mobile: 98386981	
Nationality: MALAYSIAN			Email:		
Sex: Male	Age:	Date of Birth: 22/09/1994	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: DRIVER			Driving Licence Information Class: 3,4	: Date of Expiry:	

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 11/10/2018 10:40	Type of Location	
Location: Along Road 1 CLEMENTI R					
Weather:		Road Surface:		Road Speed Limit:	
	Traffic Flow:				
Traffic Flow:		Traffic Control:	Tra	affic Volume:	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
XE1125G						0
YN798L						0

Police Report





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20181011/2054

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report TP / MUHAMMAD SYUKRI BIN ABU BAKAR	A second
Signature Of Interpreter: Not applicable	Date/Time: 11/10/2018 12:14
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI	Classification Of Case:
Contact No.: 65476902 Authentication Stamp	EINGAPORE POLICE FORCE
NE 100	E

Police Report





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20181011/2054

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION

I WAS TRAVELLING ALONG THE EXTREM LEFT LANE AND WAS GOING STRAIGHT WHEN SUDDENLY A VEHICLE (YN798L) CAME FROM MY RIGHT SIDE AND FILTERED INTO MY LANE. AS THE VEHICLE WAS FILTERING INTO MY ANE, THE VEHICLE ALSO COLLIDED INOT THE FRONT RIGHT SIDE OF MY VEHICLE. AFTER THE COLLISION, YN798L CONTINUED ON DRIVING AND DID NOT STOP.















