



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18018479/Upa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CYNTHIA LOH

Date : 25-09-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGA 655Y	Veh. Inspected	SKZ 758E
Policy No.	GA164232/1	Coverage (\$)	0.00
Claim No.	S8M00XZZ	Excess (\$)	0.00
Assign From		Assign Date	09/10/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11107474	Colour	WHITE
Odometer	31990	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/10/2018	Inspection Date	12/10/2018
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------