

ASS. REC. BY:

REF:

CS3/CTI/80/8486/Tlcd307

Special Instruction:

Survey of
men

Tau fish

ASSIGNMENT (Office)

From (Person):

Irene Juy

of

CTI

Date/Time:

11/10/18 @ 2:52pm

Estimated Cost:

Bill to:

OD-~~TP~~/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FT 1625P

Insured:

GBH 6357R

at Workshop m/s

Thong sheng Motors

Tel:

9617 2433

of

BLK 7, Pioneer Rd North # 01-50

Policy No:

DM CVSN 1825531800

Claim No:

8NM18D04729C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/10/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

3:09pm @ 11/10/18

Person Contacted:

Michael

Vehicle (IN) OUT

[illegible]

Surveyor Tanji

REF:


CT1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FT162SP Yr Regn: Mar / 01
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Kawasaki C.C. 148
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 94060 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KR150KA53113
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: (Nil) / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 80/40 KLT
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 4/10/180 B.S.P.
 Survey held at Thong Seng Motor
 Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction No G.I.A.

Range 4,000/2 - 5,000/2

23/10/2018
Tanji
lin

23/10/18

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format : PR2

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. SI _____
 Photos _____
 Others _____

TOTAL

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2018		11 Oct 2018 14:52 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RICH RESOURCES LOGISTICS PTE. LTD., Co. Reg. No.: 201415853K		
Main Claimant:	NOR RIDHWAN BIN ZAINAL		
Vehicle Reg. No.:	FT1625P	Date of Loss:	01/10/2018 12:00 - :59
Claim Type:	TP / SNM18D04729C02	Policy/Cover Note No.:	DMCVSN1825531800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH6357R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Thong Sheng Motors Trading (HQ) Blk 7 Pioneer Road North, #01-50 Off Loyang Way, 2262 Pioneer - Tel: 62610412		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Daniel Poon & Co.

Advocates & Solicitors
Commissioners for Oaths

Daniel Poon Cheon Kow
LL. B. (Hons), LLM

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227-2469
Fax: +65 6225-2579
Email: law@dpco.com.sg
(UEN: 53130838C)

Our Ref: DP.sl.isk.10713.18.TSM

Your Ref: -----

Please quote our reference number when replying

Date: 10 OCTOBER 2018

M/S CHINA TAIPING INSURANCE (S) PTE. LTD.
3 ANSON ROAD
#16-00
SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIMS DEPARTMENT

FAX (6224-7478) ONLY

DEAR SIRs,

PRE-REPAIR INSPECTION

**YOUR INSURED VEHICLE REGISTRATION NO: GBH 6357R
ACCIDENT ON 01 OCTOBER 2018 INVOLVING FT 1625P AND GBH 6357R
ALONG CHIN BEE DRIVE TOWARDS CORPORATION DRIVE**

We are instructed by Nor Ridhwan Bin Zainal to notify you of a road traffic accident on 01st October 2018 at about 12:35 along Chin Bee Drive towards Corporation Drive involving our client's vehicle registration number FT 1625P and vehicle registration number GBH 6357R driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of nine (09) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S THONG SHENG MOTORS TRADING
BLK 7 PIONEER ROAD NORTH
#01-50
SINGAPORE 628459
ATTN: MICHAEL (9617-2433)

... 2/-

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5330G
Vehicle Details	
Vehicle No.:	FT1625P
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Oct 2018
Vehicle Make:	KAWASAKI
Vehicle Model:	KRR-ZX150
Primary Colour:	Blue
Secondary Colour:	White
Manufacturing Year:	2000
Engine No.:	KR150EEA53113
Chassis No.:	KR150KA53113
Maximum Power Output:	-
Open Market Value:	\$3,715.00
Original Registration Date:	01 Mar 2001
First Registration Date:	01 Mar 2001
Transfer Count:	5
Actual ARF Paid:	\$558.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,567.00
COE Rebate Amount:	\$860.00
Total Rebate Amount:	\$860.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 22 Oct 2018

OK

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FT1625P		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	KAWASAKI		
Vehicle Model :	KRR-ZX150		
Chassis No. :	KR150KA53113		
Propellant :	Petrol		
Engine No. :	KR150EEA53113		
Engine Capacity :	148 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	-		
Year Of Manufacture :	2000		
Original Registration Date :	01 Mar 2001		
Lifespan Expiry Date :	30 Jun 2028		
COE Category :	D - Motorcycle		
PQP Paid :	\$1,567.00		
COE Expiry Date :	28 Feb 2021		
Road Tax Expiry Date :	17 Nov 2018		
Inspection Due Date :	17 May 2019		
Intended Transfer Date :	22 Oct 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
<p>The current road tax expiry is 17 Nov 2018. You may renew the road tax from 18 Aug 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 17 Nov 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.</p> <p>Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.</p>			
Amount Payable (From 18 Nov 2018 to 17 May 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	48.00	-	48.00
Total Amount Payable :			73.00
Amount Payable (From 18 Nov 2018 to 17 Nov 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	96.00	-	96.00
Total Amount Payable :			121.00
Message			
<p>Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.</p> <p>This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.</p> <p>This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.</p> <p>For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.</p>			

You may print this page for reference.



SINGAPORE POLICE FORCE



T/20181008/2177

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20181008/2177

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/10/2018 23:26		Vide Report No.:		Station Diary No.: 201
Informant's Particulars				
Name of Informant: NOR RIDHWAN BIN ZAINAL		Address: APT BLK 662A JURONG WEST STREET 64 #03-328 SINGAPORE 641662		
ID Type / ID No.: NRIC NO / S9725330G		Contact No.: Home/Office: Mobile: 94884401		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 21	Date of Birth: 04/08/1997	Type of Informant: Rider	
Race: Malay		Language: English	Institution / School Name:	
Occupation: DESPATCH RIDER		Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/10/2018 12:35	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 CHIN BEE DRIVE CORPORATION DRIVE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FT1625P	Motorcycle	KAWASAKI	KRR-ZX150	Blue	Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FT1625P	TENET SOMPO INSURANCE PTE. LTD.	D18MTMC0100267 5	18/05/2018	17/05/2019



**SINGAPORE
POLICE FORCE**



T/20181008/2177

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20181008/2177

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	NOR RIDHWAN BIN ZAINAL	ID No.	S9725330G
Related Vehicle	FT1625P (Motorcycle)	Contact No.	94884401
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	01/10/2018	Date Discharge	04/10/2018
No. of Days granted Medical Leave	96	Degree of Injury	Serious

Brief Details.

On 01/08/2018 at about 1234hrs, I was riding my motorcycle bearing FT1625P along Chin Bee Dr heading towards Corporation Dr where the accident happened. As I was riding straight, from afar I saw a lorry from an oncoming lane. Out of a sudden, the lorry makes a right turn wanting to turn into a company without signalling his intention at all. As it was too sudden, my motorcycle collided into the middle portion of the lorry. After the collision, I could not remember anything at all. I was aware that I was being conveyed to Ng Teng Fong General Hospital via ambulance. I was then discharged on 04/10/2018 and was given hospitalization leave from 01/10/2018 to 04/01/2019.

**SINGAPORE
POLICE FORCE**

T/20181008/2177

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20181008/2177

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 SUHAILI BINTE HASSAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

08/10/2018 23:26

Officer In Charge Of Case:

TP / GIT /

Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN

Contact No.: 65476185

Classification Of Case:

Authentication Stamp
NP168

SN 120

Signature:

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2018		11 Oct 2018 14:52 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RICH RESOURCES LOGISTICS PTE. LTD., Co. Reg. No.: 201415853K								
Main Claimant:	NOR RIDHWAN BIN ZAINAL								
Vehicle Reg. No.:	FT1625P	Date of Loss:	01/10/2018 12:00 - :59 [211 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04729C02	Policy/Cover Note No.:	DMCVSN1825531800 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH6357R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Thong Sheng Motors Trading (HQ) Blk 7 Pioneer Road North, #01-50 Off Loyang Way, 2262 Pioneer - Tel: 62610412								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/10/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FT1625P (SNM18D04729C02)

[GBH6357R]

TP
















































NOR RIDHWAN BIN ZAINAL

Oct 1 2018 12:00PM

[RICH RESOURCES LOGISTICS PTE. LTD.]


Thong Sheng Motors Trading







Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)								Thumbnail	Print	
1	02/10/18 14:00	Accident Statement								Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)								Thumbnail	Print	
1	02/10/18 13:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
2	02/10/18 13:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
3	02/10/18 13:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
4	02/10/18 13:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
5	02/10/18 13:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
6	02/10/18 13:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
2	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
3	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
4	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
5	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
6	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
7	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
8	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
9	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
10	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
11	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
12	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
13	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
14	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
15	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
16	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
17	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
18	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
19	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
20	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
21	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
22	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
23	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
24	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	
25	12/10/18 12:40	General View								Load JPG	<input checked="" type="checkbox"/>	




Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
26	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
65	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
66	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
67	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
68	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
69	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
70	12/10/18 12:40	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/10/18 14:52	PRS	 Load PDF	
2	11/10/18 14:52	OI GIA	 Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/10/18 13:57	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	02/10/18 13:58	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	
3	02/10/18 13:58	IC,CI,DL. [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/10/18 14:00	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/10/18 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/10/18 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/10/18 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/10/18 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/10/18 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	02/10/18 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/10/18 13:57	Sketch Plan	 Load TIF	
2	02/10/18 13:58	POLICE REPORT	 Load TIF	
3	02/10/18 13:58	IC,CI,DL.	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18018486/T1CD3E2

Date: 26/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1825531800

Claimant Vehicle
No: FT1625PInsured Vehicle
No: GBH6357R

Date of Loss: 01/10/2018

Nature of Claim: TP

Claim
No: SNM18D04729C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FT1625P

Make & Model: KAWASAKI KRR ZX150, 148cc (M)

Engine No: KR150EEA53113

Reg. Date: 01/03/2001 (Man. Year: 2000)

Chassis No: KR150KA53113

Colour: Blue

Odometer: 94060 km

Engine Capacity: 148 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90 R17

Rear Tyre Size: 80/90 R17

Front Left Side: Maxxis 6 mm

Rear Left Side: Maxxis 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/10/2018

Date Inspected: 11/10/2018 Inspected At:

Thong Sheng Motors Trading (HQ)
Blk 7 Pioneer Road North, #01-50 Off
Loyang Way
Singapore 2262

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Oct 2018)

Parts: N/A KAWASAKI KRR ZX150 148cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FT1625P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >