

ASS. REC. BY:

REF:

CS3/MSG18018496, Tidd36

Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Mennen

Pauline Tham

of

MSG

Date/Time:

11/10/18 @ 3:55pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 7892H

Insured:

SMC 1256C

at Workshop m/s

Team Autopro

Tel:

6258 1955

of

385 Sin Ming Drive #01-02

Policy No:

A804591430MX

Claim No:

572718

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09/10/2018

CA / REV / REP. / REV 24 HRS

(up)

Insp: 8 kaki Bkt Ave 4 # 01-07

12/10/2018

H.O.D. Endorsement:

Date/Time:

4:08pm @ 11/10/18

Person Contacted:

Michelle

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (X) Estimate
	SJR 7892H - X
	SMC 1256C - X
	Dismantle: 15/10/18
	After repair: 18/10/18

PRs
Tanjung
Malam

REF: MSLH

ASSIGNMENT

From: Date: 12.10.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR 7892H
at Workshop m/s Team Autopro
of 8 Kaki Bukit Ave 4 #06-21

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GI / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJR 7892H Yr Regn: Jul / 09

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream C.C. 1799

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 121827 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRN 68809 C200331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 25/50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

Survey held at Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction No 617.

Range 5,000/2 - 6,000/2

23/10/2018

TAM
23/10/18

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Report Format : PRS -

Lump Sum / I.B.I. (\$)

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2018 16:22		11 Oct 2018 15:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ALBERT AZMI, ID: S8972032Z		
Main Claimant:	SM PARTNERS PTE LTD, Co. Reg. No.: 201811126M		
Vehicle Reg. No.:	SJR7892H	Date of Loss:	09/10/2018 10:00 - :59 [110 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 572718	Policy/Cover Note No.:	A80459143QMX (Comprehensive) Coverage: 26/06/2018 - 25/06/2019
Vehicle Reg. No. (Insured):	SMC1256C	Policy No. (Claimant):	
		Excess:	
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/10/2018]		
Adj Asg. Remarks:	on WP, liability not clear. TP Request IHS Kenneth to survey, contact: Alan Koh - 9092 7279		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1126M
Vehicle Details	
Vehicle No.:	SJR7892H
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L AT RSZ
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	R18A13850331
Chassis No.:	JHMRN68809C200331
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$27,560.00
Original Registration Date:	14 Jul 2009
First Registration Date:	14 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$27,560.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2019
PARF Rebate Amount:	\$13,780.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jul 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$14,840.00
COE Rebate Amount:	\$1,090.00
Total Rebate Amount:	\$14,870.00

The information contained herein is correct as at 18 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2018 13:20
Date Of Accident	09/10/2018 10:15
Exact Location Of Accident	30 NAPIER ROAD TOWARDS HOLLAND ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR7892H
Insured/Policyholder	
Name Of Registered Owner	5M PARTNERS PTE LTD
Co Reg No	201811126M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-85716485

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5100184044
Cover Note Number	

Driver

Name of Driver	TAN SU BOON
NRIC No	S8877243A
Date Of Birth	25/01/1988
Occupation	OUTDOOR
Date Of Driving Pass	15/02/2011
Driving Experience	7 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-85716485

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 488D CHOA CHU KANG AVE 5 #06-171 SINGAPORE
Postcode	684488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC1256C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Vehicle B: GMC 1256C

On the stated date and time, I vehicle A turned right into that lane. I checked my blindspot before I turned. Suddenly Vehicle B drive very fast towards me and cut into the lane I'm turning into too. That's how we collided

I/We declare the foregoing particulars are true in every respect.



the true in every re

Centre Personnel's

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2018 16:22		11 Oct 2018 15:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

ALBERT AZMI, ID: S8972032Z

Main Claimant:

5M PARTNERS PTE LTD, Co. Reg. No.: 201811126M

Vehicle Reg. No.:

SJR7892H

Claim Type:

TP / 572718

Vehicle Reg. No. (Insured):

SMC1256C

Excess:

Repairster:

Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by **Pauline Tham** - 6594 2545]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by **MOHD TAUFIKH BIN HAMID**] ... [Imm.Advice due 12/10/2018]

Adj Asg. Remarks:

on WP. liability not clear. TP Request IHS Kenneth to survey. contact: Alan Koh - 9092 7279

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJR7892H (572718)**
[SMC1256C]

TP


























5M PARTNERS PTE LTD

Oct 9 2018 10:00AM

[ALBERT AZMI]

Team Autopro Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/10/18 16:40	Accident Statement From: SC - Reg. No: SMC1256C, Claimant: ALBERT AZMI		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
2	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
3	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
4	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
5	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
6	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
7	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
8	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
9	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
10	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
11	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
12	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
13	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
14	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
15	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
16	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
17	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
18	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
19	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
20	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
21	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
22	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
23	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
24	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
25	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
26	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
27	19/10/18 12:24	General View		Load JPG	<input checked="" type="checkbox"/>
28	19/10/18 12:25	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
29	19/10/18 12:25	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
30	19/10/18 12:25	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
31	19/10/18 12:25	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	19/10/18 12:25	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	19/10/18 12:25	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	19/10/18 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	19/10/18 12:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/10/18 16:23	SJR7892H E-FILE REPORT	 Load PDF	
2	10/10/18 16:23	TP PRI NOTICE	 Load PDF	
3	10/10/18 16:28	TP agree SJE - Request IHS Kenneth to survey	 Load PDF	
4	15/10/18 13:02	tp reject sje - assign LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18018496/T1CD3E2

Date: 29/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80459143QMX

Claimant Vehicle No : SJR7892H

Insured Vehicle No : SMC1256C

Date of Loss: 09/10/2018

Nature of Claim: TP

Claim No: 572718

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR7892H**

Make & Model: HONDA STREAM, 1.8 L RSZ (A)

Engine No: R18A13850331

Reg. Date: 14/07/2009 (Man. Year: 2009)

Chassis No: JHMRN68809C200331

Colour: Black

Odometer: 121827 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/10/2018

Date Inspected: 12/10/2018 Inspected At:

Team Autopro Pte Ltd (Sin Ming)
385 Sin Ming Drive, #01-02 Vicom
Inspection Centre
Singapore 575718

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Oct 2018)

Parts: M1-MPV HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR7892H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >