



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18018522/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-04-2020



ATTN:KHOR SAW THENG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHF 666C	Veh. Inspected	SGL 5148D
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S8M00XGJ	Excess (\$)	0.00
Assign From		Assign Date	12/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100326617	Colour	METALLIC DARK BLUE
Odometer	192166	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	ROADSTONE	3 mm
L/H Front Tyre	215/45 R17	ROADSTONE	3 mm
R/H Rear Tyre	215/45 R17	ROADSTONE	5 mm
L/H Rear Tyre	215/45 R17	ROADSTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/09/2018	Inspection Date	12/10/2018
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------