

Surveyor:

Xhd.

REF:

18/3/6pa²


B1853X

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s lai Huat Motor
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$12K
 IDAC Accident Rpt.: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBB9308U Yr Regn: 31 Aug 2010
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Caddy c.c. 1894
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 163965 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WU/888 2KZAXG18574

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEUTON

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at W/S

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 20-12-18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OK Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

coe : 5538.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1853X
Vehicle Details	
Vehicle No.:	GBB9308U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	CADDY 1.9 TDI
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	BLSA87080
Chassis No.:	WV1ZZZ2KZAX018574
Maximum Power Output:	-
Open Market Value:	\$31,457.00
Original Registration Date:	31 Aug 2010
First Registration Date:	31 Aug 2010
Transfer Count:	0
Actual ARF Paid:	\$1,573.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,389.00
COE Rebate Amount:	\$4,977.00
Total Rebate Amount:	\$4,977.00

The information contained herein is correct as at 20 Dec 2018

OK