

22/03/2002

ASS. REC. BY:

REF: CS3/CTI18018541/GC d3/

Special Instruction:

Surveyor:

menmen

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time: 12/10/18 @ 11:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 5209K

Insured:

XD 7598R

at Workshop m/s

Yap Motor

Tel:

6451 1705

of

Blk 7 Sin Ming Ind. Est. Sec. C # 01-82

Policy No:

DMCVSN1804931800

Claim No:

SNM18D04841C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/10/2018

CA / REV / REP. / REV 24 HRS

lup

15/10/18

H.O.D. Endorsement:

Date/Time:

11:56am @ 12/10/18

Person Contacted:

Ms. Pan

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLT 5209K - NA / CTI18018298 / 24
	XD 7598R - NA / CTI18018298 / 24
	Dismantle: 16/10/2018

DOA: 9/10/2018

DOA: 9/10/2018

Surveyor

PRS  
XKL

REF: CTI

B4769W /

### ASSIGNMENT

From: \_\_\_\_\_ Date: 15/10/2018

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 5209K

at Workshop m/s Yap Motor

of Blk 7 8n Ming Ind Est. Sec. C # 01-82

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLT 5209K Yr Regn: 31 Oct 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Infiniti Q30 c.c. 1461

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 63404 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: SIKDAAH 15U-1019095

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17 R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 15-10-18

Survey held at w/s 2:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$4000 - \$8000

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: 5

1)

☐: Final Report

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation:

S + RS. SI

Photos

Others

TOTAL

150

Date/Time, File Return to?

2)

Add Fee: ☐: Site Insp (\$ )

☐: Interview (\$ )

☐: Tech. Invs (\$ )

☐: Weekend (\$ )

Report Format: PRG.

Lump Sum / I.B.I. (\$) )

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2018		12 Oct 2018 11:28 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>KOK TONG TRANSPORT &amp; ENGINEERING WORKS PTE LTD</b> , Co. Reg. No.: 199904117E		
Main Claimant:	<b>MEHIRE</b>		
Vehicle Reg. No.:	<b>SLT5209K</b>	Date of Loss:	09/10/2018 09:00 - :59
Claim Type:	<b>TP / SNM18D04841C02</b>	Policy/Cover Note No.:	DMCVSN1804931800 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>XD7598R</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Yap Motor Repair Service (SIN MING)</b> Blk 7 Sin Ming Industrial Estate Sector C, #01-82, 575642 Sin Ming - Tel: 6451 1705 / 8161 9189 / 9618 7155		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 23/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4769W
Vehicle Details	
Vehicle No.:	SLT5209K
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	INFINITI
Vehicle Model:	Q30 1.5D DCT
Primary Colour:	Pink
Manufacturing Year:	2016
Engine No.:	K9KG481D002807
Chassis No.:	SJKDAAH15U1019095
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$26,987.00
Original Registration Date:	31 Oct 2017
First Registration Date:	31 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$19,782.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2027
PARF Rebate Amount:	\$14,836.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,617.00
COE Rebate Amount:	\$37,611.00
<b>Total Rebate Amount:</b>	<b>\$52,447.00</b>

The information contained herein is correct as at 16 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/10/2018 12:17
Date Of Accident	09/10/2018 09:25
Exact Location Of Accident	OUTRAM ROAD TOWARDS CANTONMENT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5209K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MEHIRE
Co Reg No	NA
Email Address	MATTCHUA2@YAHOO.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97421010

### Vehicle Particulars

Manufacturer	INFINITI
Model	Q30
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V12641/VPL/R00
Cover Note Number	

### Driver

Name of Driver	CHUA WAI TECK MATTHEW (CAI WEIDE MATTHEW)
NRIC No	S7512892D
Date Of Birth	09/05/1975
Occupation	OUTDOOR
Date Of Driving Pass	05/06/1995
Driving Experience	23 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97421010
Fax Number	
Contact Number	
Email Address	MATTCHUA2@YAHOO.COM


SKETCH PLAN


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"); and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



  
 Policyholder's Signature  
 Date & Time: 6/1/2018  
 12:05 PM

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While travelling on Lane 2 of Astoria Road a white bus  
came out from behind turning lane into my lane. I slow  
down and was going to the bus cutting into the my lane.  
The driver made toward me and not brake in time &  
that ended my car. This before the police arrived.  
Bus' driver & wife and son sitting at the front of  
vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date & Time: 01/02/2021

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2018		12 Oct 2018 11:28 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>KOK TONG TRANSPORT &amp; ENGINEERING WORKS PTE LTD</b> , Co. Reg. No.: 199904117E								
Main Claimant:	<b>MEHIRE</b>								
Vehicle Reg. No.:	<b>SLT5209K</b>	Date of Loss:	09/10/2018 09:00 - :59 [11 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D04841C02</b>	Policy/Cover Note No.:	DMCVSN1804931800 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>XD7598R</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Yap Motor Repair Service (SIN MING)</b> Blk 7 Sin Ming Industrial Estate Sector C, #01-82, 575642 Sin Ming - Tel: 6451 1705 / 8161 9189 / 9618 7155								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 23/10/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLT5209K (SNM18D04841C02)

[XD7598R]

TP

MEHIRE

Oct 9 2018 9:00AM

[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]

Yap Motor Repair Service

Upload Documents

Upload Photos

Compose New Letter



View

View in Browser

Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	09/10/18 14:50	Accident Statement							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
2	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
3	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
4	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
5	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
6	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
7	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
8	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
9	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
10	09/10/18 14:48	Accident Photo <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	18/10/18 13:13	General View							Load PDF		
2	18/10/18 13:13	Photographs of Damaged Parts							Load PDF		
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	12/10/18 11:27	PRS WITH TP GIA							Load PDF		
2	12/10/18 11:28	OI GIA							Load PDF		
No	Finalized On	National Assessment Centre Services (Ubi)							Thumbnail	Print	
1	09/10/18 14:49	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	
2	09/10/18 14:49	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>							Load JPG	<input checked="" type="checkbox"/>	

## Linked Accident Report Documents

										View	View in Browser	
Assessment Reports										1 per page		
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print	
1	09/10/18 14:50	Accident Statement								Load HTM		
Photos/Images										3 per page		
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print	
1	09/10/18 14:48	Accident Photo								Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
2	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	09/10/18 14:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	09/10/18 14:49	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	09/10/18 14:49	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18018541/GCD3E2

Date: 26/10/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1804931800

Claimant Vehicle  
No: SLT5209KInsured Vehicle  
No: XD7598R

Date of Loss: 09/10/2018

Nature of Claim: TP

Claim  
No: SNM18D04841C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLT5209K

Make &amp; Model: INFINITI Q30, 2.0 (A)

Reg. Date: 31/10/2017 (Man. Year: 2016)

Colour: Brown

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: K9KG481D002807

Chassis No: SJKDAAH15U1019095

Odometer: 63404 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 15/10/2018 Inspected At:

Yap Motor Repair Service (SIN MING)  
Blk 7 Sin Ming Industrial Estate Sector C,  
#01-82  
Singapore 575642

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 26 Oct 2018)

**Parts:** 144      INFINITI Q30 2.0 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLT5209K)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >