

ASS. REC. BY:

REF:

CS3/CTI/8018545/Rlcd34

Special Instruction:

Surveyor:

Rasul

## ASSIGNMENT (Office)

From (Person):

Meinien Chong Boon Sen

of

CTI

Date/Time:

12/10/18 @ 11:48am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 4966x

Insured:

SJZ 6331A

at Workshop m/s

Bing Tat Auto

Tel:

6777 0859

of

Blk K, No. 6 Pandan Loop

Policy No:

DMPCSN 30599971703

Claim No:

8NM18D04810C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/10/2018

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time:

12:30pm 12/10/18

Person Contacted:

Mrs. Tan

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	GBC 4966Y-X
	SJZ 6331A-X
15/10/18-	VNI yet

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 49664at Workshop m/s BING TAY AUTOof No. 6, Pannan Loop

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

after 11amRemark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBC 49664Yr Regn: 2012 / OCTType: M.Car / M.Cycle / Bus / Van / ~~Corr~~ / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN CASSIAR 3.0 C.CColour: GREY A/C: Insured / Std / NI / NASp.Reading: 157319 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN18C2F2420850455Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185R15R: 165R13CES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 5/5 mmL/Bal. 7 mm L/Bal. 5/5 mmD.O.A. 08/10/18 D.O.I. 17/10/18Survey held at BING TAY

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRSRange \$3,500 - \$4,30023/10/2018TG Lim22/10/18

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 150Transportation: S + RS, SI

Photos

Others

TOTAL

150Report Format: PRS

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		12 Oct 2018 11:48 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHIU KOK KWANG, ID: S1817190B		
Main Claimant:	CHIA MENG HAK SUPPLIER PTE LTD, Co. Reg. No.: 200812063G		
Vehicle Reg. No.:	GBC4966Y	Date of Loss:	08/10/2018 07:00 - :59
Claim Type:	TP / SNM18D04810C02	Policy/Cover Note No.:	DMPCSN3059971703 (Comprehensive)
Vehicle Reg. No. (Insured):	SJZ6331A	Policy No. (Claimant):	505598391-06
		Excess:	S\$0.00
Repairer:	Bing Tat Auto Service (HQ) 1 Pandan Loop, #01-06, 128219 West Coast - Tel: 67770859		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/10/2018]		
Driver/Custodian (Insured):	CHIU KOK KWANG (51 / Male), NRIC: S1817190B		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# K. K. CHENG & CO

Advocates and Solicitors  
101 Upper Cross Street #05-21  
People's Park Centre  
Singapore 058357  
Tel: 6227 1272 Fax: 6227 5563

Our Ref: BT/GBC 4966Y  
Your Ref: SJZ 6331A  
(Please quote our reference number when replying)

12 October 2018

CHINA TAIPING

By fax only: 6224-7478/6224-7175

Attention: Motor Claims Department

Dear Sirs

## NOTICE OF ACCIDENT

Claimant: CHIA MENG HAK SUPPLIER PTE LTD

*Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or after 1<sup>st</sup> April 2016 ["Protocol"]*

We refer to your letter dated 12 October 2018.

**Firstly**, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 11 October 2018.

**Secondly**, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 11 October 2018.

**Thirdly**, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

**Fourthly**, *for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.*

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

**Finally**, the location and contact person of the workshop are as follows:

Name of Workshop : Bing Tat Auto Service  
Address : Block K, No. 6 Pandan Loop Singapore 128224  
Contact person : Mr Tan/Mrs Tan  
Telephone No. : 67770859

Yours faithfully

CHENG KIM KUAN  
cc Workshop (REF: GBC 4966Y)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/10/2018 12:52
Date Of Accident	08/10/2018 07:55
Exact Location Of Accident	SELETAR WEST LINK TWD YISHUN AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC4966Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHIA MENG HAK SUPPLIER PTE LTD
Co Reg No	200812063G
Email Address	GENERAL@CHIAMENGHAK.COM
Mobile Phone No	
Alternative Phone No	Office-93983527

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-2.5 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	505598391-06
Cover Note Number	

### Driver

Name of Driver	PALANIVEL RAJA
NRIC No	G3250166X
Date Of Birth	22/09/1990
Occupation	OUTDOOR
Date Of Driving Pass	28/06/2018
Driving Experience	0 YEAR AND 3 MONTH

Gender	MALE
Mobile Number	(LOCAL) +65-93963527
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	NO ADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLANS

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ6331A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address  
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBA1707J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SDP908A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened <sup>along</sup> Seletar West Link (from direction of Seletar Aerospace toward Yishu Ave 1) beside PUS Lower Seletar.

I was travelling along Seletar West Link. w Traffic was very heavy. When the vehicles <sup>in front</sup> slowed down and stopped. I also stopped. Suddenly I heard sound of collision and vehicle No G SJ Z 6 3 3 1 A collided on to the rear of my vehicle. When I alighted, I noticed that Veh. No SDP 9 0 8 A had collided on to the rear of GBA 1 7 0 7 J, then GBA 1 7 0 7 J collided on to SJZ 6 3 3 1 A rear.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Holder's Name: **G3250166X**

**PALANIVEL RAJA**

Birth Date: **22 Sep 1990**  
 Issue Date: **28 Jun 2018**  
 Valid Till: **27/06/2023**

002818061G




**S PASS**  
 Employment of Foreign Manpower Act (Chapter 91A)  
 Republic of Singapore

Employer:  
**CHA MENG HAK FOOD SUPPLIER PTE. LTD.**

Sector: **SERVICE**

Name:  
**PALANIVEL RAJA**

Occupation:  
**ASSISTANT OPERATIONS SUPERVISOR**

S Pass No.  
**0 97519790**

Date of Application:  
**13-06-2017**

Date of Issue:  
**11-07-2017**

Date of Expiry:  
**11-07-2019**

L8123194




**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

**EFFECTIVE DATE**

Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg **28 Jun 2018**

NP 428A



**VISIT PASS**  
 Immigration Regulations

Name:  
**PALANIVEL RAJA**

Date of Birth: **22-09-1990** Sex: **M** Nationality: **INDIAN**

FIN: **G3250166X** Date of Issue: **11-07-2017** Date of Expiry: **11-07-2019**

**MULTIPLE JOURNEY VISA ISSUED**

**YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.**




### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		12 Oct 2018 11:48 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	CHIU KOK KWANG, ID: S1817190B		
Main Claimant:	CHIA MENG HAK SUPPLIER PTE LTD, Co. Reg. No.: 200812063G		
Vehicle Reg. No.:	GBC4966Y	Date of Loss:	08/10/2018 07:00 - :59 [72 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04810C02	Policy/Cover Note No.:	DMPCSN3059971703 (Comprehensive)
Vehicle Reg. No. (Insured):	SJZ6331A	Policy No. (Claimant):	505598391-06
		Excess:	S\$0.00
Repairer:	Bing Tat Auto Service (HQ) 1 Pandan Loop, #01-06, 128219 West Coast - Tel: 67770859		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/10/2018]		
Driver/Custodian (Insured):	CHIU KOK KWANG (51 / Female), NRIC: S1817190B		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*GBC4966Y (SNM18D04810C02)  
[SJZ6331A]  
TP  
CHIA MENG HAK SUPPLIER PTE LTD  
Oct 8 2018 7:00AM  
[CHIU KOK KWANG]  
Bing Tat Auto Service

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)							Thumbnail	Print	
1	08/10/18 13:00	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)							Thumbnail	Print	
1	08/10/18 12:58	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	08/10/18 12:58	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	08/10/18 12:58	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	08/10/18 12:58	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	08/10/18 12:58	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	08/10/18 12:58	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	22/10/18 11:38	General View							Load PDF		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	12/10/18 11:47	PRS							Load PDF		
2	12/10/18 11:47	TP GIA							Load PDF		
3	12/10/18 11:48	OI GIA							Load PDF		
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)							Thumbnail	Print	
1	08/10/18 12:58	Sketch Plan [Linked Accident Report Documents]							Load TIF		
2	08/10/18 12:58	Sketch Plan #2 [Linked Accident Report Documents]							Load TIF		

## Linked Accident Report Documents

										View	View in Browser	
Assessment Reports										1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)									Thumbnail	Print
1	08/10/18 13:00	Accident Statement									Load HTM	
Photos/Images										3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)									Thumbnail	Print
1	08/10/18 12:58	Accident Photo									Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 12:58	Accident Photo									Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 12:58	Accident Photo									Load JPG	<input checked="" type="checkbox"/>
4	08/10/18 12:58	Accident Photo									Load JPG	<input checked="" type="checkbox"/>
5	08/10/18 12:58	Accident Photo									Load JPG	<input checked="" type="checkbox"/>
6	08/10/18 12:58	Accident Photo									Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	08/10/18 12:58	Sketch Plan	 Load TIF	
2	08/10/18 12:58	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18018545/R1CD3E2

Date: 26/10/2018

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3059971703

Claimant Vehicle  
No : GBC4966YInsured Vehicle  
No : SJZ6331A

Date of Loss: 08/10/2018

Nature of Claim: TP

Claim  
No: SNM18D04810C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC4966Y

Make &amp; Model: NISSAN CABSTAR, 2.5 (M)

Reg. Date: 02/10/2012 (Man. Year: 2012)

Colour: Grey

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: ZD30303939K

Chassis No: JN1SC2F24Z0850455

Odometer: 157319 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 165 R13C

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 5/5 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 17/10/2018

Inspected At:

Bing Tat Auto Service (HQ)  
NO.6 PANDAN LOOP  
SINGAPORE 128224

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen...> 26/10/2018



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,300.00



REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Oct 2018)	
Parts:	N/A	NISSAN CABSTAR 2.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4966Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.	
Report was unsubmitted during this print-out.	

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >