

22/03/2003

ASS. REC. BY:

REF:

CS3/ Lpc/18018 617 /Uad3e

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Org Li Li

of

lpc

Date/Time:

15/10/18 @ 12.15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCV 822T

Insured:

GBD 4061C

at Workshop m/s

ZOOM Autowerks

Tel:

9450 7920

of

15 Kaki Blk Rd 4 #01-53

Policy No:

Claim No:

17118/18/VCOO/02/012

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/10/2018

CA / REV / REP. / REV 24 HRS

lup17110/2018

H.O.D. Endorsement:

Date/Time: 12:30pm @ 15/10/18

Person Contacted:

Elin

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SCV 822T- NA/INC/18018 489/24DOA: 10/10/18GBD 4061C- NA/INC/18018 489/24DOA: 10/10/1804/11/18submit m/s.

REF:

JPC

## ASSIGNMENT

From:

Date:

17/10/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SCV 822T

at Workshop m/s

ZOOM Autowerks

of

15 Kaki Bkt Rd 4 # 01-53

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

3230Z

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCV 822T

Yr Regn:

6, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Audi A4

C.C

1798

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

198904

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ8K69A229024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/35-12 19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/10/18

D.O.I.

17/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/1/19

No contact LTA 2018

according to Elin Lam from Autowerks they pass liability.

\* repairer didn't provide GIA report.

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

1) 04/1/19

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

450

Transportation:

S + RS, SI

Photos

Others

TOTAL

450

Report Format:

PRS.

Lump Sum / I.B.I. (\$) )

**Nivitha (LKK Auto)**

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 15 October 2018 12:15 PM  
**To:** Spencer Phng; MT\_Claim\_SG; assignments@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** Zoom Autowerks; Limdanny; Aarontan  
**Subject:** Our Ref: 17/18/18/VC00/021012 RE: URGENT: Accident involving SCV822T & GBD4061C on 10/10/18 (Our Ref: PD/DL/1801766 (Sp))  
**Attachments:** GIA Report - SCV822T.PDF; PRS Letter to Lonpac 15102018.pdf; GIA Report - SCV822T.PDF; PRS Letter to Lonpac 15102018.pdf

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

-----Original Message-----

From: Spencer Phng [<mailto:pri@satwantlaw.com>]  
Sent: Monday, 15 October, 2018 12:08 PM  
To: MT\_Claim\_SG  
Cc: Zoom Autowerks; Limdanny; Aarontan  
Subject: URGENT: Accident involving SCV822T & GBD4061C on 10/10/18 (Our Ref: PD/DL/1801766 (Sp))

WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly see attached our PRS letter for your urgent attention. Thank you.

Thank you & Best Regards

Spencer Phng (Branch Office)

For and on behalf of

SATWANT & ASSOCIATES

Advocates & Solicitors | Notary Public | Commissioner for Oaths Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Branch Office: 450 Lorong 6 Toa Payoh #02-03 Hersing Centre Singapore 319394 | tel: 6221 6114 | fax: 6266 6925

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at [margaretlm@satwantlaw.com.sg] and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses. We take no responsibility for any loss or damage, whether caused by our own negligence or not, that results from a computer virus or a defect in the transmission of this email or any attached file.

On 2018-10-15 13:44, Zoom Autowerks wrote:

> Hi Spencer,

>

> Kindly assist, thank you.

>

> Warmest Regards,

> ELIN CAI

>

> ZOOM AUTOWERKS PTE LTD

> 130 Bedok Reservoir Road

> #08-1339 Singapore 470130

> )9450 7920

>

> [8zoomautowerks@gmail.com](mailto:8zoomautowerks@gmail.com)

>

> \_ - PLEASE NOTE OUR CHANGE IN MAILING/REGISTERED ADDRESS WITH EFFECT  
> FROM 1ST JULY 2018 - \_

--

Spencer Phng

➤ **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3230F
<b>Vehicle Details</b>	
Vehicle No.:	SCV822T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8T FSI MU S-LINE CVT ABS D/AB HID
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CDH050272
Chassis No.:	WAUZZZ8K69A229021
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$39,011.00
Original Registration Date:	15 Jun 2009
First Registration Date:	15 Jun 2009
Transfer Count:	4
Actual ARF Paid:	\$39,011.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2019
PARF Rebate Amount:	\$19,505.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$12,901.00
COE Rebate Amount:	\$784.00
<b>Total Rebate Amount:</b>	<b>\$20,289.00</b>

The information contained herein is correct as at 17 Oct 2018

OK


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Ref: CS3/LPC18018617/Uqd3e2 Date: 08-01-2019 Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBD 4061C	Veh. Inspected	SCV 822T	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VC00/021012	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	15/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WAUZZZ8K69A229021	Colour	BLACK	
Odometer	198904 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 R19	GOODYEAR	6 mm	
L/H Front Tyre	245/35 R19	GOODYEAR	6 mm	
R/H Rear Tyre	245/35 R19	GOODYEAR	6 mm	
L/H Rear Tyre	245/35 R19	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	10/10/2018	Inspect Date / Time	17/10/2018 ( 11:01 AM )	
Survey held at	15 KAKI BUKIT AVE 4 #01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC18018617/Uqd3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.