

ASS. REC. BY:

REF: CS3/LPC18018618/UVd3^{SP}

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Gerald poh

of

LPC

Date/Time:

15/10/18 @ 10:25am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFC 9969J

Insured:

SJS 5347Z

at Workshop m/s

Motor Intel

Tel:

8838 3318

of

13 kaki Blk Rd 4 #01-20

Policy No:

Claim No:

18/18/18/vp05/021023

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/10/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12:25pm @ 15/10/18

Person Contacted:

Wilson

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SFC 9969J - X
	SJS 5347Z - CC3/AXA 10023174/H/n2c3q2 DOA: 12/11/2010
	Dismantle - 16/10/18
	After paint - 18/10/18
22/8/18	Submit PRS

Signature *no/cus*

REF:

KPC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

STC 9969J
motor inspd

at Workshop n/s

of

Insured.

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

STC 9969J

Yr Regn:

314

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

CA

Make:

mer Benz 445

c.c

199

Colour

Grey/white

A/C:

Insured / Std / Nil / NA

Sp. Reading

55379

T/Radio:

Insured / Std / Nil / NA

Eng/No:

O/No:

WDD176222J157472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/302220

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

century

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/10/18 2.57pm

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Lt 2/5

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

no settling. any sticker buyer

RECEIVED 22 OCT 2018

Date/Time File Pass to?

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

3 + RS \$

Photos

Sheet

TOTAL

1)

Date/Time File Return to?

2)

10/10- typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Web and (\$

Report Format :

PRS

Lump Sum / I.B.I. (\$

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 15 October 2018 10:25 AM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG
Subject: PRE-REPAIR SUREY- SFC9969J
Attachments: 15102018102027.pdf

Our Ref : 18/18/18/VP05/021023

Dear Catherine/Nivitha,

Please see attached and proceed with the pre-repair survey.

Aside – M/s Bonnie Kwok LLC

Attn:June- Please update our address as indicated in the email.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

BONNIE KWOK LLC*Advocates & Solicitors*

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel : (65) 6536 6026
Fax : (65) 6536 2279
(Not for service of court documents)
GST Reg. No. 2012035472

Your Vehicle: SJS 5347 Z (3rd Party Vehicle)

Our Vehicle: SFC 9969 J

15 October 2018

M/s LonPac Insurance Bhd
101 Thomson Road
#18-01 United Square
Singapore 307591

By Fax 6296 3767 Only

Dear Sir,

ACCIDENT INVOLVING SFC 9969 J & SJS 5347 Z ON 12 OCTOBER 2018

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SFC 9969 J at M/s Motor Intel Automo Pte Ltd., No. 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Please contact Mr. Wilson at 88383318 or Mr. Daniel at 93858911.

Your faithfully



Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 15 October 2018 12:20 PM
To: admin-d@lkkauto.com
Subject: FW: PRE-REPAIR SUREY- SFC9969J
Attachments: 15102018102027.pdf

Dear Catherine,

Please proceed.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: GERALD POH WEE BIN
Sent: Monday, 15 October, 2018 10:25 AM
To: 'admin-d@lkkauto.com'
Cc: 'mt_claim@lonpac.com'
Subject: PRE-REPAIR SUREY- SFC9969J

Our Ref : 18/18/18/VP05/021023

Dear Catherine/Nivitha,

Please see attached and proceed with the pre-repair survey.

Aside – M/s Bonnie Kwok LLC
Attn:June- Please update our address as indicated in the email.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

Date of accident

12 Oct 2018

Accident Time: 1613 hrs (24-HR-Format)

Accident Place

Highway @ Brookvale Rd

Vehicle No. (in blue area)

SFC9969J

Make/Model: MERC MA45

Insurance Company

Policy No: WA 0010013

Owner and primary driver of the

Jason Ng Kok Soon

S17666176 S17666176

owner of Company (if any)

96999969

Owner's Hp

Company Tel

DRIVER'S Name: R. No.

Jason Ng Kok Soon

DRIVER'S Date of Birth

02 Feb 1966

DRIVER'S License Pass Date 29 Jan 1983

Is the driver a professional driver?

Spouse Parents Children Sibling Employee Others

DRIVER'S Address

19 The Wood Rd #01-05 S17666176

DRIVER'S Contact No. Alt No.

1) 96999969

2)

DRIVER'S Occupation

INSUROR / ITDCOR (e.g. working inside or outside office)

Current Address

Sales (M) S17666176

Weather & Road Surface

LEAF & DRY RAINING & WET AFTER RAIN & WET

Reason for stop

Reporting Duty Claim Other Party Claim Own Insurance

Is there any person accompanying Driver?

Yes - None

Was there any video or camera system (e.g. CCTV)?

Place purpose for which vehicle was being used at the time of accident: Private use Work purpose

Any injury (if any)? (If any)

None

Other Party Driver's Particular (if any)

Vehicle No.

SJS 5347Z

Vehicle No.

Vehicle Make/Model

Vehicle Make/Model

Name Driver

Name Driver

IC No. Driver/Contact

IC No. Driver/Contact

* NEW - Passenger's name & gender:

$$\text{val}_1: \mathbb{R} \rightarrow \mathbb{R} \text{ is } \text{val}_1(x) = x$$

Reporting Centre Personnel's Signature:
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6617G
Vehicle Details	
Vehicle No.:	SFC9969J
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A45 AMG 4MATIC (R19 BI)
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	13398080001625
Chassis No.:	WDD1760522J157472
Maximum Power Output:	265.0 kW (355 bhp)
Open Market Value:	\$49,318.00
Original Registration Date:	03 Mar 2014
First Registration Date:	03 Mar 2014
Transfer Count:	2
Actual ARF Paid:	\$61,046.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2024
PARF Rebate Amount:	\$45,784.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$79,000.00
COE Rebate Amount:	\$42,332.00
Total Rebate Amount:	\$88,116.00

The information contained herein is correct as at 15 Oct 2018

OK


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC18018618/Uvd3s2 Date: 25-10-2018 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJS 5347Z	Veh. Inspected	SFC 9969J
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021023	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	15/10/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ A45 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD1760522J157472	Colour	GREY / WHITE
Odometer	55379 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/30ZR20	CONTINENTAL	6 mm
L/H Front Tyre	235/30ZR20	CONTINENTAL	6 mm
R/H Rear Tyre	235/30ZR20	CONTINENTAL	6 mm
L/H Rear Tyre	235/30ZR20	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
5. General Information			
Accident Date	12/10/2018	Inspect Date / Time	15/10/2018 (12:57 PM)
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC18018618/Uvd3s2

Inspected By



CHUA KANG SENG

Licensed Appraiser



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.