

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI18018623/Gcd362

Special Instruction:

Surveyor
MENMEN

Guo Qiang

ASSIGNMENT (Office)

From (Person):

chung buon sen

of

CTI

Date/Time:

15/10/18 @ 11:28am

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 1786P

Insured:

YN 8201P

at Workshop m/s

Alpha Car Services

Tel:

65095258

of

1 kaki 3let tre 6 # 01-59

Policy No:

DMCVSN3054361801

Claim No:

8NM18D04837C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/10/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11:58am 15/10/18

Person Contacted:

cai ling

Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate	
	GBD 1786P- NA/CTI18018200/r3	DOA: 7/10/2018
	YN 8201P- NA/CTI18018200/r3	DOA: 7/10/2018
	Dismantle: 16/10/2018	

REF:

71

C06762 /

ASSIGNMENT

From:

Date:

Veh No:

GSD1786P

Yr Regn:

16 Jul 2014

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Nissan cabstar c.c 2953

at Workshop m/s

Alpha Car

Colour:

Blue

A/C: Insured / Std / NI / NA

of

Sp. Reading

70245

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JNISC2F 247.0855762

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or


Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195 R15
R: 155 R13

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Condor (Rear)

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5 mm

R/Bal.

5/45 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5 mm

L/Bal.

5/45 mm

Est. Repairs:

4

days

Res.: Yes or No

D.O.A.

D.O.I.

15-10-18

Lum Sum:

20

%

3 Val.: Yes or No

Survey held at

w/s

CA / REV / REP. / 24 HRS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 3000 - \$ 4000

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

4

1)

☐

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$)

) \$ + RS. SI

☐

: Interview (\$)

) Photos

☐

: Tech. Invs (\$)

) Others

☐

: Weekend (\$)

)

TOTAL

Report Format : PRG .

Lump Sum / I.B.I. (\$))

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2018		15 Oct 2018 11:28 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	CHIAM GARDEN LANDSCAPE & CONSTRUCTION PTE LTD, Co. Reg. No.: 200000676Z		
Vehicle Reg. No.:	GBD1786P	Date of Loss:	07/10/2018 09:00 - :59
Claim Type:	TP / SNM18D04837C02	Policy/Cover Note No.:	DMCVSN3054361801
Vehicle Reg. No. (Insured):	YN8201P	Policy No. (Claimant):	DMCVSN3044961803
		Excess:	\$0.00
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0676Z
Vehicle Details	
Vehicle No.:	GBD1786P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	ZD30338479K
Chassis No.:	JN1SC2F24Z0855762
Maximum Power Output:	-
Open Market Value:	\$25,081.00
Original Registration Date:	16 Jul 2014
First Registration Date:	16 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$1,255.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$13,741.00
COE Rebate Amount:	\$7,895.00
Total Rebate Amount:	\$7,895.00

The information contained herein is correct as at 16 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2018 12:29
Date Of Accident	07/10/2018 09:45
Exact Location Of Accident	KJE SLIP ROAD TOWRS CCK WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD1786P
Insured/Policyholder	
Name Of Registered Owner	M/S CHIAM GARDEN LANDSCAPE & CONSTRUCTION PTE LTD
Co Reg No	200000676Z
Email Address	CHIAMGARDEN@LIVE.COM
Mobile Phone No	(LOCAL) +65-92379788
Alternative Phone No	OFFICE-92379788

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 5M/T ABS 2DR 2WD EURO 5 (A)
Exact Purpose for which vehicle was being used at time of accident	TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3044961803
Cover Note Number	

Driver

Name of Driver	NG BAK SENG
NRIC No	S0182005B
Date Of Birth	13/06/1952
Occupation	OUTDOOR
Date Of Driving Pass	20/10/1972
Driving Experience	45 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96336657
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 118 YISHUN RING ROAD #02-659
Postcode	760118
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : MONDOL SAPON
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN ATTACHED. ***ADDENDUM - AMEND PASSENGER'S NAME FROM MONDOC SAPON TO MONDOL SAPON*** ***ADDENDUM - AMEND VEHICLE REG NO FROM XE9903A TO YN8201P***

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN8201P
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	NG BAK SENG
Approximate Age	66
Injuries Sustain	
Injured person in which vehicle?	GBD1786P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 118 YISHUN RING #02-659
Postcode	760118

DETAILS OF INJURED PERSON 2

Name	MONDOL SAPON
Approximate Age	30
Injuries Sustain	
Injured person in which vehicle?	GBD1786P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
 Date & Time:

8/10/18 11:00


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:




Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



VEH A: GBD 1786D.
VEH B: XE 9903 A-

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving and was late slip rd turning
into C-c-lc way. As I was about to turn
a big truck hit into the rear of my
veh. Causing my veh to surge forward.
I myself and my pass had neck and back
pain due to the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

8/10/18
11-00

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 200208384E

MZ300/C
R SN
AN0420A
Cov. Type: C

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1959
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No.	DMCV5N3044961803	Engine No : Z030338479K Chano: JN1SC2F24Z08S5762
1. Index Mark and Registration Number of Vehicle	GB01786P	AUTOSAFE
2. Name of Policy Holder	M/S CHIAM GARDEN LANDSCAPE & CONSTRUCTION PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	16 July 2018	EXCESS SECT I S\$500.00 EX ON WINDSCREEN S\$100.00
4. Date of Expiry of Insurance	15 July 2019	
5. Persons or Classes of Persons entitled to drive*	Any person who is driving on the Policyholder's order or with their permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
6. Limitations as to use*	(1) Use in connection with the Policyholder's business. (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. (3) Use for social, domestic or pleasure purposes. The Policy does not cover: (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing. (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.	

HIRE PURCHASE CO. : HITACHI CAPITAL SINGAPORE PTE LTD AS HP OWNER


* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:  
Authorized Officer


Authorized Signatory

3 Anson Road #16-00 Springleaf Tower Singapore 078909 Tel: 6389 6111 Fax: 6225 3592 Website: www.sg.cntaiping.com

Drive.



AMENDED SKETCH PLAN Pg. 1

**GENERAL
INSURANCE
ASSOCIATION**
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCCA 18/30/40-01 Vehicle Registration No: GBD 1786 P
Name(as shown in NRIC): Chiam Garden Landscape & Construction Pte Ltd NRIC/FIN/Passport No : 300000676 Z
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 88 Tampines Road Singapore(535071)
Contact (Tel) : _____ Mobile No. : 9237 9788
Email Address : chiamgarden@live.com
Date of Accident : 07/10/2018 Time of Accident : 9:45 am
Place of Accident : KJE Slip Road towards CCK way.
Insurance Company: China Taiping Insurance (Singapore) Pte Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:


Amend Other Vehicle Reg No From XE 9903A to YN 8201P.

Policyholder / Driver's Signature
Date: 11/10/18
2 pm



Reporting Centre Personnel's Signature

Name: Sally
NRIC/FIN No.: 5184Z
Date: 11/10/18





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66SS00206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCCA18130140 Vehicle Registration No: 9BD 1786 P
Name (as shown in NRIC) : M/ CHIAM GARDEN LANDSCAPE & CONSTRUCTION P/L NRIC/FIN/Passport No : 2000 00676Z
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. : 92379728
Email Address : chiamgarden@live.com
Date of Accident : 07/10/2018 Time of Accident : 09:45 am
Place of Accident : KJE Ship Road Towards CCK Way
Insurance Company : China Taiping Insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend passenger's Name from MONDOC Japan to
MONDOL SAPON

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: Sally
NRIC/FIN No.:



Addendum Sheet Pg. 1

**GENERAL
INSURANCE
ASSOCIATION**
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MCCA 18/30/40-01 Vehicle Registration No: G8D 1786 P
Name (as shown in NRIC): Chiam Garden Landscape & Construction Pte Ltd NRIC/FIN/Passport No: 300000676 Z
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: 88 Tampines Road Singapore (535671)
Contact (Tel): _____ Mobile No.: 9237 9788
Email Address: chiamgarden@live.com
Date of Accident: 07/10/2018 Time of Accident: 9:45 am
Place of Accident: KJE Slip Road towards CCK way.
Insurance Company: China Taiping Insurance (Singapore) Pte Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend Other Vehicle Reg No From XE 9903A to YN 8201P.

Policyholder / Driver's Signature

Date: 11/10/18

[Signature]



Reporting Centre Personnel's Signature

Name: Sally

NRIC/FIN No.: 5184Z

Date: 11/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2018		15 Oct 2018 11:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	CHIAM GARDEN LANDSCAPE & CONSTRUCTION PTE LTD, Co. Reg. No.: 200000676Z								
Vehicle Reg. No.:	GBD1786P	Date of Loss:	07/10/2018 09:00 - :59 [50 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04837C02	Policy/Cover Note No.:	DMCVSN3054361801						
Vehicle Reg. No. (Insured):	YN8201P	Policy No. (Claimant):	DMCVSN3044961803						
		Excess:	S\$0.00						
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/10/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBD1786P (SNM18D04837C02)

[YN8201P]

TP

CHIAM GARDEN LANDSCAPE & CONSTRUCTION PTE LTD

Oct 7 2018 9:00AM

[-]

Alpha Car Services Pte Ltd


[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser






Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/10/18 13:59	Accident Statement	Load HTM	
2	08/10/18 16:37	Addendum Sheet	Load TIF	
3	08/10/18 16:39	Accident Statement Addm. #1	Load HTM	
4	11/10/18 14:12	Addendum Sheet	Load TIF	
5	11/10/18 14:24	Accident Statement Addm. #2	Load HTM	











Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 13:08	INSURED CHASSIS NO [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	08/10/18 13:08	INSURED VEH [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/10/18 11:10	General View	Load PDF	
2	19/10/18 11:11	Photographs of Damaged Parts	Load PDF	






Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/10/18 15:06	PRS	Load PDF	
2	12/10/18 15:07	OI GIA	Load PDF	
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/10/18 13:06	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	08/10/18 13:06	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	08/10/18 13:06	INSURED CI [Linked Accident Report Documents]	Load TIF	
4	08/10/18 13:06	DRIVER IC & DL [Linked Accident Report Documents]	Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
5	11/10/18 14:19	AMENDED SKETCH PLAN [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print	
1	08/10/18 13:59	Accident Statement	 Load HTM		
2	08/10/18 16:37	Addendum Sheet	 Load TIF		
3	08/10/18 16:39	Accident Statement Addm. #1	 Load HTM		
4	11/10/18 14:12	Addendum Sheet	 Load TIF		
5	11/10/18 14:24	Accident Statement Addm. #2	 Load HTM		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 13:08	INSURED CHASSIS NO	 Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
4	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
5	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
6	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
7	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
8	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
9	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
10	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
11	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
12	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>
13	08/10/18 13:08	INSURED VEH	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/10/18 13:06	Sketch Plan	 Load TIF	
2	08/10/18 13:06	Sketch Plan #2	 Load TIF	
3	08/10/18 13:06	INSURED CI	 Load TIF	
4	08/10/18 13:06	DRIVER IC & DL	 Load TIF	
5	11/10/18 14:19	AMENDED SKETCH PLAN	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18018623/GCD3E2

Date: 30/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3054361801

Claimant Vehicle
No: GBD1786PInsured Vehicle
No: YN8201P

Date of Loss: 07/10/2018

Nature of Claim: TP

Claim
No: SNM18D04837C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD1786P

Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO
5 (A)

Engine No: ZD30338479K

Reg. Date: 16/07/2014 (Man. Year: 2014)

Chassis No: JN1SC2F24Z0855762

Colour: Blue

Odometer: 70245 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R13 (D)

Front Left Side: Bridgestone 5 mm

Rear Left Side: Condor 5/5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Condor 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/10/2018

Date Inspected: 15/10/2018 Inspected At:

Alpha Car Services Pte Ltd (HQ)
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Oct 2018)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD1786P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >