

22/03/2002

ASS. REC. BY:

REF:

CS3/SMO18018638/Rld362

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Thelma Choo of SMO

Date/Time: 15/10/18 @ 10.26am

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG1210T

Insured:

GBB7164E

at Workshop m/s

AMA Autocare

Tel:

8778 3636

of

36 ton Guan Rd East # 01-36

Policy No: DISMTH CVE 000154

Claim No:

CMTD1804124

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/09/18

CA / REV / REP. / REV 24 HRS

Wp

H.O.D. Endorsement:

Date/Time: 11:43am @ 15/10/18

Person Contacted:

Melvin

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBG1210T - X
	GBB7164E - CC4/AXA/0025964/Rafg 2 DOR: 23/12/2010
	Dismantle: 16/10/2018.

08/11/13

Surveyor:

Ramu

REF:

49352

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBG 1210Tat Workshop m/s AMA AUTOCAREof 36, TOL HUAN RD KMT #101-36Insured: Smo

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBG 1210T Yr Regn: 2017 / may

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NV 200 1.5 MT c.c. 1461Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 39685 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: USKY BAR 2020141867Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/70R14C

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 28/09/18 D.O.I. 15/10/18Survey held at AMA AUTOCAREDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>PRS</u>
	<u>Range 12,000/2 - 14,000/2</u>
	<u>Repair days 9</u>
	<u>19/10/2018</u>
	<u>T. Grim</u>
	<u>19/10/18</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 9

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : PRS

Lump Sum / I.B.I. (\$) \_\_\_\_\_

100

60

10

170

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018		15 Oct 2018 10:26 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	CIS-TRONICS PTE LTD, Co. Reg. No.: 200104955R		
Vehicle Reg. No.:	GBG1210T	Date of Loss:	20/09/2018 18:00 - :59
Claim Type:	TP / CMTD1804124	Policy/Cover Note No.:	D18MTHCVE000154 (Third Party Only)
Vehicle Reg. No. (Insured):	GBB7164E	Policy No. (Claimant):	
		Excess:	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by <b>Thelma Choo</b> - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 24/10/2018]</b>		
Driver/Custodian (Insured):	NORSHAFIEE BIN SAPON (), NRIC: S9213596I, Tel: +6591111111		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

Our Ref : GBG 1210T (wk)

Your Ref : To be advised

12 October 2018

Sompo Insurance Singapore Pte. Ltd.

BY EMAIL

Dear Sirs,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : CIS-TRONICS PTE LTD**  
**ACCIDENT INVOLVING GBG 1210T & GBB 7164E ALONG PIE ON 20**  
**SEPTEMBER 2018**  
**PRE-REPAIR SURVEY NOTICE**

1. We act for Cis-Tronics Pte Ltd, the owner of motor vehicle no. GBG 1210T which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. GBB 7164E for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	AMA Autocare Pte Ltd
Address	36 Toh Guan Road East #01 – 36 Singapore 608580
Contact Person	Mr. Melvin (8778 3636)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next **two (2) working days** (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiaarul.com

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4955R
Vehicle Details	
Vehicle No.:	GBG1210T
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	K9KC400D056547
Chassis No.:	VSKYBAM20Z0141817
Maximum Power Output:	-
Open Market Value:	\$20,122.00
Original Registration Date:	31 May 2017
First Registration Date:	31 May 2017
Transfer Count:	0
Actual ARF Paid:	\$1,007.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,600.00
COE Rebate Amount:	\$26,363.00
Total Rebate Amount:	\$26,363.00

The information contained herein is correct as at 18 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/09/2018 10:21
Date Of Accident	20/09/2018 19:00
Exact Location Of Accident	ALONG PIE (CITY) BEFORE THE EXIT TO BKE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG1210T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CIS-TRONICS PTE LTD
Co Reg No	200104955R
Email Address	CISTRONICS.ADM@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62538852

### Vehicle Particulars

Manufacturer	NISSAN
Model	NV200
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPCVE001404
Cover Note Number	

### Driver

Name of Driver	RADHAKRISHNAN VENKADA PRABHU
NRIC No	G5421029P
Date Of Birth	02/06/1988
Occupation	OUTDOOR
Date Of Driving Pass	26/02/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91311427
Fax Number	
Contact Number	
Email Address	VENKATAPRABHU.SOLAI@GMAIL.COM

Address	BLOCK 9 SELEGIE ROAD #13-30
Postcode	180009
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please refer to the attached Sketch Plan and the accident details

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB7164E
Vehicle Make/Model/Colour	VEHICLE ( B )
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NORSHAFIEE BIN SAPON
NRIC/Passport Number	S9213596I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKZ7136D
-----------------------------	----------

Vehicle Make/Model/Colour	VEHICLE ( C )
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANG TIONG YEOW
NRIC/Passport Number	S7047279A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

R.v. Png.



Policyholder's Signature  
Date & Time:


R.v. Png. 21/09/18

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

10AM

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan Pg. 2



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On September 20, 2018 at about 7.00 pm, I was driving my vehicle (A) bearing registration number GBG1210T along PIE towards city. The road was wet and it was raining.

Whilst I was driving along the PIE on the 2nd lane from the left and just before the exit to BKE, suddenly I felt an impact from the rear and my vehicle was pushed forward and collided onto a front vehicle bearing registration number SKZ7136D (C).

I stopped my vehicle and alight to check and noted that my vehicle was hit by a Nissan Van bearing registration GBB7164E (B).

As there was no injury to all parties, we exchange our particulars as follows:

Vehicle B : GBB7164E  
Driver : Norshafiee Bin Sapon  
IC No : S9213596I

Vehicle C : SKZ7136D  
Driver : Ang Tiong Yeow  
IC No : S7047279A

### **DECLARATION**

I/We declare the foregoing particulars are true in every aspect.



*R.v. Poy.*  
Policyholder's Signature  
Date & Time

*R.v. Poy 21/09/18*  
Driver's Signature (if driver is not the policyholder)  
Date / Time

\_\_\_\_\_  
Reporting Centre Personnel Signature  
Name :  
NRIC / FIN No :



S PASS

Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer  
CIS-TRONICS PTE LTD

Sector: CONSTRUCTION



Name

RADHAKRISHNAN VENKADA PRABHU

Occupation

PROJECT SUPERVISOR

S Pass No.  
0 37144851

Date of Application  
24-11-2016

Date of Issue  
19-12-2016

Date of Expiry  
19-12-2018



L7484511

Address:

BLK 9, #13-30  
Selegie Rd  
Singapore - 180009

VISIT PASS

## Immigration Regulations

Name

RADHAKRISHNAN VENKADA PRABHU




Date of Birth	Sex	Nationality
02-06-1988	M	INDIAN
FIN	Date of Issue	Date of Expiry
G5421029P	19-12-2016	19-12-2018

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED  
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



**REPUBLIC OF SINGAPORE DRIVING LICENCE**




Licence Number: **G 5421029P**

Name: **RADHAKRISHNAN VENKADA PRABHU**

Birth Date: **02 Jun 1988**

Issue Date: **26 Feb 2014**

Valid Till **25 Feb 2019**



002278966A

Hlp: 91311427


Venkataprabhu.salai@gmail.com

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

		EFFECTIVE DATE
Class 2B	Motorcycles =< 200 cc	26 Feb 2014
Class 3	Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg	26 Feb 2014

NP 428A

Licence No: G5421029P



# Certificate of Insurance Pg. 1



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048673  
Tel: 6461 6555 | Fax: 6221 3502 | Website: www.sompo.com.sg  
Co. Reg No.: 196905490E | GST Reg No.: M200903196

200104955R

## Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTPCVE001404  
1. Registration No. : GBG1210T  
2. Insured Name : CIS-TRONICS PTE LTD  
3. Commencement Date : 31 MAY 2018 00:00  
4. Expiry Date : 30 MAY 2019 23:59  
5. Coverage : Market value at time of loss - Comprehensive  
6. Excess : \$500 - Section I

6253 8852

Cistronics.adm@gmail.com

### 7. Persons or Classes of Persons entitled to drive\*

b) Any person who is driving on the Insured's order or with their permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.  
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

### 8. Limitations as to use\*

- 1) Use in connection with the Insured's business.
- 2) Use for the carriage of passengers (other than for hire or reward) in connection with the policyholder's business
- 3) Use for social, domestic or pleasure purposes.

The Policy does not cover

- 1) Use for hire or reward or racing, pacemaking, reliability trial or speed-testing.
- 2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

### 9. ExcelDrive Workshops & Accident Reporting

It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.

It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, otherwise claim is not payable.

In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6461 6555

Visit [www.sompo.com.sg](http://www.sompo.com.sg) for list of ExcelDrive Workshops and Accident Reporting Centers.

We HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Sompo Insurance Singapore Pte. Ltd.

Stella

Date/Time of Issue : 18 APRIL 2018 09:02

*\*Limitation rendered inoperative by section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189 and section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.*

### IMPORTANT NOTICE

1. Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicles without a valid policy of insurance under the Act.
2. Insureds are further warned that on the sale of a motor vehicle or if for any reason the Insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the Insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189)
3. The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
4. Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.
5. Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy

Intermediary Code & Name : 11E07804 & ENSURE PTE. LTD. CI Code: 20D \_\_JD5ZZ44BJ8TVZA

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018		15 Oct 2018 10:26 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

ETHOZ GROUP LTD, Co. Reg. No.: 198104531H

Main Claimant:

CIS-TRONICS PTE LTD, Co. Reg. No.: 200104955R

Vehicle Reg. No.:

GBG1210T

Claim Type:

TP / CMTD1804124

Vehicle Reg. No. (Insured):

GBB7164E

Repairer:

Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/10/2018]

Driver/Custodian (Insured):

NORSHAFIEE BIN SAPON (), NRIC: S92135961, Tel: +6591111111

Date of Loss:

20/09/2018 18:00 - :59  
[15 Months and 20 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

D18MTHCVE000154 (Third Party Only)

Policy No. (Claimant):

Excess:

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.



































**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents



























**\*GBG1210T (CMTD1804124)**  
**[GBB7164E]**  
**TP**  
**CIS-TRONICS PTE LTD**  
**Sep 20 2018 6:00PM**  
**[ETHOZ GROUP LTD]**  
**Ama Autocare Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	15/10/18 10:27	<b>Accident Statement</b> From: SC - Reg. No: GBB7164E, Claimant: ETHOZ GROUP LTD	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/10/18 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
84	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	18/10/18 10:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	12/10/18 17:22	LETTER - CHIA S ARUL	 Load PDF	
2	15/10/18 10:25	Third Party E-filed GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18018638/R1CD3E2

Date: 02/11/2018

### REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE000154
Claimant Vehicle No :	GBG1210T	Insured Vehicle No :	GBB7164E
Date of Loss:	20/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1804124

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBG1210T</b>		
Make & Model:	NISSAN NV200, 1.5 (A)	Engine No:	K9KC400D056547
Reg. Date:	31/05/2017 (Man. Year: 2016)	Chassis No:	VSKYBAM20Z0141817
Colour:	Grey	Odometer:	39685 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	15/10/2018	
Date Inspected:	15/10/2018	Inspected At: Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36 Singapore 608580
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,000.00 - \$14,000.00

## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Nov 2018)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG1210T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >