

ASS. REC. BY:

REF:

CS/MSG18018640/R/ld302

Special Instructions:

Survivor
Meyner

Rasul

ASSIGNMENT (Office)

From (Person):

Ong chin kiat

of

MSLG

Date/Time:

12/10/18 3:39pm

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 69255

Insured:

at Workshop m/s

Volkswagen

Tel:

63057176 / 63057133

of

247 Alexandra Road

Policy No:

A29094477 AVW

Claim No:

5718 44

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

(Client's Record)

D.O.A.

30/09/2018

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:35am @ 15/10/18

Person Contacted:

Edmund

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 69255-X
16/10/18	@ 14:12pm revised IA to Ong chin kiat via meynier.
16/10/18	@ 14:14pm mandate requested authorise repair to Ong chin kiat via meynier.
19/10/18	@ 11:34 a.m. mandate approved by Eng Huey Ni via meynier.
19/10/18	@ 15:07 p.m. revert authorised repair to Edmund (owner) via email

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMD 69255
 at Workshop m/s Volkswagen
 of 247, mcradale rd
 Insured: MSI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 1000
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

2 pm on
 warranty
 forward 63057133

N/S	O/S

Bal. or Market Value: 120K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD 69255 Yr Regn: 2018 / AUC
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Beetle Cab 1.2 cc 1197Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 1089 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW22218234512700Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 235/45ZR18
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/09/18 D.O.I. 15/10/18Survey held at Volkswagen

Des. of Damages: Frit / Rear / O/S / N/S / U/C / Roof top or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/11/18 Confirmed 1/P \$ 3,596.53 @ 3 days with Rear 1.
 (B 7,091.34 Red - 66%)

RECEIVED 21 NOV 2018

Date/Time, File Pass to?

21/11/18

1) Type

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Survey Fee: 200

Transportation: _____

S + RS _____

Photos

Others

TOTAL

10

210

Report Format :

Lump Sum / I.B.I. (\$) 3,596.53 p/p

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2018		12 Oct 2018 15:39 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ONG CHUI YUI, ANGELA GENEVIEVE, ID: S7201245C, Tel: +6581823363, Email: THAI.ANGELA@GMAIL.COM		[Created by insurer]
Vehicle Reg. No.:	SMD6925S	Date of Loss:	30/09/2018 12:00 - :59 [1 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 571844	Policy/Cover Note No.:	A29094477AVW (Comprehensive) Coverage: 30/08/2018 - 29/08/2019
		Excess:	S\$1,000.00
Repairer:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/10/2018]		
Driver/Custodian:	ONG CHUI YUI, ANGELA GENEVIEVE (46 / Female), NRIC: S7201245C, Tel: +6581823363		
Adj Asg. Remarks:	Survey appt 15/10/18(Mon), 2pm. Owner waiting. Survey & revert. Please contact us ASAP if you cannot attend this assignment. to revert, thank you		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1245C
Vehicle Details	
Vehicle No.:	SMD69255
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	BEETLE CABRIOLET 1.2 DSG
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CYV618781
Chassis No.:	WVWZZZ16ZJM512700
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$24,308.00
Original Registration Date:	30 Aug 2018
First Registration Date:	30 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$26,032.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2028
PARF Rebate Amount:	\$19,524.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,997.00
COE Rebate Amount:	\$31,575.00
Total Rebate Amount:	\$51,099.00

The information contained herein is correct as at 16 Oct 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 21 November 2018 10:24 AM
To: 'Cheong, Pearlyn (VWG Singapore)'
Cc: 'Kong, Charmaine (VWG Singapore)'; 'Wong, Meiy (VWG Singapore)'; 'Foo, John (VWG Singapore)'; Rasul (LKKAuto); SUR; Admin A; Admin-D (LKKAuto)
Subject: RE: SMD6925S - FINALISE

Dear Pearlyn,

Confirmed final fig \$ 3,596.53 @ 3 days of repairs before excess \$1,000/- & GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]
Sent: Wednesday, 14 November 2018 3:12 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR (sur@lkkauto.com) <sur@lkkauto.com>; Admin-A (LKK Auto) (admin-a@lkkauto.com) (admin-a@lkkauto.com) <admin-a@lkkauto.com>; Admin-D (LKK Auto) (admin-d@lkkauto.com) <admin-d@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>
Subject: SMD6925S - FINALISE

Dear Rasul,

Please confirmed

COR \$ 2596.53 after less excess \$1000 before GST

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
-Main line: +65 6305 7299
Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 19 October 2018 3:07 PM
To: 'Goh, Edmund (VWG Singapore)'
Cc: 'Cheong, Pearlyn (VWG Singapore)'; 'Kong, Charmaine (VWG Singapore)'; 'Wong, Meiy (VWG Singapore)'; SUR
Subject: SMD 6925S OD (MSIG)

Dear Edmund,

As instructed by our client, please proceed to repair the insured vehicle **SMD 6925S** (Excess \$ 1,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SMD6925S (571844)**

OD

Sep 30 2018 12:00PM

[ONG CHUI YUI, ANGELA GENEVIEVE]

Volkswagen Centre Singapore

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 20/11/2018 16:39 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$3596.53) - SMD6925S - Claim Handler: Vimmala D/O Raja Singam

Approved:3596.53:Approved mandate \$3668.25(before excess \$1000). Check items of \$5069.17 to be verified

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SMD6925S (571844)**

OD

Sep 30 2018 12:00PM

[ONG CHUI YUI, ANGELA GENEVIEVE]

Volkswagen Centre Singapore

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 08/11/2018 08:48 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$3668.25) - SMD6925S - Claim Handler: Vimmala D/O Raja Singam

Approved:3668.25:Approved mandate \$3668.25(before excess \$1000). Check items of \$5069.17 to be verified

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SMD69255 (571844)**

OD

Sep 30 2018 12:00PM

[ONG CHUI YUI, ANGELA GENEVIEVE]

Volkswagen Centre Singapore

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/10/2018 11:34 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2986.34) - SMD69255 - Claim Handler: Vimmala D/O Raja Singam

Approved:2986.34;Approved mandate \$2986.34 (before excess \$1000). Check items of \$5069.17 to be verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 20 Nov 2018

Preliminary Advice

Vehicle No	: SMD6925S	Accident Date	: 30/09/2018
Make	: VOLKSWAGEN BEETLE CABRIOLET	Policy No.	: A29094477AVW
Assignment Date	: 12/10/2018	Excess	: S\$1,000.00
Date of Inspection	: 15/10/2018	Est. Duration of Repair	: 3 days
Inspection At	: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,687.87 (inclusive supplementary)
Revised Amount	:S\$	3,596.53 (inclusive supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,596.53

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	51,099.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,901.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 07 Nov 2018

Preliminary Advice

Vehicle No	: SMD6925S	Accident Date	: 30/09/2018
Make	: VOLKSWAGEN BEETLE CABRIOLET	Policy No.	: A29094477AVW
Assignment Date	: 12/10/2018	Excess	: S\$1,000.00
Date of Inspection	: 15/10/2018	Est. Duration of Repair	: 3 days
Inspection At	: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,687.42 (inclusive supplementary)
Revised Amount	:S\$	3,668.25 (inclusive supplementary)
Check Items (Estimated)	:S\$	5,069.17
Total	:S\$	8,737.42
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	51,099.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,901.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Other Comments : Supplementary amount is \$ 681.91.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 16 Oct 2018

Preliminary Advice

Vehicle No	: SMD6925S	Accident Date	: 30/09/2018
Make	: VOLKSWAGEN BEETLE CABRIOLET	Policy No.	: A29094477AVW
Assignment Date	: 12/10/2018	Excess	: S\$1,000.00
Date of Inspection	: 15/10/2018	Est. Duration of Repair	: 3 days
Inspection At	: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,005.51
Revised Amount	:S\$	2,986.34
Check Items (Estimated)	:S\$	5,069.17
Total	:S\$	8,055.51

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	51,099.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,901.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

MSG (Wingme)
OD
anf

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2018 16:34
Date Of Accident	30/09/2018 12:50
Exact Location Of Accident	LEFT TURN FRM CCK NORTH 5 TO CCK DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD6925S
Insured/Policyholder	
Name Of Registered Owner	ONG CHUI YUI, ANGELA GENEVIEVE (WANG CUIYI,ANGELA
NRIC No	S7201245C
Email Address	THAI.ANGELA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81823363
Alternative Phone No	OFFICE-81823363

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	BEETLE CABRIOLET GP 1.2(A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29094477 AVW
Cover Note Number	

Driver

Name of Driver	ONG CHUI YUI, ANGELA GENEVIEVE (WANG CUIYI,ANGELA
NRIC No	S7201245C
Date Of Birth	18/01/1972
Occupation	INDOOR
Date Of Driving Pass	01/08/1990
Driving Experience	28 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-81823363
Fax Number	
Contact Number	OFFICE-81823363
Email Address	THAI.ANGELA@GMAIL.COM

Address	52 CHOA CHU KANG NORTH 6 #05-13
Postcode	689575
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : THAI LOW JIN YANG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MORE DETAILS PLEASE REFET TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT1337L
Vehicle Make/Model/Colour	
Details Of Properties	MAZDA
Vehicle Category	PRIVATE CAR
Name of Driver	LI MALIE
NRIC/Passport Number	S2694848G
Contact Number	90120792
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 1/10/18
4:25pm


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 30 sept 2018
Time: Approximately 12:50 pm
Place: Left turn from choa chu kang North 5 to Choa Chu Kang Drive
I was going to turn left to choa chu kang Drive. I saw the Mazda in front of me move forward at the left turn. I also moved forward and looked right to check my blind spot and then I hit the Mazda.
Third party Name: Li Malie Car/Vehicle: Mazda Licence Plate: SKT 1337 L Telephone: 9012 0792 I/c No: S 2694848 G

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 1/10/18
 4:25 pm.

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

VW DRIVEEASY

THE SCHEDULE

Policy Number	Period of Insurance	Place of Issue
A 29094477 AVW	30/08/2018 to 29/08/2019	SINGAPORE
Name and Address of Insured		Date of Issue
Ong Chui Yui Angela Genevieve 52 Choa Chu Kang North 6 #05-13 Yew Mei Green Singapore 689575		04/09/2018
		Account Number
		156346
Premium	GST	Total Due
SGD1,708.38	SGD119.59	SGD1,827.97

RISK NUMBER 1

VW DRIVEEASY

OCCUPATION

Teacher

SCOPE OF COVER Comprehensive

INTEREST INSURED

REGISTRATION NO.	SMD6925S	SUM INSURED	MARKET VALUE
MAKE/MODEL	Volkswagen Beetle Cabriolet1.2	INCL. COE/PARF	YES
ENGINE NUMBER		OFF-PEAK CAR	NO
CHASSIS NUMBER	WVWZZZ16ZJM512700	NO CLAIM DISCOUNT	NIL
YEAR OF MFG	2018	NCD PROTECTOR	NOT COVERED
CAPACITY	1197 C.C.	EXCESS	SGD1,000
SEATING CAPACITY	5 (INCL. DRIVER)	ANNUAL PREMIUM	SGD1,708.38
WINDSCREEN	UNLIMITED		

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit, rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Ong Chui Yui Angela Genevieve

Any other person provided he is driving on the Insured's order or with the Insured's permission.

LIMITATION AS TO USE

Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo





Accident Photo





Accident Photo





Accident Photo





Identification Card




email : thai.angela@gmail.com

mobile : 8192 3363



Identification Card



Accident Photo



PDI TUAS



PDI TUAS

ONG CHUI YUI, ANGELA GENEVIEVE @ 8182 3363
 (WANG CUIYI, ANGELA GENEVIEVE)
 52 CHOA CHU KANG NORTH
 #05-13
 Singapore, 689575
 Singapore

SUV
 APPT. 10/10, 247, 1600

Phone No.
 Fax No.
 E-Mail

VAT Registration No. M20098505-2
 Tax No. 199101494Z

Service Quote

Customer No. CV041785
 Quote No. SER/QUO/1801634
 QuoteDate 01/10/18
 Salesperson Ian Yeo
 Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Beetle Cabriolet GP 1.2(A)	15	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SMD6925S	WVWZZZ16ZJM512700	30/08/18	Ian Yeo
Engine Code	Labor Type	Engine No.	Model Code
	M5	CYV 618781	5C83EZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		475 1,425.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		500 1,500.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		81 80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		360.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		200.00
	Sum Labor				3,565.00
P 5C2941031D	HEADLIGHT LH	1	Pieces		3,632.91
P 5C5807109D	BUMPER REINFORCEMENT	1	Pieces		538.16
P 5C5807217BHGRU	FRT BUMPER COVER	1	Pieces		1,371.34
P 5C5807248F	FOAM INSER LH Use Predecessor 5C5807248A-	1	Pieces		160.26
P 5C5807248G	FOAM INSER RH Use Predecessor 5C5807248B-	1	Pieces		160.26
P 5C5807651	MEMBER	1	Pieces		194.96
P 5C5807665B	FOAM INSER LH	1	Pieces		33.85
P 5C5853655A 9B9	COVER	1	Pieces		105.53
P 5C5854661K ZLL	GRILLE LH	1	Pieces		243.24
P 5C5854662J ZLL	GRILLE RH	1	Pieces		
Sum carried forward					10,005.51

Payments to: - BBN - Acc.-No.:

PDI TUAS

Phone No.
Fax No.
E-Mail

PDI TUAS

ONG CHUI YUI, ANGELA GENEVIEVE
(WANG CUIYI, ANGELA GENEVIEVE)
52 CHOA CHU KANG NORTH
#05-13
Singapore, 689575
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV041785
Quote No. SER/QUO/1801634
QuoteDate 01/10/18
Salesperson Ian Yeo
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Beetle Cabriolet GP 1.2(A)	15	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SMD6925S	WVWZZZ16ZJM512700	30/08/18	Ian Yeo
Engine Code	Labor Type	Engine No.	Model Code
	M5	CYV 618781	5C83EZ

Continued 10,005.51

Sum Item 6,440.51

Sum Labor 3,565.00
Sum Item 6,440.51

Total SGD 10,005.51
7% GST 700.39
Total SGD Incl. GST 10,705.90

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve generator spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary work must be notified and signed
- Is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
Signature:
Date:

Payments to: - BBN: - Acc.-No.:

Rasul
Hp 90010068

3 days

15/10/18 @ 1400

EXCESS: 1000

REVERT

Resurvey by paint

10687-87

19/10/18

PDI TUAS

PDI TUAS

ONG CHUI YUI, ANGELA GENEVIEVE
(WANG CUIYI, ANGELA GENEVIEVE)
52 CHOA CHU KANG NORTH
#05-13
Singapore, 689575
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV041785
Quote No. SER/QUO/1801851
QuoteDate 11/07/18
Salesperson Ian Yeo
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Beetle Cabriolet GP 1.2(A)	15	
License No.	VIN	Initial Registration	Sales Advisor
SMD6925S	WVWZZZ16ZJM512700	08/30/18	Ian Yeo
Engine Code	Labor Type	Engine No.	Model Code
	M5	CYV 618781	5C83EZ

SUPPLEMENTARY

No.	Description	Qty.	UoM	Unit Price	Amount
5C5121283A	AIR GUIDE LH <i>CRA</i>	1	Pieces	32.27	32.27 <i>A</i>
5C5853671T ZLL	CENTRE LOWER GRILLE <i>CRA</i>	1	Pieces	405.31	405.31 <i>A</i>
5C5854661K ZLL	LHS FOG GRILLE <i>CRA</i>	1	Pieces	243.24	243.24 <i>A</i>
5M0820538A	SENS.HOLDE <i>MIS</i>	1	Pieces	1.09	1.09 <i>A</i>
	Sum Item				681.91
					<i>682.36</i>
	Sum Item				681.91
	Total SGD				681.91
	7% GST			681.91	47.73
	Total SGD Incl. GST				729.64

Payment Terms No Credit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO: 1BIP2679

CUSTOMER NO.: CV041785

CUSTOMER NAME: ONG CHUI YUI, ANGELA GENEVIEVE

TELEPHONE NO.:

ADDRESS: 52 CHOA CHU KANG NORTH #05-13

Singapore

VEH No.: SMD6925S

Order Date: 15/10/18

Reg Date: 30/08/18

KM: 15

VIN NO.: WVVZZZ16ZJM512700

ENGINE NO:

SA: Kong Charmaine

MODEL: Beetle Cabriolet GP 1.2(A)

MODEL NO.: SC83EZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	360		360 ✓
2	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	200		200 ✓
3	B&P INSURANCE EXCESS INSURANCE EXCESS / DEDUCTIBLE	1	TU	-1,000		-1,000
4	B&P ALEX LABOUR LABOUR	1	UNIT	475		475 ✓
5	B&P ALEX PAINT SPRAY PAINT	1	UNIT	500		500 ✓
6	B&P NUMBER PLATE B&P NUMBER PLATE -NETT	1	ST	80		80 ✓
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Rem						
9	SC5807217BHGRU FRT BUMPER COVER	1	PCS	1,371.34	28	987.36 ✓
10	SC5854861K ZLL LHS FOG GRILLE	1	PCS	243.24	28	175.13 ✓
11	SC5853671T ZLL CENTRE LOWER GRILLE	1	PCS	405.31	28	291.82 ✓
12	SC5807109D REINFORCEMENT	1	PCS	538.18	28	387.48 ✓
13	SC5807348F FOAM LOWER LH	1	PCS	160.26	28	115.38 ✓
14	SC5121283A AIR GUIDE LH	1	PCS	32.72	28	23.56 ✓
15	5M0620536A SENS.HOLDE	1	PCS	1.09	28	0.78 ✓

Remarks : COMING IN 5 NOV 2018

Service Order Confirmation

SERVICE ORDER NO: 18IP2679

CUSTOMER NO.: CV041785

CUSTOMER NAME: ONG CHUI YUI, ANGELA GENEVIEVE

TELEPHONE NO.:

ADDRESS: 52 CHOA CHU KANG NORTH #05-13
Singapore

VEH No.: SMD6925S

Order Date: 15/10/18

Reg Date: 30/08/18

KM: 15

VIN NO.: WVVWZZZ16ZJM512700

ENGINE NO:

SA: Kong Charmaine

MODEL: Beetle Cabriolet GP 1.2(A)

MODEL NO.: 5C83EZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	2,596.53
GST AMOUNT	181.76
TOTAL AMOUNT	2,778.28

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2018		12 Oct 2018 15:39 Edit Adj Rpt	S\$3,596.52 Edit Estimates	S\$3,596.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ONG CHUI YUI, ANGELA GENEVIEVE, ID: S7201245C, Tel: +6581823363, Email: THAI.ANGELA@GMAIL.COM								
Vehicle Reg. No.:	SMD6925S	Date of Loss:	30/09/2018 12:00 - :59 [1 Months From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 571844	Policy/Cover Note No.:	A29094477AVW (Comprehensive) Coverage: 30/08/2018 - 29/08/2019						
		Excess:	S\$1,000.00						
Repairer:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/11/2018]								
Driver/Custodian:	ONG CHUI YUI, ANGELA GENEVIEVE (46 / Female), NRIC: S7201245C, Tel: +6581823363								
Adj Asg. Remarks:	Survey appt 15/10/18(Mon), 2pm. Owner waiting. Survey & revert. Please contact us ASAP if you cannot attend this assignment. to revert, thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (20/11/2018): Alert - Adj Mandate Approved (S\$3596.53) - SMD6925S - Claim Handler: Vimmala D/O... - MSIG_SG (08/11/2018): Alert - Adj Mandate Approved (S\$3668.25) - SMD6925S - Claim Handler: Vimmala D/O... - MSIG_SG (19/10/2018): Alert - Adj Mandate Approved (S\$2986.34) - SMD6925S - Claim Handler: Vimmala D/O...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD6925S (571844)
 OD
 Sep 30 2018 12:00PM
 [ONG CHUI YUI, ANGELA GENEVIEVE]
 Volkswagen Centre Singapore

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	01/10/18 16:48	Volkswagen Centre Singapore (HQ) Accident Statement	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/18 14:12	Adjuster Immediate Advice	Load HTM	
2	07/11/18 14:36	Adjuster Immediate Advice	Load HTM	
3	20/11/18 11:50	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder		Thumbnail	Print
1	16/10/18 13:37	LKK Auto Consultants Pte Ltd (HQ) Odometer Reading	Load JPG	☒
2	16/10/18 13:37	Chassis Number	Load JPG	☒
3	16/10/18 13:37	General View	Load JPG	☒
4	16/10/18 13:37	General View	Load JPG	☒
5	16/10/18 13:37	General View	Load JPG	☒
6	16/10/18 13:37	General View	Load JPG	☒
7	16/10/18 13:37	General View	Load JPG	☒
8	16/10/18 13:37	General View	Load JPG	☒
9	16/10/18 13:37	General View	Load JPG	☒
10	16/10/18 13:37	General View	Load JPG	☒
11	16/10/18 13:37	General View	Load JPG	☒
12	16/10/18 13:37	General View	Load JPG	☒
13	16/10/18 13:37	General View	Load JPG	☒
14	16/10/18 13:37	General View	Load JPG	☒
15	16/10/18 13:37	General View	Load JPG	☒
16	16/10/18 13:37	General View	Load JPG	☒
17	16/10/18 13:37	General View	Load JPG	☒
18	16/10/18 13:37	General View	Load JPG	☒
19	16/10/18 13:37	General View	Load JPG	☒
20	16/10/18 13:37	General View	Load JPG	☒
21	16/10/18 13:37	General View	Load JPG	☒
22	16/10/18 13:37	General View	Load JPG	☒
23	16/10/18 13:37	General View	Load JPG	☒
24	16/10/18 13:37	General View	Load JPG	☒
25	16/10/18 13:37	General View	Load JPG	☒
26	16/10/18 13:37	General View	Load JPG	☒
27	16/10/18 13:37	General View	Load JPG	☒
28	16/10/18 13:37	General View	Load JPG	☒
29	16/10/18 13:37	General View	Load JPG	☒
30	16/10/18 13:37	General View	Load JPG	☒
31	16/10/18 13:37	General View	Load JPG	☒
32	07/11/18 14:37	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
33	07/11/18 14:37	Reinspection Photo	 Load JPG	☒
34	07/11/18 14:37	Reinspection Photo	 Load JPG	☒
35	07/11/18 14:37	Reinspection Photo	 Load JPG	☒
36	07/11/18 14:37	Reinspection Photo	 Load JPG	☒
37	07/11/18 14:37	Reinspection Photo	 Load JPG	☒
38	07/11/18 14:37	Reinspection Photo	 Load JPG	☒
39	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
40	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
41	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
42	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
43	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
44	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
45	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
46	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
47	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
48	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
49	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
50	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
51	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
52	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
53	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
54	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
55	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
56	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
57	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
58	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
59	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
60	07/11/18 14:38	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/10/18 10:26	COE PARF - SMD692SS	 Load PDF	
2	02/10/18 10:26	email from VW to arrange OD survey	 Load PDF	
3	02/10/18 10:26	Estimate	 Load PDF	
4	02/10/18 10:26	TP SKT1337L GIA Report	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	05/10/18 16:58	Email - Survey Appt 10/10/18	 Load PDF	
2	09/10/18 14:59	Email - Survey Appt 15/10/18	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/18 14:21	ESTIMATE.pdf	 Load PDF	
2	07/11/18 14:28	SUPPLEMENTARY.pdf	 Load PDF	
3	20/11/18 11:37	ESTIMATE MARKED & SUPPLEMENTARY.pdf	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	01/10/18 16:48	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	01/10/18 16:40	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
2	01/10/18 16:40	Accident Photo	 Load JPG	☒
3	01/10/18 16:40	Accident Photo	 Load JPG	☒
4	01/10/18 16:40	Accident Photo	 Load JPG	☒
5	01/10/18 16:40	Accident Photo	 Load JPG	☒
6	01/10/18 16:40	Accident Photo	 Load JPG	☒
7	01/10/18 16:40	Accident Photo	 Load JPG	☒
8	01/10/18 16:40	Accident Photo	 Load JPG	☒
9	01/10/18 16:41	Identification Card	 Load JPG	☒
10	01/10/18 16:41	Identification Card	 Load JPG	☒
11	01/10/18 16:47	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	01/10/18 16:40	Sketch Plan	 Load TIFF	
2	01/10/18 16:40	Sketch Plan #2	 Load TIFF	
3	01/10/18 16:40	Sketch Plan #3	 Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18018640/R1SD3E2

Date: 26/11/2018

REFERENCE

Insured/Claimant: ONG CHUI YUI, ANGELA GENEVIEVE
Date of Loss: 30/09/2018

Policy No: A29094477AVW

Nature of Claim: OD

Claim No: 571844

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD6925S**
Make & Model: VOLKSWAGEN BEETLE CABRIOLET, 1.2 TSI DSG (A) Engine No: CYV618781
Reg. Date: 30/08/2018 (Man. Year: 2018) Chassis No: WWZZZ16ZJM512700
Colour: Blue Odometer: 1089 km
Engine Capacity: 1197 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45ZR18 Rear Tyre Size: 235/45ZR18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,202.87	2,061.52	5,141.35	71.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,485.00	1,535.00	1,950.00	55.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,687.87	3,596.52	7,091.35	66.35
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	9,687.87	2,596.52	7,091.35	73.20
+ GST 7.00/7.00% (S\$)	678.15	181.76	496.39	73.20
Nett Amount (S\$)	10,366.02	2,778.28	7,587.74	73.20

INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 15/10/2018 Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$3,596.53

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Nov 2018)	
Parts:	N/A	VOLKSWAGEN BEETLE CABRIOLET 1.2 TSI DSG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD6925S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT LH	Serviceable	3,632.91 FS	*- FS
2	1		*BUMPER REINFORCEMENT	Bent	538.16 FS	*387.48 FS
3	1		*FRT BUMPER COVER	Deformed	1,371.34 FS	*987.36 FS
4	1		*FOAM INSR LH	Serviceable	160.26 FS	*- FS
5	1		*FOAM INSR RH	Deformed	160.26 FS	*115.39 FS
6	1		*MEMBER	Serviceable	194.96 FS	*- FS
7	1		*FOAM INSR LH	Serviceable	33.85 FS	*- FS
8	1		*COVER	Serviceable	105.53 FS	*- FS
9	1		*GRILLE LH	Serviceable	243.24 FS	*- FS
10	1		*GRILLE RH (NPA)	Serviceable	0.00 FS	*- FS
11	1		*B&P NUMBER PLATE	Bent	80.00 FS	*80.00 FS
12	1		*AIR GUIDE LH	Cracked	32.72 FS	*23.56 FS
13	1		*CENTRE LOWER GRILLE	Cracked	405.31 FS	*291.82 FS
14	1		*LHS FOG GRILLE	Cracked	243.24 FS	*175.13 FS
15	1		*SENS,HOLDE	Missing	1.09 FS	*0.78 FS
Total Parts (S\$)					7,202.87	2,061.52

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	1,425.00	475.00
2	SPRAY PAINT	New	1,500.00	500.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	360.00	360.00
4	CHECK WIRE HARNESS,ECU,S	New	200.00	200.00
Gross Labour Cost (S\$)			3,485.00	1,535.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >