

ASS. REC. BY:

REF:

CS3/MSG18018648/RICD304

Special Instruction:

Survivor:
Mennin

Rasyi

ASSIGNMENT (Office)

From (Person):

Irene fan

of

MSG

Date/Time:

12/10/18 @ 3:13pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 36298

Insured:

SKU 72724

at Workshop m/s

One zone Autocare

Tel:

9230 8294

of

7 Suon lee street #01-05

Policy No:

A80399042AVW

Claim No:

572835

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/10/2018

CA / REV / REP. / REV 24 HRS

1up?

H.O.D. Endorsement:

Date/Time:

9:46pm @ 15/10/18

Person Contacted:

ERIC

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction	(X) Estimate
	SMD 36298 - NA/1AIG/18018472/24	DOA: 10/10/18
	SKU 72724 - CS3/1AIG/17011718/R/K9 392	DOA: 10/6/2017
	Dismantle: 16/10/2018	
	After repair: 18/10/2018	


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMD 8629S
 at Workshop m/s ONE ZONE AUTO CARE
 of 7, Sunnyside ST #61-05
 Insured: MSK
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

92308294-ERIC

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 12K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMD 3629S Yr Regn: 2009 / July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA VIOS E AUTO c.c. 1497
 Colour: GRY A/C: Insured / Std / NI / NA
 Sp. Reading: 143898 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053449305123419
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 10/10/18 D.O.I. 15/10/18
 Survey held at ONE ZONE
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT & REAR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>PRS</u>
	<u>Range 7000/- - 8000/-</u>
	<u>Repair days 8</u>
	<u>19/10/2018</u>
	<u>19/10/18</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 8Resurvey No. of Trip: 2

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : PRS

Lump Sum / I.B.I. (\$) _____

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Oct 2018		12 Oct 2018 15:13 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA PING GEE, ID: S1805114A, Tel: +6596234862, Email: PINGGEE.CHUA@YAHOO.COM.SG		
Main Claimant:	MAJESTY CAR LEASING, Co. Reg. No.: 53387122X		
Vehicle Reg. No.:	SMD3629S	Date of Loss:	10/10/2018 18:00 - :59 [110 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 572835	Policy/Cover Note No.:	A80399042AVW (Comprehensive) Coverage: 29/05/2018 - 28/05/2019
Vehicle Reg. No. (Insured):	SKU7272U	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	One Zone Autocare (HQ) 7 SOON LEE STREET, #01-05 I SPACE BUILDING, 627608 Jurong Island - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/10/2018]		
Driver/Custodian (Insured):	CHUA PING GEE (51 / Female), NRIC: S1805114A, Tel: +6596234862		
Adj Asg. Remarks:	on WP. SJE - DISAGREED / LIABILITY 100% Please appoint LKK AUTO CONSULTANTS to conduct the survey. Kindly contact MR ERIC @ 9230 8294 directly .		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7122X
Vehicle Details	
Vehicle No.:	SMD3629S
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1NZX946960
Chassis No.:	MR053HY9305123919
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	24 Jul 2009
First Registration Date:	24 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$12,717.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2019
PARF Rebate Amount:	\$6,358.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$1,100.00
Total Rebate Amount:	\$7,458.00

The information contained herein is correct as at 16 Oct 2018

OK

12,000
 7,458

 4,542
 //

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	11/10/2018 11:35
Date Of Accident	10/10/2018 18:35
Exact Location Of Accident	WOODLANDS AVE 12 BFR RIGHT TURN(WOODLANDS AVE 5)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMD3629S
Insured/Policyholder	
Name Of Registered Owner	MAJESTY CAR LEASING
Co Reg No	53387122X
Email Address	BQONG1@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92267689
Alternative Phone No	OFFICE-91706915
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5103792048
Cover Note Number	
Driver	
Name of Driver	FANG ZONGHONG, ANDREW
NRIC No	S8902758F
Date Of Birth	30/01/1989
Occupation	OUTDOOR
Date Of Driving Pass	12/06/2012
Driving Experience	6 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92267689
Fax Number	
Contact Number	OFFICE-91706915
Email Address	ANDREWFANG89@GMAIL.COM

Address	APT BLK 503 JELAPANG ROAD #11-382 SINGAPORE
Postcode	670503
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHING WEI JIN, SIMON GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU7272U
Vehicle Make/Model/Colour	VOLKSWAGEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA PING GEE
NRIC/Passport Number	S1805114A
Contact Number	96234862
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SMF201B

Vehicle Make/Model/Colour

HYUNDAI

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NORAINI BINTE OSMAN

NRIC/Passport Number

S7434043A

Contact Number

83238392

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

FANG ZONGHONG, ANDREW

Approximate Age

29

Injuries Sustain

REFER POLICE REPORT

Injured person in which vehicle?

SMD3629S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

APT BLK 503 JELAPANG ROAD
#11-382 SINGAPORE

Postcode

670503

DETAILS OF INJURED PERSON 2

Name

CHING WEI JIN SIMON

Approximate Age

Injuries Sustain

REFER POLICE REPORT

Injured person in which vehicle?

SMD3629S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Roadside Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instruction or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of all correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulatory provisions or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
If driver is not the policyholder
Date & Time: 13/10/18

Reporting Centre Person's Signature
Name
NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN

A: SMD 3629 S

$$B = SKY \approx 272.4$$

C = SMF 2013

WOODLANDS AVE 12

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

— REFER POLICE REPORT —

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date: 8/1/2011

Driver's Signature _____

Date & Time 11/10/18, 1140

Reporting Control E. Spence's Signature

NAME _____

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2018		12 Oct 2018 15:13 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case


















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHUA PING GEE , ID: S1805114A, Tel: +6596234862, Email: PINGGEE.CHUA@YAHOO.COM.SG								
Main Claimant:	MAJESTY CAR LEASING , Co. Reg. No.: 53387122X								
Vehicle Reg. No.:	SMD3629S	Date of Loss:	10/10/2018 18:00 - :59 [110 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 572835	Policy/Cover Note No.:	A80399042AVW (Comprehensive) Coverage: 29/05/2018 - 28/05/2019						
Vehicle Reg. No. (Insured):	SKU7272U	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	One Zone Autocare (HQ) 7 SOON LEE STREET, #01-05 I SPACE BUILDING, 627608 Jurong Island - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 13/10/2018]								
Driver/Custodian (Insured):	CHUA PING GEE (51 / Female), NRIC: S1805114A, Tel: +6596234862								
Adj Asg. Remarks:	on WP. SJE - DISAGREED / LIABILITY 100% Please appoint LKK AUTO CONSULTANTS to conduct the survey. Kindly contact MR ERIC @ 9230 8294 directly .								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									









Claim Documents

*SMD3629S (572835)
[SKU7272U]
TP
MAJESTY CAR LEASING
Oct 10 2018 6:00PM
[CHUA PING GEE]
One Zone Autocare

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
2	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
3	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
4	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
5	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
6	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
7	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
8	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
9	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
10	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
11	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
12	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
13	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
14	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
15	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
16	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
17	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
18	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
19	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
20	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
21	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
22	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
23	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
24	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
25	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
26	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
27	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
28	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
29	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
30	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
31	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
32	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
33	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
34	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
35	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
36	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
37	18/10/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/10/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
56	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	22/10/18 12:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
141	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
142	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
143	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
144	22/10/18 12:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/10/18 08:55	TPD SMD3629S GIA REPORT	 Load PDF	
2	12/10/18 08:55	OI SKU7272U GIA REPORT	 Load PDF	
3	12/10/18 09:04	TPD SMD3629S - PRI	 Load PDF	
4	12/10/18 10:17	Reject to TP Lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18018648/R1CD3E2

Date: 23/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80399042AVW

Claimant Vehicle No : SMD3629S

Insured Vehicle No : SKU7272U

Date of Loss: 10/10/2018

Nature of Claim: TP

Claim No: 572835

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD3629S

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX946960

Reg. Date: 24/07/2009 (Man. Year: 2009)

Chassis No: MR053HY9305123919

Colour: Grey

Odometer: 143898 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 15/10/2018 Inspected At:

One Zone Autocare (HQ)
7 SOON LEE STREET, #01-05 I SPACE
BUILDING
Singapore 627608

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Oct 2018)

Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD3629S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >