

ASS. REC. BY:

REF. es.

MSG18018652/K19d3/12

Special Instruction:

Survivor:  
Meimen

Rasu

ASSIGNMENT (Office)

From (Person): Monica chung

of

MSIG

Date/Time: 12/10/18 @ 3:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD1346R

Insured:

XD 4848P

at Workshop m/s

Ace Buroh

Tel:

96312797 / 9452 4798

of

2 Buroh Crescent #04-08

6268 0010 / 6250 9521

Policy No:

27557412TMV

Claim No:

562950

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28/06/2018

64548007 Judy. TOB

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:54am @ 15/11/18

Person Contacted:

Mr. Kee

Vehicle ☒ IN / OUT

| Date/Time         | Action/Instruction                                     |
|-------------------|--------------------------------------------------------|
|                   | (✓), Estimate                                          |
|                   | XD1346R - CS / SM018016846 / K1sb                      |
|                   | XD4848P - X                                            |
| 16/10/18 @ 4pm    | Informed Monica Chung, pending estimate from repairer. |
| 30/11/18 @ 2:42pm | Revised to Monica Chung via Meimen.                    |
|                   | Rasu Analised with Judy is \$6400, 9 days.             |
|                   | (Red \$6405.90, 50%)                                   |

Surveyor: Fane

REF:


## ASSIGNMENT

COPY: 2022/2024

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: XD 1346R  
 at Workshop m/s ACE BURSH  
 of 2, BURSH CRESCENT #04-08/09  
 Insured: MSH  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.  
TNB-96321002



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 9 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: XD 1346R Yr Regn: 2002 / July  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN GK B45 CL BHN B C.C. 13074Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 300850 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GK B4 CL B00099

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 295/80R22.5R: 21 (W)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 28/06/18 D.O.I. 15/10/18Survey held at ACE BURSH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S PR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ESTIMATE provided (New estimate will be given later)

RECEIVED 20 DEC 2018

[Signature]  
20/12/2018

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / L.B.I. (\$)

OVER TP640020010210

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 30 Nov 2018

**Preliminary Advice**

|                    |                                                                         |                         |              |
|--------------------|-------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : XD4848P                                                               | Accident Date           | : 28/06/2018 |
| TP Vehicle No      | : XD1346R                                                               | Assignment Date         | : 12/10/2018 |
| Make               | : NISSAN GKB45CLBHNH                                                    | Est. Duration of Repair | : 7.00       |
| Date of Inspection | : 15/10/2018                                                            |                         |              |
| Inspection At      | : ACE@BUROH (HQ)<br>2 BUROH CRESCENT #04-08, #04-09<br>SINGAPORE 627546 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 12,805.90 |
| Revised Amount              | :S\$ | 8,022.43  |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 8,022.43  |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 28 Jun 2018 |               | 12 Oct 2018<br>15:12<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |                          |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

|                             |                                                                                                                                                                                                                                                                           |                        |                                                                               |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------|
| Insured:                    | Pan Ocean Leasing Pte Ltd, Co. Reg. No.: 199303559W                                                                                                                                                                                                                       |                        |                                                                               |
| Main Claimant:              | CA TRANSPORTATION & WAREHOUSING PTE LTD, Co. Reg. No.: 199200740D                                                                                                                                                                                                         |                        |                                                                               |
| Vehicle Reg. No.:           | XD1346R                                                                                                                                                                                                                                                                   | Date of Loss:          | 28/06/2018 06:00 - :59<br>[132 Months and 16 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 562950                                                                                                                                                                                                                                                               | Policy/Cover Note No.: | 27557412TMV (Comprehensive)<br>Coverage: 15/08/2017 - 14/08/2018              |
| Vehicle Reg. No. (Insured): | XD4848P                                                                                                                                                                                                                                                                   | Policy No. (Claimant): | D17MTHCVE002012                                                               |
|                             |                                                                                                                                                                                                                                                                           | Excess:                |                                                                               |
| Repairer:                   | Ace@buroh (HQ) 2 Buroh Crescent #04-08, #04-09, 627546 Jurong East - Tel:                                                                                                                                                                                                 |                        |                                                                               |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pel Zhen - 6594 2552]                                                                                                                                                         |                        |                                                                               |
| Claimant's Insurer:         | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555                                                                                                                                                                                                                 |                        |                                                                               |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/10/2018]                                                                                                                                                                                        |                        |                                                                               |
| Driver/Custodian (Insured): | PANG KAI HONG (46 / Male), NRIC: S7131868J, Tel: +6596857690                                                                                                                                                                                                              |                        |                                                                               |
| Adj Asg. Remarks:           | on WP. LIABILITY UNCLEAR ASSIGNED KENNETH KONG FROM LKK AUTO CONSULTANTS Please contact Mr Kee at 9631 2797, 94524798 and 6268 0010 for the said arrangement on an urgent basis. XD 1346 R is now available at 2 Buroh Crescent #04-08, #04-09 ACE@BUROH Singapore 627546 |                        |                                                                               |

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 20 December 2018 11:54 AM  
**To:** 't n b motor'; Admin-D (LKKAUTO); SUR  
**Cc:** assignments  
**Subject:** RE: Finalize of Vehicle: XD1346R  
**Attachments:** XD1346 EST.pdf

Dear Judy,

WITHOUT PREJUDICE

According to our surveyor, he already finalised with you at repair cost Lump Sum \$6,400.00 and 9 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** t n b motor <tbmotor@hotmail.sg>  
**Sent:** Thursday, 20 December 2018 10:00 AM  
**To:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** Re: Finalize of Vehicle: XD1346R

Morning Shiau Chan,

Kindly let us have your revised copy please, thanks

Best Regards,  
Judy Ong

T & B Motor Repairs Services Pte Ltd  
160 Sin Ming Drive #08-03  
Sin Ming AutoCity  
Singapore 575722  
Tel: 6454 8007 / 6458 0296  
Fax: 6554 2640

---

**From:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Friday, November 30, 2018 2:31 PM  
**To:** t n b motor; Admin-D (LKKAUTO); SUR  
**Cc:** assignments  
**Subject:** RE: Finalize of Vehicle: XD1346R

## Shiau Chan (LKKAUTO)

---

**From:** t n b motor <tbmotor@hotmail.sg>  
**Sent:** Friday, 30 November 2018 5:21 PM  
**To:** Shiau Chan (LKKAUTO); Admin-D (LKKAUTO); SUR  
**Cc:** assignments  
**Subject:** Re: Finalize of Vehicle: XD1346R

Dear Shiau Chan,

My Boss Mr Tay request for <sup>9 days</sup> 12 days of repair, Pls advise

Best Regards,  
Judy Ong

T & B Motor Repairs Services Pte Ltd  
160 Sin Ming Drive #08-03  
Sin Ming AutoCity  
Singapore 575722  
Tel: 6454 8007 / 6458 0296  
Fax: 6554 2640

Confirmed with Judy repair cost of  
\$6,400 is confirmed, number of repair  
days add on to 9 days of repair

---

**From:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
**Sent:** Friday, November 30, 2018 2:31 PM  
**To:** t n b motor; Admin-D (LKKAUTO); SUR  
**Cc:** assignments  
**Subject:** RE: Finalize of Vehicle: XD1346R

Dear Judy,

WITHOUT PREJUDICE

Offer Lump Sum \$6,400.00 and 7 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** t n b motor <tbmotor@hotmail.sg>  
**Sent:** Thursday, 29 November 2018 2:24 PM  
**To:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>  
**Cc:** assignments <assignments@lkkauto.com>  
**Subject:** Re: Finalize of Vehicle: XD1346R

Dear Shiau Chan,

**Shiau Chan (LKKAuto)**

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Tuesday, 16 October 2018 4:00 PM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** VEHICLE XD 1346R (YOUR REF: 562950)

This mail is associated with :

**\*XD1346R (562950)**

**[XD4848P]**

TP

CA TRANSPORTATION & WAREHOUSING PTE LTD

Jun 28 2018 6:00AM

[Pan Ocean Leasing Pte Ltd]

Ace@buroh

Dear Monica,

Please be informed that we have inspected the vehicle XD 1346R on 15/10/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                              |                         |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                             |                         |
| Owner ID Type:                                                                                                                                               | Company                 |
| Owner ID:                                                                                                                                                    | 0740D                   |
| <b>Vehicle Details</b>                                                                                                                                       |                         |
| Vehicle No.:                                                                                                                                                 | XD1346R                 |
| Vehicle to be Exported:                                                                                                                                      | No                      |
| Intended Deregistration Date:                                                                                                                                | 30 Nov 2018             |
| Vehicle Make:                                                                                                                                                | NISSAN                  |
| Vehicle Model:                                                                                                                                               | GKB45CLBHNB             |
| Primary Colour:                                                                                                                                              | White                   |
| Manufacturing Year:                                                                                                                                          | 2007                    |
| Engine No.:                                                                                                                                                  | GE13333947B             |
| Chassis No.:                                                                                                                                                 | GKB4CLB00099            |
| Maximum Power Output:                                                                                                                                        | -                       |
| Open Market Value:                                                                                                                                           | \$67,156.00             |
| Original Registration Date:                                                                                                                                  | 13 Jul 2007             |
| First Registration Date:                                                                                                                                     | 13 Jul 2007             |
| Transfer Count:                                                                                                                                              | 0                       |
| Actual ARF Paid:                                                                                                                                             | \$0.00                  |
| <b>Intended PARF Rebate Details</b>                                                                                                                          |                         |
| PARF Eligibility:                                                                                                                                            | No                      |
| PARF Eligibility Expiry Date:                                                                                                                                | -                       |
| PARF Rebate Amount:                                                                                                                                          | \$0.00                  |
| <b>Intended COE Rebate Details</b>                                                                                                                           |                         |
| COE Expiry Date:                                                                                                                                             | 12 Jul 2022             |
| COE Category:                                                                                                                                                | C - Goods Vehicle & Bus |
| COE Period(Years):                                                                                                                                           | 5                       |
| PQP Paid:                                                                                                                                                    | \$17,035.00             |
| COE Rebate Amount:                                                                                                                                           | \$12,318.00             |
| <b>Total Rebate Amount:</b>                                                                                                                                  | <b>\$12,318.00</b>      |
| <b>Message</b>                                                                                                                                               |                         |
| Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle. |                         |

The information contained herein is correct as at 30 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                               |
|----------------------------|-------------------------------|
| Date Of Report             | 28/06/2018 12:32              |
| Date Of Accident           | 28/06/2018 06:45              |
| Exact Location Of Accident | PASIR PANJANG TERMINAL GATE 4 |
| Country/State of Loss      | SINGAPORE                     |

### DETAILS OF OWN VEHICLE

|                             |                                         |
|-----------------------------|-----------------------------------------|
| Vehicle Registration Number | XD1346R                                 |
| <b>Insured/Policyholder</b> |                                         |
| Name Of Registered Owner    | CA TRANSPORTATION & WAREHOUSING PTE LTD |
| Co Reg No                   | 199200740D                              |
| Email Address               | JUDY@CATPTN.COM                         |
| Mobile Phone No             |                                         |
| Alternative Phone No        | Office-66974581                         |

### Vehicle Particulars

|                                                                              |                        |
|------------------------------------------------------------------------------|------------------------|
| Manufacturer                                                                 | NISSAN                 |
| Model                                                                        | GKB45CLBHNB-13.1 D (A) |
| Exact Purpose for which vehicle was being used at time of accident           |                        |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                     |
| If No, Please state action to be taken                                       | THIRD PARTY            |
| Vehicle Category                                                             | COMMERCIAL VEHICLE     |

### Insurance Company

|                           |                                     |
|---------------------------|-------------------------------------|
| Name of Insurance Company | SOMPO INSURANCE SINGAPORE PTE. LTD. |
| Type Of Coverage          | THIRD PARTY                         |
| Fleet Policy              | YES                                 |
| Policy Number             | D17MTHCVE002012                     |
| Cover Note Number         |                                     |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | AGILAN A/L JAYABALAN  |
| Passport No/FIN      | G7496989K             |
| Date Of Birth        | 23/08/1981            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 13/08/2014            |
| Driving Experience   | 3 YEARS AND 10 MONTHS |

|                                                     |                      |
|-----------------------------------------------------|----------------------|
| Gender                                              | MALE                 |
| Mobile Number                                       | (LOCAL) +65-98906515 |
| Fax Number                                          |                      |
| Contact Number                                      |                      |
| E-Mail Address                                      | NOEMAIL              |
| Address                                             | NIL                  |
| Postcode                                            |                      |
| Was driver an employee of the Insured's Company     | YES                  |
| If No, Relationship of the Driver with the Insured  |                      |
| Vehicle Registration Number of Driver's Own Vehicle | -                    |
|                                                     | -                    |
| Insurance Company of Driver's Own Vehicle           | -                    |
|                                                     | -                    |

#### General Information of the Accident

|                    |                               |
|--------------------|-------------------------------|
| Type Of Accident   | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR                         |
| Road Surface       | DRY                           |

#### Other Information

|                                                                                             |     |
|---------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in this accident?                                          | NO  |
| Number of vehicles involved in the accident                                                 |     |
| Was any body injured in the Accident?                                                       | NO  |
| Was any injured conveyed to hospital by ambulance?                                          | NO  |
| Was any other material or property damaged?                                                 | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)                                                     | 1   |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

refer to attach report

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | XD4848P            |
| Vehicle Make/Model/Colour   |                    |
| Details Of Properties       |                    |
| Vehicle Category            | COMMERCIAL VEHICLE |
| Name of Driver              | PANG KAI HING      |
| NRIC/Passport Number        | S7131868J          |
| Contact Number              | 96857690           |

Address  
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature  
Name:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/6/18 around 06:45hrs, I was travelling from Harbour Dr towards Pasir Panjang Terminal Gate 4. I was on centre lane when I, approaching Gate 4. I slow down to give way for vehicle c on the right lane to avoid collision as the vehicle C is also too near to my vehicle. Suddenly vehicle XD4848P with empty chasis from left lane grazed on my passenger door and cut into my lane. Nobody was injured.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



*[Signature]*

\_\_\_\_\_

Insurance certificate



SOMPO Insurance Singapore Pte. Ltd.  
50 Raffles Place, 45th-47th Singapore Land Tower, Singapore 048623  
Tel: 645 6555 : Fax: 671 5002 : Website: www.sompo.com.sg  
Co. Reg. No.: 199304490E : GST Reg. No.: M200002796

### Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1968  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

- Cert No./Policy No. : D17MTHCVE002012  
1. Registration No. : XD1348R  
2. Insured Name : CA TRANSPORTATION & WAREHOUSING PTE LTD  
3. Commencement Date : 13 JULY 2017 00:00  
4. Expiry Date : 12 JULY 2018 23:59  
5. Coverage : Third Party  
6. Excess : NIL  
7. Persons or Classes of Persons entitled to drive\*  
1) Whilst the vehicle is being used in connection with the Insured's business -  
a) The Insured.  
b) Any other person provided he is in the Insured's employ and is driving on his order or with his permission.  
2) Whilst the vehicle is being used for social, domestic or pleasure purposes -  
a) The Insured.  
b) Any other person who is driving on the Insured's order or with his permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.  
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.  
8. Limitations as to use\*  
1) Use in connection with the Insured's business.  
2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.  
3) Use for social, domestic or pleasure purposes.  
The Policy does not cover:  
1) Use for racing, pacemaking, reliability trial or speed-testing.  
2) Use whilst drawing a greater number of trailers in all than is permitted by law.  
3) Use for the carriage of passengers for hire or reward.  
9. ExcelDrive Workshops & Accident Reporting  
It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.  
In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6461 6555

Visit [www.sompo.com.sg](http://www.sompo.com.sg) for list of Accident Reporting Centers.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Sompo Insurance Singapore Pte. Ltd.

*Stella*

Date/Time of Issue : 13 JUNE 2017 09:25

\*Sanction rendered in respect of section 9 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and section 36 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

#### IMPORTANT NOTICE

- Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- Insureds are further warned that on the sale of a motor vehicle or if for any reason the insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company if the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).
- The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
- Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.

driver IC & Work permit

**WORK PERMIT**  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer:  
**CA TRANSPORTATION & WAREHOUSING PTE LTD**

Worker: **SERVICE**

Name:  
**AGILAN A.S. JAYABALAN**

Occupation:  
**TRUCK-TRUCK DRIVER**

Work Permit No.:  
**4 01500306**

Date of Application:  
**12-12-2016**

Date of Issue:  
**15-12-2016**

Date of Expiry:  
**14-12-2018**

**L7477093**

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

**G7406989K**

**AGILAN A.S. JAYABALAN**

**23 Aug 1961**

**05 Oct 2017**

**Valid Till 14-12-2022**

**0027318048**

**VISIT PASS**  
Immigration Regulations

Name:  
**AGILAN A.S. JAYABALAN**

Date of Birth: **23-08-1961** Sex: **M** Nationality: **MALAYSIAN**

Pass No.: **07406989K** Date of Issue: **12-12-2016** Date of Expiry: **14-12-2018**

**YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.**

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES**

| Class    | Description                                                                                                                                | Effective Date |
|----------|--------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| Class 2B | Motorcycles <= 200 cc                                                                                                                      | 15 Oct 2012    |
| Class 3  | Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver, and other motor vehicles with unladen weight <= 2500kg | 15 Oct 2012    |
| Class 4  | Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg                                           | 13 Aug 2014    |
|          | Motor vehicles which are not constructed to carry load or passengers and the unladen weight >= 7750kg                                      |                |

**NP 428A**

**07406989K**

①

X 1346R

No.

Date

G-K, B-4 UD

- 1 1pc front bumper X - old damage
- 2 1pc front bumper side garnish L/H X
- 3 1pc front door #3131.00 ✓
- 4 1pc front door inner Lock \$179.40 ✓
- 5 1pc front door outer opening handle L/H X
- 6 1pc front door side signal lamp L/H ✓
- 7 1pc front door glass outer moulding L/H ✓
- 8 1pc front door glass channel L/H X
- 9 1pc front door glass channel/lower panel L/H X
- 10 1pc front door inner Trim board L/H ?
- 11 1pc front door Top Hinge L/H ?
- 12 1pc front door Lower Hinge L/H ?
- 13 1pc front door UD Emblem L/H ✓
- 14 1pc Cabin body panel L/H X
- 15 1pc Cabin side fender L/H ~~Repair~~ ✓
- 16 1pc Cabin side fender Lower garnish L/H <sup>son</sup> ✓
- 17 1pc Cabin side upper step board panel L/H X ✓
- 18 1pc Cabin side upper step board top garnish X

(2)

X.DI 346 R

No

Date

G.K. B-4

19. 1pc Cabin Lower Step Cover L/H ✓

20. 1pc Cabin Lower Step board L/H <sup>mis</sup> ✓21. 1pc Cabin Lower Step board bracket ON 14 }  
repair

22. 1pc Cabin Lower Step board bracket ON 24 }

23. 1pc Cabin fender inner shield L/H ✓

24. 1pc Cabin fender inner shield clip ✓

25. 1pc Cabin fender rear step board L/H X

Ramu

Hp 90010068

6 days

L/S

15/10/18 @ 1240

Recy after repair

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items are not included and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**T & B MOTOR REPAIRS SERVICES PTE LTD**

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

CA TRANSPORTATION & WAREHOUSING PTE LTD  
3 SOON LEE STREET #06-03, PIONEER JUNCTION  
SINGAPORE 627606

Attention : Motor Claim Department

Estimate : ES003329

Date : 29/06/2018

Vehicle Num. : XD1346R

Make/Model : NISSAN GKB45CLBHNH

Chassis/Eng# :

Accident Date : 28/06/2018

Claim No. :

Reference :

Policy No. : D17MYHCVE002012

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

- LIST ITEMS :
- |     |   |                                             |
|-----|---|---------------------------------------------|
| 1.  | 1 | FRONT BUMPER SIDE GARNISH LH                |
| 2.  | 1 | FRONT DOOR                                  |
| 3.  | 1 | FRONT DOOR INNER LOCK LH                    |
| 4.  | 1 | FRONT DOOR TRIM BOARD LH                    |
| 5.  | 1 | FRONT DOOR TOP HINGE LH                     |
| 6.  | 1 | FRONT DOOR LOWER HINGE LH                   |
| 7.  | 1 | FRONT DOOR CLOSET LH                        |
| 8.  | 1 | FRONT CABIN SIDE FENDER L/H                 |
| 9.  | 1 | FRONT CABIN SIDE FENDER PROTECTOR L/H       |
| 10. | 1 | FRONT CABIN STEP BORAD PANEL L/H            |
| 11. | 1 | FRONT CABIN STEP BORAD PANEL CENTRE GARNISH |
| 12. | 1 | FRONT CABIN STEP BORAD PANEL LOWER GARNISH  |
| 13. | 1 | FRONT CABIN STEP BORAD                      |
| 14. | 1 | FRONT CABIN STEP BORAD BRACKET NO.1 L/H     |
| 15. | 1 | FRONT CABIN STEP BORAD BRACKET NO.2 L/H     |
| 16. | 1 | FRONT DOOR SIGNAL LAMP LH                   |

List Total S\$ :

30.00% Discount S\$ :

NETT ITEMS :

- |    |       |                                  |
|----|-------|----------------------------------|
| 1. | 1 SET | FRONT CABIN SIDE FENDER SCREW    |
| 2. | 1 SET | FRONT CABIN SIDE PROTECTOR SCREW |

Nett Total S\$ :

10.00% Discount S\$ :

|         |           |      |
|---------|-----------|------|
| 4500    | 147.00    | SCA  |
|         | 8,527.50  | PT   |
|         | 325.60    | PT   |
|         | 450.50    | PT   |
|         | 265.60    | X 80 |
|         | 265.60    | BT   |
|         | 210.40    | X 80 |
|         | 785.50    | X 80 |
|         | 255.00    | SCA  |
|         | 260.60    | DE   |
|         | 295.60    | CAN  |
|         | 195.60    | DE   |
|         | 385.80    | BT   |
|         | 258.60    | BT   |
|         | 185.50    | X 80 |
|         |           | PT   |
| 8310.90 | 13,073.00 |      |
| 30%     | 3,921.90  |      |
| 5877.63 | 9,151.10  |      |
| 72      | 36.00     | new  |
|         | 36.00     | new  |
|         | 72.00     |      |
|         | 7.20      |      |
|         | 64.80     |      |

CONTINUE / ...

17/10/18 4.00 pm.

**T & B MOTOR REPAIRS SERVICES PTE LTD**

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722  
 Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640  
 E-Mail : tbmotor@hotmail.sg  
 Bus. Reg. No. : 199001597D

WITHOUT PREJUDICE

CA TRANSPORTATION & WAREHOUSING PTE LTD  
 3 SOON LEE STREET #06-03, PIONEER JUNCTION  
 SINGAPORE 627606

Attention : Motor Claim Department

Estimate : ES003329

Date : 29/06/2018  
 Vehicle Num. : XD1346R  
 Make/Model : NISSAN GKB45CLBHN8  
 Chassis/Eng# :  
 Accident Date : 28/06/2018  
 Claim No. :  
 Reference :  
 Policy No. : D17MYHCVE002012

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

## LABOUR :

1. REMOVE & REFIX DOOR GLASS
2. TO CHECK WRING AND REPAIR DOOR WIRE
3. TO SPRAY TUFF KOTE
4. TO SPRAY PAINT ON SFFECTED PORTION
5. LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE
6. DOOR STICKER (TEL & FAX) NUMBER

Labour Total S\$ :

100  
 180.00  
 120.00  
 150.00  
 1,200.00  
 1,800.00  
 140.00  
 3,590.00

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SingDollars : Twelve Thousand Eight Hundred Five &amp; Cents Ninety Only

E. &amp; O.E.

Total S\$ : 12,805.90

for T &amp; B MOTOR REPAIRS SERVICES PTE LTD

P-5817.63  
 N 64.80  
 L-2140.00  
 T-8022.43  
 20%  
 6417.94  
 45-6,400  
 7 days

Rasul  
 Hp 90010068  
 7 days  
 4/5  
 15/10/18 @ 1200h  
 Reg after repair

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18018652/R1QD3N2  
Date: 26/12/2018

## REFERENCE

|                       |                                      |                      |             |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | 27557412TMV |
| Claimant Vehicle No : | XD1346R                              | Insured Vehicle No : | XD4848P     |
| Date of Loss:         | 28/06/2018                           | Nature of Claim:     | TP          |
|                       |                                      | Claim No:            | 562950      |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                                |             |              |
|-----------------------------|--------------------------------|-------------|--------------|
| Reg No:                     | XD1346R                        | Engine No:  | GE13333947B  |
| Make & Model:               | NISSAN GKB45CLBHNH, 13.1 D (A) | Chassis No: | GKB4CLB00099 |
| Reg. Date:                  | 13/07/2007 (Man. Year: 2007)   | Odometer:   | 300850 km    |
| Colour:                     | White                          |             |              |
| Engine Capacity:            | 13074 cc                       |             |              |
| Market Value/New Car Price: | N/A                            |             |              |
| Sum Insured (S\$):          | Market Value/New Car Price     |             |              |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |                  |
|-------------------|---------------|------------------|------------------|
| Front Tyre Size:  | 295/80 R22.5  | Rear Tyre Size:  | 295/80 R22.5 (D) |
| Front Left Side:  | Goodyear 8 mm | Rear Left Side:  | Goodyear 8/8 mm  |
| Front Right Side: | Goodyear 8 mm | Rear Right Side: | Goodyear 8/8 mm  |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 9,215.90   | 5,882.43   | 3,333.47   | 36.17  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 3,590.00   | 2,140.00   | 1,450.00   | 40.39  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 12,805.90  | 8,022.43   | 4,783.47   | 37.35  |
| Approved Total (Overridden) (S\$) |            | 6,400.00   |            |        |
| Nett Amount (S\$)                 | 12,805.90  | 6,400.00   | 6,405.90   | 50.02  |

## INSPECTION

|                     |            |                                                |
|---------------------|------------|------------------------------------------------|
| Date of Assignment: | 12/10/2018 |                                                |
| Date Inspected:     | 15/10/2018 | Inspected At:                                  |
|                     |            | ACE BUROH- 2 BUROH CRESCENT #04-08             |
|                     |            | REPAIRER: T & B MOTOR REPAIRS SERVICES PTE LTD |
|                     |            | BLK 20 SIN MING ROAD #01-28                    |
|                     |            | SINGAPORE 575678                               |

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

|               |                                                                                                                                                                              |                                                                |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| Part Source:  | (Last Synchronised: 26 Dec 2018)                                                                                                                                             |                                                                |
| Parts:        | N/A                                                                                                                                                                          | NISSAN GKB45CLBHN 13.1 D (A) (Model not available in database) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| Print Code:   | (Unsubmitted, no print-code for XD1346R)                                                                                                                                     |                                                                |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *                                                                                                      |                                                                |

## Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition   | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------------|-------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER SIDE GARNISH LH                | Scratched   | 147.00 FL   | *147.00 FL   |
| 2   | 1   |          | *FRONT DOOR                                  | Bent        | 8,527.50 FL | *4,500.00 FL |
| 3   | 1   |          | *FRONT DOOR INNER LOCK LH                    | Bent        | 325.60 FL   | *325.60 FL   |
| 4   | 1   |          | *FRONT DOOR TRIM BOARD LH                    | Deformed    | 450.50 FL   | *450.50 FL   |
| 5   | 1   |          | *FRONT DOOR TOP HINGE LH                     | Serviceable | 265.60 FL   | *- FL        |
| 6   | 1   |          | *FRONT DOOR LOWER HINGE LH                   | Bent        | 265.60 FL   | *265.60 FL   |
| 7   | 1   |          | *FRONT DOOR CLOSET LH                        | Serviceable | 210.40 FL   | *- FL        |
| 8   | 1   |          | *FRONT CABIN SIDE FENDER L/H                 | Cracked     | 785.50 FL   | *785.50 FL   |
| 9   | 1   |          | *FRONT CABIN SIDE FENDER PROTECTOR L/H       | Scratched   | 255.00 FL   | *255.00 FL   |
| 10  | 1   |          | *FRONT CABIN STEP BOARD PANEL L/H            | Deformed    | 260.60 FL   | *260.60 FL   |
| 11  | 1   |          | *FRONT CABIN STEP BOARD PANEL CENTRE GARNISH | Cracked     | 295.60 FL   | *295.60 FL   |
| 12  | 1   |          | *FRONT CABIN STEP BOARD PANEL LOWER GARNISH  | Deformed    | 195.60 FL   | *195.60 FL   |
| 13  | 1   |          | *FRONT CABIN STEP BOARD                      | Broken      | 385.80 FL   | *385.80 FL   |
| 14  | 1   |          | *FRONT CABIN STEP BOARD BRACKET NO.1 L/H     | Bent        | 258.60 FL   | *258.60 FL   |
| 15  | 1   |          | *FRONT CABIN STEP BOARD BRACKET NO.2 L/H     | Serviceable | 258.60 FL   | *- FL        |
| 16  | 1   |          | *FRONT DOOR SIGNAL LAMP L/H                  | Broken      | 185.50 FL   | *185.50 FL   |
| 17  | 1   |          | *SET FRONT CABIN SIDE FENDER SCREW           | Necessary   | 36.00 FN    | *36.00 FN    |
| 18  | 1   |          | *SET FRONT CABIN SIDE PROTECTOR SCREW        | Necessary   | 36.00 FN    | *36.00 FN    |

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

|                                                    |           |          |
|----------------------------------------------------|-----------|----------|
| Sub Total (S\$)                                    | 13,145.00 | 8,382.90 |
| - List Item Discount on L Items 30.00/30.00% (S\$) | 3,921.90  | 2,493.27 |
| - Nett Item Discount on N Items 10.00/10.00% (S\$) | 7.20      | 7.20     |
| Total Parts (S\$)                                  | 9,215.90  | 5,882.43 |

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

| No                       | Particulars                                                                                         | Lab.Type | Repairer's | Amount   |
|--------------------------|-----------------------------------------------------------------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>      |                                                                                                     |          |            |          |
| 1                        | TO REMOVE & REFIX DOOR GLASS                                                                        | New      | 180.00     | 100.00   |
| 2                        | TO CHECK WIRING AND REPAIR DOOR WIRE                                                                | New      | 120.00     | 80.00    |
| 3                        | TO SPRAY TUFF KOTE                                                                                  | New      | 150.00     | 80.00    |
| 4                        | TO SPRAY PAINT ON SFFECTED PORTION                                                                  | New      | 1,200.00   | 800.00   |
| 5                        | LABOUR CHARGE FOR<br>REPAIRING,ADJUSTING,KNOCKING,WELDING THE<br>DAMAGED PARTS,STRAIGHTEN THE ABOVE | New      | 1,800.00   | 1,000.00 |
| 6                        | DOOR STICKER (TEL & FAX) NUMBER                                                                     | New      | 140.00     | 80.00    |
| Gross Labour Cost (\$\$) |                                                                                                     |          | 3,590.00   | 2,140.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;