

22/03/2002

ASS. REC. BY:

REF:

CS3 / SM018018656 / Gcd30

Special Instruction:

Surveyor:

GWO @igney

ASSIGNMENT (Office)

From (Person):

Ginh pau hung

of

SMO

Date/Time:

12/10/18 @ 5.42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 2277A

Insured:

PC 126R

at Workshop m/s

Speed Antowerkz

Tel:

8533 2934

of

68 Keiki Bulkit Ave 6 # 02-05

Policy No:

DISMTSCBU 000041

Claim No:

CMTD1804237

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/09/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:20am @ 15/10/18

Person Contacted:

Sun Sun

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate	
	PC 2277A - NA / INC 15013038 / h4	DOA: 03/08/2015
	PC 126R - X	

c 4523 R

TOTAL

100

10

110

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Sep 2018		12 Oct 2018 17:42 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HUI LEONG TRANSPORT (2010) PTE LTD, Co. Reg. No.: 201010850C		
Main Claimant:	UNKNOWN4237		
Vehicle Reg. No.:	PC2277A	Date of Loss:	27/09/2018 13:00 - :59
Claim Type:	TP / CMTD1804237	Policy/Cover Note No.:	D18MTSCBU000041 (Comprehensive)
Vehicle Reg. No. (Insured):	PC126R	Policy No. (Claimant):	
		Excess:	
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/10/2018]		
Driver/Custodian (Insured):	PETER TING CHERNG JEIN (), NRIC: S7989536I, Tel: +6584014515		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4923R

Vehicle Details

Vehicle No.:	PC2277A
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE HIGH ROOF COMMUTER TURBO AUTO
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2376002
Chassis No.:	JTFST22P700019125
Maximum Power Output:	-
Open Market Value:	\$38,054.00
Original Registration Date:	25 Mar 2014
First Registration Date:	25 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$1,903.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	24 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,361.00
COE Rebate Amount:	\$14,314.00
Total Rebate Amount:	\$14,314.00

The information contained herein is correct as at 19 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2018 16:17
Date Of Accident	27/09/2018 13:15
Exact Location Of Accident	SINGAPORE ZOO (BUS COACH AREA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2277A
Insured/Policyholder	
Name Of Registered Owner	HEAVENLY TOURS PTE LTD
Co Reg No	NA
Email Address	SHAFIQ_MUHD@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-94461887

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVBPSB0005851800
Cover Note Number	

Driver

Name of Driver	MUHAMMAD SHAFIQ BIN MOHAMED ZAFURULLA
NRIC No	S9018837B
Date Of Birth	27/05/1990
Occupation	OUTDOOR
Date Of Driving Pass	30/05/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94461887
Fax Number	
Contact Number	
Email Address	SHAFIQ_MUHD@HOTMAIL.COM

Address	BLK 474 JURONG WEST STREET 41 #12-398
Postcode	640474
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC126R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	PETER TING CHERNG JEIN
NRIC/Passport Number	S79895361
Contact Number	84014515
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
NRIC / Fin No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 Sept 2018, at about 13.15hrs my company's vehicle (PC2277A) was parked at Singapore Zoo bus coach area. My vehicle was hit by another vehicle (PC126R) while ^{he was} reversing to move out from his lot.

IMPORTANT NOTE

Under General Condition - Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC / Fin Ng.






































...CLAIM SUBFOLDER...(Pending for Survey Report)
















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2018		12 Oct 2018 17:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HUI LEONG TRANSPORT (2010) PTE LTD , Co. Reg. No.: 201010850C								
Main Claimant:	HEAVENLY TOURS PTE LTD , Co. Reg. No.: 201014923R								
Vehicle Reg. No.:	PC2277A	Date of Loss:	27/09/2018 13:00 - :59 [54 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1804237	Policy/Cover Note No.:	D18MTSCBU000041 (Comprehensive)						
Vehicle Reg. No. (Insured):	PC126R	Policy No. (Claimant):							
		Excess:							
Repairer:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB, 417896 Kaki Bukit - Tel: 85332934								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/10/2018]								
Driver/Custodian (Insured):	PETER TING CHERNG JEIN (), NRIC: S7989536I, Tel: +6584014515								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***PC2277A (CMTD1804237)**
[PC126R]
TP
HEAVENLY TOURS PTE LTD
Sep 27 2018 1:00PM
[HUI LEONG TRANSPORT (2010) PTE LTD]
6 Speed Autowerkz Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
6	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
18	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
34	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/10/18 12:16	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	12/10/18 15:35	PRI REQ FAX FROM CATHERINE LIM LLC DT 12/10/18 FOR PC2277A	 Load PDF	
2	12/10/18 16:03	Third Party E-filed GIA report	 Load PDF	
3	12/10/18 17:40	PRS - NO CONSENSUS	 Load HTM	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18018656/GCD3E2

Date: 02/11/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000041
Claimant Vehicle No :	PC2277A	Insured Vehicle No :	PC126R
Date of Loss:	27/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1804237

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2277A	Engine No:	1KD2376002
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFST22P700019125
Reg. Date:	25/03/2014 (Man. Year: 2014)	Odometer:	331603 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/10/2018	
Date Inspected:	18/10/2018 Inspected At:	6 Speed Autowerkz Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6, #02-05 ARK@KB Singapore 417896
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 -\$2,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Nov 2018)

Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC2277A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >