

22/03/2002

ASS. REC. BY:

REF:

CS/CTI/18018658/ Gvd3et

Special Instruction:

Surveyor:

Gwo Chang

From (Person):

Irene Tay

of

CTI

Date/Time:

12/10/18 @ 4:20pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 4438T

Insured:

SKN 8723R

at Workshop m/s

Allswell Motor

Tel:

66791146

of

24 Defu Jere 12

Policy No:

DMPCSN 1436901803

Claim No:

SNM18D0479C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/10/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

16/10/18 @ 11am

Date/Time:

10:36am @ 15/10/18

Person Contacted:

chai yee

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLP 4438T - X

SKN 8723R - CCB / CAT 15012969 / H1j93q2

DOA: 30/7/2015

Surveyor

XRL

REF:

CTE

C 28847 25413

ASSIGNMENT

From:

Date:

16/10/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLP 4438T

at Workshop m/s

Allswell

of

24 Deft Lane 12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11 am @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP 4438T

Yr Regn:

05 Jun 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

125707

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Ru3n45254

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16-10-18

Survey held at

W/S

11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/10

Finalised \$300 with Ben (Red 300, 529)

RECEIVED 17 OCT 2018

17/10/2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

17/10 - typist

Days Of Repair:

2

Resurvey No. of Trip:

-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

Merimen

Lump Sum / I.B.I. (\$

300/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2018		12 Oct 2018 16:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN KENG HONG RICHARD, ID: S0004980H		
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 201432541Z		
Vehicle Reg. No.:	SLP4438T	Date of Loss:	05/10/2018 16:00 - :59
Claim Type:	TP / SNM18D04790C02	Policy/Cover Note No.:	DMPCSN1436901803 (Comprehensive)
Vehicle Reg. No. (Insured):	SKN8723R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN XING QUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2541Z
Vehicle Details	
Vehicle No.:	SLP4438T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	LEB5945272
Chassis No.:	RU31245254
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,303.00
Original Registration Date:	05 Jun 2017
First Registration Date:	05 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$45,750.00
Total Rebate Amount:	\$49,500.00

The information contained herein is correct as at 17 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/10/2018 18:21
Date Of Accident	05/10/2018 17:20
Exact Location Of Accident	JUNCTION OF LORONG MAZUKI AND SIM AVE EAST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP4438T
Insured/Policyholder	
Name Of Registered Owner	ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No	201432541Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64625405
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5087620250-01
Cover Note Number	
Driver	
Name of Driver	NG AIK KOON MICHAEL
NRIC No	S1311488I
Date Of Birth	14/07/1958
Occupation	OUTDOOR
Date Of Driving Pass	07/10/2000
Driving Experience	17 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86833626
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

*Address	BLK 231 PASIR RIS DRIVE 4 #02-452
Postcode	510231
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SKN8723R WAS ON MY LEFT AT THE JUNCTION OF LOR MARZUKI WITH SIMS AVE EAST. BOTH OF OUR CARS HAD STOP AT THE JUNCTION . WHEN THE TRAFFIC WAS CLEAR, I PROCEED TO TURN RIGHT INTO SIM AVE EAST. SKN8723R MUST HAVE BEEN TOO ENSROSS WITH THE TRAFFICE ON HIS LEFT THAT HE KNOCKED INTO MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN8723R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:
08/10/18


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SKN 8723R WAS ON MY LEFT AT THE JUNCTIONS OF LOR MARZUKI
WITH SONS AVE EAST. BOTH OF OUR CARS HAD STOP AT THE JUNCTION.
WHEN THE TRAFFIC WAS CLEAR, I PROCEED TO TURN RIGHT INTO
SONS AVE EAST. SKN 8723R MAY HAVE BEEN TOO ENGRESS WITH
THE TRAFFIC ON HIS LEFT THAT HE KNOCKED INTO MY CAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: 
Date & Time: 21/7

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

16/10/18

email:ben@allswellmotor.com.sg

1

Ben

04-06-2027

Date of survey

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Oct 2018		12 Oct 2018 16:20 Edit Adj Rpt	S\$300.00 Edit Estimates	S\$300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN KENG HONG RICHARD , ID: S0004980H									
Main Claimant: ALLSWELL LEASING & LIMOUSINE PTE LTD , Co. Reg. No.: 201432541Z									
Vehicle Reg. No.: SLP4438T		Date of Loss: 05/10/2018 16:00 - :59 [16 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04790C02		Policy/Cover Note No.: DMPCSN1436901803 (Comprehensive)							
Vehicle Reg. No. (Insured): SKN8723R		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/10/2018]									
Adj Asg. Remarks: NO EST, ASSIGN XING QUO QIANG AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLP4438T (SNM18D04790C02)**
[SKN8723R]

TP

ALLSWELL LEASING & LIMOUSINE PTE LTD

Oct 5 2018 4:00PM

[TAN KENG HONG RICHARD]

Allswell Motor Traders

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	06/10/18 14:59	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	06/10/18 14:56	SCENE PHOTO [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	06/10/18 14:56	SCENE PHOTO [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	06/10/18 14:56	SCENE PHOTO [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	06/10/18 14:56	SCENE PHOTO [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	06/10/18 14:56	SCENE PHOTO [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	06/10/18 14:56	3RD PARTY CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	06/10/18 14:56	3RD PARTY CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	06/10/18 14:56	SCENE PHOTO [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
12	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
13	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
14	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
15	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
16	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
17	06/10/18 14:57	INSURED CAR [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/10/18 11:27	General View		Load PDF	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/10/18 16:20	PRS		Load PDF	
2	12/10/18 16:20	TP GIA		Load PDF	
3	12/10/18 16:20	OI GIA		Load PDF	

No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	06/10/18 14:52	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	06/10/18 14:52	Sketch Plan #3 [Linked Accident Report Documents]		Load TIF	
3	06/10/18 14:53	SKETCH PLAN A		Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
		[Linked Accident Report Documents]		
4	06/10/18 14:53	DOC A [Linked Accident Report Documents]	Load TIF	
5	06/10/18 14:53	CI [Linked Accident Report Documents]	Load TIF	
6	06/10/18 14:53	OWNER / DRIVER IC N DL [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print	
1	06/10/18 14:59	Accident Statement	Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print	
1	06/10/18 14:56	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>	
2	06/10/18 14:56	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>	
3	06/10/18 14:56	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>	
4	06/10/18 14:56	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>	
5	06/10/18 14:56	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>	
6	06/10/18 14:56	3RD PARTY CAR	Load JPG	<input checked="" type="checkbox"/>	
7	06/10/18 14:56	3RD PARTY CAR	Load JPG	<input checked="" type="checkbox"/>	
8	06/10/18 14:56	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>	
9	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
10	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
11	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
12	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
13	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
14	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
15	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
16	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
17	06/10/18 14:57	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print	
1	06/10/18 14:52	Sketch Plan	Load TIF		
2	06/10/18 14:52	Sketch Plan #3	Load TIF		
3	06/10/18 14:53	SKETCH PLAN A	Load TIF		
4	06/10/18 14:53	DOC A	Load TIF		
5	06/10/18 14:53	CI	Load TIF		
6	06/10/18 14:53	OWNER / DRIVER IC N DL	Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018658/GVD3E2

Date: 22/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1436901803

Claimant Vehicle
No: SLP4438TInsured Vehicle
No: SKN8723R

Date of Loss: 05/10/2018

Nature of Claim: TP

Claim
No: SNM18D04790C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP4438T

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5945272

Reg. Date: 05/06/2017 (Man. Year: 2017)

Chassis No: RU31245254

Colour: Blue

Odometer: 125707 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	300.00	320.00	51.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	620.00	300.00	320.00	51.61
+ GST 7.00/7.00% (\$\$)	43.40	21.00	22.40	51.61
Nett Amount (\$\$)	663.40	321.00	342.40	51.61

INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 16/10/2018

Inspected At:

Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP4438T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY / SAND PAPER & POLISH	New	260.00	100.00
2	SPRAY PAINTING OF DOOR / FENDER ARC / SKIRTING	New	360.00	200.00
Gross Labour Cost (\$\$)			620.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >