

22/03/2002

ASS. REC. BY:

REF:

CS/III18018664/Asd36

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Gabriel wee

of

III

Date/Time:

12/10/18 @ 5:18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS:

To Inspect Vehicle No:

FBK 1865H

Insured:

SHA 2461P

at Workshop m/s

First Motor

Tel:

96391004

of

B11c 3006, ubi Rd 1 #01-348

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/08/2018

CA / REV / REP. / REV 24 HRS

/up

H.O.D. Endorsement:

Date/Time:

10:22am @ 15/10/18

Person Contacted:

Mr. Lim

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓), Estimate
	FBK 1865H-CS / MSG18014464 / Khd3n2 DOA: 06/08/2018
	SHA 2461P-CS / MSG18014464 / Khd3n2 DOA: 06/08/2018
15/10/18	Pending GIA Report from Repairer
23/10/18	Confirmed with Nicole Nicole Clavier film 7, No GIA report.

REF: III

ASSIGNMENT

From: _____ Date: 15/10/18

Estimated Cost: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBK 186SH

at Workshop m/s First Motor

of Blk 3006, Ubi Rd 1 # 01-398

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Mr. Lim @ 9639 1004

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBK186SH Yr Regn: 13/04/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha. C.C. 134

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 34086 T/Radio: Insured / Std / NI / NA

Eng/No: 50C743214

C/No: MH350C 006EK 743050

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 70/90 R17.

R: 100/70 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 15/10/18

Survey held at First Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP III

21/06/19 @ 16:56 pm checked with Mr. Lim (owner) & Nicole (lawyer firm), the owner withdrawn claim. Vehicle has not repair.

RECEIVED 26 JUN 2019

Date/Time, File Pass to?

26/06/19

1) Typist

Date/Time, File Return to?

2) _____

☒ : Preli. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) S + RS. SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format: Preli.

Lump Sum / I.B.I. (\$))

Survey Fee: 250

Transportation:

S + RS. SI

Photos

Others

TOTAL

261

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 12 October 2018 5:18 PM
To: Nicole Soong; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Zuhaidah Samsuri
Subject: RE: Our Ref: CG/CH/ns/4842.18.Kock Chong(PD); Your Ref: SHA2461P
Attachments: sha2461p_20181012091824.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FBK1865H and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Nicole Soong [mailto:nicole@cosmas.com.sg]
Sent: 12 October, 2018 4:05 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Our Ref: CG/CH/ns/4842.18.Kock Chong(PD); Your Ref: SHA2461P

Dear Gabriel

We refer to the above matter and your email dated 12 October 2018.

Kindly arrange LKK Auto Consultants Pte Ltd for the inspection at our client's workshop.

Yours faithfully,

Nicole

p: 6536 4662 f: 6536 0738
a: 133 New Bridge Road, #16-05
Chinatown Point, Singapore 059413
w: www.cosmas.com.sg
e: nicole@cosmas.com.sg



COSMAS LLC
A LIMITED LIABILITY LAW CORPORATION

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including

the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> Back to OneMotoring

Enquire Transfer Fee

Inquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBK1865H		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	JUPITER MX (HC)		
Chassis No. :	MH350C006EK743050		
Propellant :	Petrol		
Engine No. :	50C743214		
Engine Capacity :	134 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	242 kg		
Unladen Weight :	116 kg		
Year Of Manufacture :	2014		
Original Registration Date :	13 Apr 2015		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$5,800.00		
COE Expiry Date :	12 Apr 2025		
Road Tax Expiry Date :	12 Apr 2020		
Inspection Due Date :	12 Apr 2020		
Intended Transfer Date :	26 Jun 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3584Z
Vehicle Details	
Vehicle No.:	FBK1865H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	YAMAHA
Vehicle Model:	JUPITER MX (HC)
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	50C743214
Chassis No.:	MH350C006EK743050
Maximum Power Output:	-
Open Market Value:	\$1,954.00
Original Registration Date:	13 Apr 2015
First Registration Date:	13 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$294.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,800.00
COE Rebate Amount:	\$3,362.00
Total Rebate Amount:	\$3,362.00

The information contained herein is correct as at 26 Jun 2019

OK

**COSMAS LLC**

A LIMITED LIABILITY LAW CORPORATION



Your Ref: To be advise

Our Ref: CG/CH/ns/4842.18.Kock Chong (PD)

10th October 2018**India International Insurance Pte Ltd**64 Cecil Street,
#04-05 IOB Building
Singapore 049711Attention: Motor Claims Department**WITHOUT PREJUDICE****BY FAX & HAND**

Fax No: 8224 4174

Dear Sir,

CLAIMANT: CHAR KOCK CHONG (NRIC NO.S2743584Z)**ACCIDENT INVOLVING FBK 1865H & SHA 2461P AT "T" JUNCTION OF TAMPINES AVENUE 10 ON
6TH AUGUST 2018 AT ABOUT 1815 HOURS
(PROPERTY DAMAGE CLAIM)**

1. We refer to the above matter in which we act for Char Kock Chong, the owner of motor vehicle No. FBK 1865H.
2. Our client's motor vehicle No. FBK 1865H was involved in an accident with motor vehicle No. SHA 2461P on the 6th August 2018 which we understand was insured by your company.
3. We hereby give you three (3) days (i.e. 16th October 2018 and 17th October 2018) notice for your surveyor to arrange for an inspection on our client's motor vehicle No. FBK 1865H at our client's workshop with the address and time as follows:-

Place: **M/s First Motor**
Block 3006 Ubi Road 1
#01-398
Singapore 408700Contact No: **67431911 / 96391004 (Mr Lim)**Time: **Between 10 am to 5 pm**

.../2

133 New Bridge Road, #16-05, Chinatown Point, Singapore 059413

Tel: 65364662 | Fax: 65360738

UEN & GST Registration No. 201334745C

E-mail: cosmas@cosmas.com.sg | Website: www.cosmas.com.sg

**COSMAS LLC**

A LIMITED LIABILITY LAW CORPORATION

COSMAS LLC**Page 2****India International Insurance Pte Ltd**

Your Ref:

10th October 2018Attention: Claims Department

4. We enclose a copy of the estimate repair bill on our client's motor vehicle from the workshop for your attention.
5. In the event the inspection does not take place, our client shall proceed to repair the said vehicle.

Yours faithfully,

Cosmas Gomez
COSMAS LLC

Enc.

cc. **M/s First Motor**
Fax No: 67458131
Attention: Mr. Lim

133 New Bridge Road, #16-05, Chinatown Point, Singapore 059413

Tel: 65364662 | Fax: 65360738

UEN & GST Registration No. 201334745C

E-mail: cosmas@cosmas.com.sg | Website: www.cosmas.com.sg



T_20180812_7004_

SINGAPORE
POLICE FORCE

T/20180812/7004

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180812/7004

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/08/2018 13:25	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: CHAR KOCK CHONG	Address: APT BLK 537 BEDOK NORTH STREET 3 #01-559 SINGAPORE 460537	
ID Type / ID No.: NRIC NO / S2743584Z	Contact No.:	Mobile: 82805582
Nationality: MALAYSIAN	Email: annie.char@hotmail.com	
Sex: Male	Age: 55	Date of Birth: 25/02/1963
Type of Informant: Vehicle Owner		
Race: Chinese	Language: English	Institution / School Name:
Occupation: Bricklayer/Blocklayer	Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 06/08/2018 18:15	Type of Location: T-Junction
Location: tampines ave 10				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 70 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK1865H	Motorcycle	YAMAHA	134cc	Black	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBK1865H	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSD/VMS/17- 36292-CA	15/04/2018	14/04/2019

SINGAPORE
POLICE FORCE

T/20180812/7004

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBK1865H	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSD/VMS/17- 36292-CA	15/04/2018	14/04/2019



**SINGAPORE
POLICE FORCE**



T/20180812/7004

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180812/7004

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Vehicle Owner			
Name	CHAR KOCK CHONG	ID No.	S2743584Z
Related Vehicle	FBK1865H (Motorcycle)	Contact No.	82805582
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	06/08/2018	Date Discharge	11/08/2018
No. of Days granted Medical Leave	48	Degree of Injury	Serious

Brief Details.

i intended to go tampines ave 1 for caltex petrol station, i was on the road tampines ave 10. The traffic light was green. I made a right turn(refer to attachment). The taxi was behind me, and then i was hit by the taxi behind me when i made the turn. My speed was around 50-60km/h at the time.



SINGAPORE
POLICE FORCE



T:20180812/7004

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T:20180812/7004

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
MOHAMMAD ZULKARNIAN BIN SAMSUDIN
Contact No.: 65476429

Authentication Stamp

NP168

Signature Of Informant:

The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
12/08/2018 13:25

Classification Of Case:

Enquire Vehicle & Owner Information (Vehicle No. SHA2461P As At 06 Aug 2018 / 18:15:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: CG/CH/4842.18

Company Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Forward Vehicle Details

Vehicle No.: SHA2461P
Make Description/Model: HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Insurance Company Name: INDIA INT'L INS PTE LTD

05 Sep 18 09:49a

p.2

CG/CH/4842.18.1 work change

FIRST MOTOR

BLK 3006 UBI ROAD | #01-398 SINGAPORE 408700

TEL: 6743 1911 / 6744 8333 FAX NO: 6745 8131

RCB REG NO: 289644/OOC

E-mail: lionell@singnet.com.sg

E-mail: first_motor_sg@yahoo.com

DATE: 31/8/2018

REF NO:

VEH NO: FBR1865H

YAMAHA MX 135 LC

ATTN: CLAIM DEPT

RE: ESTIMATION FOR ACCIDENT INVOLVING VEH NO. FBR1865H /

ITEM	QTY	DESCRIPTION	ON	PRICE(S\$)
1	1	HANDLE BAR <i>Not new</i>		90.00
2	2	MIRROR SET(LH)&(RH)\$26.00 <i>LH missing</i>		52.00
3	1	BALANCER <i>ut</i>		22.00
4	1	FRONT COWLING <i>ut</i>		98.00
5	1	FRONT SIDE COWLING (LH) <i>ut</i>		75.00
6	1	FRONT MUDGUARD <i>ut</i>		62.00
7	2	FORK ASSY (RH)&(LH) @\$250.00 <i>Not new</i>		500.00
8	1	FRONT WHEEL <i>Not new</i>		200.00
9	1	TAIL COVER (LH) <i>ut</i>		65.00
10	2	FOOTREST RUBBER (LH)&(RH)@\$14.00 <i>LH ut</i>		28.00
11	1	REAR FOOTREST (LH) <i>ut</i>		38.00
12	1	REAR FOOTREST BRACKET (RH) <i>Not new</i>		75.00
13	1	SEAT BAR <i>Not new</i>		65.00
14	1	GIVI BOX BRACKET <i>crushed</i>		150.00
15	1	REAR NUMBER PLATE <i>3rd</i>		20.00
16	1	EXHAUST PIPE <i>Repair</i>		330.00
17	1	EXHAUST CHROM COVER <i>Dented</i>		96.00
18	1	FRONT COWLING (RH) <i>Not new</i>		75.00
19	1	REAR DISC PAD		135.00
20	1	REAR WHEEL ASSY <i>Not new</i>		220.00
21	1	SWIM ARM ASSY <i>Not new</i>		390.00
22	1	REAR ASOBER <i>Not new</i>		180.00
23	1	REAR MUDGUARD <i>Not new</i>		65.00
24	1	SIDE STAND <i>Not new</i>		48.00

25

ERP IU UNIT (NETT) *ut*

TOTAL PARTS	3,079.00
LESS 10%	307.90
TOTAL	2,771.10
TOTAL	160.00
TOTAL	2,931.10

LABOUR & MISC

LABOUR CHARGE	250.00
CHASSIS REPAIR	250.00

GRAND TOTAL: 3,431.10

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 1067.90

h/s: 850

04 Days

...CLAIM SUBFOLDER...(Pending for Survey Report)


















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2018 Edit Reg		12 Oct 2018 00:00 Edit Adj Rpt	S\$850.00 Edit Estimates	S\$850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	CHAR KOCK CHONG, ID: -								
Vehicle Reg. No.:	FBK1865H	Date of Loss:	06/08/2018 00:00 - :59 [39 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18080186	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA2461P	Policy No. (Claimant):							
		Excess:							
Repairer:	First Motor (HQ) Blk 3006 #01-398, Ubi Road 1, 408700 Ubi - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK1865H (MCT18080186)
[SHA2461P]
TP
CHAR KOCK CHONG
Aug 6 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
First Motor

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
2	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
3	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
4	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
5	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
6	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
7	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
8	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
9	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
10	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
11	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
12	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
13	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
14	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
15	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
16	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
17	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
18	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
19	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
20	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
21	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
22	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
23	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
24	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
25	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
26	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
27	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
28	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
29	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
30	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
31	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
32	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
33	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
34	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
35	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
36	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	
37	26/06/19 09:38	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/06/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	16/10/18 09:10	Singapore Accident Statement	 Load PDF	
2	17/10/18 15:56	Letter of Demand from Third Party FAXED COPY	 Load PDF	
3	17/10/18 17:00	Letter of Demand from Third Party cosmas original	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18018664/ASD3E2

Date: 04/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : FBK1865H **Insured Vehicle No :** SHA2461P
 Date of Loss: 06/08/2018 Nature of Claim: TP Claim No: MCT18080186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK1865H**
 Make & Model: YAMAHA JUPITER MX, 134cc HC Engine No: 50C743214
 Reg. Date: 13/04/2015 (Man. Year: 2014) Chassis No: MH350C006EK743050
 Colour: Black Odometer: 34096 km
 Engine Capacity: 134 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 Rear Tyre Size: 100/70 R17
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,931.10	817.90	2,113.20	72.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	250.00	250.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,431.10	1,067.90	2,363.20	68.88
Approved Total (Overridden) (S\$)		850.00		
Nett Amount (S\$)	3,431.10	850.00	2,581.10	75.23

INSPECTION

Date of Assignment: 12/10/2018
 Date Inspected: 15/10/2018 Inspected At: First Motor (HQ)
 Blk 3006 #01-398, Ubi Road 1
 Singapore 408700
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jul 2019)	
Parts:	N/A	YAMAHA JUPITER MX 134cc HC (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK1865H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	90.00 FL	*- FL
2	1		*SET MIRROR LH & RH	N/S Missing	52.00 FL	*26.00 FL
3	1		*BALANCER	Cut	22.00 FL	*22.00 FL
4	1		*FRONT COWLING	Cut	98.00 FL	*98.00 FL
5	1		*FRONT SIDE COWLING (LH)	Cut	75.00 FL	*75.00 FL
6	1		*FRONT MUDGUARD	Cut	62.00 FL	*62.00 FL
7	2		*FORK ASSY RH & LH	Not Necessary	500.00 FL	*- FL
8	1		*FRONT WHEEL	Not Necessary	200.00 FL	*- FL
9	1		*TAIL COVER (LH)	Cut	65.00 FL	*65.00 FL
10	1		*FOOTREST RUBBER LH & RH	N/S Cut	28.00 FL	*14.00 FL
11	1		*REAR FOOTREST (LH)	Cut	38.00 FL	*38.00 FL
12	1		*REAR FOOTREST BRACKET (RH)	Not Necessary	75.00 FL	*- FL
13	1		*SEAT BAR	Not Necessary	65.00 FL	*- FL
14	1		*GIVI BOX BRACKET	Cracked	150.00 FL	*150.00 FL
15	1		*REAR NUMBER PLATE	Bent	20.00 FL	*20.00 FL
16	1		*EXHAUST PIPE	Repair	330.00 FL	*- FL
17	1		*EXHAUST CHROM COVER	Dented	96.00 FL	*96.00 FL
18	1		*FRONT COWLING (RH)	Not Necessary	75.00 FL	*- FL
19	1		*REAR DISC PAD	Not Necessary	135.00 FL	*- FL
20	1		*REAR WHEEL ASSY	Not Necessary	220.00 FL	*- FL
21	1		*SWIM ARM ASSY	Not Necessary	390.00 FL	*- FL
22	1		*REAR ASOBER	Not Necessary	180.00 FL	*- FL
23	1		*REAR MUDGUARD	Deformed	65.00 FL	*65.00 FL
24	1		*SIDE STAND	Not Necessary	48.00 FL	*- FL
25	1		*ERP IU UNIT	Cut	160.00 FS	*160.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,239.00	891.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	307.90	73.10
Total Parts (\$\$)	2,931.10	817.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	250.00	250.00
2	CHASSISC REPAIR	New	250.00	0.00
Gross Labour Cost (S\$)			500.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >