

Summary no/cus.

REF:

CS/72 18018714/UVbn2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SBW 16197

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A 735ff

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SBW 16197

Yr Regn:

10 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Topla Previa AERAS 2362

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

22385

T/Radio:

Insured / Std / NI / NA

Eng/No:

Q/No:

JTEGDS6M707149194

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/10/18

D.O.I.

16/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/10/18 MUC 71A 2/5 # 4250

(Red 5844.20, 57b)

RECEIVED 31 OCT 2018

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time File Return to?

2) 31/10- typist

Report Format:

TP

Lump Sum / I.B.I. (\$

4250b

Days Of Repair:

6

Resurvey No. of Trip:

1+1

Survey Fee

Transportation

1. S + R + S

1. Photos

1. Other

TOTAL

170

50

50+50

57

80

457

Ref. No :	CS/TP 18018714/Uvb ⁷²		Res. Date:	17/10/18	Date Received:	
Veh. No :	SBW1619P		SP:		WKSP:	BW
C/No :						
Action/Instruction:						
1.File	2.Submit Photo?	YES / NO		Message:		
3.Indicate Res. Date On Photo Page?	YES / NO					
If No, due to	a) No authorisation	b) Days of repair				
others:						
Final Re-inspection or Progress Photos					Inspected By:	

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0791A
Vehicle Details	
Vehicle No.:	SBW1619P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PREVIA AERAS 2.4 CVT MR
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2AZ4A86075
Chassis No.:	JTEGD56M707149194
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$34,489.00
Original Registration Date:	23 Oct 2017
First Registration Date:	23 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$40,285.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2027
PARF Rebate Amount:	\$30,213.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$43,375.00
Total Rebate Amount:	\$73,588.00

The information contained herein is correct as at 16 Oct 2018

OK

MSNIC18132201 / SME Motor Pro Ltd - Kuli Bukit
ENTRY DATE & TIME: 11/10/2018 16:46
SUBMITTED BY: Chio Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available stored.

ACCIDENT STATEMENT

Date Of Report 11/10/2018 16:46
Date Of Accident 10/10/2018 14:20
Exact Location Of Accident JALAN BUKIT MERAH
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBW1619P
Insured/Policyholder
Name Of Registered Owner DERRICK NICHOLAS GOH TZAN-HAN
NRIC No S7310791A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97991619
Alternative Phone No OFFICE-97991619
Vehicle Particulars
Manufacturer TOYOTA
Model PREVIA
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number P2012866
Cover Note Number
Driver
Name of Driver DERRICK NICHOLAS GOH TZAN-HAN
NRIC No S7310791A
Date Of Birth 26/03/1973
Occupation INDOOR
Date Of Driving Pass 17/04/1993
Driving Experience 25 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97991619
Fax Number
Contact Number OFFICE-97991619
Email Address NOEMAIL

Address BLK 116C JALAN MEMBINA #29-113
 Postcode 163118
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 10/10/2018 AT ABOUT 2.20PM, I STOPPED MY CAR A ALONG JALAN BUKIT MERAH WAITING FOR TRAFFIC LIGHT TO TURN GREEN. ABOUT FEW SECONDS LATER, CAR B CAME AND HIT THE REAR OF MY CAR A.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJH2304A
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver LIM SHI YIN
 NRIC/Passport Number S8022162B
 Contact Number 81611714
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name DERRICK NICHOLAS GOH TZAN-HAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SBW1619P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 11/10/18, 1500pm

Driver's Signature

(If driver is not the policyholder)


Date & Time: 11/10/18, 1500pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/10/18 at about 2:20pm, I stopped my car (A) along Jalan Bukit Merah waiting for traffic light to turn green. About few seconds later, car (B) came and hit the rear of my car (A).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 11/10/18, 150pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 11/10/18, 150pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GLA/RMG SketchPlanForm_V3

2



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

not Allowed
 alone
 n/s \$4250
 6th.

SBW1619P

	Tailgate	R	1599.10	X
	Tailgate Rear logo	ner	68.10	✓
	Tailgate 'previa' emblem	ner	91.70	✓
	Tailgate inner lock	n1	409.10	X
	Tailgate weatherstrip	ner	302.30	✓
	Rear bumper	no/or	688.10	✓
2pcs	Rear bumper side holders @ 98.10	Best	196.20	✓
1set	Rear bumper clips	ner	60.20	✓
2pcs	Rear bumper PDC sensors @ 315.00	shook	630.00	✓
	Rear 'Toyota' emblem	ner	72.10	✓
	Rear end panel	no	987.20	✓
	Rear end panel top garnish	nw	378.20	✓
	Rear floor panel	R	1025.10	X
			6564.20	
				3530.9
	S. Work			
	Rear bumper top chrome moulding	set	450.00	S.N
	To check wiring		80.00	20
	To dismantle & replacing PDC sensor		100.00	50
	To dismantle & refix seat, cushion upholstery		120.00	100
	To spray rust proofing		80.00	50
	labour for sand beating & replacing parts		1200.00	1000
	To partly & spray painting		1500.00	1000
			TOTAL	10094.20

LKR Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

5318.17

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18018714/Uvbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 01-11-2018

ON BEHALF OF DERRICK NICHOLAS GOH TZAN-
HAN

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SBW 1619P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	16/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PREVIA AERAS (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTEGD56M707149194	Colour	SILVER
Odometer	22395	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/10/2018	Inspection Date	16/10/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBW 1619P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	TO REPAIR SEE LABOUR	1,599.10	-
1	TAILGATE REAR LOGO	NECESSARY	68.10	68.10
1	TAILGATE "PREVIA" EMBLEM	NECESSARY	91.70	91.70
1	TAILGATE INNER LOCK	NOT NECESSARY	409.10	-
1	TAILGATE WEATHERSTRIP	NECESSARY	362.30	362.30
1	REAR BUMPER	DENTED / DEFORMED	685.10	685.10
2	REAR BUMPER SIDE HOLDERS @\$98.10	BENT	196.20	196.20
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
2	REAR BUMPER PDC SENSORS @\$315.00	SHORTED	630.00	630.00
1	REAR "TOYOTA" EMBLEM	NECESSARY	72.10	72.10
1	REAR END PANEL	DENTED	987.20	987.20
1	REAR END PANEL TOP GARNISH	TWISTED	378.20	378.20
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,025.10	-
	LESS 25% DISCOUNT		-	-882.73
			6,564.20	2,648.17
SPECIAL NETT ITEMS				
1	REAR BUMPER TOP CHROME MOULDING (SN)	BENT	450.00	450.00
			450.00	450.00
LABOUR				
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACING PDC SENSOR.		100.00	50.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	100.00
	TO SPRAY RUST PROOFING.		80.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR FLOOR PANEL.		1,200.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,080.00	2,220.00
GRAND TOTAL			10,094.20	5,318.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CS/TP18018714/Uvbn2



Report Ref No. CS/TP18018714/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.