

22/03/2002

ASS. REC. BY:

REF: CS3/AIG18018732/Gcd3^{sr} Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person): chin lee ying of AIG Date/Time: 16/10/18 @ 11:36 am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGX 7234L Insured: SJK 726SE

at Workshop m/s Green star Spray Painting Tel: 6546 3092

of Blk 3011, Bedok North Ave 4 #01-2004

Policy No: 1800019281 Claim No: 4765774934SG

Sum Insured: Excess:

Make of Veh: D.O.A. 11/10/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 12:04pm @ 16/10/18 Person Contacted: Debbie Vehicle: IN / OUT

Date/Time	Action/Instruction (x) Estimate
	SGX 7234L -x
	SJK 726SE -x
	Disassemble: 23/10/2018

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 16/10/2018 11:36:58 AM
Attachments:  SGX 7234L GIA REPORT.PDF  SGX 7234L PRI.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Sales-GreenStarSP [mailto:sales@greenstarsp.com]
Sent: Monday, October 15, 2018 1:56 PM
To: Azlan, Syazairdina
Subject: FW: REF: ACCIDENT INVOLVING YOUR REF: SJK 7265E & OUR REF: SGX 7234L DOA : 11.10.2018 1810HOURS

Without Estimate

Dear Sirs,

Please find the attached GIA report and PRI letter for your attention and further action.
To avoid delay, please let us know if you want to conduct the pre-repair inspection within 2 working days.

Thank you and looking forward to your prompt response.

Kind Regards,

DEBBIE
GREEN STAR SPRAY PAINTING
Blk 3011 Bedok North Ave 4

#01-2004 Bedok Ind Park E Singapore 489977

Tel: +6546 3092 | Fax: 6545 2066 | Website: www.greenstarsp.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

15.10.18

Attn: Motor claims Department

To: Defendant's Insurers AIG ASIA PACIFIC INSURANCE PTE LTD

Address

BY FAX & POST

Dear Sir

We are instructed by (name of claimant) to notify you of a road traffic accident on (date) at about (time) at (place of accident which must be sufficiently detailed to establish location) involving our client's vehicle registration number (SGX 7234L) and vehicle registration number (SSK 7263E insured by you at the material time. A copy of the Singapore Accident Statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Green Star Spray Painting

Tel: 6546 3092

Bik 3011 Bedok North Ave 4

Fax : 6545 2066

01-2004 Bedok Industrial Park E

Email : sales @ greenstarsp.com.

Singapore 489977

Enc

Cc 1. Defendant's name

Address

2. *Other Defendant and his insurers*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/10/2018 10:47
Date Of Accident	11/10/2018 18:10
Exact Location Of Accident	BASEMENT CARPARK EXIT OF CHANGI HOSPITAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX7234L
Insured/Policyholder	
Name Of Registered Owner	NUR HIDAWATI BINTE RAHMAN
NRIC No	S8408812I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91871733
Alternative Phone No	OFFICE-91871733
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER-1.5 MIVEC SPORTS AT ABS D/AB (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA258256
Cover Note Number	
Driver	
Name of Driver	MOHAMAD FAZLI BIN RAHMAT
NRIC No	S8108583H
Date Of Birth	18/03/1981
Occupation	INDOOR
Date Of Driving Pass	30/06/2008
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90270704
Fax Number	
Contact Number	
E-Mail Address	ZECK_CIS@YAHOO.COM

Address	BLK 281B SENGKANG EAST AVENUE #15-601
Postcode	542281
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NUR ADILA GENDER: : FEMALE
Passenger 2	NAME: : DIAN AUN GENDER: : FEMALE
Passenger 3	NAME: : DIAN ADNI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE CAR CARE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK7265E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MENG QIUSHA
NRIC/Passport Number	S77747071
Contact Number	88768156

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please read carefully the content of the attached to complete the police process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Specialist provided must be as truthful and accurate as possible. Any willful misrepresentation will result in material being withheld from your insurer to renewate policy liability.
4. The Police Investigation of the Police Insurance Office does not constitute an admission of liability or acceptance of responsibility on the part of the insured.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the 24 Hour Roadside Help Unit and forwarded to the relevant Roadside Assistance of Singapore (PRA) for monitoring and that report of the road side unit may be made available upon request by interested parties.
7. A copy of the report is the insured's and shall be kept as the evidence of the report at the police and 12 copies of the report being made available to the insured.
8. Consent under the Personal Data Protection Act (PDPA)

I hereby state, acknowledge, agree and consent that:

- a) My insurer, my workplace and the General Insurance Association of Singapore (GIAS) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or requested by my insurer collectively the "Personal Information" and database and I understand that Personal Information is all personal and legal information related to the accident (other persons who have interest in the accident) involved in the accident shall be collected referred to as the "Insurers", the insurers' lawyers/law firms, the Motor Insurance Association of Singapore and any relevant government agencies, authorities (such as the police, fire, the companies), etc.
- b) processing, handling and/or dealing with my claim including the submission of the claim and any necessary investigation relating to the claim;
- c) investigating the accident and/or my claim;
- d) processing and/or dealing with my instructions or responding to any enquiries by me;
- e) determining my claim (including the making of any necessary statements, records, reports or notices to me, which might involve disclosure of certain personal data and/or to bring to my delivery of the notice, and/or the collection of which can find background checks;
- f) complying with applicable laws, including my compliance with filing and/or dealing with my claim, to facilitate the "Process";
- g) all insurers who have claims involved in this accident and the insurer's lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
- h) my Personal Information may/ will be disclosed by me, if the insurers and/or law to their third party service providers or agents including their lawyers/law firms, which may be their outside of Singapore, for one or more of the above Purpose(s);
- i) my Personal Information will also be collected and used by my legal claim history for the purpose of legal dispute investigation and management in present and all future claim;
- j) the information collected under this form, by insurers' collected:
- k) to be used by and/or my other third parties that assist in settling my investigation, processing or management of my claim; the insurer and government agencies or regulatory authorities, the insurers' lawyers/law firms;
- l) my insurer may, with my consent, disclose my Personal Information to the relevant authorities.

Policyholder's Signature
(Date & Time)

Insurer's Signature
(Date & Time)

Resolving Third Party's Signature
(Date & Time)

Sketch Plan #2

SKETCH PLAN

	Vehicle A - 25x7200 B - 33x2210
	Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

was at stoplight behind vehicle 'B' at Chicago hospital exit of ramp when suddenly vehicle 'B' roll back and hit the back of my front car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurance policy has a fourteen (14) day time limit to report an accident to your insurance company. Failure to report an accident within this time limit may result in your policy being voided.

Policyholder's Signature
 Date & Time

Driver's Signature
 (if driver is not the policyholder)
 Date & Time

Reporting Service Personnel's Signature
 Name
 NRIC/IN No.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	88121

Vehicle Details

Vehicle No.:	SGX7234L
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS SPORTS 4A/T SR
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	4A910040204
Chassis No.:	JMYSRCY2A8U000272
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,161.00
Original Registration Date:	04 Sep 2007
First Registration Date:	04 Sep 2007
Transfer Count:	1
Actual ARF Paid:	\$17,778.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	03 Sep 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,041.00
COE Rebate Amount:	\$17,029.00
Total Rebate Amount:	\$17,029.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Oct 2018

Owned The Car For The Last 6 Years. WhatsApp For Viewing Appt. Con...

Office No. - 66028046

Prem Roy - 84684000

Mitsubishi Lancer 1.6A GLX \$20,900 \$6,820 /yr 15-Nov-2006 1,584 cc - SG Car Consign Pte Ltd Availal
(COE till 11/2021)

Look No Further, Best Value For Your Money. Direct Owner's Black, Nov 2009 Lancer 1.6 A With Black Leather Upholstery. Selling Due To Upgrading To New Car. Original Paintwork Condition, Genuine Mileag...

Office No. - 61000200

Danny Loh - 97622873 | Andy Tay - 94891030 | Joey Kwan - 87158050 | Bryan Tan - 91795745

Mitsubishi Lancer 1.6A GLX \$26,800 \$7,640 /yr 27-Apr-2007 1,584 cc 116,275 km Tim Bock Enterprise Availal
(COE till 04/2022)

New 6 Months Road Tax! Up To 90% Loan. 1 Owner. Beautiful Condition. Well Kept. Don't Miss, Call Now To Arrange A Test Drive Today!

Office No. - 64595611

Richard - 98197977 | Raymond - 91596282

Mitsubishi Lancer 1.6A (COE \$24,800 \$6,970 /yr 14-May-2007 1,584 cc - FredLink Auto Trading Availal
till 05/2022)

Just Arrived! Well Maintained By Previous Owner. High Loan With High Trade In. Price Negotiable. Call Now!

Office No. - 67788997 / 67788995

Daniel Loh - 83938889 | Mohammad - 81121493 | Vincent Tan - 96710179 | Mr LEE - 96923373

Mitsubishi Lancer 1.6A GLX \$22,800 \$6,410 /yr 15-May-2007 1,584 cc 137,000 km Carway Availal
Sports (COE till 05/2022)

100% Loan Avail! \$690 Low Monthly Installment, Bank/In House Loan Available, "One Year In House Warranty!" With Official Warranty Certificate (Peace Of Mind), Fully Refurbished, New Paintwork, Acciden...

Office No. - 68440777

Addy Ho - 88330777 | Peter Quek - 84840777 | Melvin Phua - 86865777

Mitsubishi Lancer 1.6A GLX \$25,000 \$7,020 /yr 15-May-2007 1,584 cc - Availal
(COE till 05/2022)

Mitsubishi Lancer GLX (CS3), Reg: May 2007, COE Renew: May 2022, Balance: 4 Years, Selling At \$25,000, Down Payment Only \$8,100, 70% Loan Remaining, Depreciation: \$6,750, Free Road Tax Till Nov 18, It...

Office No. - -

Jeremy - 90685052

Mitsubishi Lancer 1.6A GLX \$20,500 \$5,640 /yr 11-Jun-2007 1,584 cc 78,000 km D&L Auto Trading Availal
(COE till 06/2022)

100% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex-Bankruptcy, 100% Guaranteed Accident Free, Guaranteed Genuine Low Mileage 78,000KM, Only 1 Owner! Extreme Well Maintained, Guaranteed Superb Condi...

Office No. - 62960188

Darren Low - 96236322

Mitsubishi Lancer 1.6A GLX \$26,800 \$7,300 /yr 25-Jun-2007 1,584 cc - Car Guru.Com Pte Ltd Availal
(COE till 06/2022)

100% Loan Guaranteed Approval! All Our Cars Have Undergone A Workshop Check. Buy With Trust And Assurance! Expect Only Honest Dea Call Our Friendly Sales Staff For A Non Obligatory Viewing Now!

Office No. - 67639595

Lawrence - 92228747 | Jimmy - 90079944

Mitsubishi Lancer EX 1.5A \$23,800 \$6,250 /yr 13-Aug-2007 1,499 cc - Boeki Auto & Marine Availal
GLS (COE till 08/2022)

High Loan And Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Office No. - 65549390

Boeki - 82180500

Mitsubishi Lancer EX 2.0M GT \$28,888 \$7,540 /yr 23-Aug-2007 1,998 cc - Roadlink Auto Pte Ltd Availal
(COE till 08/2022)

API Coilover, Carbon Fibre Bonnet And Boot, Throttle Control, Defi Meter, HKS Power Charger, Upgraded Subwoofer AMP And HKS Exhaust V Cert. No Expenses Spared For Preventive Maintenance And Always ...

Office No. - 66360538

Colin Lim - 82255588

Mitsubishi Lancer EX 2.0A GT \$23,800 \$6,920 /yr 11-Sep-2007 1,998 cc 152,678 km Car Search **Availal**
Sunroof (COE till 03/2022)

Up To 90% Loan! Car Converted To GRAB, But Seldom Drive So Low Mileage! Flexible Loan Scheme Available! Trade In Welcome! Consignm Unit, Call For Appointment Now!

Office No. - 62620728

Charles - 94527972 | Rachel - 91126538 | Justin - 91827511 | Kelvin - 97593539

Mitsubishi Lancer 1.6M GLX \$26,000 \$6,590 /yr 04-Oct-2007 1,584 cc - **Availal**
(COE till 10/2022)

Evo 3 Brakes, D1 Spec Coilover, XXR Rims With Re003, Engine Strut Bar, Boot Bar, Double Din Conversion, Buck Et Seat, Nardi Steering, Grc Shades Curtain, Etc. Price Nego For Sincere Buyers.

Office No. - -

Jonathan - 90909480

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD		
1005	992341	Frt Bumper Clips	NEC		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS		
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRA		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA		
1022	991328	Frt Grille Emblem	NEC		
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT R		
1026	992025	Frt Support Panel Top Garnish Cover	DIS		
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	CRA		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: **SGX 7234L**

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Author:

John
31/10/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018 Edit Reg		16 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	ZOU DONGJIE, ID: S6979540D		
Main Claimant:	NUR HIDAWATI BINTE RAHMAN, ID: S8408812I		
Vehicle Reg. No.:	SGX7234L	Date of Loss:	11/10/2018 00:00 - :59 [133 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4765774934SG	Policy/Cover Note No.:	1800019281 (Comprehensive)
Vehicle Reg. No. (Insured):	SJK7265E	Policy No. (Claimant):	
		Excess:	
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaljye.Wui@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/10/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (17/10/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS



































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SGX7234L (4765774934SG)**
[SJK7265E]
TP
NUR HIDAWATI BINTE RAHMAN
Oct 11 2018 12:00AM
[ZOU DONGJIE]
GREEN STAR SPRAY PAINTING

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/10/18 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	24/10/18 12:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	24/10/18 12:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	24/10/18 12:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	24/10/18 12:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	24/10/18 12:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	24/10/18 12:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	24/10/18 12:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	24/10/18 12:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/10/18 14:02	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18018732/GCD3S2
Date: 05/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800019281
Claimant Vehicle No: SGX7234L Insured Vehicle No: SJK7265E
Date of Loss: 11/10/2018 Nature of Claim: TP Claim No: 4765774934SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGX7234L**
Make & Model: MITSUBISHI LANCER, 1.5 MIVEC SPORTS AT ABS D/AB (A) Engine No: 4A910040204
Reg. Date: 04/09/2007 (Man. Year: 2007) Chassis No: JMYSRCY2A8U000272
Colour: Red Odometer: 185578 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50R17 Rear Tyre Size: 215/50R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/10/2018
Date Inspected: 22/10/2018 Inspected At: GREEN STAR SPRAY PAINTING (HQ)
BLK 3011 BEDOK NORTH AVENUE 4 #01-2004
BEDOK INDUSTRIAL PARK E
Singapore 489977
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
4	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
5	1		*FRT GRILLE	Cracked	0.00 F	*- F
6	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
7	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
8	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Distorted	0.00 F	*- F
9	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >