

Veron Chen (LKKAuto)

From: glory.tan@premiumauto.com.sg
Sent: Wednesday, 7 November 2018 4:35 PM
To: SUR
Cc: Adrian Ling (LKKAuto); claims@premiumauto.com.sg
Subject: Check item photos for SCA 818 S
Attachments: WhatsApp Image 2018-11-07 at 1.58.54 PM (1).jpeg; WhatsApp Image 2018-11-07 at 1.58.54 PM (2).jpeg; WhatsApp Image 2018-11-07 at 1.58.54 PM.jpeg; WhatsApp Image 2018-11-07 at 1.58.55 PM (1).jpeg; WhatsApp Image 2018-11-07 at 1.58.55 PM.jpeg; WhatsApp Image 2018-11-07 at 1.58.56 PM (1).jpeg; WhatsApp Image 2018-11-07 at 1.58.56 PM (2).jpeg; WhatsApp Image 2018-11-07 at 1.58.56 PM.jpeg; WhatsApp Image 2018-11-07 at 1.58.57 PM (1).jpeg; WhatsApp Image 2018-11-07 at 1.58.57 PM (2).jpeg; WhatsApp Image 2018-11-07 at 1.58.57 PM.jpeg; WhatsApp Image 2018-11-07 at 1.58.58 PM (1).jpeg; WhatsApp Image 2018-11-07 at 1.58.58 PM (2).jpeg; WhatsApp Image 2018-11-07 at 1.58.58 PM.jpeg; WhatsApp Image 2018-11-07 at 1.58.59 PM (1).jpeg; WhatsApp Image 2018-11-07 at 1.58.59 PM.jpeg

Hi all,

Please refer attached for check item photos. Thank you.

- 1) Bracket lock carrier
- 2) RHS front fender closing element
- 3) RHS front fender bracket
- 4) RHS front fender brace
- 5) 1 set of attachment parts for wheel housing liner
- 6) RHS front fender top cover(short)
- 7) RHS lift cylinder

Best Regards,
Glory Tan.