

22/03/2002

ASS. REC. BY:

REF: CS/FCI180187521 Uqdzl Special Instruction:

Survivor:

MS

ASSIGNMENT (Office)

From (Person): Sithara of FCI Date/Time: 15/10/18 @ 6:40pm

Estimated Cost: Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGX 82D Insured: SHC 0723L

at Workshop m/s: Tring Eun Kar's Tel: 8128 9802

of 12 Sungai Kodut Ave

Policy No: 0-18088937MFSH Claim No: D18007079MFSH

Sum Insured: Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/09/2018

18/10/18 @ 5 ubi close

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:39am @ 16/10/18 Person Contacted: JCS

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGX 82D - X
19/10/18 @ 3:53pm	SHC 0723L - NS/INC/18018299/Klob revised to Sithara by email.

D.O.A. 7/10/2018

REF: FCI

ASSIGNMENT

From: _____ Date: 18/10/2018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SGX 82D
at Workshop m/s Trans Eurokars
of S ubi Close

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Jess

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGX 82D Yr Regn: 418

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda 6 C.C. 1998

Colour: 3200 A/C: Insured / Std / NI / NA

Sp. Reading: 9446 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM66L1071J0137318

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55-24

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/9/18 D.O.I. 18/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/12/18 vehicle hasn't send on for rep-

RECEIVED 19 DEC 2018

Date/Time, File Pass to?

1) 19/12 11:00 AM

Date/Time, File Return to?

2) _____

☒ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 170

Transportation: 50

) \$ + RS, \$ SI

) Photos

) Others

TOTAL

247

Report Format: _____

Lump Sum / I.B.I. (\$) _____

MOTOR SURVEY ASSIGNMENT

Date	27-09-2018	Our Ref No. D18007079MFSH
Accident Date	25-09-2018	Claim Type. Third Party
Insured Vehicle	SHC0723L	Third Party Vehicle. SGX82D
Survey Location	EUROKARS CENTRE 12 SUNGEI KADUT AVE	
Contact Person.	JESS FRANCIS CARLOS	
Contact No.	81289802/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244542)



PRI Documents



Close



PRI Header Details

Claim No	D18007079MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS EL
Workshop Name	TRANS EUOKARS PTE LTD (Contact Person : JESS FRANCIS CARLOS)	Survey Location & Contact Details	EUOKARS CENTRE 12 SUNGEI KADUT AVE Mobile: 0 , Phone: 81289802 , Fax: 0 EmailId: JESS.FRANCIS@EUOKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0723L	TP Vehicle No	SGX82D
PRI Recieved Date	15-10-2018 07:05:55 PM	Surveyor Appointed Date	15-10-2018 06:39:22 PM	Surveyor Accept Date	16-10-2018 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	16-10-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 19 October 2018 3:53 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007079MFSH/1
Attachments: CSFCI18018752Uqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SGX 82D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 16 October 2018 10:25 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007079MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 18/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 15 October 2018 6:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007079MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007079MFSH

Date: 19 October 2018

Our Ref: CS/FCI18018752/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGX 82D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/10/2018 at the premises of M/s TRANS EUROKARS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,591.75</u> .
Revised Estimate Amount	: S\$ <u>4,029.85</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the n/s rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4583A
Vehicle Details	
Vehicle No.:	SGX82D
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT STANDARD EU6
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	PE21042953
Chassis No.:	JM6GL1071J0137318
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$17,096.00
Original Registration Date:	03 Apr 2018
First Registration Date:	03 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$17,096.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Apr 2028
PARF Rebate Amount:	\$12,822.00
Intended COE Rebate Details	
COE Expiry Date:	02 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,903.00
COE Rebate Amount:	\$37,736.00
Total Rebate Amount:	\$50,558.00

The information contained herein is correct as at 18 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2018 08:16
Date Of Accident	25/09/2018 19:20
Exact Location Of Accident	MARINE PARADE ROAD OUTSIDE PARKWAY PARADE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX82D
Insured/Policyholder	
Name Of Registered Owner	FOO HOE NAN
NRIC No	S7914583A
Email Address	HOENANFOO@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96576014
Alternative Phone No	OTHERS-96576014

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800043167
Cover Note Number	

Driver

Name of Driver	FOO HOE NAN
NRIC No	S7914583A
Date Of Birth	21/05/1979
Occupation	INDOOR
Date Of Driving Pass	21/09/1999
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96576014
Fax Number	
Contact Number	OTHERS-96576014
Email Address	HOENANFOO@HOTMAIL.COM

Address	36B JALAN EUNOS
Postcode	419499
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : FOO RUI XIN CHARLENE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC723L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	OOI CHEE TEONG
NRIC/Passport Number	S2570837G
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	FOO HOE NAN
Approximate Age	39
Injuries Sustain	SEE POLICE REPORT
Injured person in which vehicle?	SGX82D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NEIC/ID No.:

LA001602, SketchPlan Form V.1

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Travelling along Marine Parade Road (on the middle lane). This is a straight road with 3 lanes. Mentioned vehicle exiting from Parkway Parade and came into contact with left rear portion of SGX82D.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Regulating Officer's Signature
Name:
NRIC/ID No.:

GAMVIC Sketchplan page 1/1

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20180926/2073

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180926/2073

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/09/2018 13:16		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: FOO HOE NAN			Address: APT BLK 36B JALAN EUNOS SINGAPORE 419499		
ID Type / ID No.: NRIC NO / S7914583A			Contact No.: Home/Office: Mobile: 96576014		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 21/05/1979	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: BANK OFFICER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 25/09/2018 19:20	Type of Location: Straight Road
Location: Along Road 1 MARINE PARADE ROAD OUTSIDE PARKWAY PARADE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGX82D	Car	MAZDA	MAZDA6 SEDAN 2.0 AT STANDARD EU6	Black	Slightly Damaged	1
SHC723L	Car	HYUNDAI	I40 1.7L CRDI AT ABS AIRBAG 4DR	Yellow	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180926/2073

2 of 3

Report No. T/20180926/2073

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGX82D	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800043167	03/04/2018	02/04/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL			
Driver		Use of Pedestrian Crossing: NA	
Name	FOO HOE NAN	ID No.	S7914583A
Related Vehicle	SGX82D (Car)	Contact No.	96576014
Hospital/Clinic	THE BALMORAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	26/09/2018	Date Discharge	NIL
No. of Days granted Medical Leave	06	Degree of Injury	Slight

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION I WAS TRAVELLING ALONG THE SAID LOCATION. THIS IS A STRAIGHT ROAD WITH 3 LANES. I WAS ON THE MIDDLE LANE. THE MENTIONED VEHICLE EXITED FROM PARKWAY PARADE. HIS FRONT PORTION OF THE VEHICLE THEN CAME INTO CONTACT WITH THE REAR LEFT PORTION OF MY VEHICLE. AFTERWHICH WE STOP AND GOT OFF TO ASSESS THE SITUATION. FIRST OF ALL, WE EXCHANGE OUR PARTICULARS. THE SITUATION WAS STILL NORMAL AT THAT MOMENT. IT WAS ONLY AS HE WENT BACK INTO HIS VEHICLE, HE STARTED SWEARING AND CURSING AT ME. UPON HEARING THOSE, I WENT BACK TO HIS VEHICLE AND PROMPT HIM TO REPEAT WHAT HE JUST SAID. HOWEVER, HE USE THE VEHICLE'S DOOR TO HIT AGAINST ME. I THEN TOOK OUT MY PHONE AND STARTED TO TAKE VIDEO OF HIM. UPON NOTICING IT, HE QUIETLY WENT BACK TO HIS VEHICLE AND START TO TAKE OFF. AS MY VEHICLE WAS INFRONT OF HIS, I HAD TO WALK BACK TO THE FRONT. HE THEN DELIBERATELY DRIVE WITH THE INTENT TO CAUSE INJURY TO ME. HIS VEHICLE CAME INTO CONTACT WITH MY LEFT LEG. I WENT CONSULT A DOCTOR AS MY LEFT LEG AND LOWER BACK ARE STARTING TO FEEL PAINFUL.

HIS PARTICULARS ARE AS FOLLOWS:
NAME: OOI CHEE TEONG
IC: S2570837G

Sketch Plan Pg. 5



SINGAPORE
POLICE FORCE



T/20180926/2073

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180926/2073

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
NG JIN SHENG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
26/09/2018 13:16

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt ONG YONG HOCK
Contact No.: 65476436



Classification Of Case:
SINGAPORE
POLICE FORCE

Authentication Stamp
NP168

Signature:



CERTIFICATE OF INSURANCE

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : FOO HOE NAN (FU HENAN)
Period of Insurance : 03 Apr 2018 To 02 Apr 2020
Engine No. : PE21042953
Chassis No. : JM6GL1071J0137318

Vehicle No. : SGX82D
Policy No. : 1800043167
Endorsement No. :
Issued Date : 20 Apr 2018

ABOUT THE COVER

Make/Model : MAZDA 6 2.0 SKYACTIV
Engine Capacity/Tonnage : 1,998.0C CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Concition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Foo Hoe Nan (Fu Henan) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Trans Eurokars Pte Ltd Add: 5 Ubi Close, Singapore 408605 63958899

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 169), Part I of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

0503599190


ARF (AP) PTE LTD - MAZDA
7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX
SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7914583A






Name
FOO HOE NAN
(FU HENAN)
符和南

Race
CHINESE

Date of birth
21-05-1979

Sex
M

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S7914583A

NAME FOO HOE NAN

DATE OF BIRTH 21 May 1979

EXPIRY DATE 10 Sep 2009




000818997J

4444698



NRIC No. S7914583A



Date of issue
12-08-2009

38B JALAN EUNOS
SINGAPORE 419499

NRIC No: S7914683A Date: 07/01/2018


YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE 21 Sep 1999

NP 428A

Licence No: S7914583A





TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



(UB)

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Foo Hoe Nan ADDRESS : 36B Jalan Eunus Singapore 419499 TEL : 96576014		WIP : 30025 EXCESS : DATE: 27-Sep-18	
VEH NO :	SGX82D	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6GL1071J0137318	MILEAGE :		TYPE OF CLAIM :	3RD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	3-Apr-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJR9-50-221ABB	R	\$ 1,172.80
2	RETAINER LHS	1	MGJR9-50-2J1	11	\$ 39.00
3	BRACKET CENTER	1	MKD53-50-251	11	\$ 5.10
4	GROMMET, REAR BUMPER	4	MBHN1-50-021A	11	\$ 10.00
5	CLIP, REAR BUMPER	4	MC274-50-133	11	\$ 14.00
6	GROMMET, REAR BUMPER	2	M9991-00-501	11	\$ 5.60
7	FASTENER, REAR BUMPER	6	MB45A-56-146A	11	\$ 16.80
8	REAR DOOR LHS	1	MGHY1-73-02XB	R	\$ 1,249.60
9	FASTENER, REAR DOOR	1	MGHP9-58-762A	11	\$ 3.00
10	FASTENER, REAR DOOR	1	MGHP9-73-762	11	\$ 11.70
11	FASTENER, REAR DOOR	1	MBBM6-58-762	11	\$ 3.00
12	CLIP, REAR DOOR	1	MGS1D-58-315A	11	\$ 2.20
13	GROMMET, REAR BUMPER	1	M9991-00-503	11	\$ 3.60
14	FASTENER, REAR DOOR	1	MGD7A-50-EA1	11	\$ 3.00
15	GROMMET, REAR BUMPER	7	MGJ6A-58-975	11	\$ 19.60
16	GROMMET, SPEAKER	7	MGJ6A-58-975	11	\$ 19.60
17	CLIP, DOOR GARNISH	8	MKD53-50-M38	11	\$ 93.60
18	CLIP, DOOR GARNISH	3	MTD11-51-SJ3A	11	\$ 34.20
19	GUARD STONE LHS	1	MGHP9-50-4R2A	11	\$ 16.50
20	REAR WHEEL RIM LHS	1	M9965-07-7570	R	\$ 1,277.10
21	REAR BEARING LHS	1	MKD31-26-15XA	11	\$ 457.50
TOTAL PARTS					\$ 4,457.50
LESS 10%					\$ 445.75
TOTAL PARTS COST					\$ 4,011.75
Labour Description					
1	MZ-BR-FRONT1	TO REPLACE REAR BUMPER, REAR DOOR LH. TO REPAIR REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.			1260 \$ 1,890.00

2	MZ-SP-SFRT01	TO RESPRAY REAR BUMPER, REAR FENDER LH AND REAR DOOR LH.		\$ 1,800.00
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	11	\$ 630.00
4	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.	11	\$ 630.00
5	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	11	NETT \$ 120.00
6	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		NETT \$ 560.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	50	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
10	MZ-BR-SUNDRI	SUNDRIES.	net 20	NETT \$ 100.00
			TOTAL LABOUR	\$ - \$ 6,580.00
			TOTAL PARTS	\$ - \$ 4,011.75
			TOTAL	\$ - \$ 10,591.75
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

not Authorized
LKK
Take photo After repair
18/10/18
5 day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18018752/Uqd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 723L	Veh. Inspected	SGX 82D	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18007079MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	15/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JM6GL1071J0137318	Colour	BLACK	
Odometer	9446	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/09/2018	Inspection Date	18/10/2018	
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 82D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,172.80	-
1	RETAINER LHS	NOT NECESSARY	39.00	-
1	BRACKET CENTER	NOT NECESSARY	5.10	-
4	GROMMET, REAR BUMPER	NECESSARY	10.00	10.00
4	CLIP, REAR BUMPER	NECESSARY	14.00	14.00
2	GROMMET, REAR BUMPER	NECESSARY	5.60	5.60
6	FASTENER, REAR BUMPER	NECESSARY	16.80	16.80
1	REAR DOOR LHS	TO REPAIR SEE LABOUR	1,249.60	-
1	FASTENER, REAR DOOR	NOT NECESSARY	3.00	-
1	FASTENER, REAR DOOR	NOT NECESSARY	11.70	-
1	FASTENER, REAR DOOR	NOT NECESSARY	3.00	-
1	CLIP, REAR DOOR	NOT NECESSARY	2.20	-
1	GROMMET, REAR BUMPER	NECESSARY	3.60	3.60
1	FASTENER, REAR DOOR	NOT NECESSARY	3.00	-
7	GROMMET, REAR BUMPER	NOT NECESSARY	19.60	-
7	GROMMET, SPEAKER	NOT NECESSARY	19.60	-
8	CLIP, DOOR GARNISH	NOT NECESSARY	93.60	-
3	CLIP, DOOR GARNISH	NOT NECESSARY	34.20	-
1	GUARD STONE LHS	NECESSARY	16.50	16.50
1	REAR WHEEL RIM LHS	TO REPAIR SEE LABOUR	1,277.10	-
1	REAR BEARING LHS	NOT NECESSARY	457.50	-
	LESS 10% DISCOUNT		-445.75	-6.65
			4,011.75	59.85
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00

Report Ref No. CS/FCI18018752/Uqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER, REAR DOOR LH. TO REPAIR REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR DOOR LHS AND REAR WHEEL RIM LHS.		1,890.00	1,260.00
	TO RESPRAY REAR BUMPER, REAR FENDER LH AND REAR DOOR LH.		1,800.00	1,800.00
	TO TRANSFER THE DOOR MECHANISM.	NOT NECESSARY	630.00	-
	TO REPLACE AXLE AND SUSPENSION MECHANISM.	NOT NECESSARY	630.00	-
	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NOT NECESSARY	120.00	-
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		560.00	560.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	50.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			6,480.00	3,970.00
	GRAND TOTAL		10,591.75	4,049.85
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				4,049.85

Report Ref No. CS/FCI18018752/Uqd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.