

INSURANCE

INS. CASE OWNER:

CC 3 / CTI1801 8769, #2763

LKK:

IDAC:

Surveyor:

Kalvin

DOI:

ASSIGNMENT

15/10/18

Date / Time:

15/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEJ 3904P

Name of Insured:

NEO MOH TEK

Insured Tel No.:

HP: 94571193

Excess Sec II :SS

D.O.A: 14/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VA: YES / NO)

Claim No.:

SNM180190600 ✓

Policy No.:

DMPLSN1514971803

Make / Model:

TOYOTA

Place of Accident:

LTE TUNWEN

OI GIA REPORT YES / NO

YES

TP GIA REPORT YES / NO

YES

Insured Liability:

%

Final ? Yes / No

SH 3695



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time:

15/10/18  
20:00

SH 3695-X

SEJ 3904P-X

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call GI:

After call hr to GI: 20:00-11:18

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

X

After call hr to GI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD

X

Payment Breakdown Form:

X

Post-Repair Photos:

X

Others:

X

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

Repair Cost:

\$S

321.24

Loss of Rental (LOR):

\$S

313.20

( 25 days) 125.40

Loss of Use (LOU):

\$S

15

( 5 days)

Loss of Income (LOI):

\$S

125

( 5 days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

\$S

7.49

Medical:

\$S

-

Disbursement:

\$S

-

(e.g. Tow/ Independent)

Legal Cost:

\$S

766.99

Total:

\$S

720.24

Global Sum \$S:

720

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

720.24

Name 1:

COMFORTDELORO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

\$S

-

Name 2:

X

Payee 3: (Strike if N.A.)

\$S

-

Name 3:

X

COPY SENT

1) Claim status: Normal/Reject/Private Settle  
2) Report Format:  
3) Survey fee:

(08/11/13)

Surrey: Kelvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop no: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SH 76915 Yr Regn: 23 Aug 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / T/B / Prime Mover /

Truck / Trailer or

Make: Toyota Prous cc: 1798Colour: Blue A/C: Ins Good / Std / Nil / NASp. Reading: 19 6820 T/Radio: Ins Good / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: JTDKBJFu 4035 63x36Gen. Cond: Good / FB / Poor / BurntSteering: Ign Good / Jammed / Leaked / Burnt orBrake: Inc Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / SD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentlake

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 14/10/18 D.O.I. 15/10/18Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis Frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
22-10-18 P/P	<u>\$300</u>

CTZ  
PIP

R ( \$ 601.50 / 672 )

Date/Time, File Pass to:

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to:

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18018769/K1jb3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-10-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 3904P	Veh. Inspected	SH 7691S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/10/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	14/10/2018	Inspection Date	15/10/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

31 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/CTI18018769/K1jb3

Date: 16.10.2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SH7691S**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.10.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	901.52
Revised Estimate Amount	: S\$	300.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
N/S Front Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser



Member of COMFORTDELGRO

Date/Time: 15.10.2018 13:35

Page : 1

Team: ARC Repair TP(CLS0)1

**JOB CARD**

Sales Order:

JC NO.: 305225854

MEMBER NO. 7010045  
383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755

REGN NO.: SH 7691S	MILEAGE
MAKE: TOYOTA	FUEL E 1/2 F
MODEL: PRIUS HYBRID(G4)	DATE/TIME IN: 14.10.2018 13:45
YR OF MANU: 23.08.2017	TARGET DATE
CHASSIS CODE: JTDKB3FU403563436	COMPLETION DATE/TIME


CHINA

UNIT CARD NO.

JOB DESCRIPTION

Accident Date: 14.10.2018  
NATURE: 3P 14.10.2018

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



ISSUED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Logement Slip

Exit Pass

Vehicle No.: SH 7691S LKE

Vehicle No.: SH 7691S

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

HKK/Kalvin pbyf  
15/10/2018 14:47

15/10/2018 14:47

Like CHINA

Like CHINA

Like CHINA

Kalvin Ukky  
15/10/18 15:55 hrs.  
2 Dps.  
P/P  
After Repair photo

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is only a reference
- No illegal modifications
- Supplementary item is subject to final approval

**Acknowledged by Repairer**  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## Shu Pei (LKKAUTO)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 18 October 2018 8:50 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Lucas Lee; Joy Irene (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SKJ3904P (OI : CTI - TBA) AND SH7691S (TP : LKK REF - CC3/CTI18018769/K1jb3) on 14.10.2018 / OUR REF: SNM18D04906C02  
**Attachments:** oi report.pdf

Dear Shu Pei,

Pls note our Insured report and our reference.

Await your further findings.

Thank you.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

### **China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: boonsen.chong@sg.cntaiping.com  
Website: www.sg.cntaiping.com

#### *Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Wednesday, 17 October, 2018 10:13 AM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Cc:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving SKJ3904P (OI : CTI - TBA) AND SH7691S (TP : LKK REF - CC3/CTI18018769/K1jb3) on 14.10.2018

### **WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SH 7691S at M/s ComfortDelGro Engineering Pte Ltd (Loyang) on a WP basis and TP repairer purposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



Our Reference: **SNM18D04906/C01/4**

Date : **17 OCTOBER 2018**

via Ordinary & Registered Mail

**NEO MOH TECK  
BLK 223D COMPASSVALE WALK  
#08-681  
SINGAPORE 544223**

Dear Sir / Madam

**ACCIDENT INVOLVING SKJ3904P AND SH7691S ON 14 OCTOBER 2018  
ALONG CTE TUNNEL**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SH7691S** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd

Attn : JOY  
Ref : CC3/CTI18018769/K1JB3  
Contact No : 68412409  
via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0132A) - LAKE-VIEW (USED CARS) TRADING

F01/LKKDS-2013

Our Ref : T 1018 / SH 7691S /WT(st)  
Your Ref :  
Date : 24-Oct-18

CDGE Taxi Claims Dept  
59 Loyang Drive 4th Flr  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 10969042W

## Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508969

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 609286

**Ubi**  
320 Ubi Road 3  
Singapore 408649

**Senoko**  
24 Senoko Loop  
Singapore 758156

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 728791

**Yishun**  
Shun Industrial Park A  
Singapore 768732

**CHINA TAIPING INSURANCE CO LTD**  
**3 ANSON ROAD**  
**#16-00 SPRINGLEAF TOWER**  
**SINGAPORE 079909**

**Attn : Motor Claims Department**

**WITHOUT PREJUDICE**

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 7691S YOUR INSURED SKJ3904P**  
**AND OTHER \_\_\_\_\_ ON 14.10.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SH 7691S which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SKJ3904P we are submitting these claims for your consideration on behalf of the claimants.

### TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 321.00
2	<u>3</u> days Loss of Rental @ \$ 125.40 per day	\$ 376.20
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation Fees	\$ -
<b>Sub Total :</b>		<b>\$ 704.69</b>

### HIRER'S CLAIM

7	<u>3</u> days Loss of Income @ \$ 80.00 per days	\$ 240.00
<b>Total Claims :</b>		<b>\$ 944.69</b>

We enclose herewith the following documents to support the claims :-

- a) Original repair bill and photocopies of photographs : 9 pcs.  
b) LTA search slip/s of : SKJ3904P  
c) GIA / Police report/s of : SH 7691S  
d) Letter of authority from owner / hirer / operator  
( ) Traffic Compound ( ) Towing/Medical bill/receipts ( ) Certificate of Insurance  
( ) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

*William Tan*

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC3/CTI18018769/K1jb3**

07 November 2018

**NEO MOH TECK**  
BLK 223D COMPASSVALE WALK  
#08-681  
SINGAPORE 544223

Dear Sir/Madam,

**ACCIDENT INVOLVING SKJ 3904P AND SH 7691S ON 14/10/2018**

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,



Joy Irene  
Case Handler

DID: 6841 2409

FAX: 6741 4108

Email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com)

c.c. *China Taiping Insurance (Singapore) Pte Ltd*  
*(Motor Claims Dept)*

## LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING  
ALONGTOYOTA PRIUS SH7691S , SKJ3904P  
CTE TWDS SLE

ON 14-Oct-18 11:55

I / We

TEO WEN WEI (ZHANG ...

(Hirer) NRIC No.:

S8333645E

and/or

CHUA SEOW KIANG

(Relief) NRIC No.:

S0105977G

Taxi Number

SH7691S

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

15-Oct-2018

Name of Hirer

TEO WEN WEI (ZHANG WEN WEI)

Hirer NRIC .

S8333645E

Signature :



Address

510 JELAPANG ROAD #09-64  
670510

Contact No.

98150175

Name of Relief

CHUA SEOW KIANG

Relief NRIC

S0105977G

Signature :



Address

407 FAJAR ROAD 10-321  
670407

Contact No.

67606755



MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN1514931803  
Claimant : COMFORT TRANSPORTATION PTE LTD

Claim No : SNM18D04906/C01/4

Amount : S\$720.00  
SINGAPORE DOLLARS SEVEN HUNDRED TWENTY ONLY.

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SH 7691S  
Insured Vehicle No. : SKJ 3904P

Date of Loss : 14/10/2018  
Place of Accident : CTE TUNNEL

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : NEO MOH TECK  
Driver Name : NEO MOH TECK

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum S\$ 720.00

TOTAL . . . . . S\$ 720.00

CLAIMS DEPARTMENT  
COMFORTDELGRO ENGINEERING PTE LTD  
351 DOWNS DRIVE  
SINGAPORE 508088  
Claimant Name : \_\_\_\_\_ NRIC No : \_\_\_\_\_

Signature :  Date : 20.11.18

"This document is the property of COMFORTDELGRO ENGINEERING PTE LTD  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document"

Please forward your cheque made payable to  
COMFORTDELGRO ENGINEERING PTE LTD



GST REG. NO. M2-8921817-3

## TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD  
SPRINGLEAF TOWER

3 ANSON ROAD #16-00  
SINGAPORE 079909

CONTACT NO: 62222366

VEHICLE NO  
SH 7691S

MAKE  
TOYOTA

MODEL  
PRIUS HYBRID(G4)

DATE OF REG  
23.08.2017

CHASSIS CODE  
JTDKB3FU403563436

NO/DATE  
91403551 24.10.2018

JOB NO.  
305225854

ODOMETER READING

JOB TYPE

Description : 3P 14.10.2018

### Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	300.00
Add GST @ 7.000 %	21.00
<b>Total Invoice amount</b>	<b>321.00</b>

Issued by : CHEWBEELENG 24.10.2018 09:09:39  
Repair Type : CLSO/57/57  
Payment Type/Term : /Credit 30 days

omfortDelGro Engineering Pte Ltd  
member of COMFORTDELGRO

Head Office:  
15 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT18100454



Date: 23 October 2018

## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	14/10/2018 @ 11:55 hrs
ALONG	CTE TWDS SLE
INVOLVING	SKJ3904P

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH7691S** (the "Taxi"). The Taxi was hired to **TEO WEN WEI (ZHANG WEN WEI) IC NO S8333645E** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate \$125.40 per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
	FROM	TO
250	0350	1245
243	1720	0100
248	0352	1248
295	1500	0140
249	0350	1355
244	1800	0150
298	0350	1351
280	1800	0440
253	0405	1520
244	1800	0355
245	0445	1535

DATE	NAME OF DRIVER	MILEAGE READING				MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
		1	2	3	4		FROM	TO
07/10/18	Tao	1	4	5	2	6	8	1900 0200
08/10	Lian	1	9	5	5	6	6	0350 1410
08/10	Tao	1	9	5	8	1	3	1800 0100
09/10	Lian	1	9	6	0	9	5	0350 1150
09/10	Tao	1	9	6	5	8	8	1100 0350
14/10	CHUA	1	9	6	8	1	9	0400 1325
14/10/18	Accident ?						1345	—
16/10/18	Repair						—	1730

**Enquire Vehicle Insurer**

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SKJ3904P 14 Oct 2018 / 11:55:00 Successful C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#)[OK](#)

SH769LS

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18018769/K1jb3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 22-11-2018



Code : CTI

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SKJ 3904P	Veh. Inspected	SH 7691S
Policy No.	DMPCSN1514931803	Coverage (\$)	0.00
Claim No.	SNM18D04906/C01/4	Excess (\$)	0.00
Assign From		Assign Date	15/10/2018

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU403563436	Colour	BLUE
Odometer	196820	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.
---

**5. General Information**

Accident Date	14/10/2018	Inspection Date	15/10/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7691S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	499.90	-
1	FRONT BUMPER SIDE RETAINER	SERVICEABLE	77.00	-
	LESS 20% DISCOUNT		-115.38	-
			461.52	-
	<b>LABOUR</b>			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER .		220.00	100.00
	SPRAY PAINTING CHARGE.		220.00	200.00
			440.00	300.00
	<b>GRAND TOTAL</b>		<b>901.52</b>	<b>300.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>300.00</b>

Report Ref No. CC3/CT118018769/K1jb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.