

22/03/2002

ASS. REC. BY:

REF:

CS3/MSG18018786/Gcd312

Special Instruction:

Survivor:
Mention

Guo Gang

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time:

16/10/18 @ 2:09pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YM 9148J

Insured:

SLX 2128J

at Workshop m/s

Motor Intel

Tel:

8838 3318

of

13 Kaki Bkt Road 4 # 01-20

Policy No:

A29 085997 QMX

Claim No:

569284

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/08/2018

CA / REV / REP. / REV 24 HRS

lup

17/10/2018

H.O.D. Endorsement:

Date/Time:

3:46pm @ 16/10/18

Person Contacted:

Wilson

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	YM 9148J - X
	SLX 2128J - X
	Dismantle: 17/10/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		16 Oct 2018 14:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CH'NG SOON KIAT, ID: S7671033C, Tel: +6598355165, Email: NOEMAIL		
Main Claimant:	CARPRO TOWING, Co. Reg. No.: 53295217X		
Vehicle Reg. No.:	YM9148J	Date of Loss:	28/08/2018 01:00 - :59 [120 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569284	Policy/Cover Note No.:	A29085997QMX (Comprehensive) Coverage: 20/06/2018 - 19/06/2019
Vehicle Reg. No. (Insured):	SLX2128J	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/10/2018]		
Driver/Custodian (Insured):	CH'NG SOON KIAT (42 / Male), NRIC: S7671033C, Tel: +6598355165		
Adj Asg. Remarks:	Liab- not clear. SJE DISAGREE APPOINT LKK. pls conatct Wilson @8838 3318 / Tinie 6281 0087		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5217X
Vehicle Details	
Vehicle No.:	YM9148J
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	ISUZU
Vehicle Model:	NHR85AUE4A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	4JJ1703577
Chassis No.:	JAANHR85E87100164
Maximum Power Output:	-
Open Market Value:	\$24,223.00
Original Registration Date:	22 Aug 2008
First Registration Date:	22 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$1,212.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$15,582.00
COE Rebate Amount:	\$15,087.00
Total Rebate Amount:	\$15,087.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 18 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/08/2018 14:08
Date Of Accident	28/08/2018 01:40
Exact Location Of Accident	PIE TOWARD CITY BEFORE BEDOK NORTH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	YM9148J
Insured/Policyholder	
Name Of Registered Owner	CARPRO TOWING
Co Reg No	53295217X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-87771161
Vehicle Particulars	
Manufacturer	ISUZU
Model	3.1
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCV185013436
Cover Note Number	
Driver	
Name of Driver	CHU PUI PING
NRIC No	F7906483K
Date Of Birth	08/11/1977
Occupation	OUTDOOR
Date Of Driving Pass	19/12/2014
Driving Experience	3 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83614074
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 109 HOUGANG AVE 1 #03-1022
Postcode	S530109
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX2128J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect

REG NO 53295217

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

29/8/2013 2.05pm
Reporting Centre/Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CARPRO TOWING
REG NO 53295217X

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		16 Oct 2018 14:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CH'NG SOON KIAT , ID: S7671033C, Tel: +6598355165, Email: NOEMAIL									
Main Claimant: CARPRO TOWING , Co. Reg. No.: 53295217X									
Vehicle Reg. No.: YM9148J		Date of Loss:	28/08/2018 01:00 - :59 [120 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / 569284		Policy/Cover Note No.:	A29085997QMX (Comprehensive) Coverage: 20/06/2018 - 19/06/2019						
Vehicle Reg. No. (Insured): SLX2128J		Policy No. (Claimant):							
		Excess:							
Repairer: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 17/10/2018]									
Driver/Custodian (Insured): CH'NG SOON KIAT (42 / Male), NRIC: S7671033C, Tel: +6598355165									
Adj Asg. Remarks: Liab- not clear. SJE DISAGREE APPOINT LKK. pls conatct Wilson @8838 3318 / Tinie 6281 0087									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YM9148J (569284)**
[SLX2128J]
TP
CARPRO TOWING
Aug 28 2018 1:00AM
[CH'NG SOON KIAT]
Motor Intel Automo Pte Ltd - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/10/18 09:58	Accident Statement <small>From: SC - Reg. No: SLX2128J, Claimant: CH'NG SOON KIAT</small>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/10/18 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/10/18 17:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/10/18 09:58	Third Party Accident Report From: SC - Reg. No: SLX2128J, Claimant: CH'NG SOON KIAT	 Load PDF	
2	16/10/18 09:58	PRI From: SC - Reg. No: SLX2128J, Claimant: CH'NG SOON KIAT	 Load PDF	
3	16/10/18 09:58	WORKSHOP DETAILS From: SC - Reg. No: SLX2128J, Claimant: CH'NG SOON KIAT	 Load PDF	
4	16/10/18 09:58	SJE DISAGREE APPOINT LKK From: SC - Reg. No: SLX2128J, Claimant: CH'NG SOON KIAT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18018786/GCD3E2

Date: 29/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29085997QMX

Claimant Vehicle
No : YM9148J

Insured Vehicle No : SLX2128J

Date of Loss: 28/08/2018

Nature of Claim: TP

Claim No: 569284

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YM9148J**

Make & Model: ISUZU NHR85AUE4A, 3.0 D (M)

Engine No: 4JJ1703577

Reg. Date: 22/08/2008 (Man. Year: 2008)

Chassis No: JAANHR85E87100164

Colour: Blue

Odometer: 0 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16 (D)

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5/5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/10/2018

Date Inspected: 17/10/2018 Inspected At:

Motor Intel Automo Pte Ltd - Kaki Bukit
(HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz
Centre
Singapore 417807

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Oct 2018)

Parts: N/A ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YM9148J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >