

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

To: M/s EQ INSURANCE COMPANY LTD

Date: 21/10/2019

THIRD PARTY DIRECT SETTLEMENT

V / (/ / KT	SLQ 3550C	(Insd Veh)	Your Ref. No.: DM18HO02769-JG
Vehicle No.	SHC 3055L	(TP Veh)	Our Ref. No.: CC3/EQI18018787/K1pb3s2
Date of Accident	12/10/2018		

	100%	
: \$	3,036.10	(W/GST)
: \$	150.00	3 days
: \$	375.57	3 days
: \$	7.49	
: \$		
	3,569.16	
: \$	3,560.00	(GLOBAL SUM)
	: \$: \$: \$: \$ 150.00 : \$ 375.57 : \$ 7.49 : \$ 3,569.16

1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$	3,560.00
		: \$	

NUR SHAQILAH LKK Auto Consultants Pte Ltd



COMFORTDELGRO

Our Ref :T 1018 / SHC3055L /JW(st)	ENGINEERING
Your ref: Date: 29-Oct-18	CDGE Taxi Claims Dept ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701
EQ Insurance Company Limited	59 Loyang Drive 4th Fir Mainline +65 6383 6280 Singapore 508969 Faccimilie +65 6280 9755
5 Maxwell Road, MND Complex	Singapore 508969 Facsimilie +65 6280 9755 www.cdge.com.sg
#17-00 Tower Block	Company Registration No. 199506048W
Singapore 069110	Workshops
50 VIII (#10 1750 VIII 10 174 1750 VIII 10 10 10 10 10 10 10 10 10 10 10 10 10	OUT PREJUDICE Braddell Road Singapore 579701
ACCIDENT INVOLVING OUR TAXI SHC3055L	YOUR INSURED SLQ3550C Loyang Drive Singapore 508969
24 24 45 52 40 40 40 50 40 50 40 50 50 50 50 50 50 50 50 50 50 50 50 50	ON 12.10.18 Sin Ming 383 Sin Ming Drive Singapore 575717
We are the authorised repair workshop for Comfort Tra Vehicle No: <u>SHC3055L</u> which was involved in the cap vehicle. The vehicle owner and the taxi driver concerne	tioned accident with your insured 45 Pandan Road
assist them in presenting their claims against the party arising from the damage to the vehicle.	
As the accident was caused by the negligent act of yo we are submitting these claims for your consideration of	Ningangre / 58756
TAXI OWNER'S CLAIM 1 Cost of Repair 2 4 days Loss of Rental @ \$ 125.19 p 3 Survey Report Fees (Surveyed by M/s LKK) 4 LTA Search Fees 5 GIA / Police Report Fees 6 Towing / Medical / Transporation Fees HIRER'S CLAIM 7 4 days Loss of Income @ \$ 80.00 p We enclose herewith the following documents to support a) Original repair bill and photocopies of photographs b) LTA search slip/s of: C) GIA / Police report/s of: GIA / Police report/s of: GIA / Police report/s from owner / hirer / operator	\$ 3,036.10
() Witness statement/s () Towing/Medical bill/rece (X) Photograph/s of Accident Scene (x) Downtime/M	11.0.1
Kindly look into the matter and let us hear from you on soon as possible.	the settlement of the said claims as
Please note that it is a condition of any settlement reac to any personal injury claim (if any) of the taxi driver.	hed that it shall be without prejudice
Yours faithfully	

Jim Wong

CDGE Claims Department

Tel: 6214 8374 Fax: 6214 1843 Email: jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.









51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC3/EQI18018787/K1pb3

11 September 2019

ONG KOK HEE BLK 412 PASIR RIS DRIVE #11-373 SINGAPORE 510412

Dear Sir/Madam.

ACCIDENT INVOLVING SLQ 3550C AND SHC 3055L ON 12/10/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SHC 3055L against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour as your vehicle was making a right turn and collided with third party who was driving straight on the opposite direction. Under Motor Accident Guide, onus is on the turning vehicle. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler DID: 6742 3197 FAX: 6741 4108

EMAIL: chewht@lkkauto.com

c.c. EQ INSURANCE COMPANY LIMITED (Motor Claims Dept)

ı	ET	TED	OF	AUTI	HODI	CAT	TON

(NAF / PAF)

ACCIDENT INVOLVING Hyundai Ioniq SHC3055L , SLQ3550C

ON 12-Oct-18 22:40

ALONG

JUNCTION OF TANJONG KATONG RD AND JOO CHIAT RD

1/We

ONG KIAN YING

(Hirer) NRIC No.: \$2021664F

and/or

(Relief) NRIC No .:

Taxi Number

SHC3055L

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of

"ComfortDelGro Engineering Pte Ltd".

Date

14-Oct-2018

Name of Hirer

ONG KIAN YING

Hirer NRIC

S2021664F

Signature:

127

Address

341 CHOA CHU KANG AVENUE 3 #0...

689874

Contact No.

87987109

COMFORT DELGRO ENGINEERING

A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 756156 7 Sungel Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76873;

> COMPANY REG. NO.: 199506048W Page: 1

8010325		
EQ INSURANCE COMPANY LIMITED	VEHCLE NO SHC3055L	INV. NO/DATE 91403564 24.10.2018
5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110	MAKE HYUNDAI	JOB NO. 305225853
CONTACT NO: 62239433	MODEL IONIQ(G2)	ODOMETER READING
	DATE OF REG 03.07.2018	DATE/TIME IN 14.10.2018 10:45

CHASSIS CODE Description: 3P 12.10.2018 KMHC851CVJU103419

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART	REQUISITION					
0001	04-01-0104-2164	IONIQUE GRILLE ASSY-RADIA	1	1,227.50	20.00	982.00
0002	04-01-0104-2815	IONIQVC LAMP ASSY-HEAD LH	1	1,198.80	20.00	959.04
0003	FNPS	NO PLATE(S)	1	55.00	0.00	55.00
0004	04-01-0104-2534	IONIQV2 COVER-FR BUMPER#	1	418.30	20.00	334.64
0005	04-01-0104-2361	IONIQ MOULDING-FRONT BUMP	1	108.50	20.00	86.80
			SUB-TOTAL	3	2,41	17.48

JOB NATURE

9	0001	L	PANEL BEATING	200.00	200.00
	0002	23-502	SPRAYPAINT ON AFFECTED AREA	200.00	200.00
	0003	17-01	CHECK ALL LIGHTING	20.00	20.00

ComfortDelGro Engineering Pte Ltd

A member of COMFORIDELGRO

Head Office: 205 Braddell Road Singapore 579701

A	CCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
	8010325	91403564	3,036.10	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY



A member of ComportDeLGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

59 Loyang Orive Singapore 508969 383 Sin Ming Drive Singapore 675717 45 Pandan Road Singapore 609296 320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yehun Industrial Park A Singapore 768735

COMPANY REG. NO.: 199506048W Page: 2

8010325

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110

CONTACT NO: 62239433

VEHCLE NO SHC3055L

INV. NO/DATE 91403564 24.10.2018

MAKE HYUNDAI

MODEL IONIQ(G2)

ODOMETER READING

DATE OF REG 03.07.2018

DATE/TIME IN 14.10.2018 10:45

CHASSIS CODE KMHC851CVJU103419

S/No Part No.

Qty Unit Price %Disc

Net

SUB-TOTAL

420.00

Items total

2,837.48

Add GST @

7.000 %

198.62

Invoice amount

3,036.10

Issued by : CHEWBEELENG 29.10.2018 09:41:17
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELCRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No. 8010325 91403564 3,036.10

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18100434

Date: 23 October 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

12/10/2018 @ 22:40 hrs

ALONG

JUNCTION OF TANJONG KATONG RD AND JOO

CHIAT RD

INVOLVING

SLQ3550C

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC3055L (the "Taxi"). The Taxi was hired to ONG KIAN YING IC NO S2021664F a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with India International Insurance Pte Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	MILEAGE	HOURS OPE	HOURS OPERATED (TIME)		SHC30556		MILEAGE	HOURS OPE	HOURS OPERATED (TIME)
U	TRAVELLED	FROM	- 2	DATE	NAME OF DRIVER	MILEAGE HEADING	(KM)	FROM	10
	(many)		2	SOL	Tay	17467	29C.	0430	11711
				B1-11-11	000	47938	188	14.10	05.32
				13.10-15	mot sol	53157	8/5	2530	0530 131x
				13-10-18	ONG		,	12.40	
				14/10/18	Acroslant?	. \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Loyang	1045	
1				81/01/t)	Repair	0 NG 167W 41 NG	V	1	1500
1									
1									
-									

Enquire Vehicle Insurer

 Vehicle No.
 Incident Date/Time
 Search Status
 Insurance Company Code
 Insurance Company Name

 SLQ3550C
 12 Oct 2018 / 22:40:00
 Successful
 E04
 EQ INSURANCE COMPANY LTD

 SLQ3550C
 12 Oct 2018 / 22:40:00
 Successful
 A04
 AIG ASIA PACIFIC INSURANCE PTE, LTD.

Disclaimer message:

Your search is displaying 2 records as there is an overlap in the period covered by the insurance policies. You may wish to contact the insurance companies for more information.

Previous

OK

SUC BOR L