

ASS. REC. BY:

REF: CS3/ALG18018795/Gcd3^{fz}

Special Instruction:

Surveyor:

meunmen

Gilo Qiang

ASSIGNMENT (Office)

From (Person):

chin lee Ying

of

ALG

Date/Time:

16/10/18 @ 3:04pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8TH 2145T

Insured:

SLW 8282L

at Workshop m/s

Neo Automotive

Tel:

8127 0799

of

53 Ubi Ave 1 #05-14

Policy No:

1700094303

Claim No:

2631246710SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/10/18

CA / REV / REP. / REV 24 HRS

(up)

17/10/18 @ After 10:30am

H.O.D. Endorsement:

Date/Time:

4:16pm @ 16/10/18

Person Contacted:

Mrs. Neo

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLH 2145T - NA/INC18018620/K4
	SLW 8282L - NA/INC18018620/K4
	Dismantle: 18/10/2018
	After repair: 24/10/2018

DOA: 13/10/2018

DOA: 13/10/2018

PRS
Karl

REF: AIG

CU915N /

ASSIGNMENT

From: Date: 17/10/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 2145T

at Workshop m/s Neo Automotive

of 53 ubi Ave 1 # 05-44

Insured:

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

After 10.30 am

Make of Veh: Mrs. Neo @ 8127 0799

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLH 2145T Yr Regn: 26 Oct 2016

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598

Colour: Blue Grey. A/C: Insured / Std / NI / NA

Sp. Reading: 128790 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR 053 REH 10455 8853

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ Rim or

Tyre Size: F: 205 / 55 R16

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 17-10-18

Survey held at w/s 11AM

Des. of Damages: Frt / Rear / O/S / ☒ N/S / UIC / Rooftop or

The ☒ UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$3000 - \$4000
	Repair days 5
	TCum line
	23/10/18

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Report Format: DAR

Lump Sum / I.B.I. (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 16/10/2018 3:04:26 PM
Attachments:  tmp5.tif

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

From: lheny@yoga-legal.com [mailto:lheny@yoga-legal.com]

Sent: Tuesday, October 16, 2018 2:23 PM

To: Azlan, Syazairdina

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLW8282L AND SLH2145T ON 13/10/2018

Dear Sirs

Please be informed that our client's vehicle can be inspected at:

M/s. Neo Automotive Pte Ltd

53 Ubi Ave 1

#05 – 44 Paya Ubi Industrial Park

Singapore (408934)

Mrs. Neo (8127 0799)

Fax no : 6385 8262

Best regards,

Lheny

M/s C YOGARAJAH LLC

883 North Bridge Road

#11-03 Southbank

Singapore 198785

Tel: 6292 5838

Fax: 6292 5938

Email: lheny@yoga-legal.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

C. YOGARAJAH LLC ADVOCATES & SOLICITORS

Our Ref : CY.SLH2145T.18.NA.wp(Lh)

Your Ref : Your insured vehicle **SLW 8282L**

15 October 2018

LEE PEI'EN LYNETTE
 c/o The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way #07-16
 Singapore 079120

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLH 2145T & SLW 8282L ON 13.10.2018 @ 09:15HRS ALONG TIONG BAHRU ROAD

We are instructed by NEO AUTO LEASING PTE LTD to notify you of a road traffic accident on 13.10.2018 @ 09:15hrs along Tiong Bahru Road involving our client's customer's vehicle registration number SLH 2145T and vehicle registration number SLW 8282L driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


C. Yogarajah LLC
 Enc

Cc: M/s. Neo Automotive Pte Ltd
 53 Ubi Ave 1
 #05 - 44 Paya Ubi Industrial Park
 Singapore (408934)
 Mrs. Neo (9091 4853)
 Fax no : 6385 8262

883 North Bridge Road
 #11-03 Southbank
 Singapore 198785
 T: 6282 5938
 F: 6282 5938
 (UEN No. 201333127N)
 (GST Reg No. 201333127N)

By Fax No: 6835 7416

workshop

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 10:59
Date Of Accident	13/10/2018 09:15
Exact Location Of Accident	TIONG BAHRU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH2145T
Insured/Policyholder	
Name Of Registered Owner	NEO AUTO LEASING PTE LTD
Co Reg No	201814915N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97982180
Alternative Phone No	OFFICE-97982180

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5103424803
Cover Note Number	

Driver

Name of Driver	TAN HOCK CHYE
NRIC No	S1694185I
Date Of Birth	21/12/1965
Occupation	OUTDOOR
Date Of Driving Pass	04/02/1988
Driving Experience	30 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97982180
Fax Number	
Contact Number	OTHERS-97982180
Email Address	NOEMAIL

Address	343 CHOA CHU KANG AVENUE 3 #12-25
Postcode	689875
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW8282L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Tiong Bahru Market.

Tiong Bahru Road.

car park.



A - SLH2145T
B - SLW8282L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

car A - Go straight through Tiong Bahru Road, and when I reach car B, car B drive out and hit on my side door.

car B - car B drive out from car park and never give way.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature] 15/10/2018

Enquire Vehicle Information

Vehicle No.

Vehicle No. :

SLH2145T

Vehicle Details

Vehicle Type :

Private Hire (Chauffeur) Motor Car

Vehicle Attachment 1 :

No Attachment

Make / Model :

TOYOTA / COROLLA ALTIS CLASSIC 1.6 CVT

Primary Colour :

Grey

Year of Manufacture :

2016

Maximum Laden Weight :

1640 kg

Unladen Weight :

1205 kg

No. Of Axles :

2

Engine No. :

1ZRY335265

Chassis No. :

MR053REH104558853

Engine Capacity :

1598 cc

Maximum Power Output :

90.0 kW (120 bhp)

IU Label No. :

1126967976

Propellant :

Petrol

Passenger Capacity :

4

Original Registration Date :

26 Oct 2016

First Registration Date :

26 Oct 2016

Open Market Value :

\$16,800.00

Additional Registration Fee Rate :

First \$16,800.00 (100%)

Actual ARF Paid :

\$16,800.00

PARF Eligibility :

Yes

Minimum PARF Benefit :

\$8,400.00

PARF Eligibility Expiry Date :

25 Oct 2026

COE No. :

2016110101000987E

COE Category :

A - Car up to 1600cc & 97kW (130bhp)

COE Expiry Date :

25 Oct 2026

Quota Premium (QP) :

\$51,507.00

QP Paid :

\$51,507.00

OPC Cash Rebate Eligibility :

No

QP during COE Bidding Exercise :

\$51,507.00

Private Hire Vehicle Decal No. :

A021506 (Issued on 29 May 2017)

CO2 Emission:

151.00 (g/km)

CEV/VES Rebate Utilised Amount:

-

CO Emission:

-

HC Emission:

-

NOx Emission:

-

PM Emission:

-

Previous

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4915N
Vehicle Details	
Vehicle No.:	SLH2145T
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY335265
Chassis No.:	MR053REH104558853
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	26 Oct 2016
First Registration Date:	26 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$16,800.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2026
PARF Rebate Amount:	\$12,600.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$41,302.00
Total Rebate Amount:	\$53,902.00

The information contained herein is correct as at 18 Oct 2018

OK

(10)Bent (21)Distorted (4)Cracked (5)Cut (6)Scratched
(107)Deformed (108)Shifted (99)Buckled (10)Broken (11)Necessary (12)Missing
(13)Torn (14)Unconfirmed (15)Not Working

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

MOTOR CAR (RH)

Vehicle No: SLH 2145T

[illegible]

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	DD	✓	
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber	DD	✓	
1360	993276	Rear RH Door Outer Handle	GUT	✓	
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper	GUT	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender	DD	✓	
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			
		- Rear bumper reflector NS	BR	✓	1
		- Rear Window Sealant	NEC	✓	
		- Rear LH Lower Arm		?	
		- " " Knuckle Arm		?	
		- " " Wheel Bearing		?	

23/10/2018

Assessor: _____

TGLIM

him

23/10/18

Original Com.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Oct 2018 Edit Reg		16 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lee Pei'en Lynette, ID: S8413097D		
Main Claimant:	NEO AUTO LEASING PTE LTD, Co. Reg. No.: 201814915N		
Vehicle Reg. No.:	SLH2145T	Date of Loss:	13/10/2018 09:00 - :59 [23 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2631246710SG	Policy/Cover Note No.:	1700094303 (Comprehensive)
Vehicle Reg. No. (Insured):	SLW8282L	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/10/2018]		
Claimant's Solicitor:	C YOGARAJAH LLC - Tel: 62925838		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (17/10/2018): Request to upload TP GIA Report
- AIG_SG (17/10/2018): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLH2145T (2631246710SG)**
[SLW8282L]
TP
NEO AUTO LEASING PTE LTD
Oct 13 2018 9:00AM
[Lee Pei'en Lynette]

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#)

Photos/Images

3 per page
 ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/10/18 12:57	General View	 Load JPG	☒
2	22/10/18 12:57	General View	 Load JPG	☒
3	22/10/18 12:57	General View	 Load JPG	☒
4	22/10/18 12:57	General View	 Load JPG	☒
5	22/10/18 12:57	General View	 Load JPG	☒
6	22/10/18 12:57	General View	 Load JPG	☒
7	22/10/18 12:57	General View	 Load JPG	☒
8	22/10/18 12:57	General View	 Load JPG	☒
9	22/10/18 12:57	General View	 Load JPG	☒
10	22/10/18 12:57	General View	 Load JPG	☒
11	22/10/18 12:57	General View	 Load JPG	☒
12	22/10/18 12:57	General View	 Load JPG	☒
13	22/10/18 12:57	General View	 Load JPG	☒
14	22/10/18 12:57	General View	 Load JPG	☒
15	22/10/18 12:57	General View	 Load JPG	☒
16	22/10/18 12:57	General View	 Load JPG	☒
17	22/10/18 12:57	General View	 Load JPG	☒
18	22/10/18 12:57	General View	 Load JPG	☒
19	22/10/18 12:57	General View	 Load JPG	☒
20	22/10/18 12:57	General View	 Load JPG	☒
21	22/10/18 12:57	General View	 Load JPG	☒
22	22/10/18 12:57	General View	 Load JPG	☒
23	22/10/18 12:57	General View	 Load JPG	☒
24	22/10/18 12:57	General View	 Load JPG	☒
25	22/10/18 12:57	General View	 Load JPG	☒
26	22/10/18 12:57	General View	 Load JPG	☒
27	22/10/18 12:57	General View	 Load JPG	☒
28	22/10/18 12:57	General View	 Load JPG	☒
29	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒
30	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒
31	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒
32	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒
33	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒
34	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒
35	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒
36	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
38	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
39	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
40	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
41	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
42	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
43	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
44	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
45	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
46	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
47	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
48	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
49	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
50	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
51	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
52	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
53	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
54	22/10/18 12:57	Photographs of Damaged Parts	 Load JPG	✓
55	25/10/18 17:28	Photo After Spray	 Load JPG	✓
56	25/10/18 17:28	Photo After Spray	 Load JPG	✓
57	25/10/18 17:28	Photo After Spray	 Load JPG	✓
58	25/10/18 17:28	Photo After Spray	 Load JPG	✓
59	25/10/18 17:28	Photo After Spray	 Load JPG	✓
60	25/10/18 17:28	Photo After Spray	 Load JPG	✓
61	25/10/18 17:28	Photo After Spray	 Load JPG	✓
62	25/10/18 17:28	Photo After Spray	 Load JPG	✓
63	25/10/18 17:28	Photo After Spray	 Load JPG	✓
64	25/10/18 17:28	Photo After Spray	 Load JPG	✓
65	25/10/18 17:28	Photo After Spray	 Load JPG	✓
66	25/10/18 17:28	Photo After Spray	 Load JPG	✓
67	25/10/18 17:28	Photo After Spray	 Load JPG	✓
68	25/10/18 17:28	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/10/18 11:52	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18018795/GCD3S2
Date: 29/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700094303
Claimant Vehicle No: SLH2145T Insured Vehicle No: SLW8282L
Date of Loss: 13/10/2018 Nature of Claim: TP Claim No: 2631246710SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH2145T
Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZRY335265
Reg. Date: 26/10/2016 (Man. Year: 2016) Chassis No: MR053REH104558853
Colour: Grey Odometer: 128790 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/10/2018
Date Inspected: 17/10/2018 Inspected At: NEO AUTOMOTIVE PTE LTD
53 UBI AVE 1 #05-44
PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	0.00 F	*- F
2	1		*REAR RH DOOR RUBBER	Dented	0.00 F	*- F
3	1		*REAR RH DOOR OUTER HANDLE	Cut	0.00 F	*- F
4	1		*REAR BUMPER	Cut	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1		*REAR RH FENDER	Dented	0.00 F	*- F
7	1		*REAR BUMPER REFLECTOR N/S	Broken	0.00 F	*- F
8	1		*REAR WINDOW SEALANT	Necessary	0.00 F	*- F
9	1		*REAR LH LOWER ARM	*Check	0.00 F	*- F
10	1		*REAR LH KNUCKLE ARM	*Check	0.00 F	*- F
11	1		*REAR LH WHEEL BEARING	*Check	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >