

ASS. REC. BY:

REF: Tml /

CC3 / Tml18018828 / Kqbⁿ²

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cob

of _____

Insured: SJK 6195E

Policy No. MV000985

Claims No. M1804987

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S1AC 52264 Yr Regn: 02, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Renault Latitude c.c. 1995

Colour: M. White / R A/C: Insured / Std / NI / NA

Sp. Reading: 579206 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL 15AUC 276539

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 4/10/18 D.O.I. 16/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>100 File pass to Catherine, EST NOT HOLD</u>
	<u>S1AC 52264 - CC3/AXA/5000053 / Khq92</u>
	<u>SJK 6195E - X</u>
	<u>12/10/18 @ 4pm Email GIA report to Tml.</u>
	<u>US @ 2650, 2 days (Paid @ 15583.49, 85%)</u>

RECEIVED 18 OCT 2018

Date/Time, File Pass to?

: Prell. Report

1) 18/10/18

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250
10
260

Report Format: MER-TP

Lump Sum / I.B.L. (\$) 2650

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 17 October 2018 4:00 PM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD - DOA: 04/10/2018 SHC 5226Y (TP), SJK 6195E (OI)
Attachments: SHC5226 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle **SHC 5226Y** M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC5226Y

Vehicle to be Exported: Yes

Intended Deregistration Date: 16 Oct 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2013

Engine No.: M9R8839C000853

Chassis No.: VF1ABL15AUC276539

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 19 Feb 2014

First Registration Date: 19 Feb 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Feb 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 18 Feb 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$58,590.00

COE Rebate Amount: \$24,456.00

Total Rebate Amount: \$33,829.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Oct 2018

OK

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	5HC5226Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000853
Chassis No.:	VF1ABL15AUC276539
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	19 Feb 2014
First Registration Date:	19 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Feb 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	18 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$58,590.00
COE Rebate Amount:	\$24,717.00
Total Rebate Amount:	\$34,090.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/10/2018 14:55
Date Of Accident	04/10/2018 13:45
Exact Location Of Accident	ANG MO KIO AVENUE 4 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5226Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM SENG BEE WILLIAM
NRIC No	S0136042F
Date Of Birth	23/08/1954
Occupation	OUTDOOR
Date Of Driving Pass	31/03/1978
Driving Experience	40 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96480918
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 14A LORONG 7 TOA PAYOH #20-227
Postcode	311014
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 04.10.2018 at about 1345hours, I was travelling straight along Ang Mo kio Avenue 4 Carpark. Suddenly I felt an impact. Vehicle B (SJK6195E) made a reverse without checking for his rear. Hence, Vehicle B's rear portion hit onto my taxi right side door portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK6195E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A: SHC 5226Y
B: SJK 6195E
Ang mo kio Avenue 4
carpark


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls see the attach GRIA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/10/2018 14:55
Date Of Accident	04/10/2018 13:45
Exact Location Of Accident	ANG MO KIO AVENUE 4 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5226Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM SENG BEE WILLIAM
NRIC No	S0136042F
Date Of Birth	23/08/1954
Occupation	OUTDOOR
Date Of Driving Pass	31/03/1978
Driving Experience	40 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96480918
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 14A LORONG 7 TOA PAYOH #20-227
Postcode	311014
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 04.10.2018 at about 1345hours, I was travelling straight along Ang Mo kio Avenue 4 Carpark. Suddenly I felt an impact. Vehicle B (SJK6195E) made a reverse without checking for his rear. Hence, Vehicle B's rear portion hit onto my taxi right side door portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK6195E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Kgb.

Trans-cab Auto Services Pte Ltd

AAD1810-060

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5226Y

Not Notarised

L1Bp @ 2650h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5226Y
 VF1ABL15AUC276539
 RENAULT
 LATITUDE
 4.10.2018
TOKIO MARINE

PART		LIST	
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 X
1	WHEELARCH FRT RH	\$	<i>Sm</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>Sm</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>R</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>By</i> 2,844.66
1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>Sm</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>Sm</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>Sm</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>Sm</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sm</i> 133.60
1	DOOR REGULATOR FRT RH	\$	<i>Sm</i> 505.19
1	DOOR REGUALTOR MOTOR FRT RH	\$	<i>Sm</i> 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>Sm</i> 120.97
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sm</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>R</i> 1,024.79
1	ROCKER PANEL CENTER RH	\$	<i>R</i> 990.25
		\$	10,379.29
		10% \$	1,037.93
		\$	9,341.36

Special Nett

1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i> 30.50 X
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>na</i> 80.00 <i>60sm</i>
1	FRONT DOOR STICKER 'Chassis'	\$	<i>na</i> 50.00 <i>15sm</i>

Trans-cab Auto Services Pte Ltd

AAD1810-060

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5226Y

1	DOOR CHECK BOLT	\$	SH 22.69	}
1	DOOR GUIDE SCREW	\$	SH 10.85	
1	DOOR HINGE BOLT	\$	SH 10.85	
1	DOOR HINGE NUT RH	\$	SH 14.60	
1	DOOR CHECK BOLT	\$	SH 22.69	
1	DOOR CHECK NUT	\$	SH 3.75	
1	DOOR LOCK SCREW L70Y	\$	SH 6.12	
1	DOOR CATCH SCREW L70Y	\$	SH 10.06	

TOTAL \$ 262.13

TOTAL PARTS \$ 9,603.49

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	2001
Putty and spray painting of the affected portion.	\$	3,000.00	480
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	na 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1810-060

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5226Y

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

TOTAL \$ 8,630.00

Over All Total \$ 18,233.49

47

LUMP SUM (REPAIR DAY)

15 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey, on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18018828/KQBN2
Date: 25/10/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW000955
Claimant Vehicle No :	SHC5226Y	Insured Vehicle No :	SJK6195E
Date of Loss:	04/10/2018	Nature of Claim:	TP
		Claim No:	M1804987

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5226Y	Engine No:	M9R8839C000853
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276539
Reg. Date:	19/02/2014 (Man. Year: 2013)	Odometer:	579206 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,603.47	2,635.19	6,968.28	72.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,630.00	690.00	7,940.00	92.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,233.47	3,325.19	14,908.28	81.76
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	18,233.47	2,650.00	15,583.47	85.47
+ GST 7.00/7.00% (S\$)	1,276.34	185.50	1,090.84	85.47
Nett Amount (S\$)	19,509.81	2,835.50	16,674.31	85.47

INSPECTION

Date of Assignment:	17/10/2018	
Date Inspected:	16/10/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2018)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5226Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL FRT RH	Repair	783.83 FL	*- FL
2	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
3	1		*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
4	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
5	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
6	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*- FL
7	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
8	1		*DOOR CHECK FRT RH	Serviceable	194.77 FL	*- FL
9	1		*DOOR LOCK FRT RH	Repair	908.75 FL	*- FL
10	1		*DOOR CATCH FRT RH	Serviceable	131.23 FL	*- FL
11	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*- FL
12	1		*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	*- FL
13	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
14	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	*- FL
15	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*- FL
16	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*- FL
17	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
18	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
19	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
20	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
21	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
22	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS
23	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
24	1		*DOOR GUIDE SCREW	Serviceable	10.85 FS	*- FS
25	1		*DOOR HINGE BOLT	Serviceable	10.85 FS	*- FS
26	1		*DOOR HINGE NUT RH	Serviceable	14.60 FS	*- FS
27	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
28	1		*DOOR CHECK NUT	Serviceable	3.75 FS	*- FS
29	1		*DOOR LOCK SCREW L70Y	Serviceable	6.12 FS	*- FS
30	1		*DOOR CATCH SCREW L70Y	Serviceable	10.06 FS	*- FS

F=Franchise part. S=SpcNett L=ListItemDisc.

Sub Total (S\$)	10,641.40	2,919.66
- List Item Discount on L Items 10.00/10.00% (S\$)	1,037.93	284.47
Total Parts (S\$)	9,603.47	2,635.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
9	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
10	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	-
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	-
Gross Labour Cost (\$\$)			8,630.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >