

22/03/2002

ASS. REC. BY:

REF: CS31SMO18018841Ad362

Special Instruction:

Surveyor:

menmen

Adrian

ASSIGNMENT (Office)

From (Person):

Enoh pau laung

of

SMO

Date/Time:

17/10/18 @ 12:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 502B

Insured:

PC 3365Y

at Workshop m/s

Bluwel Automotive

Tel:

6745 2088

of

1 Kaki Bkt Ave 6 # 01-28

Policy No:

D17MTSCBU000754

Claim No:

CMTD1804470

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/10/2018

CA / REV / REP. / REV 24 HRS

1wp

22/10/18

H.O.D. Endorsement:

Date/Time:

12:24pm @ 17/10/18

Person Contacted:

Sally

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SKZ 502B-X

PC 3365Y-X

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

6 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SK2502B Yr Regn: 2016 Jan.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda CX5

C.C

1998

Colour: Blue

A/C:

Insured / Std / NI / NA

Sp. Reading: 82432

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JM6KE1072G0343037

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R15

R: 225/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIN / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

D.O.I. 22/10/18

Survey held at Bluebird

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo PRS.

- Estimated repair range \$5,500 - \$6,000

24/10/2018

Date/Time. File Pass to?

☐

Preli. Report

11

☐

Final Report

Date/Time. File Return to?

21

Days Of Repair:

Resurvey No. of Trip: -

Survey Fee.

Transportation:

) S + RS. SI

) Photos

) Others

Report Format: PRE

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

100

10

110

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Oct 2018		17 Oct 2018 12:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ROHAYAH BTE OSMAN, ID: S1483890B		
Main Claimant:	TOH YEW HOCK, ID: S7005332B		
Vehicle Reg. No.:	SKZ502B	Date of Loss:	12/10/2018 17:00 - :59
Claim Type:	TP / CMTD1804470	Policy/Cover Note No.:	D17MTSCBU000754 (Comprehensive)
Vehicle Reg. No. (Insured):	PC3365Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/10/2018]		
Driver/Custodian (Insured):	MUHAMMAD FADLY BIN RAMLAN (), NRIC: S8614094B, Tel: +6591064882		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5332B
Vehicle Details	
Vehicle No.:	SKZ502B
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 SKYACTIV-G 2.0 SP6EAT 2WD LED
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	PE10279487
Chassis No.:	JM6KE1072G0343037
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$24,327.00
Original Registration Date:	06 Jan 2016
First Registration Date:	06 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$26,058.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2026
PARF Rebate Amount:	\$19,543.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$39,594.00
Total Rebate Amount:	\$59,137.00

The information contained herein is correct as at 24 Oct 2018

OK

J29/180805/1018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 15:33
Date Of Accident	12/10/2018 17:40
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ502B
Insured/Policyholder	
Name Of Registered Owner	TOH YEW HOCK
NRIC No	S7005332B
Email Address	DENNIS.TOH@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96690272
Alternative Phone No	OFFICE-96690272

Vehicle Particulars

Manufacturer	MAZDA
Model	CX5

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80452695 QMY
Cover Note Number	

Driver

Name of Driver	TOH YEW HOCK
NRIC No	S7005332B
Date Of Birth	15/02/1970
Occupation	INDOOR
Date Of Driving Pass	04/08/1988
Driving Experience	30 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96690272
Fax Number	
Contact Number	OFFICE-96690272
EEmail Address	DENNIS.TOH@HOTMAIL.COM

Address	BLK 225C COMPASSVALE WALK #10-353
Postcode	543225
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO POLICE DIVISIONAL HQ (F DIVISION)
Police Station Address	ROAD: 51 ANG MO KIO AVENUE 9 , POSTCODE: 569929 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2180000 - FAX NO: 64814246
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC3365Y
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	BUS
Name of Driver	MUHAMMAD FADLY BIN RAMLAN
NRIC/Passport Number	S8614094B
Contact Number	NA
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA


No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TOH YEW HOCK
Approximate Age	
Injuries Sustain	NECK PAIN
Injured person in which vehicle?	SKZ502B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 225C COMPASSVALE WALK #10-353
Postcode	543225

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHMENT X

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Demis *Demis*

Policyholder's Signature

Date & Time: 15/10/18, 3pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 15/10/18, 3pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

QAMM SketchPlan Form V3



**SINGAPORE
POLICE FORCE**



F/20181013/7001

1 of 3

POLICE REPORT (NP299)

Report No. F/20181013/7001

Police Station Of Origin
Ang Mo Kio Police Divisional HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No:1800-2180000

Date/Time Report Made 13/10/2018 00:14	Vide Report No.	Station Diary No.
Name Of Informant TOH YEW HOCK	Address APT BLK 225C COMPASSVALE WALK #10-353 SINGAPORE 543225	
ID Type / ID No. NRIC NO / S7005332B	Contact No. Home/Office: Mobile: 96690272	
Nationality SINGAPORE CITIZEN	Email Address dennis.toh@hotmail.com	
Occupation SALES ENGINEER	Sex Male	Age 48
Institution/School Name	Date of Birth 15/02/1970	Race Chinese
Date/Time Of Incident 12/10/2018 17:40 - 12/10/2018 17:50	Language English	
	Location Of Incident APT BLK 225C COMPASSVALE WALK #10-353 SINGAPORE 543225	

Brief details.

I was driving along the PIE heading towards Changi Airport. My location was near ToaPayoh. I was driving on the middle lane at about 70km/hr.

A silver van PC3365Y then hit on the rear of my car SKZ502B. The impact was so hard that I jerked forward twice.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 13/10/2018 00:14
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20181013/7001

There were no other cars involved in this accident besides PC3365Y and SKZ502B.

My chest feel a bit tight. My head and neck were in pain due to the jerk. After exchanging information with the other driver, I called my insurance company. She told me to go hospital for an x-ray and check up.

The doctor suggested that I stayed for further observations but I prefer to go home and rest. After the x-ray and medication, I left Sengkang Hospital about 940pm.

Subjects Involved			
Suspect			
Person Name	Muhammad Fadly Bin Ramlan		
ID Type	NRIC NO	ID No	S8614094B
Gender	Male	Race	Malay
Language	English	Complexion	Dark
Attire Last Worn	t shirt	Hair Colour	Black
Hair Style	Short-Natural Curls		
Victim			
Person Name	TOH YEW HOCK		
ID Type	NRIC NO	ID No	S7005332B
Gender	Male	Age	48
Race	Chinese	Language	English
Signature Of Officer Recording The Report:		Signature Of Informant:	
Not applicable		The identity of the person making this report has been authenticated by SingPass. No signature is required.	
Signature Of Interpreter:		Date/Time:	
Not applicable		13/10/2018 00:14	
Officer In-Charge Of Case:		Classification Of Case:	

Authentication Stamp



**SINGAPORE
POLICE FORCE**



F/20181013/7001

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20181013/7001

Occupation	SALES ENGINEER	Address Type	
Address	APT BLK 225C COMPASSVALE WALK #10- 353 SINGAPORE 543225	Mobile No	96690272
Is Informant A Victim?	Yes		
Person Name	TOH YEW HOCK (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

13/10/2018 00:14

Classification Of Case:

Authentication Stamp

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Oct 2018		17 Oct 2018 12:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All	
------	--	-----------	--	---------------	--	-----------	--	----------	--

CLAIM SUBFOLDER DETAILS						[Created by insurer]												
Insured:	ROHAYAH BTE OSMAN, ID: S1483890B																	
Main Claimant:	TOH YEW HOCK, ID: S7005332B																	
Vehicle Reg. No.:	SKZ502B			Date of Loss:	12/10/2018 17:00 - :59 [33 Months and 6 Days From LTA Reg Date (Man Yr)]													
Claim Type:	TP / CMTD1804470			Policy/Cover Note No.:	D17MTSCBU000754 (Comprehensive)													
Vehicle Reg. No. (Insured):	PC3365Y			Policy No. (Claimant):														
				Excess:														
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088																	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]																	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/10/2018]																	
Driver/Custodian (Insured):	MUHAMMAD FADLY BIN RAMLAN (), NRIC: S8614094B, Tel: +6591064882																	

ASSOCIATED MAIL RECEIVED						View All		Compose Case Mail	
There are no mail for this case.									

ALL ASSOCIATED TASKS						View All		Search Tasks		Create New Task		Complete			
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?						
No results.															

Claim Documents

***SKZ502B (CMTD1804470)**
[PC3365Y]
TP
TOH YEW HOCK
Oct 12 2018 5:00PM
[ROHAYAH BTE OSMAN]
Bluwel Automotive Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
6	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
7	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
8	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
9	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
10	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
11	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
12	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
13	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
14	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
15	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
16	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
17	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
18	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
19	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
20	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
21	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
22	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
23	23/10/18 17:35	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	16/10/18 14:29	PRI REQ FAX FROM JUSEQUITY LAW CORPORATION DT 16/10/18 - SKZ502B	Load PDF	
2	16/10/18 15:09	Third Party E-filed GIA report	Load PDF	
3	17/10/18 12:08	TPPD Pre-Repair Survey	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18018844/ACD3E2

Date: 02/11/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTSCBU000754
Claimant Vehicle No :	SKZ502B	Insured Vehicle No :	PC3365Y
Date of Loss:	12/10/2018	Nature of Claim:	TP
		Claim No:	CMTD1804470

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ502B	Engine No:	PE10279487
Make & Model:	MAZDA CX-5, 2.0 (A)	Chassis No:	JM6KE1072G0343037
Reg. Date:	06/01/2016 (Man. Year: 2015)	Odometer:	82432 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R15	Rear Tyre Size:	225/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/10/2018	
Date Inspected:	22/10/2018 Inspected At:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500.00 -\$6,800.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Nov 2018)

Parts: M1-SUV MAZDA CX-5 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ502B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >