



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Ref: CC4/ASM18018851/Uba3q2 Date: 09/02/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 6235R	Veh. Inspected	SMD 965R	
Policy No.	GA149148	Coverage (\$)	0.00	
Claim No.	S8M00XAD	Excess (\$)	0.00	
Assign From		Assign Date	17/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS (A)	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KNAHU815VJ7211391	Colour	BLUE	
Odometer	9510 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	NEXEN	8 mm	
L/H Front Tyre	205/55 R16	NEXEN	8 mm	
R/H Rear Tyre	205/55 R16	NEXEN	8 mm	
L/H Rear Tyre	205/55 R16	NEXEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2018	Inspection Date	17/10/2018	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	