

Surveyor:

KALVIN

ASSIGNMENT (Office) ✓

aws

From (Person):

May chuan

of

FCI

Date/Time:

16/10/18 4:54pm

Estimated Cost:

Bill to:

OD ☒ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6252P

Insured:

SH 6980P

at Workshop in/s

Premier Automotive

Tel:

6344 6689

of

23 Changi South Ave 2 #03-02

Policy No:

D-18088936 MFSH

Claim No:

D18007478 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/10/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:56am 17/10/18

Person Contacted:

Vincent

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6252P-x
	SH 6980P- CC3/CTI18001207/Klwb3g2
24/10/18	1130am rented to May chuan by email.

DOA: 17/10/18

001113

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 6252P Yr Regn: 5 Nov 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: KIA Optima C.C. 1685

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 325000 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA6M414MF554381X

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: -1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. _____ D.O.I. 24/10/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
7/11/8	Check PIP \$330 / 24h. (Red B 2909.80, 90%) FCI 4/5

RECEIVED 07 NOV 2010

Date/Time, File Pass to?

☐ : Preli. Report

1) 21/11/14 Final

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

130

50

50

18

248

Report Format: 7P

Lump Sum / I.B.I.: (\$ 330)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007478MFSH

Date: 24 October 2018

Our Ref: CS/FCI18018857/K1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6252P .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/10/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,239.80 .
Revised Estimate Amount	: S\$ 330.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the rear portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-10-2018	Our Ref No.	D18007478MFSH
Accident Date	14-10-2018	Claim Type.	Third Party
Insured Vehicle	SH6980P	Third Party Vehicle.	SHC6252P
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02		
Contact Person.	VINCENT CHUA		
Contact No.	62148880/ 65446689	Fax No.	62141511
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MAY CHUA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/245074)



PRI Documents



Close



PRI Header Details

Claim No	D18007478MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : VINCENT CHUA)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446689 , Phone: 62148880 , Fax: 62141511 EmailId: VINCENT.CHUA@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6980P	TP Vehicle No	SHC6252P
PRI Recieved Date	15-10-2018 09:20:44 PM	Surveyor Appointed Date	16-10-2018 04:58:48 PM	Surveyor Accept Date	17-10-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	17-10-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 24 October 2018 11:30 AM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007478MFSH/1
Attachments: CSFCI18018857K1qd3.pdf

Dear May,

Enclosed herewith preliminary advice of SHC 6252P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 17 October 2018 9:58 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007478MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 16 October 2018 4:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007478MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	05 Nov 2014 / 09:19:17	Receipt No.:	AACCK001-AX239-141105-000005
Asset Type:	Vehicle	Transaction Amount:	\$63,855.00
Asset ID:	SHC6252P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141105091917993142		

Vehicle No.:	SHC6252P
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)

First Registration Date:	05 Nov 2014
--------------------------	-------------

Original Registration Date:	05 Nov 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5543814
Engine No.:	D4FDEH311463
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050

Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$19,878.00
Minimum PARF Benefit:	\$7,426.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	05 Nov 2014 09:19:17
COE No.:	2014110501001226N
COE Expiry Date:	04 Nov 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,337.00
Lifespan Expiry Date:	04 Nov 2022
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

22-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6252 P

1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X sue</i>	\$	206.00
		\$	902.00
	Less 10%	\$	90.20
		\$	811.80

S/NETT

1 set	Rear bumper clips <i>X 1"</i>	\$	48.00
1 set	Reverse sensor <i>X sue</i>	\$	280.00
1 set	Bootlid stickers <i>X 1"</i>	\$	100.00
1 pc	Rear bumper top protector <i>/ ne</i>	\$	80.00 <i>50</i>
	Sundry	\$	50.00 <i>X 1"</i>
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 <i>X 1"</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>X 1"</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc	\$	650.00 <i>100</i>
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel <i>X</i>	\$	800.00 <i>180</i>
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 <i>X 1"</i>
		\$	3,239.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE

ANY UNFORESEEN DAMAGES.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification is allowed
- Supplementary repair must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

Kalvin 10/11/18

22/10/18 1310hrs

2 hrs.

After Repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18018857/K1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6980P	Veh. Inspected	SHC 6252P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18007478MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	16/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414MF5543814	Colour	SILVER	
Odometer	325000	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	7 mm	
L/H Front Tyre	205/65 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/10/2018	Inspection Date	22/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6252P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	SERVICEABLE	206.00	-
	LESS 10% DISCOUNT		-90.20	-
			811.80	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	SET BOOTLID STICKERS (SN)	NOT NECESSARY	100.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			558.00	50.00
	LABOUR			
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		650.00	100.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL.		800.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			1,870.00	280.00
	GRAND TOTAL		3,239.80	330.00

Report Ref No. CS/FCI18018857/K1qd3n2



RECOMMENDED COST OF REPAIRS			330.00
-----------------------------	--	--	--------

Report Ref No. CS/FCI18018857/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.