

ASS. REC. BY:

REF: CS/C7118018902/ Uvd30

Special instruction:

Surveyor
men

March

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

17/10/18 @ 3:36pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV¹/CS

To Inspect Vehicle No:

GBF 508Y

Insured:

GBD 4306 y

at Workshop m/s

Liu's brother

Tel:

67411730

of

1 kaki Blt Ave G # 01-01

Policy No:

DMCVSN3102481701

Claim No:

SNM18D04908C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/10/2018

CA / REV / REP. / REV 24 HRS 14/11

18/10/2018

H.O.D. Endorsement:

Date/Time:

4.03pm @ 17/10/18

Person Contacted:

Jasmine

Vehicle IN/OUT

Date/Time

Action/Instruction	(✓)	Estimate
1. Review the project scope and objectives.		
2. Identify the key stakeholders and their roles.		
3. Conduct a risk assessment and develop a risk management plan.		
4. Develop a detailed project schedule and timeline.		
5. Allocate resources and assign tasks to team members.		
6. Monitor project progress and communicate regularly with stakeholders.		
7. Address any issues or changes that arise during the project.		
8. Complete the project and evaluate the results against the objectives.		

GIBF 508Y-X

QBD 4306 Y-X

ASSIGNMENT

From: _____ Date: 18/10/2018

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: GBF 508Y

at Workshop m/s Liu's Brother

of Ikaki Bkt Ave 6 # 01-01

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: 63F508Y Yr Regn: 6, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM

Make: FIAT 206/0 c.c. 1598

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: 33040 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2FA263000638539f

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/10/18 D.O.I. 18/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 2/5

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time 2/11/18 Action / Instruction 4/5 \$2500 confirmed with Susan. (Red 2532.30, 5070)

RECEIVED 02 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 2/11 - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:	<u>220</u>
Transportation:	_____
_____ S + RS. _____ SI	_____
Photos	_____
Others	_____
TOTAL	<u>220</u>

Report Format: Merimen

Lump Sum / I.B.I. (\$) 2500/2

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		17 Oct 2018 15:36 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	EVERFRESH VEGETABLE FARM, Co. Reg. No.: 52866859E		
Main Claimant:	GOLDBELL LEASING PTE LTD		
Vehicle Reg. No.:	GBF508Y	Date of Loss:	15/10/2018 10:00 - :59
Claim Type:	TP / SNM18D04908C02	Policy/Cover Note No.:	DMCVSN3102481701 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD4306Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 16 Oct 2018 / 15:29:57

Receipt Date/Time : 16 Oct 2018 / 15:29:57

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181016-001619

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - GBD4306Y As at 15 Oct 2018/10:30:00 Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD			
1	Insurance Enquiry - GBD4306Y Enquiry Fee 20181016152846775115	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx4559 Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBF508Y
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	263A50007512380
Chassis No.:	ZFA26300006B85398
Maximum Power Output:	-
Open Market Value:	\$19,894.00
Original Registration Date:	03 Jun 2016
First Registration Date:	03 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$995.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$35,452.00
Total Rebate Amount:	\$35,452.00

The information contained herein is correct as at 18 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 17:40
Date Of Accident	15/10/2018 10:30
Exact Location Of Accident	ALONG UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF508Y
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833
Vehicle Particulars	
Manufacturer	FIAT
Model	DOBLO CARGO MAXI-1.6 D MTJ AMT GLAZE (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090757MFCV
Cover Note Number	
Driver	
Name of Driver	SINNAIYA A/L PERIASAMY
Passport No/FIN	F8420460U
Date Of Birth	22/02/1977
Occupation	OUTDOOR
Date Of Driving Pass	05/11/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93873950
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	18 TUAS AVE 10 LEVEL 6
Postcode	639142
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 15/10/18 AT ABOUT 1030HRS, I WAS AT THE TRAFFIC LIGHT JUNCTION BETWEEN UPPER BUKIT TIMAH ROAD AND OLD JURONG ROAD. MY VEHICLE WAS STATIONARY AS THE TRAFFIC LIGHT WAS RED. SUDDENLY, I FELT AN IMPACT FROM THE REAR. BEFORE I COULD ALIGHT FROM MY VEHICLE AND TAKE PHOTOGRAPHS, VEHICLE B DRIVER HAD SHIFTED HIS VEHICLE TO THE RIGHT LANE. MY VEHICLE'S REAR RIGHT DOOR GLASS WAS BROKEN. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD4306Y
Vehicle Make/Model/Colour	TOYOTA / DYNA / BLUE
Details Of Properties	VEH B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	91299580
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature *[Signature]*
(If driver is not the policyholder)
Date & Time: 28 FEB 2014



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/10/13 at about 1030hrs, I was at the traffic light junction between Upper Bukit Timah Rd and Old Junc Road. My vehicle was stationary as the traffic light was red. Suddenly, I felt an impact from the rear before I could alight from my vehicle and take photographs. Vehicle B driver had shifted his vehicle to the right lane. My vehicle's rear right door glass was broken. No one was injured.

'A' stopped at traffic light junction. B collided into his vehicle's rear door glass. Before 'A' driver could alight to take photos, B had shifted his vehicle to the ~~the~~ right lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/TIN No.:

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF508Y181015

Estimate

Customer

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Date: 16-10-18

Vehicle No: GBF508Y

Model/Make: Fiat Doblo Cargo

SX JTD 1.6 MJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear 1 Bumper <i>2e/cut</i>	\$ 627.00	✓
2	Bumper Clips 1 set <i>neu</i>	\$ 65.00	SN ✓
3	Bumper Reinforcement <i>nn</i>	\$ 475.30	X
4	Bumper Reverse Sensor 1 set <i>1 1</i>	\$ 220.00	SN X
5	Tailgate Outer Garnish <i>nn</i>	\$ 279.00	X
6	Tailgate "Fiat Logo" Emblem <i>nn</i>	\$ 87.80	X
7	Tailgate "Professional" Emblem <i>neu</i>	\$ 163.50	✓
8	Tailgate "6 PAX" Sticker <i>neu</i>	\$ 12.00	SN 10 S. N
9	Tailgate Windscreen Glass <i>shatter</i>	\$ 540.00	✓
10	Tailgate Windscreen Glass Sealant <i>neu</i>	\$ 80.00	SN 40 S. N
11	Tail Lamp <i>neu</i>	\$ 462.70	✓
12	"Corporate" Advertisement & Artwork <i>neu</i>	\$ 300.00	SN ✓ S. N
	To check all wiring & electrical component for proper function	\$ 50.00	20
	Remove and refix rear bumper reverse sensor	\$ 100.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	520
	To putty & spray painting & including touch up paint on accident affected	\$ 600.00	400
	Remove & reinstall Tailgate Glass to facilitate repairs & perform water test	\$ 120.00	✓
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 50.00	X

Total Parts & Labour of estimate for damaged vehicle

\$ 5,032.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Allowed**due**d/s 2500/**427**18/10/18**2kght. After rep.**2-1882**17**1672.38**3132.38*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Oct 2018		17 Oct 2018 15:36 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: EVERFRESH VEGETABLE FARM , Co. Reg. No.: 52866859E									
Main Claimant: GOLDBELL LEASING PTE LTD									
Vehicle Reg. No.: GBF508Y		Date of Loss: 15/10/2018 10:00 - :59 [28 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04908C02		Policy/Cover Note No.: DMCVSN3102481701 (Comprehensive)							
Vehicle Reg. No. (Insured): GBD4306Y		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/10/2018]									
Adj Asg. Remarks: NO EST, ASSIGN MARCUS CHUA AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF508Y (SNM18D04908C02)
[GBD4306Y]
TP
GOLDBELL LEASING PTE LTD
Oct 15 2018 10:00AM
[EVERFRESH VEGETABLE FARM]
Liu's Brother Auto Engineering Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	15/10/18 17:42	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	15/10/18 17:41	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/11/18 09:35	General View	Load PDF	










Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/10/18 15:36	PRS	Load PDF	
2	17/10/18 15:36	TP GIA	Load PDF	
3	17/10/18 15:36	OI GIA	Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	15/10/18 17:40	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	15/10/18 17:41	IC,DL,CI [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	15/10/18 17:42	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	15/10/18 17:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	15/10/18 17:41	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
3	15/10/18 17:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	15/10/18 17:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	15/10/18 17:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	15/10/18 17:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	15/10/18 17:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	15/10/18 17:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	15/10/18 17:41	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	15/10/18 17:40	Sketch Plan	 Load TIF	
2	15/10/18 17:41	IC,DL,CI	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018902/UVD3E2

Date: 05/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3102481701

Claimant Vehicle
No: GBF508YInsured Vehicle
No: GBD4306Y

Date of Loss: 15/10/2018

Nature of Claim: TP

Claim
No: SNM18D04908C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF508Y**

Make & Model: FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M) Engine No: 263A50007512380

Reg. Date: 03/06/2016 (Man. Year: 2015) Chassis No: ZFA26300006B85398

Colour: White Odometer: 33040 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,312.30	2,022.38	1,289.92	38.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	1,110.00	610.00	35.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,032.30	3,132.38	1,899.92	37.75
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	5,032.30	2,500.00	2,532.30	50.32

INSPECTION

Date of Assignment: 17/10/2018

Date Inspected: 18/10/2018 Inspected At:

Liu's Brother Auto Engineering Workshop
(HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO
BAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2018)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF508Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Cut	627.00 F	*627.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*65.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	475.30 F	*- FL
4	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
5	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	279.00 F	*- FL
6	1		*REAR TAILGATE FIAT LOGO EMBLEM	Not Necessary	87.80 F	*- FL
7	1		*REAR TAILGATE PROFESSIONAL EMBLEM	Necessary	163.50 F	*163.50 FL
8	1		*REAR TAILGATE 6 PAX STICKER	Necessary	12.00 FS	*10.00 FS
9	1		*REAR TAILGATE WINDSCREEN GLASS	Shorted	540.00 F	*540.00 FL
10	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
11	1		*REAR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	300.00 FS	*300.00 FS
12	1		*REAR TAIL LAMP O/S	Cracked	462.70 F	*462.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,312.30	2,208.20
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	185.82
Total Parts (S\$)	3,312.30	2,022.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	100.00	50.00
3	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	520.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	600.00	400.00
5	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST	New	120.00	120.00
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
Gross Labour Cost (\$\$)			1,720.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >