

ASS. REC. BY:

REF:

CS3/MSG18018932/Gcd3

Special Instruction:

Surveyor
menmen

ASSIGNMENT (Office)

From (Person): Christina Wong of MSG Date/Time: 17/10/18 @ 4:06pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBA 3522L Insured: SLL 4847S

at Workshop m/s H.E Xin Motor Tel: 9487 7625

of Blk 25 Kaki Blk Rd 4 # 01-75

Policy No: A804 5357 0AMX Claim No: 573349

Sum Insured: Excess:

Make of Veh: D.O.A. 15/10/2018
(Client's Record) 23/10/18

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 9:40am @ 18/10/18 Person Contacted: Irene Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	FBA 3522L - X
	SLL 4847S - X.
	Dismantle: 25/10/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		17 Oct 2018 16:06 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GOH AR HEE, ID: S1456390C		
Main Claimant:	GOH JIN FA, ID: S9111327I		
Vehicle Reg. No.:	FBA3522L	Date of Loss:	15/10/2018 10:00 - :59 [150 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 573349	Policy/Cover Note No.:	A80453570QMX (Comprehensive) Coverage: 27/01/2018 - 13/02/2019
Vehicle Reg. No. (Insured):	SLL4847S	Policy No. (Claimant):	
		Excess:	
Repairer:	He Xin Motor (HQ) BLK 25 KAKI BUKIT ROAD 4 #01-75 SYNERGY@KB SINGAPORE 417800, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/10/2018]		
Driver/Custodian (Insured):	WONG JUN JIE (), NRIC: S8531653B, Tel: +6581514545		
Adj Asg. Remarks:	Liability is down, TP disagree with our SJE list. Proceed to appoint LKK. Contact Person: Ah Keong / 9060 3128 - Serene / 9487 7625.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 13:24
Date Of Accident	15/10/2018 10:10
Exact Location Of Accident	JALAN TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBA3522L
Insured/Policyholder	
Name Of Registered Owner	GOH JIN FA
NRIC No	S9111327I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81633559
Alternative Phone No	OTHERS-81633559

Vehicle Particulars

Manufacturer	YAMAHA
Model	SPARK 135 M
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5053861738-06
Cover Note Number	

Driver

Name of Driver	GOH JIN FA
NRIC No	S9111327I
Date Of Birth	07/04/1991
Occupation	INDOOR
Date Of Driving Pass	11/03/2010
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81633559
Fax Number	
Contact Number	OTHERS-81633559
Email Address	NOEMAIL

Address	BLK 871B #08-28 TAMPINES STREET 86 SINGAPORE 522871
Postcode	522871
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION. MY VEHICLE WAS STATIONERY AT THAT TIME OF ACCIDENT. WHEN VEHICLE B-SLL4847S UNABLE TO REACT ON TIME AND THUS COLLIDED ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4847S
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG JUN JIE(HUANG JUNJIE)
NRIC/Passport Number	S8531653B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT PORTION
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

15 OCT 2018


Policyholder's Signature

Date & Time:


Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre Roadside Assistance

Name: **Singapore 415933**

NRIC/TEL: **67416697** Fax: **67492305**

Email: **vackb@singnet.com.sg**

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ref
e-file

DECLARATION

I/We declare the foregoing particulars are true in every respect.

DAVID TAN
POLICYHOLDER'S SIGNATURE
Date & Time: 15 OCT 2018

DRIVER'S SIGNATURE
(If driver is not the policyholder)
Date & Time:

15 OCT 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Reporting Centre Personnel's Signature
Name:
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg



SINGAPORE POLICE FORCE



T/20181017/2003D

1 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20181017/2003D

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/10/2018 21:23		Vide Report No.:		Station Diary No.: 5009	
Informant's Particulars					
Name of Informant: GOH JIN FA			Address: APT BLK 871B TAMPINES STREET 86 #08-28 SINGAPORE 522871		
ID Type / ID No.: NRIC NO / S9111327I			Contact No.: Home/Office: Mobile: 81633559		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 07/04/1991	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: sales			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 15/10/2018 10:15	Type of Location: Straight Road
Location: Along Road 1 PAN-ISLAND EXPRESSWAY (JALAN TOA PAYOH)				
TOWARDS MACHPERSON				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBA3522L	Motorcycle	YAMAHA	SPARK 135 M	Black	Seriously Damaged	0
SLL4847S	Car				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBA3522L	NTUC Income Insurance Co-Operative	5053861738-06	07/04/2018	06/04/2019



SINGAPORE POLICE FORCE



T/20181017/2003D

2 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20181017/2003D

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	GOH JIN FA	ID No.	S9111327I
Related Vehicle	FBA3522L (Motorcycle)	Contact No.	81633559
Hospital/Clinic	B.T GOH FAMILY CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	17/10/2018	Date Discharge	17/10/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 15/10/2018 at about 1012hrs, I was riding along Jalan Toa Payoh heading towards Machperson in my motorcycle bearing the plate number FBA3522L. The traffic was heavily congested at that point of time.

Subsequently, the traffic light in front turned to red and thus I stopped my m/cycle when suddenly one vehicle bearing the plate number SLL4847S had collide with the rear of my m/cycle.

No one was injured at that point of time. Both exchanged particulars with each other before resuming our journey. Then I felt some pain at the back thus I seek medical attention and were given 3 days MC.



**SINGAPORE
POLICE FORCE**



T/20181017/2003D

3 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20181017/2003D

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 3 MOHAMAD IZWAN BIN MOHAMAD
ISHAK

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
17/10/2018 21:23

Classification Of Case:



SINGAPORE
POLICE FORCE

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	13271
Vehicle Details	
Vehicle No.:	FBA3522L
Vehicle to be Exported:	No
Planned Deregistration Date:	24 Oct 2018
Vehicle Make:	YAMAHA
Vehicle Model:	SPARK 135 M
Primary Colour:	Black
Secondary Colour:	Grey
Manufacturing Year:	2005
Chassis No.:	5YP709053
Engine No.:	5YP709053
Maximum Power Output:	-
Current Market Value:	\$1,786.00
Original Registration Date:	07 Apr 2006
Latest Registration Date:	07 Apr 2006
Transfer Count:	6
Total ARF Paid:	\$268.00
Eligible PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Eligible COE Rebate Details	
COE Expiry Date:	06 Apr 2021
COE Category:	D - Motorcycle
COE Period(Years):	5
COE Paid:	\$3,280.00
COE Rebate Amount:	\$1,608.00
Final Rebate Amount:	\$1,608.00
Remarks	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Oct 2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Oct 2018		17 Oct 2018 16:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GOH AR HEE, ID: S1456390C		
Main Claimant:	GOH JIN FA, ID: S91113271		
Vehicle Reg. No.:	FBA3522L	Date of Loss:	15/10/2018 10:00 - :59 [150 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 573349	Policy/Cover Note No.:	A80453570QMX (Comprehensive) Coverage: 27/01/2018 - 13/02/2019
Vehicle Reg. No. (Insured):	SLL4847S	Policy No. (Claimant):	
		Excess:	
Repairer:	He Xin Motor (HQ) BLK 25 KAKI BUKIT ROAD 4 #01-75 SYNERGY@KB SINGAPORE 417800, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 18/10/2018]		
Driver/Custodian (Insured):	WONG JUN JIE (), NRIC: S8531653B, Tel: +6581514545		
Adj Asg. Remarks:	Liability is down. TP disagree with our SJE list. Proceed to appoint LKK. Contact Person: Ah Keong / 9060 3128 - Serene / 9487 7625.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBA3522L (573349)**
[SLL4847S]
TP
GOH JIN FA
Oct 15 2018 10:00AM
[GOH AR HEE]
He Xin Motor

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports				1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	17/10/18 14:45	Accident Statement From:SC - Reg. No: SLL4847S, Claimant: GOH AR HEE	1	Load HTM	

Photos/Images				3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/10/18 12:40	General View	1	Load JPG	✓
2	28/10/18 12:40	General View	1	Load JPG	✓
3	28/10/18 12:40	General View	1	Load JPG	✓
4	28/10/18 12:40	General View	1	Load JPG	✓
5	28/10/18 12:40	General View	1	Load JPG	✓
6	28/10/18 12:40	General View	1	Load JPG	✓
7	28/10/18 12:40	General View	1	Load JPG	✓
8	28/10/18 12:40	General View	1	Load JPG	✓
9	28/10/18 12:40	General View	1	Load JPG	✓
10	28/10/18 12:40	General View	1	Load JPG	✓
11	28/10/18 12:40	General View	1	Load JPG	✓
12	28/10/18 12:40	General View	1	Load JPG	✓
13	28/10/18 12:40	General View	1	Load JPG	✓
14	28/10/18 12:40	General View	1	Load JPG	✓
15	28/10/18 12:40	General View	1	Load JPG	✓
16	28/10/18 12:40	General View	1	Load JPG	✓
17	28/10/18 12:40	General View	1	Load JPG	✓
18	28/10/18 12:40	General View	1	Load JPG	✓
19	28/10/18 12:40	General View	1	Load JPG	✓
20	28/10/18 12:40	General View	1	Load JPG	✓
21	28/10/18 12:40	General View	1	Load JPG	✓
22	28/10/18 12:40	General View	1	Load JPG	✓
23	28/10/18 12:40	General View	1	Load JPG	✓
24	28/10/18 12:40	General View	1	Load JPG	✓
25	28/10/18 12:40	General View	1	Load JPG	✓
26	28/10/18 12:41	Photographs of Damaged Parts	1	Load JPG	✓
27	28/10/18 12:41	Photographs of Damaged Parts	1	Load JPG	✓
28	28/10/18 12:41	Photographs of Damaged Parts	1	Load JPG	✓
29	28/10/18 12:41	Photographs of Damaged Parts	1	Load JPG	✓
30	28/10/18 12:41	Photographs of Damaged Parts	1	Load JPG	✓
31	28/10/18 12:41	Photographs of Damaged Parts	1	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
33	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
34	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
35	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
36	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
37	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
38	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
39	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
40	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
41	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
42	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
43	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
44	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
45	28/10/18 12:41	Photographs of Damaged Parts	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/10/18 14:45	FBA3522L GIA Rpt From:SC - Reg. No: SLL4847S, Claimant: GOH AR HEE	Load PDF	
2	17/10/18 14:46	PRI - RIAZ LLC	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	17/10/18 16:06	Christina's instruction	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18018932/GCD3S2

Date: 30/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80453570QMX
Claimant Vehicle No :	FBA3522L	Insured Vehicle No :	SLL4847S
Date of Loss:	15/10/2018	Nature of Claim:	TP
		Claim No:	573349

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBA3522L	Engine No:	5YP709053
Make & Model:	YAMAHA SPARK, 135cc	Chassis No:	5YP709053
Reg. Date:	07/04/2006 (Man. Year: 2005)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/10/2018	He Xin Motor (HQ) BLK 25 KAKI BUKIT ROAD 4 #01-75 SYNERGY@KB SINGAPORE 417800 Singapore 417800
Date Inspected:	23/10/2018 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500.00 - \$1,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Oct 2018)	
Parts:	N/A	YAMAHA SPARK 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBA3522L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >