

22/03/2002

ASS. REC. BY:

REF:

CS3/ALG18018948/God302

Special Instruction:

Surveyor:

From (Person):

GWO Siang
Meymen
Chin Lee Ying

ASSIGNMENT (Office)

of ALG

Date/Time: 18/10/18 @ 1:15pm

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 9489G

Insured:

SLT 4220H

at Workshop m/s

Apex Motoring

Tel:

9234 2543

of

25 Kaki Bukit Road 4 # 01-55

Policy No:

1F00071605

Claim No:

15044603862G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/10/18

CA / REV / REP. / REV 24 HRS

hp

H.O.D. Endorsement:

Date/Time:

2:00pm 18/10/18

Person Contacted:

Mr. Wei

Vehicle IN/OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|-----------------------------------|
| | SLV 9489G - X |
| | SLT 4220H - X |
| | |
| | |
| | |
| | |
| | |

Signature

PKS
XAL

REF:

ALG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV9489G

Yr Regn:

Jan 18

Type: M/Gas / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

09811

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP 71121 399

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185 / 60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

18-10-18

Survey held at

w/s

23:40pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~\$2000 - \$3000~~

~~No GIA Given~~

Repair days 4

TGLim
19/10/18

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format : DAR.

Lump Sum / I.B.I. (\$

180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 18/10/2018 1:15:08 PM
Attachments:  NEW PRI - SLT4220H AND SLV9489G.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



17/102018

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

Fax : 6415 3727

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SLV 9489 G AND VEHICEL NO. SLT 4220 H
ON 14/10/2018 @ 1610 Hrs**

We are the appointed repair workshop of vehicle no. **SLV 9489 G**

We understand that you are the insurer of vehicle no. **SLT 4220 H**

The owner of vehicle number **SLV 9489 G** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800
Mobile No. 9234 2543 Please email 10 surveyors list. Email: peijic@expresscar.com.sg

Yours faithfully

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|-------------------------------------|---------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 0532R |
| Vehicle Details | |
| Vehicle No.: | SLV9489G |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 19 Oct 2018 |
| Vehicle Make: | HONDA |
| Vehicle Model: | SHUTTLE HYBRID 1.5 AUTO |
| Primary Colour: | Silver |
| Manufacturing Year: | 2017 |
| Engine No.: | LEB6326385 |
| Chassis No.: | GP71121399 |
| Maximum Power Output: | 101.0 kW (135 bhp) |
| Open Market Value: | \$20,941.00 |
| Original Registration Date: | 23 Jan 2018 |
| First Registration Date: | 23 Jan 2018 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,000.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 22 Jan 2028 |
| PARF Rebate Amount: | \$3,750.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 22 Jan 2028 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$42,661.00 |
| COE Rebate Amount: | \$39,495.00 |
| Total Rebate Amount: | \$43,245.00 |

The information contained herein is correct as at 19 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--|
| Date Of Report | 15/10/2018 18:07 |
| Date Of Accident | 14/10/2018 16:10 |
| Exact Location Of Accident | JUNCTION OF PASIR RIS GROVE AND PASIR RIS DR8 FLYV |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SLV9489G |
| Insured/Policyholder | |
| Name Of Registered Owner | STALLION AUTO PTE LTD |
| Co Reg No | 201730532R |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-90034963 |
| Alternative Phone No | OFFICE-90034963 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | HONDA |
| Model | SHUTTLE |
| Exact Purpose for which vehicle was being used at time of accident | HIRER USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5097634604 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | TEO GEK HUAY |
| NRIC No | S1637846A |
| Date Of Birth | 15/06/1964 |
| Occupation | INDOOR |
| Date Of Driving Pass | 04/05/1982 |
| Driving Experience | 36 YEARS AND 5 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-90034963 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|---------------------------------|
| Address | BLK 266 PASIR RIS ST 21 #04-408 |
| Postcode | 510266 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | RAINING |
| Road Surface | WET |

Other Information

| | |
|---|-------------------------------------|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 3 |
| Passenger 1 | NAME: : UNKNOWN GENDER: : MALE |
| Passenger 2 | NAME: : UNKNOWN GENDER: : FEMALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------|
| Vehicle Registration Number | SLT4220H |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | CECILIA TANG |
| NRIC/Passport Number | |
| Contact Number | 98508821 |
| Address | |
| Postcode | |
| Insurance Company Name | |

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 15/10/18
3 30 PM

Driver's Signature


(If driver is not the policyholder)
Date & Time: 15/10/18
3 30 PM

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14 Oct, Sunday, at around 4.10 pm, my car was at junction of pasir ris road waiting to filter onto pasir ris flyover and SLT4220H driven by Ms Cecilia Tang knocked onto the back of my car SW9488G.

DECLARATION

I/We declare the above particulars are true in every respect.



Policyholder's Signature

Date & Time: 15/10/18
3 30pm

Driver's Signature

(If driver is not the policyholder)
Date & Time: 15/10/18
3 30pm

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

MOTORCAR (Rear)

Rear Portion

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-----------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | DD | ✓ | |
| 1142 | 993085 | Rear Bumper Upper | | | |
| 1143 | 993017 | Rear Bumper Lower | | | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | NEC | ✓ | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | | | |
| 1149 | 993045 | Rear Bumper Reinforcement | | | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor | | | |
| 1159 | 993327 | Rear End Panel | DD | ✓ | |
| 1160 | 993339 | Rear End Panel Top Garnish | | | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | | | |
| 1171 | 991328 | Bootlid Emblem | | | |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector | | | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | | | |
| 1177 | 995243 | Bootlid Lock | | | |
| 1178 | 990377 | Bootlid Rubber | | | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | DD | ✓ | |
| 1182 | 991328 | Tailgate Emblem | NEC | ✓ | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | NEC | ✓ | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | BT | ✓ | |
| 1198 | 994651 | Tailgate Rubber | DD | ✓ | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

Vehicle No: SLV 9489G

| NAC | INC | Item | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1255 | 990247 | Sticker | | | |

No of Items: 6

Assessor: ..

TGim 19/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|------|---|---------------|---|--|--|-------------|---|
| Main | 18 Oct 2018 Edit Reg | | 18 Oct 2018 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: Tang Yan Qing Cecilia , ID: S8511995H | | | | | | | | | |
| Main Claimant: - | | | | | | | | | |
| Vehicle Reg. No.: SLV9489G | | Date of Loss: 14/10/2018 00:00 - :59 [8 Months and 21 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP / 1504460386SG | | Policy/Cover Note No.: 1700071605 | | | | | | | |
| Vehicle Reg. No. (Insured): SLT4220H | | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel: | | | | | | | | | |
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/10/2018] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG (19/10/2018): Request to upload TP GIA Report AIG_SG (19/10/2018): No OI GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |






















Claim Documents

***SLV9489G (1504460386SG)**
[SLT4220H]

TP

-

Oct 14 2018 12:00AM
[Tang Yan Qing Cecilia]
Apex Motoring

| | | | | | | | | | | | | | | | | | | | | |
|------------------|-----------------|-----------------------------------|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|---|-----------|-------------------------------------|-------------------------------------|--|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View | | | View in Browser | | |
| Photos/Images | | | | | | | | | | | | | | | 3 per page | | | <input checked="" type="checkbox"/> | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | | | Thumbnail | Print | | | |
| 1 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 2 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 3 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 4 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 5 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 6 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 7 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 8 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 9 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 10 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 11 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 12 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 13 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 14 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 15 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 16 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 17 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 18 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 19 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 20 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 21 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 22 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |
| 23 | 19/10/18 12:14 | General View | | | | | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | | | |

Documents Checklist

| | | | | |
|--|--|-------|------|-------|
| DOCUMENTS CHECKLIST | | Reset | Save | Print |
| There are no document checklists configured. | | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div> | | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18018948/GCD3E2

Date: 30/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700071605
Claimant Vehicle No : SLV9489G **Insured Vehicle No :** SLT4220H
 Date of Loss: 14/10/2018 Nature of Claim: TP Claim No: 1504460386SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV9489G**
 Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6326385
 Reg. Date: 23/01/2018 (Man. Year: 2017) Chassis No: GP71121399
 Colour: Silver Odometer: 69811 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 18/10/2018
 Date Inspected: 18/10/2018 Inspected At: Apex Motoring
 25 Kaki Bukit Road 4, #01-55 Synergy @
 KB
 Singapore 417800
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|-----------------------------|--------------------------|-------------|-------------|
| 1 | 1 | | *REAR BUMPER | Dented | 0.00 F | *- F |
| 2 | 1 | | *REAR BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 3 | 1 | | *REVERSE SENSOR | * Check | 0.00 F | *- F |
| 4 | 1 | | *REAR END PANEL | Repair | 0.00 F | *- F |
| 5 | 1 | | *REAR END PANEL TOP GARNISH | * Check | 0.00 F | *- F |
| 6 | 1 | | *TAILGATE | Dented | 0.00 F | *- F |
| 7 | 2 | | *TAILGATE EMBLEM / HYBRID | Necessary | 0.00 F | *- F |
| 8 | 1 | | *TAILGATE GLASS RUBBER | Necessary | 0.00 F | *- F |
| 9 | 1 | | *TAILGATE GLASS MOULDING | Necessary | 0.00 F | *- F |
| 10 | 1 | | *TAILGATE GLASS SEALANT | Necessary | 0.00 F | *- F |
| 11 | 1 | | *TAILGATE LOCK | Bent | 0.00 F | *- F |
| 12 | 1 | | *TAILGATE RUBBER | Dented | 0.00 F | *- F |
| F=Franchise part. | | | | | | |
| | | | | Total Parts (S\$) | 0.00 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >