

15/5/2011

INS. CASE OWNER:

CC 6/CTI1801 8966, K Johnz

LKK:

IDAC:

Surveyor:

FSC

DOI:

ASSIGNMENT

17/10/18

Date / Tim:

17/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SGD 3222X

Claim No. :

SWM1500467002

Name of Insured :

UM Fok Ann

Policy No. :

UMP15N71067083

Insured Tel No. :

HP:

98208225

Make / Model :

TOYOTA

Excess Sec II :SS

D.O.A. :

11/10/18

Place of Accident :

JUNE BEL PERMET RD TO LOWER DELTA RD.

Is driver the owner? (YES) / NO

(YES) / NO

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L) (YES) / NO

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability : % Final ? Yes / No

SN 7645B



INSRS:

WSP:

Tel :

Liability :

RMKS:

wei lee



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time	STAGE	DATE / PIC
24/10/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	JULY 1 22 JAN 19
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	days) Reduction:	% Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 23-19	Confirm with: KAREN	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No. :	27
Repair Cost:	SS 3,050.xx		
Loss of Rental (LOR):	SS (days)		
Loss of Use (LOU):	SS 360 (560 x 6 days)		
Loss of Income (LOI):	SS - (S x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 3,417.45	Global Sum SS:	3,400
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 3,400.xx	Name 1:	WEI LEE MOTOR WORKS
Payee 2: (Strike if N.A.)	SS x	Name 2:	x
Payee 3: (Strike if N.A.)	SS	Name 3:	x

COPY SENT 17/11/18

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Wei Kee

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 13k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STN 7645B Yr Regn: 02 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or MPV

Make: Toy Wish c.c. 1.790

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading 235672 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W603 002160

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Si/Rlm / STD A/Rlm or

Tyre Size: F: Nexen 195/65R15

B: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm Rear 4 mm

L/Bal. 2 mm U/Bal. 4 mm

D.O.A. 11/10/18 D.O.I. 17/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/10 File pass to Catherine

45 \$3,050

RC \$ 3,918.17 / 56%

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trlp: _____

- Add Fee:
- : Site Insp (\$)
 - : Interview (\$)
 - : Tech Invs (\$)
 - : Weekend (\$)

Survey Fee:	
Transportation:	
S - RS, SI	
Fuel	
Others	
TOTAL	

Report Format :

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18018966/Kjb3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 18-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 3233X	Veh. Inspected	SJN 7645B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/10/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/10/2018	Inspection Date	17/10/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CT118018966/Kjb3

Date: 18.10.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJN7645B


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.10.2018 at the premises of M/s Wei Lee Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$	<u>6,968.17</u>
Revised Estimate Amount	: S\$	<u>3,568.01</u>
"Check" Items Amount	: S\$	<u>1,280.90</u>
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 1813C

Vehicle Details

Vehicle No.: SJN7645B
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Oct 2018
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 AUTO
Primary Colour: Blue
Manufacturing Year: 2009
Engine No.: 1ZZ3232829
Chassis No.: JTDER12W603002160
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$18,662.00
Original Registration Date: 26 Feb 2009
First Registration Date: 26 Feb 2009
Transfer Count: 1
Actual ARF Paid: \$18,662.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Feb 2019
PARF Rebate Amount: \$9,331.00

Intended COE Rebate Details

COE Expiry Date: 25 Feb 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$4,889.00
COE Rebate Amount: \$159.00
Total Rebate Amount: \$9,490.00

The information contained herein is correct as at 16 Oct 2018

OK

威利摩哆

WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

11/10/2018

*Not Authorized
L1 Pump @ ?
Resurvey After Paint
6 days*

17, October 2018

China Taiping Insurance (S) PL
105 Cecil Street #18-00
The Octagon
S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SGD3233X
Accident involving vehicle no: SJN7645B/SGD3233X
DOA: 11/10/2018 AT Bukit Purmei Ave

Dear officer incharge
Re: estimate cost of repair for vehicle no: SJN7645B
To supply--

photo

Descriptor	Qty		Amount	
Lid	1	<i>Hy</i>	1,210.40	✓
Lid-doorboard	1	<i>Sm</i>	328.20	X
Hid-handle	1	<i>Sm</i>	239.00	X
Lid lock	1	<i>Ac</i>	443.50	✓
Lid hinge @55.30	2	<i>R</i>	110.60	X
End panel	1		441.20	?
End panel top garnish	1	<i>mg D11</i>	232.90	✓
Spare tyre boot garnish	1	<i>Sm</i>	562.90	X
Exhaust tailpipe	1	<i>R</i>	798.80	X
Taillamp @472	2	<i>ols cm</i>	944.00	✓
Rear bumper	1	<i>Bu</i>	470.70	✓
Rear bumper retainer @56.05	2	<i>ols D11</i>	112.10	✓
Rear bumper lower skirt	1	<i>Bu</i>	423.00	✓
Rear windscreen sealant	1	<i>na</i>	76.00	<i>4asa</i>
Boot weatherstrip <i>(N 48.50)</i>	1	<i>cu</i>	97.60	<i>50/Sm</i>
		Parts	6,490.90	
		Parts less 25%	1,622.72	
			4,868.17	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental items must be resurveyed and is subject to Insurance Company approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Vehicle no: SJN7645B

To remove/transfer rear windscreen glass
Reverse sensor
To remove damaged parts and attachments.
Cut n weld damaged panel.
Straighten rear chassis where necessary.
Replace/align all parts
To spray paint

180.00 *12cl*
Shot 220.00 *2000*

950.00 *?*
750.00 *Food*

6,968.17

Kj

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

11.30 LKK

Not Authorized
61 Pump @ 3050h
Resurvey After Paint
6 days

17, October 2018

China Taiping Insurance (S) PL
105 Cecil Street #18-00
The Octagon
S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SGD3233X
Accident involving vehicle no: SJN7645B/SGD3233X
DOA: 11/10/2018 AT Bukit Purmei Ave

Dear officer incharge
Re: estimate cost of repair for vehicle no: SJN7645B
To supply--

Moto

Description	Qty	Amount	
Lid	1	1,210.40	✓
Lid-doorboard	1	328.20	X
Lid-handle	1	239.00	X
Lid lock	1	443.50	✓
Lid hinge @55.30	2	110.60	X
End panel	1	441.20	X
End panel top garnish	1	232.90	✓
Spare tyre boot garnish	1	562.90	X
Exhaust tailpipe	1	798.80	X
Taillamp @472	2	944.00	✓
Rear bumper	1	470.70	✓
Rear bumper retainer @56.05	2	112.10	✓
Rear bumper lower skirt	1	423.00	✓
Rear windscreen sealant	1	76.00	✓
Boot weatherstrip (N48.5)	1	97.60	✓
	Parts	6,490.90	
	Parts less 25%	1,622.72	
		4,868.17	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display Car repair parts during resurvey
- Parts price to be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal transactions is allowed
- Supplier must be resurveyed and is subject to approval from Insurance Company

Acc: _____ Date: _____

Vehicle no: SJN7645B

To remove/transfer rear windscreen glass

Reverse sensor

To remove damaged parts and attachments.

Cut n weld damaged panel.

Straighten rear chassis where necessary.

Replace/align all parts

To spray paint

180.00 *1201*
shot 220.00 *2001n*

950.00 *300d*

750.00 *700d*

6,968.17

Shu Pei (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 22 October 2018 2:56 PM
To: Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SGD3233X (OI : CTI - SNM18D04870C02) and SJN7645B (TP : LKK REF - CC6/CTI18018966/Kjb3) on 11.10.2018
Attachments: leeSZ_SNM18D04870C01-SGD3233X-LKKDirectSettlementAccidentLtr_CLCR95.319.pdf; MLHM18131901-SGD3233X.pdf

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupe@lkkauto.com]
Sent: Thursday, 18 October, 2018 4:56 PM
To: Claims Dept of CTI
Cc: Lucas Lee; Jowyn Tay; Admin A; Joy Irene (LKKAuto)
Subject: Direct Settlement - Accident Involving SGD3233X (OI : CTI - TBA) and SJN7645B (TP : LKK REF - CC6/CTI18018966/Kjb3) on 11.10.2018

WITHOUT PREJUDICE

Dear Jowyn,

We refer to the above matter.

We have inspected TP vehicle SJN 7645B at M/s Wei Lee Motor Works on a WP basis and TP repairer purposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.ctaiping.com

Co Reg No. 200208384E

Our Reference: **SNM18D04870/C01/3**

Date: **22 OCTOBER 2018**

via Ordinary & Registered Mail

**LIM KOK ANN
BLK 112 BUKIT PURMEI ROAD
#07-215
SINGAPORE 090112**

Dear Sir / Madam

**ACCIDENT INVOLVING SGD3233X AND SJN7645B ON 11 OCTOBER 2018
ALONG BUKIT PURMEI ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SJN7645B**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY

Ref : CC6/CT118018966/KJB3

Contact No : 68412409

via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0450A) - INXPIRE N SOLUTIONS

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18018966/Kjb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 14-03-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 3233X	Veh. Inspected	SJN 7645B
Policy No.	DMPCSN3004201803	Coverage (\$)	0.00
Claim No.	SNM18D04870/C01/3	Excess (\$)	0.00
Assign From		Assign Date	17/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTDER12W603002160	Colour	METALLIC BLUE
Odometer	235672	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	2 mm
L/H Front Tyre	195/65 R15	NEXEN	2 mm
R/H Rear Tyre	195/65 R15	FALKEN	4 mm
L/H Rear Tyre	195/65 R15	FALKEN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/10/2018	Inspection Date	17/10/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 7645B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LID	BENT	1,210.40	1,210.40
1	LID-DOORBOARD	SERVICEABLE	328.20	-
1	HID-HANDLE	SERVICEABLE	239.00	-
1	LID LOCK	DENTED	443.50	443.50
2	LID HINGE @\$55.30	TO REPAIR SEE LABOUR	110.60	-
1	END PANEL	TO REPAIR SEE LABOUR	441.20	-
1	END PANEL TOP GARNISH	MTG DISTORTED	232.90	232.90
1	SPARE TYRE BOOT GARNISH	SERVICEABLE	562.90	-
1	EXHAUST TAILPIPE	TO REPAIR SEE LABOUR	798.80	-
2	TAILLAMP @\$472.00	O/S CRACKED	944.00	472.00
1	REAR BUMPER	BUCKLED	470.70	470.70
2	REAR BUMPER RETAINER @\$56.05	O/S DISTORTED	112.10	56.05
1	REAR BUMPER LOWER SKIRT	BUCKLED	423.00	423.00
	LESS 25% DISCOUNT		-1,579.33	-827.14
			4,737.97	2,481.41
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	76.00	40.00
1	BOOT WEATHERSTRIP (50%) (SN)	CUT	97.60	48.80
	LESS 25% DISCOUNT		-43.40	-
			130.20	88.80
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			220.00	200.00
<u>LABOUR</u>				
	TO REMOVE /TRANSFER REAR WINDSCREEN GLASS.		180.00	120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED PANEL.STRAIGHTEN REAR CHASSIS WHERE NECESSARY.REPLACE /ALIGN ALL PARTS.INCLUSIVE OF THE REPAIR OF LID HINGE ,END PANEL AND EXHAUST TAILPIPE. TO SPRAY PAINT.		950.00	500.00
			750.00	700.00
			1,880.00	1,320.00
	GRAND TOTAL		6,968.17	4,090.21
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,050.00

Report Ref No. CC6/CTI18018966/Kjb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.