



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18018972/Aba3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-05-2020



ATTN:VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 750X	Veh. Inspected	SLQ 1915Y
Policy No.	P2028776	Coverage (\$)	0.00
Claim No.	S8M00ZLN	Excess (\$)	0.00
Assign From		Assign Date	18/10/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET ORLANDO	c.c	1362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KL1YA7589HK612838	Colour	GREY
Odometer	58893	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/10/2018	Inspection Date	18/10/2018
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**