

Surveyor

DOI:

ASSIGNMENT

Date / Time:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

HP:

Excess Sec II : \$5

D.O.A:

Is driver the owner?

(YES NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES/NO)

CI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call CI: 16/4/19

After call ltr to CI: Division

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to CI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: \$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Kenny

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOCA S# No. : 77

Repair Cost:

\$5 4644.92

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5 480.00

(

80

x

6

days)

Loss of Income (LOI):

\$5

(

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

\$5 2.00

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5 5126.92

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 5126.92

Name 1:

Alan's united Auto Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ASS. REC. BY:

REF:

AKA

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

05/10 File pass to Catherine

6/6/19 Confirm 2.8.2 \$ 4341.05 with 5 working days.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

(Ref: \$1518.32
26.1)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05868

Vehicle Insured : SKP9832S

Accident Date : 16-Oct-2018

Date : 18-Oct-2018

Our Ref : 218173 (AXA) / CHAN

PAGE : 1

BOON TONG KEE PTE LTD
52 WOODLANDS TERRACE
Singapore 738462

Not Noted
Henry B & paint
1-21

ESTIMATED COST OF REPAIR FOR NISSAN NV200 ACENTA GBH4636Z

1 pc N/s rear door
1 pc N/s rear door "NV200" emblem
1 pc N/s rear door nissan logo
1 pc O/s rear door
1 pc Rear bumper fascia
1 pc Rear bumper sponge
1 pc Rear end panel-inner
1 pc Rear end panel -outer

R	1,281.00	n	—
mc	87.00	n	—
mc	145.60	n	—
R	1,130.90	n	—
Bu	740.00	n	—
su	84.00	n	X
R	598.40	n	X
R	182.40	n	X

4,249.30

Less 10% : 424.93

1 pc N/s rear door 70/km sticker
1 pc N/s rear door glass sealant
1 pc O/s rear door glass sealant

	3,824.37	
mc	15.00	sn ✓
mc	60.00	sn 40s
mc	60.00	sn 40s

To remove & refix rear windscreen glass and conduct water leak test.

120.00 1001

To apply undersealing

80.00 602X

To putty and spray replaced parts

900.00 6001

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

800.00 5001

Total : S\$ 5,859.37

Singapore Dollars Five Thousand Eight Hundred and Fifty Nine and Cents Thirty Seven Only

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

◀ Service Request Details

Claim

S8M00ZP5

Reference

None 

Loss Date

October 16, 2018

Request Date

October 18, 2018

Due Date

October 25, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

18-10-2018 @ 12:04pm
Alan Weinert in

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

GBH4636Z

Make

TPVD NISSAN

Model

• NY200

Service Address

51 Ubi Avenue 1, #01-25, , 408933

Primary Contact/Insured

DING SHIAN

BLK 496D TAMPINES AVENUE 9, #05-538, 520496, Singapore

PL@ANIKA.SG

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

NON-REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:RE: S8M00ZP5- seek mandate approval

Type

🔗 Question

Message

Approved

Reply

BOON TONG KEE PTE LTD

c/o Blk 7 Sin Ming Industrial Estate

#01-76

Singapore 575642

Date: 01-11-2018

AXA INSURANCE SINGAPORE PTE LTD

MOTOR CLAIMS DEPT.

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

LKIC

W

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES GBH 4636Z AND SKP9832S
ALONG JUNCTION OF WOODLANDS AVE 9 & AVE 10 ON 16-10-2018

I / We, the owner of Vehicle No. GBH 4636Z which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

1. Costs of repair - \$4644.92
2. Loss-of-Use/Rental fees 6 days (PR / SUN) \$480.00
3. Police / GIA report / LTA fees \$2.00
4. Surveyor report fees -
5. Others -

Total: \$5126.92

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,

BOON TONG KEE PTE LTD
52 WOODLANDS TERRACE
SINGAPORE 738462
TEL: 62410432 FAX: 64424869



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

16 April 2019

DING SHIAN

BLK 496D TAMPINES AVENUE 9
#05-538,
Singapore 520496

Dear Sir/ Mdm

OUR REF : CC4/ASM18018990/Kwa3
YOUR REF : SKP 9832S

**ACCIDENT INVOLVING SKP 9832S & GBH 4636Z ALONG WOODLANDS AVE 9 ON
16/10/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **ALAN'S UNTIED AUTO PTE LTD** acting on behalf of the owner of ET 888R against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORITY

ACCIDENT INVOLVING GBH4636Z AND SKP9832S
ALONG JUNCTION OF WOODLANDS AVE 9 & AVE 10
ON 16-10-2018

BY THE LETTER OF AUTHORITY, I/We, BOON TONG KEE PTE LTD
NRIC NO. 199608580 K The owner of Vehicle No. GBH4636Z

Hereby irrevocably appoint Messrs **Alan's United Auto Pte. Ltd.** at Block 7, Sin Ming Industrial Estate, Sector C, #01-76, Singapore 575642, and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings:-

1. To submit, negotiate/compromise and to resolve settlements of my/our above mentioned claim.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favor of **Alan's United Auto Pte. Ltd.**
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I/We hereby declare that all the processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers or any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I/We further confirm that the acceptance by Messrs **Alan's United Auto Pte. Ltd.** of the settlement amount constitute the full discharge of my/our claim(s) in respect of the above accident.

Signed on the 17 (day) 10 (month) 2018 (year)



Acknowledged by Owner
(company stamp if applicable)

BOON TONG KEE PTE LTD
52 WOODLANDS TERRACE
SINGAPORE 738462
TEL: 62410432 FAX: 64424869



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SKP 9832S (Insd veh)	Model: NISSAN NV200
	GBH 4636Z (TP veh)	
Date of Accident/ Time:	16/10/2018	

Repair Estimate	: \$	6,269.53	
Final Repair Cost	: \$	4,644.92	
Loss of Use	: \$	480.00	6 days at \$ 80 per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	5,126.92	

Payee Name : Alan's United Auto Pte Ltd

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability: 100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks:

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp	Signature of Witness / Workshop stamp (if applicable)
Name of Representative: KENNY	Name of Witness: _____
Date: 23.5.2019	Date: 23.5.2019
Signature of AXA's surveyor/representative:	
Name of AXA's surveyor/Representative: _____	
Date: 24/5/19	

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 15634

Vehicle Insured : SKP9832S
Accident Date : 16-Oct-2018

Date : 31-Oct-2018

Our Ref : 218173 (AXA) / CHAN

PAGE : 1

BOON TONG KEE PTE LTD
52 WOODLANDS TERRACE
Singapore 738462

FINAL REPAIR COST FOR NISSAN NV200 ACENTA GBH4636Z

=====

1 pc	N/s rear door	1,281.00	n
1 pc	N/s rear door "NV200" emblem	87.00	n
1 pc	N/s rear door nissan logo	145.60	n
1 pc	O/s rear door	1,130.90	n
1 pc	Rear bumper fascia	740.00	n

3,384.50

Less 10% : 338.45

3,046.05

1 pc	N/s rear door 70/km sticker	15.00	sn
1 pc	N/s rear door glass sealant	40.00	sn
1 pc	O/s rear door glass sealant	40.00	sn

To remove & refix rear windscreen
glass and conduct water leak test. 100.00

To putty and spray replaced parts 600.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts 500.00

4,341.05

Add 7% GST : 303.87

Total : S\$ 4,644.92

=====

Singapore Dollars Four Thousand Six Hundred and
Forty Four and Cents Ninety Two Only



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-161026

Date of Request: 17/10/2018

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Dear Sir/Madam,

Enquiry Date 17/10/2018
Enquiry By Chan Yew Siah
TP Vehicle No. SKP9832S
Accident Date 16/10/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKP9832S	AXA Insurance Pte Ltd	28/10/2017-27/10/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-161026
Date of Request: 17/10/2018

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Dear Sir/Madam,

Enquiry Date: 17/10/2018
Enquiry By: Chan Yew Siah
TP Vehicle No: SKP9832S
Accident Date: 16/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKP 9832S (Insd veh)	Model:	NISSAN NV200
	GBH 4636Z (TP veh)		
Date of Accident:	16/10/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,269.53
Final Repair Cost	:	\$	4,644.92
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	6days at \$80.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	5,126.92

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No:

BOLA Liability: (%) Assessed Liability (*): (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	ALAN'S UNITED AUTO PTE.LTD.	:	\$ 5,126.92

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

10/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18018990/Kwa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 10-06-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 9832S	Veh. Inspected	GBH 4636Z
Policy No.	GA070819	Coverage (\$)	0.00
Claim No.	S8M00ZP5	Excess (\$)	0.00
Assign From		Assign Date	18/10/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VSKYBAM20U0153120	Colour	WHITE
Odometer	12013	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	GOODYEAR	8 mm
L/H Front Tyre	175/70 R14	GOODYEAR	8 mm
R/H Rear Tyre	175/70 R14	GOODYEAR	8 mm
L/H Rear Tyre	175/70 R14	GOODYEAR	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/10/2018	Inspection Date	24/10/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 4636Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S REAR DOOR (CONSISTENT) (N)	BENT	1,281.00	1,281.00
1	N/S REAR DOOR 'NV200' EMBLEM (CONSISTENT) (N)	NECESSARY	87.00	87.00
1	N/S REAR DOOR NISSAN LOGO (CONSISTENT) (N)	NECESSARY	145.60	145.60
1	O/S REAR DOOR (CONSISTENT) (N)	BENT	1,130.90	1,130.90
1	REAR BUMPER FASCIA (CONSISTENT) (N)	BUCKLED	740.00	740.00
1	REAR BUMPER SPONGE (CONSISTENT) (N)	SERVICEABLE	84.00	-
1	REAR END PANEL -INNER (CONSISTENT) (N)	TO REPAIR SEE LABOUR	598.40	-
1	REAR END PANEL -OUTER (CONSISTENT) (N)	TO REPAIR SEE LABOUR	182.40	-
	LESS 10% DISCOUNT		-424.93	-338.45
			3,824.37	3,046.05
SPECIAL NETT ITEMS				
1	N/S REAR DOOR 70/KM STICKER (CONSISTENT) (SN)	NECESSARY	15.00	15.00
1	N/S REAR DOOR GLASS SEALANT (CONSISTENT) (SN)	NECESSARY	60.00	40.00
1	O/S REAR DOOR GLASS SEALANT (CONSISTENT) (SN)	NECESSARY	60.00	40.00
			135.00	95.00
LABOUR				
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		120.00	100.00
	TO APPLY UNDERSEALING.	NOT NECESSARY	80.00	-
	TO PUTTY AND SPRAY REPLACED PARTS.		900.00	600.00
	TO REMOVE,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL -INNER AND REAR END PANEL -OUTER .		800.00	500.00
			-	-
			-	-
			-	-
			1,900.00	1,200.00
GRAND TOTAL			5,859.37	4,341.05

Report Ref No. CC4/ASM18018990/Kwa3q2



RECOMMENDED COST OF REPAIRS			4,341.05
-----------------------------	--	--	----------

Report Ref No. CC4/ASM18018990/Kwa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

ClaimS&M0027H5

ReferenceCCA/ASM18018990/Kws3u2

Loss Date16 October 2018

Report Date18 Oct 2018 10:57:55 AM

Request Date18 October 2018

Due Date

Vendor NameLKK AUTO CONSULTANTS PTE LTD (PTC)

Type of LossThird Party Vehicle Damage

ServicesPending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #GBH463J6Z

MakeTPVO NISSAN

ModelNV200

Service Address51 Ubi Avenue 1, #01-25, ... 408933

Primary Contact/InsuredDING SHIAN BLK 496D TAMPINES AVENUE 9, #05-53B, 520496, Singapore PI@ANNIKA.SG

Claim HandlerLOH Cynthia 6568804843 cynthia.loh@axa.com.sg















Actions

Next StepWait for Approve Invoice

Add Evidence

Additional InstructionsNON-REPORTED

Messages	Invoices	History	Documents	Assessment	Miletics	Notes
Document Type			Document SubType			
<div>+ Upload Documents</div>						
NAME		TYPE	SUB-TYPE	AUTHOR		DATE UPLOADED
<div>Accident Statement</div>						
Reports & Statement						Metnotes

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKXInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 PAYMENT BREAKDOWN_LKX.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 LKXInspection.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 LKXAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKX AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 LKX Reinspection Photos.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LKX Inspection Photos.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 Immediate Advice- GBH 4636Z.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LOD.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 MARKED ESTIMATE.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	16 April 2019

