

Gurukul

Tanglin

REF:

Independent

CS/TP18019009/Tlvbnz

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 2259S Yr Regn: 20/6/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio Hybrid cc 1496.

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: 204410 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: 175/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 17/10/18 D.O.I. 18/10/18

Survey held at Prime Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHD 2259S - CC4108E16024200/Rlyb3g2

DN: 17216

25/10/18 LS \$ 1700 confirmed by email (Ref 1196.85, 419)

RECEIVED 25 OCT 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 25/10 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 1700)

110

50

50

24

80

314

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 25 October 2018 12:38 PM  
**To:** 'Alice Leong'; Taufikh (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: FINALIZE TO SHD2259S (malaysia case)

Dear Alice,

WITHOUT PREJUDICE

Finalize at LS \$1,700/- and 5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Alice Leong <aliceleong@primeautoclaims.com>  
**Sent:** Thursday, 25 October 2018 10:06 AM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** FINALIZE TO SHD2259S (malaysia case)  
**Importance:** High

Hi Taufikh

We enclosed our after repair photos & our calculation sheet for your retention. Shall we finalize at Ls \$1,700/- and 5 days

Please let us have your confirmation within three days from our e-mail.

Thank you

**Alice Leong**

Manager, Motor Claims

**Prime Auto Claims Service Pte Ltd**  
6 Benoi Place Singapore 629927  
T (65): 6861 0908 | F (65) 6515 2948  
HP (65) 9818 4304

**A member of the Prime Group**

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

> Back to OneMotoring

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SHD2259S
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO HYBRID 1.5 A
Chassis No.:	NKE1657124685
Propellant:	Petrol-Electric
Engine No.:	1NZR330047
Motor No.:	1LM1508210807
Engine Capacity:	1496 cc
Power Rating:	45.0 kW
Maximum Power Output:	73.0 kW ( 97 bhp)
Maximum Laden Weight:	1415 kg
Unladen Weight:	1140 kg
Year Of Manufacture:	2015
Original Registration Date:	03 Mar 2016
Lifespan Expiry Date:	02 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid:	\$39,633.00
COE Expiry Date:	02 Mar 2024
Road Tax Expiry Date:	02 Mar 2019
PARF Eligibility Expiry Date:	02 Mar 2024
Inspection Due Date:	02 Mar 2019
Intended Transfer Date:	17 Oct 2018
CO2 Emission:	89.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$17,501.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/10/2018 12:26
Date Of Accident	17/10/2018 00:00
Exact Location Of Accident	BUKIT BATOK STREET 31 (NEAR TO HDB BLK. 368)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD2259S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PRIME CAR RENTAL & TAXI SERVICES PTE LTD
Co Reg No	199606293Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68982000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5068045737-03
Cover Note Number	

### Driver

Name of Driver	HENG TEIK HOCK
NRIC No	S2575560Z
Date Of Birth	08/10/1955
Occupation	OUTDOOR
Date Of Driving Pass	01/11/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92359026
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK. 360 BUKIT BATOK STREET 31 #09-419 SINGAPORE
Postcode	650360
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JSR3898 (COMMERCIAL VEHICLE)
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT NO. T/20181017/2013

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JSR3898
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:









**SINGAPORE  
POLICE FORCE**



T/20181017/2013

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20181017/2013

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/10/2018 02:33		Vide Report No.: J/20181017/0002	Station Diary No.:
<b>Informant's Particulars</b>			
Name of Informant: HENG TEIK HOCK		Address: APT BLK 360 BUKIT BATOK STREET 31 #09-419 SINGAPORE 650360	
ID Type / ID No.: NRIC NO / S2575560Z		Contact No.:	Mobile: 92359026
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 63	Date of Birth: 08/10/1955	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: TAXI DRIVER		Driving Licence Information: Class: 2B,2A,2,3,4,5 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 17/10/2018 00:00	Type of Location:
Location: Along Road 1 BUKIT BATOK STREET 31 BLOCK 368 BUKIT BATOK STREET 31				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JSR3898	Lorry					0
SHD2259S	Car		COROLLA AXIO HYBRID 1.5 A	Brown		1



SINGAPORE  
POLICE FORCE



T/20181017/2013

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20181017/2013

CONTINUATION OF REPORT

**Brief Details.**

ON THE ABOVE MENTION DATE, TIME AND LOCATION,

ON 17/10/2018 AT ABOUT 0000HRS, I WAS EXITING TO THE MAIN ROAD AT BLOCK 368 BUKIT BATOK STREET 31. AFTER THAT ONE LORRY(JSR3898) TURNING TO THE CARPARK AT MY RIGHT SIDE AND HIS REAR RIGHT OF VEHICLE COLLIDED ONTO REAR RIGHT PORTION OF MY VEHICLE. AFTER I FELT THE IMPACT, BOTH OF US CAME DOWN OF VEHICLE AND I WANT TO EXCHANGED PARTICULARS BUT THE OTHER PARTIES REFUSES TO EXCHANGED THE PARTICULARS AND I CALLED FOR POLICE. AFTER THAT, TRAFFIC POLICE CAME. NO ONE WAS INJURED. I HAVE THE IN-CAR CAM AND PHOTO.

DAMAGES FOR MY VEHICLE : REAR RIGHT PORTION OF MY VEHICLE.



**SINGAPORE  
POLICE FORCE**



T/20181017/2013

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20181017/2013

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
TP /  
TAN KOK RAY

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 SITIMARSITA BINTE BOHARI  
Contact No.: 65476219

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
17/10/2018 02:33

Classification Of Case:



SINGAPORE  
POLICE FORCE

Signature of:



## Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
6 Benoi Place Singapore 629927  
Tel: 6861 0908 Fax: 6515 2948

Date: 17.10.2018

Prime Car Rental & Taxi Services Pte. Ltd.  
5 Benoi Place  
Singapore 629926

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2259S TOYOTA COROLLA AXIO HYBRID 1.5 (2015)

### To Supply

- |         |                   |                  |        |
|---------|-------------------|------------------|--------|
| 1 ) 1pc | Right tail lamp   | \$ <i>450</i>    | 450.00 |
| 2 ) 1pc | Right rear fender | \$ <i>885.80</i> | 885.80 |

Sub total Parts	\$	1,335.80
Less: 25% discount	\$	(333.95)
	\$	1,001.85

### To Supply S.Nett Parts

- |         |                       |              |       |
|---------|-----------------------|--------------|-------|
| 1 ) 1pc | "Dial -A-Cab" sticker | \$ <i>45</i> | 45.00 |
|---------|-----------------------|--------------|-------|

Sub total S.Nett Parts	\$	45.00
------------------------	----	-------

### L/charges

- |     |   |               |        |
|-----|---|---------------|--------|
| 1 ) | To tuff kote.   | \$ <i>50</i>  | 50.00  |
| 2 ) | To remove right tail lamp. Cut/welding right rear fender. Repair right rear door & rear door handle. Replace the above parts. Align & adjust right rear door. | \$ <i>900</i> | 900.00 |
| 3 ) | To putty, respray painting right rear fender & right rear door. To polish.  | \$ <i>900</i> | 900.00 |

Sub total L/charges	\$	1,850.00
Estimated Grand Total	\$	2,896.85

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Tanpin 97495749*  
*WP*  
*5 days*  
*18/10/18*  
*Resurvey before part.*  
*sur@lkkauto.com*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

PRIME AUTO CLAIMS SERVICE PTE LTD

Ref : CS/TP18019009/T1vbn2

6 BENOI PLACE  
SINGAPORE 29927

Date : 01-11-2018



ON BEHALF OF PRIME CAR RENTAL & TAXI  
SERVICES PTE LTD

Code : TP474

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHD 2259S
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	18/10/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NKE1657124685	Colour	ORANGE
Odometer	204410	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	6 mm
L/H Front Tyre	175/65 R15	DUNLOP	6 mm
R/H Rear Tyre	175/65 R15	DUNLOP	6 mm
L/H Rear Tyre	175/65 R15	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	17/10/2018	Inspection Date	18/10/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2259S**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RIGHT TAIL LAMP	CRACKED	450.00	450.00
1	RIGHT REAR FENDER	BUCKLED	885.80	885.80
	LESS 25% DISCOUNT		-333.95	-333.95
			1,001.85	1,001.85
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	"DIAL-A-CAB" STICKER (SN)	NECESSARY	45.00	45.00
			45.00	45.00
	<b><u>LABOUR</u></b>			
	TO TUFF KOTE.		50.00	30.00
	TO REMOVE RIGHT TAIL LAMP.CUT/WELDING RIGHT REAR FENDER.REPAIR RIGHT REAR DOOR & REAR DOOR HANDLE.REPLACE THE ABOVE PARTS.ALIGN & ADJUST RIGHT REAR DOOR.		900.00	600.00
	TO PUTTY,RESPRAY PAINTING RIGHT REAR FENDER & RIGHT REAR DOOR.TO POLISH.		900.00	450.00
			1,850.00	1,080.00
	<b>GRAND TOTAL</b>		<b>2,896.85</b>	<b>2,126.85</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,700.00</b>

Report Ref No. CS/TP18019009/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.