

22/03/2002

ASS. REC. BY:

REF: CS3 / 3M018019012 / R1cd30

Special Instruction:

Surveyor:

Rasu

ASSIGNMENT (Office)

menmen

From (Person): Ngo sham Wei sham

of

8M0

Date/Time: 19/10/18 @ 11:58am

Estimated Cost:

Bill to:

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 7405P

Insured:

YP 6287U

at Workshop m/s

Willy Motor

Tel: 92767180/62617873/62680977

of

27A Jurong Port Rd # 01-32

Policy No:

018MTHCUE001247

Claim No:

CMTD1804449

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/10/2018

(vehicle will be in after 2pm).

CA / REV / REP. / REV 24 HRS / up

H.O.D. Endorsement:

Date/Time:

1:00pm @ 19/10/18

Person Contacted:

Ms: Khoo

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	YP 7405P-X
	YP 6287U-X
	After repair: 22/10/2018

(08/11/13)

REF:

38594

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 4P 7405P
 at Workshop m/s WILLY MOTOR
 of 27A, Willy motor #01-32
 Insured: SOMPO
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 4P 7405P Yr Regn: 2012 / 444
 Type: M.Car / M.Cycle / Bus / Van Lotus / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU NPR 75H USA C.C. 5193
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3AA NPR 75H H 7102696Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/75 R17R: 22BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mmL/Bal. 7 mm L/Bal. 7/7 mmD.O.A. 11/06/18 D.O.I. 19/06/18Survey held at WILLY MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS- Estimated repair range \$2,800 - \$3,500

24/10/2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 2

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : PRS.

Lump Sum / I.B.I. (\$) _____)

100

60

10

170

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		19 Oct 2018 11:58 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TANNY SERVICES PTE LTD, Co. Reg. No.: 198202836W		
Main Claimant:	MASARI BIN MASRAH, ID: S6940263A		
Vehicle Reg. No.:	YP7405P	Date of Loss:	11/10/2018 14:00 - :59
Claim Type:	TP / CMTD1804449	Policy/Cover Note No.:	D18MTHCVE001247 (Comprehensive)
Vehicle Reg. No. (Insured):	YP6287U	Policy No. (Claimant):	
		Excess:	
Repairer:	Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32, 619101 Jurong Island - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2018]		
Driver/Custodian (Insured):	MASON SEET LAI TECK (), NRIC: S7600348C, Tel: +6591732876		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3859H
Vehicle Details	
Vehicle No.:	YP7405P
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	ISUZU
Vehicle Model:	NPR75UH5A
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	4HK1621666
Chassis No.:	JAANPR75HH7102690
Maximum Power Output:	-
Open Market Value:	\$34,919.00
Original Registration Date:	10 Aug 2017
First Registration Date:	10 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$1,746.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,060.00
COE Rebate Amount:	\$16,759.00
Total Rebate Amount:	\$16,759.00

The information contained herein is correct as at 24 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/10/2018 16:08
Date Of Accident	11/10/2018 14:30
Exact Location Of Accident	KEPPEL SHIPYARD 15 BENOI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7405P
Insured/Policyholder	
Name Of Registered Owner	CHEM-GROW PTE LTD
Co Reg No	198103859H
Email Address	ARIE6921@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90874631
Alternative Phone No	OFFICE-68633124

Vehicle Particulars

Manufacturer	ISUZU
Model	NPR75UH5A-5.2 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093254155-01
Cover Note Number	

Driver

Name of Driver	MAS'ARI BIN MASRAH
NRIC No	S6940263A
Date Of Birth	21/11/1969
Occupation	OUTDOOR
Date Of Driving Pass	06/12/1991
Driving Experience	26 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90874631
Fax Number	

Email Address	ARIE6921@GMAIL.COM
---------------	--------------------

Address	APT. BLK 114 HO CHING ROAD #01-74 SINGAPORE
Postcode	610114
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6287U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MASON SEET LAI TECK
NRIC/Passport Number	S7600348C
Contact Number	91732876
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A = YP 7405 P

B = YP 6287 U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After delivery to shipyard I drove my vehicle YP 7405 P to the security to change my pass, so along the way to security, I saw a lorry queue so I park behind the lorry YP 6287 U for queuing to change my pass. it was drizzling at that time so I prefer to wait until the front lorry to move out, at around 14:30pm the lorry in front of me is reversing to ward me it is because there is a front lorry blocking him the driver, so it overtake and I thought he's going out but he the driver reversing again and hit my lorry YP 7405 P.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
If driver is not the policyholder

Reporting Centre Personnel's Signature
Name:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2018		19 Oct 2018 11:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TANNY SERVICES PTE LTD, Co. Reg. No.: 198202836W	
Main Claimant:	MASARI BIN MASRAH, ID: S6940263A	
Vehicle Reg. No.:	YP7405P	Date of Loss: 11/10/2018 14:00 - :59 [14 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804449	Policy/Cover Note No.: D18MTHCVE001247 (Comprehensive)
Vehicle Reg. No. (Insured):	YP6287U	Policy No. (Claimant):
		Excess:
Repairer:	Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32, 619101 Jurong Island - Tel:	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/10/2018]	
Driver/Custodian (Insured):	MASON SEET LAI TECK (), NRIC: S7600348C, Tel: +6591732876	































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***YP7405P (CMTD1804449)**
[YP6287U]

TP
MASARI BIN MASRAH
Oct 11 2018 2:00PM
[TANNY SERVICES PTE LTD]
Willy Motor Company

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/10/18 11:59	Accident Statement <small>From: SC - Reg. No: YP6287U, Claimant: TANNY SERVICES PTE LTD</small>	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/10/18 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
23	24/10/18 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
24	24/10/18 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
25	24/10/18 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
26	24/10/18 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
27	24/10/18 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/10/18 09:16	Third Party E-filed GIA report	 Load PDF	<input type="checkbox"/>
2	19/10/18 11:58	SOMPO - NO CONSENSUS	 Load HTM	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18019012/R1CD3E2

Date: 02/11/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE001247
Claimant Vehicle No :	YP7405P	Insured Vehicle No :	YP6287U
Date of Loss:	11/10/2018	Nature of Claim:	TP
		Claim No:	CMTD1804449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP7405P	Engine No:	4HK1621666
Make & Model:	ISUZU NPR75UH5AC, 5.2 D (M)	Chassis No:	JAANPR75HH7102690
Reg. Date:	10/08/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	5193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17	Rear Tyre Size:	215/75 R17 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	19/10/2018	
Date Inspected:	19/10/2018	Inspected At: Willy Motor Company (HQ) 27A JURONG PORT ROAD, #01-32 Singapore 619101
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Nov 2018)

Parts: N/A ISUZU NPR75UH5AC 5.2 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP7405P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >