

ASS. REC. BY:

REF: CS3/CTI18019020/RICd30 Special Instruction:

Sub-Vendor
MaximenASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

14/10/18 @ 11:06am

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGC 6925 T

Insured:

YP1086R

at Workshop m/s

Kwee Seng Motor

Tel:

9147 8165

of

240 Compassvale Walk #09-574

Policy No:

DMCVSN1803601800

Claim No:

SNM18D04936C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/10/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 12:07pm @ 14/10/18

Person Contacted:

Mr. Low

Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate Insp: Blk 5035 Amk Ind. Park 2 #01-353
	SGC 4936 T- X
	YP1086 R- X
22/10/18	VNI will arrange.
	No. GIA.
	Amended TP veh. No in Maximen.

ASSIGNMENT

From: Date: 24/10/18

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SGC 6925T

at Workshop m/s Kwee Seng Motor

of BIK 5035, Amk Ind. park 2 #01-353

Insured:

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh: Mr. Low 9147 8165

After 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGC 6925T Yr Regn: / No record

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ~~CHRYSLER~~ Toyota Corolla Ario 1.5

C.C.

Colour: GRAY

A/C: Insured / Std / NI / NA

Sp. Reading: 222741

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KLINA 196ESH108941

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

205/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

PALKEN

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A.

D.O.I.

24/10/18

Survey held at

Kwee Seng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rgn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- Estimated repair rang \$1,800 - \$2,300

29/10/2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation

\$ + RS. \$1

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$))

☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		19 Oct 2018 11:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	NG KOK SENG		
Vehicle Reg. No.:	SGC4936T	Date of Loss:	15/10/2018 00:00 - :59
Claim Type:	TP / SNM18D04936C02	Policy/Cover Note No.:	DMCVSN1803601800
Vehicle Reg. No. (Insured):	YP1086R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kwee Seng Motor Services (HQ) 240 COMPASSVALE WALK, #09-574, 540240 Sengkang - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.K81.108383.18
Your Ref: **SNM18D04936C02**

19 October 2018

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claims Department

BY FAX (6224 7175)

email: claimsdept@sg.cntaiping.com
lucas.lee@sg.cntaiping.com

Dear Sirs,

**ACCIDENT INVOLVING SGC 6925 T & YP 1086 R ON 15 OCTOBER 2018 ALONG/AT MANDAI ESTATE AT ABOUT 0915 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your letter dated 19 October 2018 informing that your wish to conduct a pre-repair survey on our client's vehicle **SJQ 9298 R**.

Please be informed that the said vehicle can be inspected at:

Kwee Seng Motor Services
Blk 5035 Ang Mo Kio Industrial Park 2
#01-353
Singapore 569538
Mr Low (9147 8165)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: **SGC 6925 T** – By fax: 6280 4795 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Oct 2018		19 Oct 2018 11:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	NG KOK SENG								
Vehicle Reg. No.:	SGC6925T	Date of Loss:	15/10/2018 00:00 - :59						
Claim Type:	TP / SNM18D04936C02	Policy/Cover Note No.:	DMCVSN1803601800						
Vehicle Reg. No. (Insured):	YP1086R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kwee Seng Motor Services (HQ) 240 COMPASSVALE WALK, #09-574, 540240 Sengkang - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/10/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGC6925T (SNM18D04936C02)**
[YP1086R]
TP
NG KOK SENG
Oct 15 2018 12:00AM
[-]
Kwee Seng Motor Services

Upload Documents	Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	27/10/18 14:54	General View	 Load PDF
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	19/10/18 11:05	PRS	 Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118019020/R1CD3E2

Date: 28/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1803601800

Claimant Vehicle
No: SGC6925TInsured Vehicle
No: YP1086R

Date of Loss: 15/10/2018

Nature of Claim: TP

Claim
No: SNM18D04936C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC6925T**

Make & Model: TOYOTA COROLLA, 1.5 AXIO (A)

Reg. Date: (Man. Year:)

Colour: Grey

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: HIDDEN

Chassis No: KL1NA196E5H108941

Odometer: 222741 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Falken 5 mm

Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/10/2018

Date Inspected: 24/10/2018 Inspected At:

Kwee Seng Motor Services (HQ)
240 COMPASSVALE WALK, #09-574
Singapore 540240

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 -\$2,300.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 19 Dec 2018)

Parts: 143 TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGC6925T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >