

LAM PAINTING COMPANY

160 SIN MING DRIVE #02-15 SIN MING AUTOCITY

SINGAPORE 575722

TEL NO: 6453 2233

EMAIL: lam_painting@yahoo.com.sg

Not Notarised
L1 Sp 8 ?
Resurvey After Paint

ESTIMATE

Name: Mr Lim Size Kiong

Date: 18th Oct 2018

Address: 2 River Valley Close
#19-05
Singapore 238428

Make/Model: Lexus IS250

Reg No: SKJ 2605 J

D.O.A: 16/10/2018

Page: 1

| S/N | QTY | DESCRIPTION | UNIT PRICE | TOTAL |
|---|-------|-------------------------------|-------------|------------------|
| 1 | 1 pce | Front Bumper | \$ 780.00 | \$ 780.00 ✓ |
| 2 | 1 pce | Front Bumper Reinforcement | \$ 575.00 | \$ 575.00 7 |
| 3 | 2 pcs | Front Bumper Lower Spoiler | \$ 325.00 | \$ 650.00 4 |
| 4 | 1 pce | Front Bumper Lower Grille | \$ 265.00 | \$ 265.00 Sn |
| 5 | 1 pce | Front Bumper Side Retainer RH | \$ 75.00 | \$ 75.00 bit |
| 6 | 1 pce | Front Bumper Spot Lamp RH | \$ 330.00 | \$ 330.00 bit |
| 7 | 1 pce | Front Head Lamp RH | \$ 1,100.00 | \$ 1,100.00 bit |
| 8 | 1 pce | Front Fender RH | \$ 1,100.00 | \$ 1,100.00 bit |
| 9 | 1 pce | Front Fender Inner Liner RH | \$ 398.00 | \$ 398.00 ? |
| Less 25% | | | | \$ 5,273.00 |
| | | | | \$ 1,318.25 |
| | | | | \$ 3,954.75 |
| Labour:- | | | | |
| To check wiring functions. | | | | \$ 50.00 201 |
| To knock, repair and straighten including replacement of parts & align where necessary; to refit and adjust the same. | | | | \$ 850.00 4501 |
| To putty and spraypaint including touch up on all affected parts. | | | | \$ 1,200.00 5001 |
| To apply rustproof treatment to the repaired and replaced parts. | | | | \$ 100.00 301 |
| *This estimate is based visually. Further items will be or may be added if found faulty. | | | | |
| TOTAL | | | | 6,154.75 |

I KK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: