

ASS. REC. BY:

REF: CS/FCI18019027/Plrd3^{nt}

Special Instruction:

Surveyor:

Rajul

ASSIGNMENT (Office)

From (Person):

CWS

May chua

of

FCI

Date/Time:

10/10/18 @ 5:37pm

Estimated Cost:

Bill to:

OD ☒ TP/WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 4934D

Insured:

SH 9360J

at Workshop m/s

Sin sheng Engineering
3tech park Crescent

Tel:

68639595

of

Policy No:

Claim No:

D18007553 MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/10/2018

CA / REV / REP. / REV 24 HRS (DS)

Date/Time: 10/10/18 @ 10:03am

Person Contacted:

Susan

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	GBE 4934 D-X
	SH 9360J - CS/FCI17002082/Kqh 3n2 DoA: 31/01/17
24/10/18	Revert 1A thru email
07/11/18	Confirm ✓ L/s \$1400 @ 3 days (Red: \$1680.97, 55%) with Susan

(08/11/17)

Surveyor: *Paul*

REF:


11764

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GAE 49340
 at Workshop m/s SIN S HENG
 of _____
 Insured: PCI / OS
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 46k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GAE 49340 Yr Regn: 2015 / DEC
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: FIAT DOBLO CARHOMAXI 1.6 c.c. 1578
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 86258 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: ZFA 2630000 6030936

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>15/10/18</u>		D.O.I. <u>19/10/18</u>

Survey held at SIN S HENGDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: \$46K, LTA: \$33,528.00, NV: \$12472.00

RECEIVED 08 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) tuipst
 Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

130
50
50+50
36
316

Report Format: TPLump Sum / LTA: (\$ 1400)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007553MFSH

Date: 24 October 2018

Our Ref: CS/FCI18019027/R1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 4934D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19.10.2018 at the premises of M/s SIN SHENG ENGINEERING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 3,080.97 .
Revised Estimate Amount	: S\$ 1,682.00 .
"Check" Items Amount	: S\$ 212.50 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-10-2018	Our Ref No. D18007553MFSH
Accident Date	15-10-2018	Claim Type. Third Party
Insured Vehicle	SH9360J	Third Party Vehicle. GBE4934D
Survey Location	3 TECH PARK CRESCENT TUAS TECH PARK	
Contact Person.	SUSAN	
Contact No.	68639595/ 0	Fax No. 68636477
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Janice Lee (LKKAUTO)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Wednesday, November 07, 2018 5:10 PM
To: Janice Lee (LKKAUTO)
Cc: Rasul (LKKAUTO); SUR
Subject: Re: Accident Involving GBE4934D with SH9360J on 15/10/2018

Yes, confirmed.

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Wed, 7 Nov 2018 at 14:37, Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com> wrote:

Dear Susan,

Kindly confirm L/S \$1,400 @ 3 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1196N

Vehicle Details

Vehicle No.:

GBE4934D

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2018

Vehicle Make:

FIAT

Vehicle Model:

DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE

Primary Colour:

White

Manufacturing Year:

2015

Engine No.:

263A50007472798

Chassis No.:

ZFA26300006B30936

Maximum Power Output:

-

Open Market Value:

\$18,950.00

Original Registration Date:

21 Dec 2015 ✓

First Registration Date:

21 Dec 2015

Transfer Count:

0

Actual ARF Paid:

\$948.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

20 Dec 2025

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$48,101.00

COE Rebate Amount:

\$33,528.00

Total Rebate Amount:

\$33,528.00

The information contained herein is correct as at 18 Oct 2018

OK

46,000
33,528

12,472
==

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002637

Date : 19/10/2018

Vehicle Num. : GBE4934D

Make/Model : FIAT DOBLO 1.6MJTD-2015

Chassis/Eng# : ZFA 26300006B30936/263A50007472798

Accident Date : 15/10/2018

Claim No. : D18007553MFSH

Reference : SH9360J

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER		734.34 <i>DE</i>
2.	2	BUMPER SIDE BRACKET	95.20	190.40 <i>X 3 one</i>
3.	2	REFLECTOR	65.20	130.40 <i>X</i>
4.	1	BUMPER REINFORCEMENT		420.95 <i>PA</i>
5.	1	REAR BODY WEATHERSTRIP		185.73 <i>X one</i>
6.	1	REAR END PANEL		345.20 <i>Repair</i>
List TotalS\$:				2,007.02
15.00% Discount S\$:				301.05
				1,705.97
NETT ITEMS :				
1.	1	REVERSE SENSOR		250.00 <i>200? nu</i>
Nett Total S\$:				250.00
10.00% Discount S\$:				25.00
				225.00
LABOUR :				
TO PANEL BEAT/REPAIR REAR BODY				650.00 <i>400</i>
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS				

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002637

Date : 19/10/2018

Vehicle Num. : GBE4934D

Make/Model : FIAT DOBLO 1.6MJTD-2015

Chassis/Eng# : ZFA 26300006B30936/263A50007472798

Accident Date : 15/10/2018

Claim No. : D18007553MFSH

Reference : SH9360J

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPRAY PAINTING

LOSS OF USE: 4 DAYS @ \$ 120/DAY

Labour Total S\$:

500.00 *300*

1,150.00

Prime

4p 9m 00b1r

3 days

4s

19/10/18 @ 1725

24/10/18

Regy after repair

Total S\$: 3,080.97

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Financial" basis
- No illegal modification is allowed
- Supplementary item(s) must be confirmed & is subject to final approval from insurance company

Acknowledged by Repairer:
Signature: _____
Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18019027/R1rd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9360J	Veh. Inspected	GBE 4934D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007553MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	18/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ZFA26300006B30936	Colour	RED	
Odometer	86258	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	NEXEN	6 mm	
L/H Front Tyre	195/60 R16	NEXEN	6 mm	
R/H Rear Tyre	195/60 R16	NEXEN	6 mm	
L/H Rear Tyre	195/60 R16	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/10/2018	Inspection Date	19/10/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4934D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	734.34	734.34
2	BUMPER SIDE BRACKET @\$95.20	SERVICEABLE	190.40	-
2	REFLECTOR @\$65.20	SERVICEABLE	130.40	-
1	BUMPER REINFORCEMENT	BENT	420.95	420.95
1	REAR BODY WEATHERSTRIP	SERVICEABLE	185.73	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	345.20	-
	LESS 15% DISCOUNT		-301.05	-173.29
			1,705.97	982.00
NETT ITEMS				
1	REVERSE SENSOR (N)	NOT WORKING	250.00	200.00
	LESS 10% DISCOUNT		-25.00	-20.00
			225.00	180.00
LABOUR				
	TO PANEL BEAT/REPAIR REAR BODY TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		650.00	400.00
	SPRAY PAINTING.		500.00	300.00
			1,150.00	700.00
GRAND TOTAL			3,080.97	1,862.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/FC118019027/R1rd3n2

MARKET VALUE: \$46,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$33,528.00=NETT VALUE: \$12,472.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.