

ASS. REC. BY:

REF: CS / UOL18019033 / Klgbnz Special Instruction:

Surveyor:

Kalin

ASSIGNMENT (Office) ✓

From (Person):

Felix

of

UOL

Date/Time:

19.10.2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8912K

Insured:

GBF 370B

at Workshop m/s

Premier

Tel:

6544 6689 / 9155 0072

of

23 Changi South Ave 2.

Policy No:

DHOM110156781701

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

19.10.2018 959am

Person Contacted:

Goh

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 891211 - X

GBF 370B - NA / UOL18019033 / 13

DUA: 18.10.2018

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate/Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 8912K Yr Regn: 10 Apr 2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / T. Ch / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685Colour: Silver A/C: Ins / Std / NI / NASp. Reading: 446200 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KNAH M414ME5462273

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 18/10/18 D.O.I. 19/10/18Survey held at Premise

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/10/18	Checked 45 \$ 2400 / 3 days. (Red to 3511.40, 59%) UOZ

RECEIVED 02 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 07/11/18 turn in

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: TPLump Sum / L.B.I. (\$) 2400

Survey Fee:

Transportation:

Photos

Others

TOTAL

210

60

80

39

389

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	10 Apr 2014 / 09:12:56	Receipt No.:	AACCK001-AX239-140410-000003
Asset Type:	Vehicle	Transaction Amount:	\$72,287.00
Asset ID:	SHB8912K	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140410091256152160		
Vehicle No.:	SHB8912K		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	10 Apr 2014		
Original Registration Date:	10 Apr 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5462273		
Engine No.:	D4FDDH307961		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,776.00		
Minimum PARF Benefit:	\$7,365.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	10 Apr 2014 09:12:56		
COE No.:	2014041001000797M		
COE Expiry Date:	09 Apr 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$59,871.00		
Lifespan Expiry Date:	09 Apr 2022		
Owner ID Type:	Company		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2018 13:42
Date Of Accident	18/10/2018 12:45
Exact Location Of Accident	JALAN BESAR BEFORE THE JUNCTION OF KITCHENER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB8912K
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

Driver

Name of Driver	LEE SIN SIONG
NRIC No	S2657708Z
Date Of Birth	08/06/1960
Occupation	OUTDOOR
Date Of Driving Pass	24/10/1987
Driving Experience	30 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87863653
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 66 #03-503 KALLANG BAHRU
Postcode	330066
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAX IN THE REAR SEAT - CHINESE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 1 PAX VEH. B - NO PAX VEH. C - NO PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR KOK KEAN KEONG - PAX IN VEH. A
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF370B
Vehicle Make/Model/Colour	MITSUBISHI CANTER/WHITE
Details Of Properties	VEH. B
Vehicle Category	GOODS VEHICLE
Name of Driver	HARON
NRIC/Passport Number	
Contact Number	918021771
Address	

Postcode

Insurance Company Name

Nature Of Damage

DAMAGED ON THE FRONT PORTION

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLT4190K

Vehicle Make/Model/Colour

MAZDA

Details Of Properties

VEH. C

Vehicle Category

PRIVATE CAR

Name of Driver

MR TAN

NRIC/Passport Number

Contact Number

83999770

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Shihui

18 OCT 2013

[Signature]


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

X 526577082
X 5468912K

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHB 8912K

B: BF 370B

C: SLT 4190K.



DECLARATION

I/We declare the foregoing particulars are true in every respect.

18 OCT 2019

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

526577082

?

Describe Circumstance of the Accident.

*** CHAIN COLLISION ***

ON 18/10/2018 @ 1245 HRS, I WAS DRIVING MY TAXI (SHB 8912 K) TRAVELLING ALONG JALAN BESAR BEFORE KITCHENER ROAD WITH A PASSENGER ONBOARD, IN LANE 2.

I STOPPED MY TAXI AS VEHICLE C (SLT 4190 K – MAZDA) WHICH WAS IN FRONT OF ME, STOPPED.

WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR AND SUBSEQUENTLY THE GREAT IMPACT CAUSED MY TAXI TO SURGE FORWARD & CAUSING THE FRONT PORTION OF MY TAXI TOUCHES ONTO THE REAR OF VEHICLE C.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE C (GBF 370 B – MITSUBISHI CANTER/WHITE) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND NO DAMAEGS ON THE FRONT PORTION.
VEHICLE B HAD DAMAGES ON THE FRONT PORTION AND NO DAMAGES TO VEHICLE C.

MY PASSENGER – MR KOK KEAN KEONG WHO WAS IN THE REAR SEAT, WILLING TO BE MY EYE WITNESS.


NO INJURY INVOLVED.

NO PASSEGNERS ONBOARD BOTH VEHICLE B & VEHICLE C.

*VIDEO FOOTAGE CAPTURED.

CHAIN COLLISION / MULTIPLE VEHICLES

DAMAGES FOUND ON VEHICLE A, B, C, D, E & F



PREMIER TAXI

THIRD PARTY VEHICLES

526577082

Driver's Signature & NRIC Number

Thursday, October 18, 2018 @ 1:57:39 PM

Sketch Plan Pg. 4

PREMIER TAXI	HIRE / RELIEF / SUPER RELIEF
VEHICLE NO.	SHB 8912K
CONTACT NO	8786 3653
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2657708Z



Name
LEE SIN SIONG

李 升 祥

Race
CHINESE

Date of birth 08-06-1960 Sex M

Country of birth
MALAYSIA

S2657708Z

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S2657708Z

Name

LEE SIN SIONG

Birth Date: 08 Jun 1960

Issue Date: 20 Aug 2003



NRIC No. S2657708Z



Date of issue
16-10-2006

APT BLK 66 KALLANG BAHRU #03-503
SINGAPORE 330066

NRIC No. S2657708Z

Date: 16/10/2006

No: 6377801

3946273

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B Motorcycles not exceeding 200 cc
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

24 Oct 1967
24 Oct 1967



Licence No: S2657708Z

NP428A

Land Transport Authority



VOCATIONAL LICENCE

Licence No: S2657708Z

Name: LEE SIN SIONG

Issue Date: 28/1/2014

Please visit www.lta.gov.sg to check the status of this vocational licence

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8912 K

1 pc	Boot lid	X repair	\$	1,119.00
1 pc	Bootlid emblem	X	\$	27.00
1 pc	Bootlid CRDi	—	\$	29.00
1 pc	Boot lid rubber weatherstrip	X see	\$	96.00
1 pc	Boot lid lower garnish	X repair	\$	290.00
2 pcs	Bootlid hinges @ \$66.00	X see	\$	132.00
1 pc	Rear bumper	—	\$	696.00
1 pc	Rear bumper lower cover	—	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X see	\$	58.00
1 pc	Rear bumper inner sponge	X torn	\$	114.00
1 pc	Rear bumper reinforcement	X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X bent	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	X see	\$	92.00
			\$	3,646.00
			Less 10%	\$ 364.60
			\$	3,281.40

S/NETT

1 set	Rear bumper clips	—	\$	48.00
1 set	End panel inner garnish clips	X	\$	30.00
1 set	Bootlid inner trim clips	X	\$	52.00
1 set	Bootlid lower garnish clips	X	\$	60.00
1 set	Bootlid stickers	—	\$	100.00
1 set	Reverse sensor	—	\$	280.00
1 pc	Rear bumper top protector	—	\$	80.00

18-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8912 K

Sundry	\$ 50.00 ²⁰ nec
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 ³⁰
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 ^{X 2}
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$ 750.00 ⁴⁰⁰
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$ 800.00 ⁵⁴⁰
To apply rustproofing on the repaired and replaced panels.	\$ 80.00 ^{X 2}
	<u>\$ 5,911.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka /nh /K/k/
19/10/18 123. hrs.
14 2 Pop.
4/3
After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To estimate before any spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is to be on a 'Prejudice' basis
- No illegal modification is allowed
- Supplementary work must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI18019033/K1qbn2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 08-11-2018	
			Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 370B	Veh. Inspected	SHB 8912K	
Policy No.	DHOM110156781701	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	FELIS	Assign Date	19/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5462273	Colour	SILVER	
Odometer	446200	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/10/2018	Inspection Date	19/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8912K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	1,119.00	-
1	BOOTLID EMBLEM	NOT NECESSARY	27.00	-
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
2	BOOTLID HINGES @\$66.00	SERVICEABLE	132.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	BENT	108.00	108.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	SERVICEABLE	92.00	-
	LESS 10% DISCOUNT		-364.60	-183.20
			3,281.40	1,648.80
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			700.00	418.00
<u>LABOUR</u>				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00

Report Ref No. CS/UOI18019033/K1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL ETC. INCLUSIVE OF THE REPAIR OF BOOTLID AND BOOT LID LOWER GARNISH.		750.00	400.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL.		800.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			1,930.00	970.00
GRAND TOTAL			5,911.40	3,036.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/UOI18019033/K1qbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.