

22/03/2002

ASS. REC. BY:

REF:

es/cpe18019037/ Rvd3⁵⁷

Special Instruction:

Surveyor

MURPHY

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CPE

Date/Time: 19/10/18 @ 13:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDQ 6228J

Insured:

SFE 1519S

at Workshop m/s

Weames Automotive
249 Alexandra Road

Tel:

9818 7217

Policy No:

DMPCSN30099A801

Claim No:

3NM18D04958C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/10/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

3:21pm @ 19/10/18

Person Contacted:

Junk

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SD

22/10/18

VNI yet

26/10/18

VNI

8/11/18

Final fig \$ 3800.85 confirmed by email (Ref 5156.65, 5870)

ASSIGNMENT

From:

Date: 01-11-2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDQ 6228J

at Workshop m/s:

Wearnes
249 Alexandra Rd.

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Derek

(Policy Condition)

after 3pm 130

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDQ 6228J

Yr Regn:

2010 NOV

Type: ☒ M, Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo S80 2011

C.C.

1999

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

171981

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

4VIA 544 583 1138397

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

245/35ZR19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/11/18

D.O.I.

01/11/18

Survey held at

WEARNES

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 08 NOV 2018

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

-

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

220

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week-end (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Egr Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		19 Oct 2018 13:13 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GUEE SU INK, ID: S6923503D		
Main Claimant:	CHAN WENG SENG		
Vehicle Reg. No.:	SDQ6228J	Date of Loss:	16/10/2018 07:00 - :59
Claim Type:	TP / SNM18D04958C02	Policy/Cover Note No.:	DMPCSN3009911801 (Comprehensive)
Vehicle Reg. No. (Insured):	SFE1519S	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2018]		
Adj Asg. Remarks:	EST \$9584.55, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Derek Oh Siong Wee <derek.oh@wearnes.com>
Sent: Tuesday, 16 October, 2018 8:54 PM
To: Claims Dept of CTI
Subject: DIRECT SETTLEMENT FOR SDQ6228J AND SFE1519S
Attachments: 0967_001.pdf

Importance: High

Hi

Please refer to the above attachment and check if possible for direct settlement

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4895 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2018 14:04
Date Of Accident	16/10/2018 07:00
Exact Location Of Accident	SLIP ROAD FROM HOUGANG AVE 8 TO HOUGANG AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDQ6228J
Insured/Policyholder	
Name Of Registered Owner	CHAN WENG SENG
NRIC No	S7210199E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96811188
Alternative Phone No	OTHERS-96811188

Vehicle Particulars

Manufacturer	VOLVO
Model	S80-2.0 T (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100239158-07
Cover Note Number	

Driver

Name of Driver	CHAN WENG SENG
NRIC No	S7210199E
Date Of Birth	20/03/1972
Occupation	INDOOR
Date Of Driving Pass	08/01/2002
Driving Experience	16 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96811188
Fax Number	
Contact Number	OTHERS-96811188
EMail Address	NOEMAIL

Address	BLK 312 SERANGOON AVENUE 2 #10-174
Postcode	550312
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer attachments.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFE1519S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing w ith my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as w ell as on the external cover of envelopes/mail packages); and/or
 - (v) complying w ith applicable law in administering, processing, handling and/or dealing w ith my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

On 16-10-2018, 7.03am, I stopped my car SP26228J at
Haugens Ave 8, before moving into Haugens Ave 7. Vehicle SFE1519S
hit my rear. There is no injury.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

✓
in 01/11/18

SERVICE ESTIMATE

5863 - C00001 SL: SERVICE SALES - PC

Mr Chan Weng Seng

Blk 312 Serangoon Avenue 2
#10-174

Singapore 550312

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 16/10/2018

WIP No. : 33204

Veh.In/Out: 16/10/2018

*Tel.No. : Mobile: 96811188

Reg.No. : SDQ6228J

Reg.date : 30/11/2010

Mileage : 0

Chassis No: YV1AS445881138397

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Chan Weng Seng

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER,REAR LO SPOLIER,REAR BRACKET,REAR SENSOR,ETC	0		2400.00	0		2,400.00 S	for ✓
800	TO PUTTY SPRAY PAINT ON REAR BUMPER,REAR LOWER SPOLIER,ETC	0		2100.00	0		2,100.00 S	700 ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		450.00	0		450.00 S	✓
1	BUMPER COVER REAR S8	1.0	EA	1454.80			1,454.80 S	1309.32
2	BUMPER SPOILER REAR	1.0	EA	434.30			434.30 S	390.87
3	BUMPER BRACKET LHR C	1.0	EA	35.70			35.70 S	
4	V030655125/BUMPER BR	1.0	EA	35.70			35.70 S	
5	BUMPER BRACKET LHR S	1.0	EA	71.70			71.70 S	
6	BUMPER BRACKET RHR S	1.0	EA	73.90			73.90 S	
7	BUMPER BRACKET REAR	1.0	EA	104.30			104.30 S	
8	BUMPER RAIL (BEAM) R	1.0	EA	1326.50			1,326.50 S	
9	BUMPER INSTALLING MT	1.0	EA	83.40			83.40 S	75.06

SERVICE ESTIMATE

5863 - C00001 SL: SERVICE SALES - PC

Mr Chan Weng Seng
Blk 312 Serangoon Avenue 2
#10-174

Singapore 550312

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 16/10/2018

WIP No. : 33204

Veh.In/Out: 16/10/2018

*Tel.No. : Mobile: 96811188

Reg.No. : SDQ6228J

Reg.date : 30/11/2010

Mileage : 0

Chassis No: YV1AS445BB1138397

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Chan Weng Seng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

10	BLIND RIVET 4.0*21 P <i>ne</i>	10.0 EA	3.00			30.00 S	27
11	BUMPER CLIP <i>ne</i>	10.0 EA	5.40			54.00 S	45.60
12	ADHESIVE TUBE CHEMIC <i>2X11</i>	4.0 EA	75.80			303.20 S	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *ne* after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
3 days
01/11/18 @ 1345
Resue by paint
8/11/18

Labour Total	4,950.00
Parts Total	4,007.50
Package Total	0.00

Gross Total.	8,957.50
Net.....	8,957.50
GST @ 7.0%	627.03
Total.....	9,584.55
Paid.....	0.00
Please Pay..	9,584.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 07/11/2018
 SINGAPORE 079909 WIP No. : 33204
 Veh.In/Out: 01/11/2018 04/11/2018

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Mr Chan Weng Seng

*Tel.No. : 63896111
 Reg.No. : SDQ6228J
 Reg.date : 30/11/2010
 Mileage : 0
 Chassis No: YV1AS445881138397

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER,REAR LO	0		800.00	0		800.00	
	SPOILER,REAR BRACKET,REAR							
	SENSOR,ETC							
800	TO PUTTY SPRAY PAINT ON REAR	0		700.00	0		700.00	
	BUMPER,REAR LOWER SPOILER,ETC							
280	TO CHECK WIRING INCLUDE	0		450.00	0		450.00	
	RESETTING OF ALL ELECTRICAL							
	MODULES							
	BUMPER COVER REAR S8 ①	1.0	EA	1454.80	10		1,309.32	S
	BUMPER SPOILER REAR ②	1.0	EA	434.30	10		390.87	S
	BUMPER INSTALLING MT ③	1.0	EA	83.40	10		75.06	S
	BLIND RIVET 4.0*21 P ④	10.0	EA	3.00	10		27.00	S
	BUMPER CLIP ⑤	10.0	EA	5.40	10		48.60	S

Gross Total. 3,800.85

Labour Total 1,950.00
 Parts Total 1,850.85
 Package Total 0.00

Net..... 3,800.85
 GST @ 7.0% 266.06
 Total..... 4,066.91
 Paid..... 0.00
 Please Pay.. 4,066.91

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 8 November 2018 11:01 AM
To: 'Richmond Ho'; Rasul (LKKAUTO); SUR
Cc: Derek Oh Siong Wee
Subject: RE: Final Bill For SDQ 6228J

Dear Richmond,

WITHOUT PREJUDICE

Confirm amount \$3800.85 before GST @ 3 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richmond Ho <richmond.ho@wearnes.com>
Sent: Wednesday, 7 November 2018 3:01 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Derek Oh Siong Wee <derek.oh@wearnes.com>
Subject: Final Bill For SDQ6228J
Importance: High

Hi Rasul,

Please refer to above attachment for the final bill.

Richmond Ho
Senior Service Consultant
Body & Paint – Insurance Claim



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4890 M (65) 9176 8543
www.wearnesauto.com richmond.ho@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2018		19 Oct 2018 13:13 Edit Adj Rpt	S\$3,800.85 Edit Estimates	S\$3,800.85 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
[Created by insurer]									
CLAIM SUBFOLDER DETAILS									
Insured:	GUEE SU INK, ID: S6923503D								
Main Claimant:	CHAN WENG SENG								
Vehicle Reg. No.:	SDQ6228J	Date of Loss:	16/10/2018 07:00 - :59 [94 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04958C02	Policy/Cover Note No.:	DMPCSN3009911801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SFE1519S	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/10/2018]								
Adj Asg. Remarks:	EST \$9584.55, CASE WITH SJE.								
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDQ6228J (SNM18D04958C02)**
[SFE1519S]

TP

CHAN WENG SENG

Oct 16 2018 7:00AM

[GUEE SU INK]

Wearnes Automotive Pte Ltd

[View](#) [View in Browser](#)

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/10/18 10:44	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
2	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
3	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
4	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
5	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
6	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
7	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
8	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
9	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
10	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG
11	17/10/18 10:43	Accident Photo [Linked Accident Report Documents]		Load JPG

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/18 10:56	General View		Load PDF

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/10/18 13:11	EMAIL FM WEARNES		Load PDF
2	19/10/18 13:12	REPAIR EST WITH TP GIA		Load PDF
3	19/10/18 13:12	OI GIA		Load PDF

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	17/10/18 10:42	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG
2	17/10/18 10:42	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG
3	17/10/18 10:42	Identification Card [Linked Accident Report Documents]		Load JPG
4	17/10/18 10:42	Driving Licence [Linked Accident Report Documents]		Load JPG
5	17/10/18 10:43	NOTICE OF COMPLIANCE [Linked Accident Report Documents]		Load JPG

Linked Accident Report Documents

Assessment Reports

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	1 per page ▾	Thumbnail	Print
1	17/10/18 10:44	Accident Statement	1	Load HTM	

Photos/Images

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	3 per page ▾	Thumbnail	Print
1	17/10/18 10:43	Accident Photo	1	Load JPG	✓
2	17/10/18 10:43	Accident Photo	1	Load JPG	✓
3	17/10/18 10:43	Accident Photo	1	Load JPG	✓
4	17/10/18 10:43	Accident Photo	1	Load JPG	✓
5	17/10/18 10:43	Accident Photo	1	Load JPG	✓
6	17/10/18 10:43	Accident Photo	1	Load JPG	✓
7	17/10/18 10:43	Accident Photo	1	Load JPG	✓
8	17/10/18 10:43	Accident Photo	1	Load JPG	✓
9	17/10/18 10:43	Accident Photo	1	Load JPG	✓
10	17/10/18 10:43	Accident Photo	1	Load JPG	✓
11	17/10/18 10:43	Accident Photo	1	Load JPG	✓

Documentation

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	1 per page ▾	Thumbnail	Print
1	17/10/18 10:42	Accident Sketch Plan	1	Load JPG	✓
2	17/10/18 10:42	Accident Sketch Plan	1	Load JPG	✓
3	17/10/18 10:42	Identification Card	1	Load JPG	✓
4	17/10/18 10:42	Driving Licence	1	Load JPG	✓
5	17/10/18 10:43	NOTICE OF COMPLIANCE	1	Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019037/R1VD3S2
Date: 15/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3009911801
Claimant Vehicle No: SDQ6228J Insured Vehicle No: SFE1519S
Date of Loss: 16/10/2018 Nature of Claim: TP Claim No: SNM18D04958C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDQ6228J** Engine No: B4204T64000746
Make & Model: VOLVO S80, 1.6 D 2 (A) Chassis No: YV1AS445BB1138397
Reg. Date: 30/11/2010 (Man. Year: 2010) Odometer: 171951 km
Colour: Grey
Engine Capacity: 1999 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35ZR19 Rear Tyre Size: 245/35ZR19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm
The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	4,007.50	1,850.85	2,156.65	53.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	1,950.00	3,000.00	60.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,957.50	3,800.85	5,156.65	57.57
+ GST 7.00/7.00% (S\$)	627.03	266.06	360.97	57.57
Nett Amount (S\$)	9,584.53	4,066.91	5,517.62	57.57

INSPECTION

Date of Assignment: 19/10/2018
Date Inspected: 01/11/2018 Inspected At: Wearnes Automotive Pte Ltd (Alexandra Road)
Estimated Period of Repair: 3.0 days 249 Alexandra Road
Singapore 159935

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2018)

Parts: 143 VOLVO S80 1.6 D 2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDQ6228J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR S8	Cut	1,454.80 FS	*1,309.32 FS
2	1		*BUMPER SPOILER REAR	Deformed	434.30 FS	*390.87 FS
3	1		*BUMPER BRACKET LHR C	Serviceable	35.70 FS	*-FS
4	1		*V030655125/BUMPER BR	Serviceable	35.70 FS	*-FS
5	1		*BUMPER BRACKET LHR S	Serviceable	71.70 FS	*-FS
6	1		*BUMPER BRACKET RHR S	Serviceable	73.90 FS	*-FS
7	1		*BUMPER BRACKET REAR	Serviceable	104.30 FS	*-FS
8	1		*BUMPER RAIL (BEAM) R	Serviceable	1,326.50 FS	*-FS
9	1		*BUMPER INSTALLING MT	Necessary	83.40 FS	*75.06 FS
10	10		*BLIND RIVET 4.0*21 P	Necessary	30.00 FS	*27.00 FS
11	10		*BUMPER CLIP	Necessary	54.00 FS	*48.60 FS
12	4		*ADHESIVE TUBE CHEMIC	Not Necessary	303.20 FS	*-FS
Total Parts (S\$)					4,007.50	1,850.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR LO SPOILER, REAR BRACKET, REAR SENSOR ETC.	New	2,400.00	800.00
2	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LOWER SPOILER, ETC.	New	2,100.00	700.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.	New	450.00	450.00
Gross Labour Cost (\$\$)			4,950.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >